

## Mahindra First Choice Wheels Certification Report

**2014 MARUTI SUZUKI SWIFT DZIRE(2011-2015) VXI**

Chennai | 22816 km | Petrol | Manual | Silver Colour | 1st Owner

✓ Eligible for Warranty ✓ 140+ Points InspectedExterior FairInterior FairEngine & Transmission Fair

Overall  
**Fair Buy** 🤝



*M Mahajan*  
M Mahajan  
Head Certification  
& Warranty - MFCWL

[Explore this car in website](#)[View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **140+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

## Vehicle Details

Owner Name

**Sri Velavan Cars**

Registration Month

**October**

Registration Year

**2014**

Color

**Silver**

Odometer Reading(km)

**22816**

Registration Number

**TN13XXXXX**

No of Owners

**1**

Insurance Status

**Available**

Chassis Number

**MA3EXXXXXXXXXXXXXX**

Engine Number

**K12MXXXXXXXXXX**

Insurance Type

**Company**

Remarks

**.**

Remarks

**.**

RC Status

**RC Available**

PUC Certificate

**Available**

Keys Availability

**In Good Condition**

Transfer Papers Availability

**All RTO papers available  
and valid NOC from Bank**

Vehicle Status

**Certified**

[View in Website](#)

**Front Bumper**

Condition : Good

Clean & slight color difference

**Grill / Emblem**

Condition : Good

No color fading marks & minimal scratches

**Windscreen glass**

Condition : Good

Minimal scratches

**Right Running Board**

Condition : Good

1-2 minor dents & minimal scratches

**Right Quarter Panel**

Condition : Good

1-2 minor dents & minimal scratches

**Right Fender**

Condition : Good

1-2 minor dents & minimal scratches

**Front Right Door**

Condition : Good

1-2 minor dents & minimal scratches

**Rear Right Indicator**

Condition : Good

Working & with very minimal scratches

**Rear Right Indicator**

Condition : Good

Working & with very minimal scratches

**Right Doors Functionality**

Condition : Good

Smooth to operate but little hinge play & no noise

**RH Side All Pillars**

Condition : Excellent

Spot welding original

**Right Side View Mirror**

Condition : Excellent

Operating smoothly & no scratches

**Windscreen Washer and Jets**

Condition : Excellent

Smooth operations

**Trunk**

Condition : Good

1-2 minor dents & minimal scratches

**Bonnet**

Condition : Good

1-2 minor dents & minimal scratches

**Front Right Tyre**

Condition : Good

Same Make/ Good & > 60% life

**Rear Right Tyre**

Condition : Good

Same Make/ Good & > 60% life

**Trunk, Bonnet and Hood functionality**

Condition : Excellent

Operating smoothly

## Exterior (Continued...)

### Rear Bumper

Condition : **Good**

Clean & slight color difference

### Spare Tyre

Condition : **Excellent**

Same Make/ Good & > 80% life

### Number Plate (Front & Rear)

Condition : **Excellent**

Good condition

### Left Running Board

Condition : **Good**

1-2 minor dents & minimal scratches

### Left Quarter Panel

Condition : **Good**

1-2 minor dents & minimal scratches

### Left Fender

Condition : **Good**

1-2 minor dents & minimal scratches

### Front Left Door

Condition : **Good**

1-2 minor dents & minimal scratches

### Rear Left Door

Condition : **Good**

1-2 minor dents & minimal scratches

### Left Doors Functionality

Condition : **Good**

Smooth to operate but little hinge play & no noise

### LH Side All Pillars

Condition : **Excellent**

Spot welding original

### Left Side View Mirror

Condition : **Excellent**

Operating smoothly & no scratches

### Fuel Cap - Check Operation/ Noise

Condition : **Excellent**

Operating smoothly

### Front Left Tyre

Condition : **Good**

Same Make/ Good & > 60% life

### Rear Left Tyre

Condition : **Good**

Same Make/ Good & > 60% life

### Frame or Underbody

Condition : **Good**

1-2 panels changed

### Paint, Polishing and Gloss

Condition : **Excellent**

No difference or negligible difference in color of panels

### Parking lights Front & Rear

Condition : **Good**

Working & with very minimal scratches

### Right Taillight

Condition : **Good**

Working & with very minimal scratches

## Exterior (Continued...)

### Left Taillight

Condition : **Good**

Working & with very minimal scratches

### Rear Left Indicator

Condition : **Good**

Working & with very minimal scratches

### Front Left Indicator

Condition : **Good**

Working & with very minimal scratches

### Front Right Indicator

Condition : **Good**

Working & with very minimal scratches

### Left Headlight (Both Points)

Condition : **Good**

Working & with very minimal scratches

### Right Headlight (Both Points)

Condition : **Good**

Working & with very minimal scratches

### Wheel Rim (Steel / Alloy) (Including Spare Wheel)

Condition : **Good**

Ok but very little color fading

### Spare Wheel Cover

Condition : **Excellent**

Good condition

### Fog lamps

Condition : **Good**

Operating but lens ok/ Minor Scratches

### Alloy Wheels

Condition : **NA**

Not Applicable

### Wheel Cap

Condition : **Excellent**

All 4 available & in good condition

**Carpet - Cleanliness, torn off, proper size**

Condition : Good

Ok but some stains

**All Door Trim**

Condition : Good

Dirty & negligible rattling noise

**Seat Adjustment**

Condition : Excellent

Working smoothly

**Safety Belts Inertia Locking System**

Condition : Excellent

Smooth to operate

**Dashboard**

Condition : Good

Some scratches & minimal rattling noise

**Rubber Beading (All)**

Condition : Good

No cut marks; Wear & tear marks in some places

**Window Mechanisms**

Condition : Excellent

Operating smoothly (All 4)

**Inside Rear View Mirror**

Condition : Excellent

Operating smoothly & no scratches

**Seat Condition**

Condition : Excellent

Seat cover is in good condition

**Instrument Panel Gauges**

Condition : Excellent

Operations & Visibility good

**Instrument Panel Warning Lights**

Condition : Excellent

Operating

**Horns**

Condition : Excellent

Operating

**Wipers (all speeds)**

Condition : Excellent

Smooth to operate

**Combination Switch**

Condition : Good

Operating but minimal wear & tear marks

**Clock / Stereo controls / Power windows & other electrical controls**

Condition : Excellent

Working smoothly

**Cigarette Lighter / Charger / USB Port**

Condition : Excellent

Working & in good condition

**Interior lights**

Condition : Excellent

Working smoothly

**Hazard lights**

Condition : Excellent

Working & in good condition

## Interior (Continued...)

### Trunk Light

Condition : **Excellent**

Working & in good condition

### AC Cooling

Condition : **Good**

Good

### Heating

Condition : **Excellent**

Working

### Air distribution (AC Vents)

Condition : **Excellent**

Operating & in good condition

### Recirculation/ Fresh air

Condition : **Excellent**

Operating Smoothly

### Manual / Power Steering (Electronic/Hydraulic)

Condition : **Excellent**

Operations are smooth & no noise/ play observed

### Hand Brake

Condition : **Good**

Operating but not very smooth

### Music System

Condition : **Good**

Ok but some wear & tear marks

### Speakers

Condition : **Good**

Ok but sound quality ok

### Defogger

Condition : **Excellent**

Operating & in good condition

### CNG/LPG kit

Condition : **NA**

Not Applicable

### Central Locking System

Condition : **Excellent**

In good condition & smooth operation

### Jack And Tommy (Tool Kit)

Condition : **Excellent**

Available & in very good condition

**Dickey Shock Absorber**

Condition : **Good**

Ok with No leakage marks /  
Operation slightly weak

**Battery - Specification /  
Voltage check / Check  
Petroleum Jelly Application**

Condition : **Excellent**

Operating smooth & < 2 years  
old

**Alternator**

Condition : **Excellent**

Smooth Operations

**Starter Motor**

Condition : **Excellent**

Smooth Operations

**Fuel Pump ( Petrol)**

Condition : **Excellent**

Smooth operations

**AC Compressor**

Condition : **Excellent**

Working smoothly

**Condenser Fan**

Condition : **Excellent**

No noise & smooth operation  
(Proper cut-off)

**Blower motor**

Condition : **Excellent**

Smooth operations

**Steering Rattling Noise**

Condition : **Excellent**

Smooth & no noise

**Suspension Arms**

Condition : **Excellent**

Working smoothly

**Front struts (Shock absorber)**

Condition : **Good**

Ok but slightly hard & no  
leakage sign

**Rear Shock Absorber/Spring**

Condition : **Excellent**

No noise & smooth Operation

**Stabiliser Bar & Other Bushes**

Condition : **Satisfactory**

Ok but slightly hard

**ABS**

Condition : **Excellent**

Smooth Operation (High Speed  
Pedal Vibration)

**Brake Pedal**

Condition : **Good**

Ok but slightly less efficient  
operations/ No excessive play

**Check Front Brake**

Condition : **Excellent**

Smooth operation & braking  
efficiency

**Check Rear Brake**

Condition : **Excellent**

Smooth operation & braking  
efficiency

**Master Cylinder / Wheel  
Cylinder**

Condition : **Excellent**

Smooth operation



**Braking Efficiency**

Condition : **Excellent**

Operating smoothly

**Gearshift level (Gear Engagement)**

Condition : **Excellent**

Smooth operation

**Gear Lever Play**

Condition : **Excellent**

Smooth operation

**Clutch Engagement**

Condition : **Excellent**

Smooth operation

**Clutch Pedal / Cable Operation**

Condition : **Excellent**

Smooth

**Axle Noise/Drive Shaft Boot Damage**

Condition : **Excellent**

No noise

**Front & Rear Wheel Bearings**

Condition : **Excellent**

No noise

**Differential**

Condition : **Excellent**

Smooth operations

**Alignment/Balancing**

Condition : **Excellent**

No pulling

**Transmission Oil (Manual/ Automatic)**

Condition : **Excellent**

No Leakage/ Good condition  
(Changed during Refurbishment)

**Engine and Transmission Mountings**

Condition : **Excellent**

No Noise/Vibrations

**Abnormal Engine Noise/ Back Compression**

Condition : **Excellent**

No noise (Tappet as well as Knocking noise)

**Engine Oil Leaks: Cylinder Head Gasket**

Condition : **Excellent**

No leakage/ Good condition  
(Changed during refurbishment)

**Gasket: Tappet Cover**

Condition : **Excellent**

No leakage

**Engine Oil Leaks: Crankcase Oil Seals/ Camshaft**

Condition : **Excellent**

No leakage

**Engine Oil Leaks: Sump Gasket**

Condition : **Excellent**

No leakage

**Engine Oil Leaks: Sump Damage**

Condition : **Excellent**

No leakage/ Damage

**Exhaust system**

Condition : **Excellent**

No noise, No rusting sign & smooth Operation

## Engine & Transmission (Continued...)

### Smoke Color (Blue)

Condition : **Excellent**

No Color

### Smoke Color (Black)

Condition : **Excellent**

No Color

### Smoke Color (White)

Condition : **Excellent**

No Color

### Air Filter

Condition : **Excellent**

Good condition (Changed during refurbishment)

### Radiator /Condenser

Condition : **Excellent**

Good Condition & no damage/rusting sign

### Engine oil

Condition : **Excellent**

No Leakage/ Good condition (Changed during RF)

### Coolant

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

### Brake Oil

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

### Hose Pipe

Condition : **Excellent**

Good condition

### Alternator Drive Belt

Condition : **Excellent**

Good condition

### Water Pump

Condition : **Excellent**

Good Condition & no noise

### Tappet Noise

Condition : **Excellent**

No noise

### Turbo Charger

Condition : **NA**

Not Applicable

### Heater Plugs / Spark Plugs

Condition : **Excellent**

Good condition (Changed during refurbishment)

### Radiator Fan

Condition : **Excellent**

No noise & smooth Operation (Proper cut-off)

### Charcoal Canister

Condition : **Excellent**

No damage & Petrol fume

### Ignition Coil (petrol only)

Condition : **Excellent**

Working smoothly

### Ignition Wire Harness (petrol only)

Condition : **Excellent**

Wiring & insulation good condition

## Engine & Transmission (Continued...)

### Fuel Tank and Pipes

Condition : **Excellent**

Good condition

### Fuel Filter (Petrol & Diesel)

Condition : **Excellent**

Good condition (Changed during refurbishment)

### Fuel Injection Pump (Diesel)

Condition : **Excellent**

No leakage & in good condition

## Vehicle Images

### Front Side



10-Oct-2022 11:58:59 am

Lat 13.0534469,Long 80.1664061

### Front Right Side



10-Oct-2022 11:59:09 am

Lat 13.0541676,Long 80.1663828

### Front Right Tyre



10-Oct-2022 11:59:27 am

Lat 13.0541422,Long 80.1663511

### Right Side



10-Oct-2022 11:59:19 am

Lat 13.0541488,Long 80.166448

### Rear Right Tyre



10-Oct-2022 11:59:36 am

Lat 13.0541634,Long 80.1663437

### Rear Right Side



10-Oct-2022 11:59:45 am

Lat 13.0541091,Long 80.1663626

### Back Side



10-Oct-2022 11:59:53 am

Lat 13.0540112,Long 80.1663967

### Rear Left Side



10-Oct-2022 12:00:02 pm

Lat 13.0541191,Long 80.1664239

[View this car in Website](#)



Rear Left Tyre



10-Oct-2022 12:00:18 pm

Lat 13.0543465,Long 80.1666337

Front Left Tyre



10-Oct-2022 12:00:28 pm

Lat 13.0542163,Long 80.166458

Odometer



10-Oct-2022 12:02:01 pm

Lat 13.0541613,Long 80.1663451

Left Side



10-Oct-2022 12:00:11 pm

Lat 13.054362,Long 80.1666376

Front Left Side



10-Oct-2022 12:00:36 pm

Lat 13.0531108,Long 80.168783