


Mahindra First Choice Wheels Certification Report



2015 CHEVROLET SAIL(2014-2017) 1.3 LS

Nagpur | 72334 km | Diesel | Manual | Black Colour | 1st Owner

- ✔ Eligible for Warranty
- ✔ 140+ Points Inspected



Overall
Fair Buy 🙌



[Explore this car in website](#)
View in Website

Overall rating is the 'quality score' of a vehicle derived from a **140+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

Saakaars

Registration Month

October

Registration Year

2015

Color

Black

Odometer Reading(km)

72334

Registration Number

MH12XXXXXX

No of Owners

1

Insurance Status

Available

Chassis Number

MA6SXXXXXXXXXXXXXX

Engine Number

10FCXXXXXXXXXXXX

Remarks

All Good

Remarks

All Good

RC Status

RC Available

PUC Certificate

Available

Keys Availability

In Good Condition

Transfer Papers Availability

All Papers available

Vehicle Status

Certified

[View in Website](#)

Front Bumper

Condition : **Good**

Clean & slight color difference

Grill / Emblem

Condition : **Excellent**

No scratch & in good condition

Windscreen glass

Condition : **Excellent**

Clean, No marks

Right Running Board

Condition : **Excellent**

No dents & scratches

Right Quarter Panel

Condition : **Excellent**

No dents or scratches

Right Fender

Condition : **Excellent**

No dents or scratches

Front Right Door

Condition : **Excellent**

No dents or scratches

Rear Right Indicator

Condition : **Excellent**

Working & in good condition

Rear Right Indicator

Condition : **Excellent**

Working & in good condition

Right Doors Functionality

Condition : **Excellent**

Smooth to operate

RH Side All Pillars

Condition : **Excellent**

Spot welding original

Right Side View Mirror

Condition : **Excellent**

Operating smoothly & no scratches

Windscreen Washer and Jets

Condition : **Excellent**

Smooth operations

Trunk

Condition : **Excellent**

No dents or scratches

Bonnet

Condition : **Excellent**

No dents or scratches

Front Right Tyre

Condition : **Good**

Same Make/ Good & > 60% life

Rear Right Tyre

Condition : **Good**

Same Make/ Good & > 60% life

Trunk, Bonnet and Hood functionality

Condition : **Excellent**

Operating smoothly

Exterior (Continued...)

Rear Bumper

Condition : **Excellent**

No damage

Spare Tyre

Condition : **Good**

Same Make/ Good & > 60% life

Number Plate (Front & Rear)

Condition : **Excellent**

Good condition

Left Running Board

Condition : **Excellent**

No dents or scratches

Left Quarter Panel

Condition : **Excellent**

No dents or scratches

Left Fender

Condition : **Excellent**

No dents or scratches

Front Left Door

Condition : **Excellent**

No dents or scratches

Rear Left Door

Condition : **Excellent**

No dents or scratches

Left Doors Functionality

Condition : **Excellent**

Smooth to operate

LH Side All Pillars

Condition : **Excellent**

Spot welding original

Left Side View Mirror

Condition : **Excellent**

Operating smoothly & no scratches

Fuel Cap - Check Operation/ Noise

Condition : **Excellent**

Operating smoothly

Front Left Tyre

Condition : **Good**

Same Make/ Good & > 60% life

Rear Left Tyre

Condition : **Good**

Same Make/ Good & > 60% life

Frame or Underbody

Condition : **Excellent**

No panel changed

Paint, Polishing and Gloss

Condition : **Excellent**

No difference or negligible difference in color of panels

Parking lights Front & Rear

Condition : **Excellent**

Working & in good condition

Right Taillight

Condition : **Excellent**

Working & in good condition

Exterior (Continued...)

Left Taillight

Condition : **Excellent**

Working & in good condition

Rear Left Indicator

Condition : **Excellent**

Working & in good condition

Front Left Indicator

Condition : **Excellent**

Working & in good condition

Front Right Indicator

Condition : **Excellent**

Working & in good condition

Left Headlight (Both Points)

Condition : **Excellent**

Working & in good condition

Right Headlight (Both Points)

Condition : **Excellent**

Working & in good condition

**Wheel Rim (Steel / Alloy)
(Including Spare Wheel)**

Condition : **Excellent**

Good condition

Spare Wheel Cover

Condition : **Excellent**

Good condition

Fog lamps

Condition : **Excellent**

Operating & in good condition

Alloy Wheels

Condition : **NA**

Not Applicable

Wheel Cap

Condition : **Excellent**

All 4 available & in good condition

Carpet - Cleanliness, torn off, proper size

Condition : **Excellent**

OK & almost negligible stains

All Door Trim

Condition : **Excellent**

Clean & no rattling noise

Seat Adjustment

Condition : **Excellent**

Working smoothly

Safety Belts Inertia Locking System

Condition : **Excellent**

Smooth to operate

Dashboard

Condition : **Excellent**

Clean & no rattling noise

Rubber Beading (All)

Condition : **Excellent**

Clean & No wear & tear marks

Window Mechanisms

Condition : **Excellent**

Operating smoothly (All 4)

Inside Rear View Mirror

Condition : **Excellent**

Operating smoothly & no scratches

Seat Condition

Condition : **Excellent**

Seat cover is in good condition

Instrument Panel Gauges

Condition : **Excellent**

Operations & Visibility good

Instrument Panel Warning Lights

Condition : **Excellent**

Operating

Horns

Condition : **Excellent**

Operating

Wipers (all speeds)

Condition : **Excellent**

Smooth to operate

Combination Switch

Condition : **Excellent**

Operating smoothly & not faded

Clock / Stereo controls / Power windows & other electrical controls

Condition : **Excellent**

Working smoothly

Cigarette Lighter / Charger / USB Port

Condition : **Excellent**

Working & in good condition

Interior lights

Condition : **Excellent**

Working smoothly

Hazard lights

Condition : **Excellent**

Working & in good condition

Interior (Continued...)

Trunk Light

Condition : **Excellent**

Working & in good condition

AC Cooling

Condition : **Good**

Good

Heating

Condition : **Excellent**

Working

Air distribution (AC Vents)

Condition : **Excellent**

Operating & in good condition

Recirculation/ Fresh air

Condition : **Excellent**

Operating Smoothly

**Manual / Power Steering
(Electronic/Hydraulic)**

Condition : **Excellent**

Operations are smooth & no noise/ play observed

Hand Brake

Condition : **Excellent**

Smooth operations

Music System

Condition : **Excellent**

Working properly & in very good condition

Speakers

Condition : **Good**

Ok but sound quality ok

Defogger

Condition : **Excellent**

Operating & in good condition

CNG/LPG kit

Condition : **NA**

Not Applicable

Central Locking System

Condition : **Good**

Working but some wear & tear marks

Jack And Tommy (Tool Kit)

Condition : **Good**

Available & in good condition

Dickey Shock Absorber

Condition : **Excellent**

Ok & in good condition

Battery - Specification / Voltage check / Check Petroleum Jelly Application

Condition : **Excellent**

Operating smooth & < 2 years old

Alternator

Condition : **Excellent**

Smooth Operations

Starter Motor

Condition : **Excellent**

Smooth Operations

Fuel Pump (Petrol)

Condition : **Excellent**

Smooth operations

AC Compressor

Condition : **Excellent**

Working smoothly

Condenser Fan

Condition : **Excellent**

No noise & smooth operation (Proper cut-off)

Blower motor

Condition : **Excellent**

Smooth operations

Steering Rattling Noise

Condition : **Excellent**

Smooth & no noise

Suspension Arms

Condition : **Excellent**

Working smoothly

Front struts (Shock absorber)

Condition : **Excellent**

No noise, Smooth Operation

Rear Shock Absorber/Spring

Condition : **Excellent**

No noise & smooth Operation

Stabiliser Bar & Other Bushes

Condition : **Excellent**

No noise & smooth operation

ABS

Condition : **Excellent**

Smooth Operation (High Speed Pedal Vibration)

Brake Pedal

Condition : **Excellent**

Smooth Operation & Play

Check Front Brake

Condition : **Excellent**

Smooth operation & braking efficiency

Check Rear Brake

Condition : **Excellent**

Smooth operation & braking efficiency

Master Cylinder / Wheel Cylinder

Condition : **Excellent**

Smooth operation

Engine & Transmission (Continued...)

Braking Efficiency

Condition : **Excellent**
Operating smoothly

Gearshift level (Gear Engagement)

Condition : **Excellent**
Smooth operation

Gear Lever Play

Condition : **Excellent**
Smooth operation

Clutch Engagement

Condition : **Excellent**
Smooth operation

Clutch Pedal / Cable Operation

Condition : **Excellent**
Smooth

Axle Noise/Drive Shaft Boot Damage

Condition : **Excellent**
No noise

Front & Rear Wheel Bearings

Condition : **Excellent**
No noise

Differential

Condition : **Excellent**
Smooth operations

Alignment/Balancing

Condition : **Excellent**
No pulling

Transmission Oil (Manual/ Automatic)

Condition : **Excellent**
No Leakage/ Good condition
(Changed during Refurbishment)

Engine and Transmission Mountings

Condition : **Excellent**
No Noise/Vibrations

Abnormal Engine Noise/ Back Compression

Condition : **Excellent**
No noise (Tappet as well as Knocking noise)

Engine Oil Leaks: Cylinder Head Gasket

Condition : **Excellent**
No leakage/ Good condition
(Changed during refurbishment)

Gasket: Tappet Cover

Condition : **Excellent**
No leakage

Engine Oil Leaks: Crankcase Oil Seals/ Camshaft

Condition : **Excellent**
No leakage

Engine Oil Leaks: Sump Gasket

Condition : **Excellent**
No leakage

Engine Oil Leaks: Sump Damage

Condition : **Excellent**
No leakage/ Damage

Exhaust system

Condition : **Excellent**
No noise, No rusting sign & smooth Operation

Engine & Transmission (Continued...)

Smoke Color (Blue)

Condition : **Excellent**

No Color

Smoke Color (Black)

Condition : **Excellent**

No Color

Smoke Color (White)

Condition : **Excellent**

No Color

Air Filter

Condition : **Excellent**

Good condition (Changed during refurbishment)

Radiator /Condenser

Condition : **Excellent**

Good Condition & no damage/rusting sign

Engine oil

Condition : **Excellent**

No Leakage/ Good condition (Changed during RF)

Coolant

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

Brake Oil

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

Hose Pipe

Condition : **Excellent**

Good condition

Alternator Drive Belt

Condition : **Excellent**

Good condition

Water Pump

Condition : **Excellent**

Good Condition & no noise

Tappet Noise

Condition : **Excellent**

No noise

Turbo Charger

Condition : **Excellent**

Good condition

Heater Plugs / Spark Plugs

Condition : **Excellent**

Good condition (Changed during refurbishment)

Radiator Fan

Condition : **Excellent**

No noise & smooth Operation (Proper cut-off)

Charcoal Canister

Condition : **Excellent**

No damage & Petrol fume

Ignition Coil (petrol only)

Condition : **Excellent**

Working smoothly

Ignition Wire Harness (petrol only)

Condition : **Excellent**

Wiring & insulation good condition

Engine & Transmission (Continued...)

Fuel Tank and Pipes

Condition : **Excellent**

Good condition

Fuel Filter (Petrol & Diesel)

Condition : **Excellent**

Good condition (Changed during refurbishment)

Fuel Injection Pump (Diesel)

Condition : **Excellent**

No leakage & in good condition

Vehicle Images

Front Side



Front Right Side



Oct 7, 2022 2:10:30 PM

Lat 21.1280183, Long 79.1048082

Front Right Tyre



Oct 7, 2022 2:10:37 PM

Lat 21.1280306, Long 79.1047922

Right Side



Oct 7, 2022 2:10:47 PM

Lat 21.1280306, Long 79.1047922

Rear Right Tyre



Oct 7, 2022 2:10:54 PM

Lat 21.1280227, Long 79.1047822

Rear Right Side



Oct 7, 2022 2:11:03 PM

Lat 21.1280227, Long 79.1047822

Back Side



Oct 7, 2022 2:11:09 PM

Lat 21.1280254, Long 79.1047922

Rear Left Side



Oct 7, 2022 2:11:16 PM

Lat 21.1280293, Long 79.1047845

[View this car in Website](#)

Rear Left Tyre



Oct 7, 2022 2:11:24 PM

Lat 21.1280157,Long 79.1047391

Left Side



Oct 7, 2022 2:11:32 PM

Lat 21.1280157,Long 79.1047391

Front Left Tyre



Oct 7, 2022 2:11:39 PM

Lat 21.1280201,Long 79.1047704

Front Left Side



Oct 7, 2022 2:11:47 PM

Lat 21.1280201,Long 79.1047704

Odometer



Oct 7, 2022 2:15:56 PM

Lat 21.1280309,Long 79.1047737