

Mahindra First Choice Wheels Inspection Report



2012 NISSAN MICRA(2010-2013) XV DIESEL

Dehradun | 97076 km | Diesel | Manual | Red Colour | 1st Owner

- ✔ Assist First Warranty
- ✔ 140+ Points Inspected



Exterior	Fair
<hr style="border: 1px solid orange;"/>	
Interior	Fair
<hr style="border: 1px solid orange;"/>	
Engine & Transmission	Fair
<hr style="border: 1px solid orange;"/>	

Overall
Fair Buy 🍀

VERIFIED
M Mahajan
Head Certification & Warranty - MFCWL

Explore this car in website [View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **140+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

Dutta Motors

Registration Month

June

Registration Year

2012

Color

Red

Odometer Reading(km)

97076

Registration Number

UK07XXXXXX

No of Owners

1

Insurance Status

Not available

Chassis Number

MDHFXXXXXXXXXXXXXX

Engine Number

K9KAXXXXXXXXXXX

Remarks

ok

Remarks

ok

RC Status

RC Available

PUC Certificate

Available

Keys Availability

In Good Condition

Transfer Papers Availability

**All RTO papers available
and valid NOC from Bank**

Vehicle Status

Inspected

[View in Website](#)

Front Bumper

Condition : Good

Clean & slight color difference

Grill / Emblem

Condition : Good

No color fading marks & minimal scratches

Windscreen glass

Condition : Good

Minimal scratches

Right Running Board

Condition : Good

1-2 minor dents & minimal scratches

Right Quarter Panel

Condition : Good

1-2 minor dents & minimal scratches

Right Fender

Condition : Good

1-2 minor dents & minimal scratches

Front Right Door

Condition : Good

1-2 minor dents & minimal scratches

Rear Right Indicator

Condition : Good

Working & with very minimal scratches

Rear Right Indicator

Condition : Good

Working & with very minimal scratches

Right Doors Functionality

Condition : Good

Smooth to operate but little hinge play & no noise

RH Side All Pillars

Condition : Excellent

Spot welding original

Right Side View Mirror

Condition : Excellent

Operating smoothly & no scratches

Windscreen Washer and Jets

Condition : Excellent

Smooth operations

Trunk

Condition : Good

1-2 minor dents & minimal scratches

Bonnet

Condition : Good

1-2 minor dents & minimal scratches

Front Right Tyre

Condition : Satisfactory

Same Make/ Good & > 40% life

Rear Right Tyre

Condition : Satisfactory

Same Make/ Good & > 40% life

Trunk, Bonnet and Hood functionality

Condition : Excellent

Operating smoothly

Exterior (Continued...)

Rear Bumper

Condition : **Good**

Clean & slight color difference

Spare Tyre

Condition : **Bad**

Different Make/ Cut Marks/
Bulge /< 30% life

Number Plate (Front & Rear)

Condition : **Excellent**

Good condition

Left Running Board

Condition : **Good**

1-2 minor dents & minimal
scratches

Left Quarter Panel

Condition : **Good**

1-2 minor dents & minimal
scratches

Left Fender

Condition : **Good**

1-2 minor dents & minimal
scratches

Front Left Door

Condition : **Good**

1-2 minor dents & minimal
scratches

Rear Left Door

Condition : **Good**

1-2 minor dents & minimal
scratches

Left Doors Functionality

Condition : **Good**

Smooth to operate but little
hinge play & no noise

LH Side All Pillars

Condition : **Excellent**

Spot welding original

Left Side View Mirror

Condition : **Excellent**

Operating smoothly & no
scratches

**Fuel Cap - Check Operation/
Noise**

Condition : **Excellent**

Operating smoothly

Front Left Tyre

Condition : **Satisfactory**

Same Make/ Good & > 40% life

Rear Left Tyre

Condition : **Satisfactory**

Same Make/ Good & > 40% life

Frame or Underbody

Condition : **Good**

1-2 panels changed

Paint, Polishing and Gloss

Condition : **Excellent**

No difference or negligible
difference in color of panels

Parking lights Front & Rear

Condition : **Good**

Working & with very minimal
scratches

Right Taillight

Condition : **Good**

Working & with very minimal
scratches

Exterior (Continued...)

Left Taillight

Condition : **Good**

Working & with very minimal scratches

Rear Left Indicator

Condition : **Good**

Working & with very minimal scratches

Front Left Indicator

Condition : **Good**

Working & with very minimal scratches

Front Right Indicator

Condition : **Good**

Working & with very minimal scratches

Left Headlight (Both Points)

Condition : **Good**

Working & with very minimal scratches

Right Headlight (Both Points)

Condition : **Good**

Working & with very minimal scratches

**Wheel Rim (Steel / Alloy)
(Including Spare Wheel)**

Condition : **Good**

Ok but very little color fading

Spare Wheel Cover

Condition : **Excellent**

Good condition

Fog lamps

Condition : **NA**

Not Applicable

Alloy Wheels

Condition : **NA**

Not Applicable

Wheel Cap

Condition : **Excellent**

All 4 available & in good condition

Carpet - Cleanliness, torn off, proper size

Condition : Good

Ok but some stains

All Door Trim

Condition : Good

Dirty & negligible rattling noise

Seat Adjustment

Condition : Excellent

Working smoothly

Safety Belts Inertia Locking System

Condition : Excellent

Smooth to operate

Dashboard

Condition : Good

Some scratches & minimal rattling noise

Rubber Beading (All)

Condition : Good

No cut marks; Wear & tear marks in some places

Window Mechanisms

Condition : Satisfactory

Operating but not smooth due to run channel hardness

Inside Rear View Mirror

Condition : Excellent

Operating smoothly & no scratches

Seat Condition

Condition : Excellent

Seat cover is in good condition

Instrument Panel Gauges

Condition : Good

Operating, minimal scratches observed

Instrument Panel Warning Lights

Condition : Excellent

Operating

Horns

Condition : Excellent

Operating

Wipers (all speeds)

Condition : Excellent

Smooth to operate

Combination Switch

Condition : Good

Operating but minimal wear & tear marks

Clock / Stereo controls / Power windows & other electrical controls

Condition : Excellent

Working smoothly

Cigarette Lighter / Charger / USB Port

Condition : Excellent

Working & in good condition

Interior lights

Condition : Excellent

Working smoothly

Hazard lights

Condition : Excellent

Working & in good condition

Interior (Continued...)

Trunk Light

Condition : **Satisfactory**

Working but with local lamp cover/ very small scratches

AC Cooling

Condition : **Good**

Good

Heating

Condition : **Excellent**

Working

Air distribution (AC Vents)

Condition : **Excellent**

Operating & in good condition

Recirculation/ Fresh air

Condition : **Excellent**

Operating Smoothly

Manual / Power Steering (Electronic/Hydraulic)

Condition : **Good**

Operations are smooth & minimal play observed

Hand Brake

Condition : **Good**

Operating but not very smooth

Music System

Condition : **Good**

Ok but some wear & tear marks

Speakers

Condition : **Good**

Ok but sound quality ok

Defogger

Condition : **NA**

Not Applicable

CNG/LPG kit

Condition : **NA**

Not Applicable

Central Locking System

Condition : **Excellent**

In good condition & smooth operation

Jack And Tommy (Tool Kit)

Condition : **Excellent**

Available & in very good condition

Dickey Shock Absorber

Condition : Good

Ok with No leakage marks /
Operation slightly weak

**Battery - Specification /
Voltage check / Check
Petroleum Jelly Application**

Condition : Bad

Not Operating / Long to start or
> 5 years old

Alternator

Condition : Excellent

Smooth Operations

Starter Motor

Condition : Excellent

Smooth Operations

Fuel Pump (Petrol)

Condition : Excellent

Smooth operations

AC Compressor

Condition : Satisfactory

Working but low noise
observed

Condenser Fan

Condition : Excellent

No noise & smooth operation
(Proper cut-off)

Blower motor

Condition : Good

Working but with low noise
observed

Steering Rattling Noise

Condition : Excellent

Smooth & no noise

Suspension Arms

Condition : Excellent

Working smoothly

Front struts (Shock absorber)

Condition : Good

Ok but slightly hard & no
leakage sign

Rear Shock Absorber/Spring

Condition : Good

Ok but slightly hard & no
leakage sign

Stabiliser Bar & Other Bushes

Condition : Satisfactory

Ok but slightly hard

ABS

Condition : Excellent

Smooth Operation (High Speed
Pedal Vibration)

Brake Pedal

Condition : Good

Ok but slightly less efficient
operations/ No excessive play

Check Front Brake

Condition : Excellent

Smooth operation & braking
efficiency

Check Rear Brake

Condition : Excellent

Smooth operation & braking
efficiency

**Master Cylinder / Wheel
Cylinder**

Condition : Excellent

Smooth operation

Engine & Transmission (Continued...)

Braking Efficiency

Condition : **Excellent**
Operating smoothly

Gearshift level (Gear Engagement)

Condition : **Excellent**
Smooth operation

Gear Lever Play

Condition : **Excellent**
Smooth operation

Clutch Engagement

Condition : **Excellent**
Smooth operation

Clutch Pedal / Cable Operation

Condition : **Excellent**
Smooth

Axle Noise/Drive Shaft Boot Damage

Condition : **Excellent**
No noise

Front & Rear Wheel Bearings

Condition : **Excellent**
No noise

Differential

Condition : **Excellent**
Smooth operations

Alignment/Balancing

Condition : **Excellent**
No pulling

Transmission Oil (Manual/ Automatic)

Condition : **Excellent**
No Leakage/ Good condition
(Changed during Refurbishment)

Engine and Transmission Mountings

Condition : **Excellent**
No Noise/Vibrations

Abnormal Engine Noise/ Back Compression

Condition : **Excellent**
No noise (Tappet as well as Knocking noise)

Engine Oil Leaks: Cylinder Head Gasket

Condition : **Excellent**
No leakage/ Good condition
(Changed during refurbishment)

Gasket: Tappet Cover

Condition : **Excellent**
No leakage

Engine Oil Leaks: Crankcase Oil Seals/ Camshaft

Condition : **Excellent**
No leakage

Engine Oil Leaks: Sump Gasket

Condition : **Excellent**
No leakage

Engine Oil Leaks: Sump Damage

Condition : **Excellent**
No leakage/ Damage

Exhaust system

Condition : **Excellent**
No noise, No rusting sign & smooth Operation

Engine & Transmission (Continued...)

Smoke Color (Blue)

Condition : **Excellent**

No Color

Smoke Color (Black)

Condition : **Excellent**

No Color

Smoke Color (White)

Condition : **Excellent**

No Color

Air Filter

Condition : **Excellent**

Good condition (Changed during refurbishment)

Radiator /Condenser

Condition : **Excellent**

Good Condition & no damage/rusting sign

Engine oil

Condition : **Excellent**

No Leakage/ Good condition (Changed during RF)

Coolant

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

Brake Oil

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

Hose Pipe

Condition : **Excellent**

Good condition

Alternator Drive Belt

Condition : **Excellent**

Good condition

Water Pump

Condition : **Excellent**

Good Condition & no noise

Tappet Noise

Condition : **Excellent**

No noise

Turbo Charger

Condition : **Excellent**

Good condition

Heater Plugs / Spark Plugs

Condition : **Excellent**

Good condition (Changed during refurbishment)

Radiator Fan

Condition : **Excellent**

No noise & smooth Operation (Proper cut-off)

Charcoal Canister

Condition : **Excellent**

No damage & Petrol fume

Ignition Coil (petrol only)

Condition : **Excellent**

Working smoothly

Ignition Wire Harness (petrol only)

Condition : **Excellent**

Wiring & insulation good condition

Engine & Transmission (Continued...)

Fuel Tank and Pipes

Condition : **Excellent**

Good condition

Fuel Filter (Petrol & Diesel)

Condition : **Excellent**

Good condition (Changed during refurbishment)

Fuel Injection Pump (Diesel)

Condition : **Excellent**

No leakage & in good condition

Vehicle Images

Front Side



07-Oct-2022 4:21:58 pm

Lat 30.4742199,Long 77.7738445

Front Right Side



07-Oct-2022 4:22:03 pm

Lat 30.4742443,Long 77.7738594

Front Right Tyre



07-Oct-2022 4:22:08 pm
GPS = 30.474227 , 77.773837

07-Oct-2022 4:22:08 pm

Lat 30.4742268,Long 77.773837

Right Side



07-Oct-2022 4:22:12 pm

Lat 30.4742268,Long 77.773837

Rear Right Tyre



07-Oct-2022 4:22:18 pm
GPS = 30.47422 , 77.773829

07-Oct-2022 4:22:18 pm

Lat 30.4742197,Long 77.7738291

Rear Right Side



07-Oct-2022 4:22:28 pm

Lat 30.4742291,Long 77.7738473

Back Side



07-Oct-2022 4:22:38 pm

Lat 30.4742269,Long 77.7738486

Rear Left Side



07-Oct-2022 4:22:48 pm

Lat 30.4742152,Long 77.7738261

[View this car in Website](#)

Rear Left Tyre



07-Oct-2022 4:22:58 pm

Lat 30.4742255,Long 77.7738341

Left Side



07-Oct-2022 4:23:08 pm

Lat 30.4742566,Long 77.7738783

Front Left Tyre



07-Oct-2022 4:23:13 pm

Lat 30.4742566,Long 77.7738783

Front Left Side



07-Oct-2022 4:23:28 pm

Lat 30.4742307,Long 77.7738507

Odometer



07-Oct-2022 4:26:48 pm

Lat 30.4742972,Long 77.7739797