

Mahindra First Choice Wheels Inspection Report



2009 MARUTI SUZUKI SWIFT DZIRE(2008-2010) VDI

Pathankot | 120819 km | Diesel | Manual | Silver Colour | 2nd Owner

- ✔ Assist First Warranty
- ✔ 140+ Points Inspected



Exterior	Fair
<hr style="border: 1px solid orange;"/>	
Interior	Fair
<hr style="border: 1px solid orange;"/>	
Engine & Transmission	Fair
<hr style="border: 1px solid orange;"/>	

Overall
Fair Buy 🍀

VERIFIED
M Mahajan
Head Certification & Warranty - MFCWL

Explore this car in website [View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **140+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

J.S grover Auto Pvt Ltd

Registration Month

February

Registration Year

2009

Color

Silver

Odometer Reading(km)

120819

Registration Number

PB10XXXXXX

No of Owners

2

Insurance Status

Not available

Chassis Number

XXXXXXX

Engine Number

1172XXX

Remarks

only one key available

Remarks

only one key available

RC Status

RC Available

PUC Certificate

Not Available

Keys Availability

In Good Condition

Transfer Papers Availability

**All RTO papers available
and valid NOC from Bank**

Vehicle Status

Inspected

[View in Website](#)

Front Bumper

Condition : **Good**

Clean & slight color difference

Grill / Emblem

Condition : **Excellent**

No scratch & in good condition

Windscreen glass

Condition : **Excellent**

Clean, No marks

Right Running Board

Condition : **Good**

1-2 minor dents & minimal scratches

Right Quarter Panel

Condition : **Excellent**

No dents or scratches

Right Fender

Condition : **Excellent**

No dents or scratches

Front Right Door

Condition : **Excellent**

No dents or scratches

Rear Right Indicator

Condition : **Good**

Working & with very minimal scratches

Rear Right Indicator

Condition : **Good**

Working & with very minimal scratches

Right Doors Functionality

Condition : **Excellent**

Smooth to operate

RH Side All Pillars

Condition : **Excellent**

Spot welding original

Right Side View Mirror

Condition : **Excellent**

Operating smoothly & no scratches

Windscreen Washer and Jets

Condition : **Excellent**

Smooth operations

Trunk

Condition : **Good**

1-2 minor dents & minimal scratches

Bonnet

Condition : **Excellent**

No dents or scratches

Front Right Tyre

Condition : **Good**

Same Make/ Good & > 60% life

Rear Right Tyre

Condition : **Good**

Same Make/ Good & > 60% life

Trunk, Bonnet and Hood functionality

Condition : **Excellent**

Operating smoothly

Exterior (Continued...)

Rear Bumper

Condition : **Good**

Clean & slight color difference

Spare Tyre

Condition : **Good**

Same Make/ Good & > 60% life

Number Plate (Front & Rear)

Condition : **Excellent**

Good condition

Left Running Board

Condition : **Excellent**

No dents or scratches

Left Quarter Panel

Condition : **Excellent**

No dents or scratches

Left Fender

Condition : **Excellent**

No dents or scratches

Front Left Door

Condition : **Excellent**

No dents or scratches

Rear Left Door

Condition : **Good**

1-2 minor dents & minimal scratches

Left Doors Functionality

Condition : **Excellent**

Smooth to operate

LH Side All Pillars

Condition : **Excellent**

Spot welding original

Left Side View Mirror

Condition : **Excellent**

Operating smoothly & no scratches

Fuel Cap - Check Operation/ Noise

Condition : **Excellent**

Operating smoothly

Front Left Tyre

Condition : **Good**

Same Make/ Good & > 60% life

Rear Left Tyre

Condition : **Good**

Same Make/ Good & > 60% life

Frame or Underbody

Condition : **Good**

1-2 panels changed

Paint, Polishing and Gloss

Condition : **Good**

1 panel has color difference

Parking lights Front & Rear

Condition : **Excellent**

Working & in good condition

Right Taillight

Condition : **Excellent**

Working & in good condition

Exterior (Continued...)

Left Taillight

Condition : **Excellent**

Working & in good condition

Rear Left Indicator

Condition : **Good**

Working & with very minimal scratches

Front Left Indicator

Condition : **Good**

Working & with very minimal scratches

Front Right Indicator

Condition : **Good**

Working & with very minimal scratches

Left Headlight (Both Points)

Condition : **Excellent**

Working & in good condition

Right Headlight (Both Points)

Condition : **Excellent**

Working & in good condition

**Wheel Rim (Steel / Alloy)
(Including Spare Wheel)**

Condition : **Good**

Ok but very little color fading

Spare Wheel Cover

Condition : **Excellent**

Good condition

Fog lamps

Condition : **Good**

Operating but lens ok/ Minor Scratches

Alloy Wheels

Condition : **NA**

Not Applicable

Wheel Cap

Condition : **Excellent**

All 4 available & in good condition

Carpet - Cleanliness, torn off, proper size

Condition : Good

Ok but some stains

All Door Trim

Condition : Good

Dirty & negligible rattling noise

Seat Adjustment

Condition : Excellent

Working smoothly

Safety Belts Inertia Locking System

Condition : Excellent

Smooth to operate

Dashboard

Condition : Good

Some scratches & minimal rattling noise

Rubber Beading (All)

Condition : Good

No cut marks; Wear & tear marks in some places

Window Mechanisms

Condition : Excellent

Operating smoothly (All 4)

Inside Rear View Mirror

Condition : Excellent

Operating smoothly & no scratches

Seat Condition

Condition : Excellent

Seat cover is in good condition

Instrument Panel Gauges

Condition : Excellent

Operations & Visibility good

Instrument Panel Warning Lights

Condition : Excellent

Operating

Horns

Condition : Excellent

Operating

Wipers (all speeds)

Condition : Excellent

Smooth to operate

Combination Switch

Condition : Good

Operating but minimal wear & tear marks

Clock / Stereo controls / Power windows & other electrical controls

Condition : Excellent

Working smoothly

Cigarette Lighter / Charger / USB Port

Condition : Excellent

Working & in good condition

Interior lights

Condition : Excellent

Working smoothly

Hazard lights

Condition : Excellent

Working & in good condition

Interior (Continued...)

Trunk Light

Condition : **Excellent**

Working & in good condition

AC Cooling

Condition : **Good**

Good

Heating

Condition : **Excellent**

Working

Air distribution (AC Vents)

Condition : **Excellent**

Operating & in good condition

Recirculation/ Fresh air

Condition : **Excellent**

Operating Smoothly

**Manual / Power Steering
(Electronic/Hydraulic)**

Condition : **Excellent**

Operations are smooth & no noise/ play observed

Hand Brake

Condition : **Excellent**

Smooth operations

Music System

Condition : **Good**

Ok but some wear & tear marks

Speakers

Condition : **Good**

Ok but sound quality ok

Defogger

Condition : **NA**

Not Applicable

CNG/LPG kit

Condition : **NA**

Not Applicable

Central Locking System

Condition : **Excellent**

In good condition & smooth operation

Jack And Tommy (Tool Kit)

Condition : **Excellent**

Available & in very good condition

Dickey Shock Absorber

Condition : **Good**

Ok with No leakage marks /
Operation slightly weak

**Battery - Specification /
Voltage check / Check
Petroleum Jelly Application**

Condition : **Excellent**

Operating smooth & < 2 years
old

Alternator

Condition : **Excellent**

Smooth Operations

Starter Motor

Condition : **Excellent**

Smooth Operations

Fuel Pump (Petrol)

Condition : **Excellent**

Smooth operations

AC Compressor

Condition : **Excellent**

Working smoothly

Condenser Fan

Condition : **Excellent**

No noise & smooth operation
(Proper cut-off)

Blower motor

Condition : **Excellent**

Smooth operations

Steering Rattling Noise

Condition : **Excellent**

Smooth & no noise

Suspension Arms

Condition : **Excellent**

Working smoothly

Front struts (Shock absorber)

Condition : **Excellent**

No noise, Smooth Operation

Rear Shock Absorber/Spring

Condition : **Excellent**

No noise & smooth Operation

Stabiliser Bar & Other Bushes

Condition : **Satisfactory**

Ok but slightly hard

ABS

Condition : **Excellent**

Smooth Operation (High Speed
Pedal Vibration)

Brake Pedal

Condition : **Good**

Ok but slightly less efficient
operations/ No excessive play

Check Front Brake

Condition : **Excellent**

Smooth operation & braking
efficiency

Check Rear Brake

Condition : **Excellent**

Smooth operation & braking
efficiency

**Master Cylinder / Wheel
Cylinder**

Condition : **Excellent**

Smooth operation

Engine & Transmission (Continued...)

Braking Efficiency

Condition : **Excellent**
Operating smoothly

Gearshift level (Gear Engagement)

Condition : **Excellent**
Smooth operation

Gear Lever Play

Condition : **Excellent**
Smooth operation

Clutch Engagement

Condition : **Excellent**
Smooth operation

Clutch Pedal / Cable Operation

Condition : **Excellent**
Smooth

Axle Noise/Drive Shaft Boot Damage

Condition : **Excellent**
No noise

Front & Rear Wheel Bearings

Condition : **Excellent**
No noise

Differential

Condition : **Excellent**
Smooth operations

Alignment/Balancing

Condition : **Excellent**
No pulling

Transmission Oil (Manual/ Automatic)

Condition : **Excellent**
No Leakage/ Good condition
(Changed during Refurbishment)

Engine and Transmission Mountings

Condition : **Excellent**
No Noise/Vibrations

Abnormal Engine Noise/ Back Compression

Condition : **Excellent**
No noise (Tappet as well as Knocking noise)

Engine Oil Leaks: Cylinder Head Gasket

Condition : **Excellent**
No leakage/ Good condition
(Changed during refurbishment)

Gasket: Tappet Cover

Condition : **Excellent**
No leakage

Engine Oil Leaks: Crankcase Oil Seals/ Camshaft

Condition : **Excellent**
No leakage

Engine Oil Leaks: Sump Gasket

Condition : **Excellent**
No leakage

Engine Oil Leaks: Sump Damage

Condition : **Excellent**
No leakage/ Damage

Exhaust system

Condition : **Excellent**
No noise, No rusting sign & smooth Operation

Engine & Transmission (Continued...)

Smoke Color (Blue)

Condition : **Excellent**

No Color

Smoke Color (Black)

Condition : **Excellent**

No Color

Smoke Color (White)

Condition : **Excellent**

No Color

Air Filter

Condition : **Excellent**

Good condition (Changed during refurbishment)

Radiator /Condenser

Condition : **Excellent**

Good Condition & no damage/rusting sign

Engine oil

Condition : **Excellent**

No Leakage/ Good condition (Changed during RF)

Coolant

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

Brake Oil

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

Hose Pipe

Condition : **Excellent**

Good condition

Alternator Drive Belt

Condition : **Excellent**

Good condition

Water Pump

Condition : **Excellent**

Good Condition & no noise

Tappet Noise

Condition : **Excellent**

No noise

Turbo Charger

Condition : **Excellent**

Good condition

Heater Plugs / Spark Plugs

Condition : **Excellent**

Good condition (Changed during refurbishment)

Radiator Fan

Condition : **Excellent**

No noise & smooth Operation (Proper cut-off)

Charcoal Canister

Condition : **Excellent**

No damage & Petrol fume

Ignition Coil (petrol only)

Condition : **Excellent**

Working smoothly

Ignition Wire Harness (petrol only)

Condition : **Excellent**

Wiring & insulation good condition

Engine & Transmission (Continued...)

Fuel Tank and Pipes

Condition : **Excellent**

Good condition

Fuel Filter (Petrol & Diesel)

Condition : **Excellent**

Good condition (Changed during refurbishment)

Fuel Injection Pump (Diesel)

Condition : **Excellent**

No leakage & in good condition

Vehicle Images

Front Side



Oct 20, 2022 11:06:09 AM

Lat 32.2729584, Long 75.6733146

Front Right Side



Oct 20, 2022 11:06:28 AM

Lat 32.2729931, Long 75.6732688

Front Right Tyre



Oct 20, 2022 11:06:35 AM
GPS - 32.273027 , 75.673244

Oct 20, 2022 11:06:35 AM

Lat 32.2730268, Long 75.6732435

Right Side



Oct 20, 2022 11:06:42 AM

Lat 32.2730898, Long 75.6732344

Rear Right Tyre



Oct 20, 2022 11:06:49 AM
GPS - 32.273108 , 75.673249

Oct 20, 2022 11:06:49 AM

Lat 32.2731079, Long 75.6732489

Rear Right Side



Oct 20, 2022 11:06:59 AM

Lat 32.2727284, Long 75.6732988

Back Side



Oct 20, 2022 11:07:13 AM

Lat 32.2728489, Long 75.6733099

Rear Left Side



Oct 20, 2022 11:07:22 AM

Lat 32.2729732, Long 75.67331

[View this car in Website](#)

Rear Left Tyre



Oct 20, 2022 11:07:30 AM
GPS - 32.273093 , 75.67328

Oct 20, 2022 11:07:30 AM

Lat 32.2730929,Long 75.6732803

Left Side



Oct 20, 2022 11:07:37 AM
GPS - 32.273094 , 75.673304

Oct 20, 2022 11:07:37 AM

Lat 32.2730952,Long 75.6733037

Front Left Tyre



Oct 20, 2022 11:07:43 AM
GPS - 32.273123 , 75.673193

Oct 20, 2022 11:07:43 AM

Lat 32.2731229,Long 75.673193

Front Left Side



Oct 20, 2022 11:07:50 AM
GPS - 32.273133 , 75.673172

Oct 20, 2022 11:07:50 AM

Lat 32.2731359,Long 75.6731923

Odometer



Oct 20, 2022 11:08:13 AM
GPS - 32.273132 , 75.673234

Oct 20, 2022 11:08:13 AM

Lat 32.2731315,Long 75.6732335