

Mahindra First Choice Wheels Inspection Report



2011 VOLKSWAGEN POLO(2010-2012) HIGHLINE 1.2L P

South Delhi | 69710 km | Petrol | Manual | Silver Colour | 1st Owner

- ✔ Assist First Warranty
- ✔ 140+ Points Inspected



Exterior	Fair
<hr style="border: 1px solid orange;"/>	
Interior	Fair
<hr style="border: 1px solid orange;"/>	
Engine & Transmission	Fair
<hr style="border: 1px solid orange;"/>	

Overall
Fair Buy 🍏

VERIFIED
M Mahajan
Head Certification
& Warranty - MFCWL

[Explore this car in website](#)
[View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **140+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

Auto Elite

Registration Month

February

Registration Year

2012

Color

Silver

Odometer Reading(km)

69710

Registration Number

DL8CXXXXX

No of Owners

1

Insurance Status

Not available

Chassis Number

WVWGXXXXXXXXXXXXX

Engine Number

CJL0XXXXX

Remarks

ten year old

Remarks

ten year old

RC Status

RC Available

PUC Certificate

Not Available

Keys Availability

In Average Condition

Transfer Papers Availability

**All RTO papers available
and valid NOC from Bank**

Vehicle Status

Inspected

[View in Website](#)

Front Bumper

Condition : Good

Clean & slight color difference

Grill / Emblem

Condition : Good

No color fading marks & minimal scratches

Windscreen glass

Condition : Bad

Deep scratches / Crack

Right Running Board

Condition : Good

1-2 minor dents & minimal scratches

Right Quarter Panel

Condition : Good

1-2 minor dents & minimal scratches

Right Fender

Condition : Good

1-2 minor dents & minimal scratches

Front Right Door

Condition : Good

1-2 minor dents & minimal scratches

Rear Right Indicator

Condition : Good

Working & with very minimal scratches

Rear Right Indicator

Condition : Good

Working & with very minimal scratches

Right Doors Functionality

Condition : Good

Smooth to operate but little hinge play & no noise

RH Side All Pillars

Condition : Excellent

Spot welding original

Right Side View Mirror

Condition : Excellent

Operating smoothly & no scratches

Windscreen Washer and Jets

Condition : Excellent

Smooth operations

Trunk

Condition : Good

1-2 minor dents & minimal scratches

Bonnet

Condition : Good

1-2 minor dents & minimal scratches

Front Right Tyre

Condition : Satisfactory

Same Make/ Good & > 40% life

Rear Right Tyre

Condition : Satisfactory

Same Make/ Good & > 40% life

Trunk, Bonnet and Hood functionality

Condition : Excellent

Operating smoothly

Exterior (Continued...)

Rear Bumper

Condition : **Good**

Clean & slight color difference

Spare Tyre

Condition : **Satisfactory**

Same Make/ Good & > 40% life

Number Plate (Front & Rear)

Condition : **Excellent**

Good condition

Left Running Board

Condition : **Good**

1-2 minor dents & minimal scratches

Left Quarter Panel

Condition : **Good**

1-2 minor dents & minimal scratches

Left Fender

Condition : **Good**

1-2 minor dents & minimal scratches

Front Left Door

Condition : **Good**

1-2 minor dents & minimal scratches

Rear Left Door

Condition : **Good**

1-2 minor dents & minimal scratches

Left Doors Functionality

Condition : **Good**

Smooth to operate but little hinge play & no noise

LH Side All Pillars

Condition : **Excellent**

Spot welding original

Left Side View Mirror

Condition : **Excellent**

Operating smoothly & no scratches

Fuel Cap - Check Operation/ Noise

Condition : **Excellent**

Operating smoothly

Front Left Tyre

Condition : **Satisfactory**

Same Make/ Good & > 40% life

Rear Left Tyre

Condition : **Satisfactory**

Same Make/ Good & > 40% life

Frame or Underbody

Condition : **Excellent**

No panel changed

Paint, Polishing and Gloss

Condition : **Excellent**

No difference or negligible difference in color of panels

Parking lights Front & Rear

Condition : **Good**

Working & with very minimal scratches

Right Taillight

Condition : **Good**

Working & with very minimal scratches

Exterior (Continued...)

Left Taillight

Condition : **Good**

Working & with very minimal scratches

Rear Left Indicator

Condition : **Good**

Working & with very minimal scratches

Front Left Indicator

Condition : **Good**

Working & with very minimal scratches

Front Right Indicator

Condition : **Good**

Working & with very minimal scratches

Left Headlight (Both Points)

Condition : **Good**

Working & with very minimal scratches

Right Headlight (Both Points)

Condition : **Good**

Working & with very minimal scratches

**Wheel Rim (Steel / Alloy)
(Including Spare Wheel)**

Condition : **Satisfactory**

Ok but color faded

Spare Wheel Cover

Condition : **Excellent**

Good condition

Fog lamps

Condition : **Good**

Operating but lens ok/ Minor Scratches

Alloy Wheels

Condition : **Satisfactory**

Ok but some scratch marks

Wheel Cap

Condition : **Excellent**

All 4 available & in good condition

Carpet - Cleanliness, torn off, proper size

Condition : Good

Ok but some stains

All Door Trim

Condition : Good

Dirty & negligible rattling noise

Seat Adjustment

Condition : Satisfactory

Operating hard and sliding / inclination operation not very smooth

Safety Belts Inertia Locking System

Condition : Satisfactory

Operating with some hardness

Dashboard

Condition : Good

Some scratches & minimal rattling noise

Rubber Beading (All)

Condition : Good

No cut marks; Wear & tear marks in some places

Window Mechanisms

Condition : Satisfactory

Operating but not smooth due to run channel hardness

Inside Rear View Mirror

Condition : Excellent

Operating smoothly & no scratches

Seat Condition

Condition : Satisfactory

Seat cover is faded

Instrument Panel Gauges

Condition : Good

Operating, minimal scratches observed

Instrument Panel Warning Lights

Condition : Excellent

Operating

Horns

Condition : Excellent

Operating

Wipers (all speeds)

Condition : Satisfactory

Working with some noise

Combination Switch

Condition : Good

Operating but minimal wear & tear marks

Clock / Stereo controls / Power windows & other electrical controls

Condition : Excellent

Working smoothly

Cigarette Lighter / Charger / USB Port

Condition : Excellent

Working & in good condition

Interior lights

Condition : Excellent

Working smoothly

Hazard lights

Condition : Excellent

Working & in good condition

Interior (Continued...)

Trunk Light

Condition : **Good**

Working & with very minimal scratches

AC Cooling

Condition : **Good**

Good

Heating

Condition : **Excellent**

Working

Air distribution (AC Vents)

Condition : **Satisfactory**

Operating but flow not very smooth

Recirculation/ Fresh air

Condition : **Excellent**

Operating Smoothly

Manual / Power Steering (Electronic/Hydraulic)

Condition : **Good**

Operations are smooth & minimal play observed

Hand Brake

Condition : **Good**

Operating but not very smooth

Music System

Condition : **Excellent**

Working properly & in very good condition

Speakers

Condition : **Excellent**

Proper cover & output in good condition (sound quality)

Defogger

Condition : **Excellent**

Operating & in good condition

CNG/LPG kit

Condition : **NA**

Not Applicable

Central Locking System

Condition : **Good**

Working but some wear & tear marks

Jack And Tommy (Tool Kit)

Condition : **Excellent**

Available & in very good condition

Dickey Shock Absorber

Condition : **Good**

Ok with No leakage marks /
Operation slightly weak

**Battery - Specification /
Voltage check / Check
Petroleum Jelly Application**

Condition : **Good**

Operating & > 3 years old

Alternator

Condition : **Satisfactory**

Operating but minimal bearing
noise

Starter Motor

Condition : **Satisfactory**

Operating with some cranking
noise

Fuel Pump (Petrol)

Condition : **Satisfactory**

Operating with some noise

AC Compressor

Condition : **Excellent**

Working smoothly

Condenser Fan

Condition : **Excellent**

No noise & smooth operation
(Proper cut-off)

Blower motor

Condition : **Satisfactory**

Working, some noise observed

Steering Rattling Noise

Condition : **Satisfactory**

No noise but slightly sticky

Suspension Arms

Condition : **Satisfactory**

Operation Ok & slight play
observed

Front struts (Shock absorber)

Condition : **Good**

Ok but slightly hard & no
leakage sign

Rear Shock Absorber/Spring

Condition : **Good**

Ok but slightly hard & no
leakage sign

Stabiliser Bar & Other Bushes

Condition : **Satisfactory**

Ok but slightly hard

ABS

Condition : **Excellent**

Smooth Operation (High Speed
Pedal Vibration)

Brake Pedal

Condition : **Good**

Ok but slightly less efficient
operations/ No excessive play

Check Front Brake

Condition : **Satisfactory**

Operating with Calliper Noise

Check Rear Brake

Condition : **Excellent**

Smooth operation & braking
efficiency

**Master Cylinder / Wheel
Cylinder**

Condition : **Excellent**

Smooth operation

Engine & Transmission (Continued...)

Braking Efficiency

Condition : **Excellent**

Operating smoothly

Gearshift level (Gear Engagement)

Condition : **Satisfactory**

Ok but little play

Gear Lever Play

Condition : **Satisfactory**

Ok but little play

Clutch Engagement

Condition : **Good**

Ok but little play

Clutch Pedal / Cable Operation

Condition : **Excellent**

Smooth

Axle Noise/Drive Shaft Boot Damage

Condition : **Satisfactory**

Ok but Hard

Front & Rear Wheel Bearings

Condition : **Satisfactory**

Ok but had run without hub cap

Differential

Condition : **Good**

Smooth Operation but little humming noise

Alignment/Balancing

Condition : **Excellent**

No pulling

Transmission Oil (Manual/ Automatic)

Condition : **Satisfactory**

Ok but was not changed during Refurbishment

Engine and Transmission Mountings

Condition : **Excellent**

No Noise/Vibrations

Abnormal Engine Noise/ Back Compression

Condition : **Excellent**

No noise (Tappet as well as Knocking noise)

Engine Oil Leaks: Cylinder Head Gasket

Condition : **Excellent**

No leakage/ Good condition (Changed during refurbishment)

Gasket: Tappet Cover

Condition : **Excellent**

No leakage

Engine Oil Leaks: Crankcase Oil Seals/ Camshaft

Condition : **Excellent**

No leakage

Engine Oil Leaks: Sump Gasket

Condition : **Excellent**

No leakage

Engine Oil Leaks: Sump Damage

Condition : **Satisfactory**

Little bit leakage (seepage) sign but not damage

Exhaust system

Condition : **Excellent**

No noise, No rusting sign & smooth Operation

Engine & Transmission (Continued...)

Smoke Color (Blue)

Condition : **Excellent**

No Color

Smoke Color (Black)

Condition : **Excellent**

No Color

Smoke Color (White)

Condition : **Excellent**

No Color

Air Filter

Condition : **Excellent**

Good condition (Changed during refurbishment)

Radiator /Condenser

Condition : **Satisfactory**

Ok but some signs of rusting

Engine oil

Condition : **Excellent**

No Leakage/ Good condition (Changed during RF)

Coolant

Condition : **Satisfactory**

Ok but was not changed during refurbishment

Brake Oil

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

Hose Pipe

Condition : **Excellent**

Good condition

Alternator Drive Belt

Condition : **Satisfactory**

Ok but signs of some cracks

Water Pump

Condition : **Excellent**

Good Condition & no noise

Tappet Noise

Condition : **Excellent**

No noise

Turbo Charger

Condition : **NA**

Not Applicable

Heater Plugs / Spark Plugs

Condition : **Excellent**

Good condition (Changed during refurbishment)

Radiator Fan

Condition : **Excellent**

No noise & smooth Operation (Proper cut-off)

Charcoal Canister

Condition : **Bad**

Disconnected / Damage

Ignition Coil (petrol only)

Condition : **Excellent**

Working smoothly

Ignition Wire Harness (petrol only)

Condition : **Excellent**

Wiring & insulation good condition

Engine & Transmission (Continued...)

Fuel Tank and Pipes

Condition : **Excellent**

Good condition

Fuel Filter (Petrol & Diesel)

Condition : **Excellent**

Good condition (Changed during refurbishment)

Fuel Injection Pump (Diesel)

Condition : **Excellent**

No leakage & in good condition

Vehicle Images

Front Side



Nov 7, 2022 2:46:52 PM

Lat 28.5645774, Long 77.2340995

Front Right Side



Nov 7, 2022 2:46:59 PM

Lat 28.5646015, Long 77.2340371

Front Right Tyre



Nov 7, 2022 2:47:05 PM

Lat 28.5646424, Long 77.234059

Right Side



Nov 7, 2022 2:47:23 PM

Lat 28.5646671, Long 77.2341758

Rear Right Tyre



Nov 7, 2022 2:47:29 PM

Lat 28.5646718, Long 77.2341812

Rear Right Side



Nov 7, 2022 2:47:37 PM

Lat 28.5646686, Long 77.2341766

Back Side



Nov 7, 2022 2:47:44 PM

Lat 28.564667, Long 77.2341749

Rear Left Side



Nov 7, 2022 2:47:59 PM

Lat 28.5646638, Long 77.2341707

[View this car in Website](#)

Rear Left Tyre



Nov 7, 2022 2:48:05 PM
GPS - 28.564657 , 77.234164

Nov 7, 2022 2:48:05 PM

Lat 28.564657, Long 77.2341637

Left Side



Nov 7, 2022 2:48:14 PM
GPS - 28.564655, 77.234165

Nov 7, 2022 2:48:14 PM

Lat 28.5646554, Long 77.2341615

Front Left Tyre



Nov 7, 2022 2:48:21 PM
GPS - 28.564656 , 77.234096

Nov 7, 2022 2:48:21 PM

Lat 28.5646564, Long 77.2340955

Front Left Side



Nov 7, 2022 2:48:30 PM
GPS - 28.564663, 77.234098

Nov 7, 2022 2:48:30 PM

Lat 28.5646633, Long 77.2340908

Odometer



Nov 7, 2022 2:49:17 PM
GPS - 28.564582 , 77.234143

Nov 7, 2022 2:49:17 PM

Lat 28.5645825, Long 77.2341434