


Mahindra First Choice Wheels Inspection Report



2012 MITSUBISHI PAJERO SPORT(2012-2021) 2.5 MT

New Delhi | 128992 km | Diesel | Manual | White Colour | 1st Owner

- ✔ Assist First Warranty
- ✔ 140+ Points Inspected



Overall
Fair Buy 🍀

M Mahajan
Head Certification & Warranty - MFCWL

[Explore this car in website](#)
View in Website

Overall rating is the 'quality score' of a vehicle derived from a **140+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

Guru Kripa Motors

Registration Month

October

Registration Year

2012

Color

White

Odometer Reading(km)

128992

Registration Number

DL1CXXXXX

No of Owners

1

Insurance Status

Available

Chassis Number

XXXXXXXX

Engine Number

XXXXXXXX

Remarks

2012 model, 1 lakh plus driven

Remarks

2012 model, 1 lakh plus driven

RC Status

RC Available

PUC Certificate

Available

Keys Availability

In Good Condition

Transfer Papers Availability

All RTO papers available and valid NOC from Bank

Vehicle Status

Inspected

[View in Website](#)

Front Bumper

Condition : Good

Clean & slight color difference

Grill / Emblem

Condition : Good

No color fading marks & minimal scratches

Windscreen glass

Condition : Good

Minimal scratches

Right Running Board

Condition : Good

1-2 minor dents & minimal scratches

Right Quarter Panel

Condition : Good

1-2 minor dents & minimal scratches

Right Fender

Condition : Good

1-2 minor dents & minimal scratches

Front Right Door

Condition : Good

1-2 minor dents & minimal scratches

Rear Right Indicator

Condition : Good

Working & with very minimal scratches

Rear Right Indicator

Condition : Good

Working & with very minimal scratches

Right Doors Functionality

Condition : Good

Smooth to operate but little hinge play & no noise

RH Side All Pillars

Condition : Excellent

Spot welding original

Right Side View Mirror

Condition : Excellent

Operating smoothly & no scratches

Windscreen Washer and Jets

Condition : Excellent

Smooth operations

Trunk

Condition : Good

1-2 minor dents & minimal scratches

Bonnet

Condition : Good

1-2 minor dents & minimal scratches

Front Right Tyre

Condition : Good

Same Make/ Good & > 60% life

Rear Right Tyre

Condition : Good

Same Make/ Good & > 60% life

Trunk, Bonnet and Hood functionality

Condition : Excellent

Operating smoothly

Exterior (Continued...)

Rear Bumper

Condition : **Good**

Clean & slight color difference

Spare Tyre

Condition : **Good**

Same Make/ Good & > 60% life

Number Plate (Front & Rear)

Condition : **Excellent**

Good condition

Left Running Board

Condition : **Good**

1-2 minor dents & minimal scratches

Left Quarter Panel

Condition : **Good**

1-2 minor dents & minimal scratches

Left Fender

Condition : **Good**

1-2 minor dents & minimal scratches

Front Left Door

Condition : **Good**

1-2 minor dents & minimal scratches

Rear Left Door

Condition : **Good**

1-2 minor dents & minimal scratches

Left Doors Functionality

Condition : **Good**

Smooth to operate but little hinge play & no noise

LH Side All Pillars

Condition : **Excellent**

Spot welding original

Left Side View Mirror

Condition : **Excellent**

Operating smoothly & no scratches

Fuel Cap - Check Operation/ Noise

Condition : **Excellent**

Operating smoothly

Front Left Tyre

Condition : **Good**

Same Make/ Good & > 60% life

Rear Left Tyre

Condition : **Good**

Same Make/ Good & > 60% life

Frame or Underbody

Condition : **Excellent**

No panel changed

Paint, Polishing and Gloss

Condition : **Excellent**

No difference or negligible difference in color of panels

Parking lights Front & Rear

Condition : **Good**

Working & with very minimal scratches

Right Taillight

Condition : **Good**

Working & with very minimal scratches

Exterior (Continued...)

Left Taillight

Condition : **Good**

Working & with very minimal scratches

Rear Left Indicator

Condition : **Good**

Working & with very minimal scratches

Front Left Indicator

Condition : **Good**

Working & with very minimal scratches

Front Right Indicator

Condition : **Good**

Working & with very minimal scratches

Left Headlight (Both Points)

Condition : **Good**

Working & with very minimal scratches

Right Headlight (Both Points)

Condition : **Good**

Working & with very minimal scratches

**Wheel Rim (Steel / Alloy)
(Including Spare Wheel)**

Condition : **Good**

Ok but very little color fading

Spare Wheel Cover

Condition : **Excellent**

Good condition

Fog lamps

Condition : **Good**

Operating but lens ok/ Minor Scratches

Alloy Wheels

Condition : **Excellent**

Good condition

Wheel Cap

Condition : **Excellent**

All 4 available & in good condition

Carpet - Cleanliness, torn off, proper size

Condition : Good

Ok but some stains

All Door Trim

Condition : Good

Dirty & negligible rattling noise

Seat Adjustment

Condition : Excellent

Working smoothly

Safety Belts Inertia Locking System

Condition : Excellent

Smooth to operate

Dashboard

Condition : Good

Some scratches & minimal rattling noise

Rubber Beading (All)

Condition : Good

No cut marks; Wear & tear marks in some places

Window Mechanisms

Condition : Excellent

Operating smoothly (All 4)

Inside Rear View Mirror

Condition : Excellent

Operating smoothly & no scratches

Seat Condition

Condition : Excellent

Seat cover is in good condition

Instrument Panel Gauges

Condition : Excellent

Operations & Visibility good

Instrument Panel Warning Lights

Condition : Excellent

Operating

Horns

Condition : Excellent

Operating

Wipers (all speeds)

Condition : Excellent

Smooth to operate

Combination Switch

Condition : Good

Operating but minimal wear & tear marks

Clock / Stereo controls / Power windows & other electrical controls

Condition : Excellent

Working smoothly

Cigarette Lighter / Charger / USB Port

Condition : Excellent

Working & in good condition

Interior lights

Condition : Excellent

Working smoothly

Hazard lights

Condition : Excellent

Working & in good condition

Interior (Continued...)

Trunk Light

Condition : **Excellent**

Working & in good condition

AC Cooling

Condition : **Good**

Good

Heating

Condition : **Excellent**

Working

Air distribution (AC Vents)

Condition : **Excellent**

Operating & in good condition

Recirculation/ Fresh air

Condition : **Excellent**

Operating Smoothly

**Manual / Power Steering
(Electronic/Hydraulic)**

Condition : **Excellent**

Operations are smooth & no noise/ play observed

Hand Brake

Condition : **Good**

Operating but not very smooth

Music System

Condition : **Good**

Ok but some wear & tear marks

Speakers

Condition : **Good**

Ok but sound quality ok

Defogger

Condition : **Excellent**

Operating & in good condition

CNG/LPG kit

Condition : **NA**

Not Applicable

Central Locking System

Condition : **Excellent**

In good condition & smooth operation

Jack And Tommy (Tool Kit)

Condition : **Excellent**

Available & in very good condition

Dickey Shock Absorber

Condition : **Good**

Ok with No leakage marks /
Operation slightly weak

**Battery - Specification /
Voltage check / Check
Petroleum Jelly Application**

Condition : **Excellent**

Operating smooth & < 2 years
old

Alternator

Condition : **Excellent**

Smooth Operations

Starter Motor

Condition : **Excellent**

Smooth Operations

Fuel Pump (Petrol)

Condition : **Excellent**

Smooth operations

AC Compressor

Condition : **Excellent**

Working smoothly

Condenser Fan

Condition : **Excellent**

No noise & smooth operation
(Proper cut-off)

Blower motor

Condition : **Excellent**

Smooth operations

Steering Rattling Noise

Condition : **Excellent**

Smooth & no noise

Suspension Arms

Condition : **Excellent**

Working smoothly

Front struts (Shock absorber)

Condition : **Good**

Ok but slightly hard & no
leakage sign

Rear Shock Absorber/Spring

Condition : **Good**

Ok but slightly hard & no
leakage sign

Stabiliser Bar & Other Bushes

Condition : **Satisfactory**

Ok but slightly hard

ABS

Condition : **Excellent**

Smooth Operation (High Speed
Pedal Vibration)

Brake Pedal

Condition : **Good**

Ok but slightly less efficient
operations/ No excessive play

Check Front Brake

Condition : **Excellent**

Smooth operation & braking
efficiency

Check Rear Brake

Condition : **Excellent**

Smooth operation & braking
efficiency

**Master Cylinder / Wheel
Cylinder**

Condition : **Excellent**

Smooth operation

Engine & Transmission (Continued...)

Braking Efficiency

Condition : **Excellent**

Operating smoothly

Gearshift level (Gear Engagement)

Condition : **Excellent**

Smooth operation

Gear Lever Play

Condition : **Excellent**

Smooth operation

Clutch Engagement

Condition : **Satisfactory**

Ok but little play / slightly hard

Clutch Pedal / Cable Operation

Condition : **Satisfactory**

Ok but slightly Hard

Axle Noise/Drive Shaft Boot Damage

Condition : **Excellent**

No noise

Front & Rear Wheel Bearings

Condition : **Excellent**

No noise

Differential

Condition : **Excellent**

Smooth operations

Alignment/Balancing

Condition : **Excellent**

No pulling

Transmission Oil (Manual/ Automatic)

Condition : **Excellent**

No Leakage/ Good condition
(Changed during Refurbishment)

Engine and Transmission Mountings

Condition : **Excellent**

No Noise/Vibrations

Abnormal Engine Noise/ Back Compression

Condition : **Excellent**

No noise (Tappet as well as Knocking noise)

Engine Oil Leaks: Cylinder Head Gasket

Condition : **Excellent**

No leakage/ Good condition
(Changed during refurbishment)

Gasket: Tappet Cover

Condition : **Excellent**

No leakage

Engine Oil Leaks: Crankcase Oil Seals/ Camshaft

Condition : **Excellent**

No leakage

Engine Oil Leaks: Sump Gasket

Condition : **Excellent**

No leakage

Engine Oil Leaks: Sump Damage

Condition : **Excellent**

No leakage/ Damage

Exhaust system

Condition : **Excellent**

No noise, No rusting sign & smooth Operation

Engine & Transmission (Continued...)

Smoke Color (Blue)

Condition : **Excellent**

No Color

Smoke Color (Black)

Condition : **Excellent**

No Color

Smoke Color (White)

Condition : **Excellent**

No Color

Air Filter

Condition : **Excellent**

Good condition (Changed during refurbishment)

Radiator /Condenser

Condition : **Excellent**

Good Condition & no damage/rusting sign

Engine oil

Condition : **Excellent**

No Leakage/ Good condition (Changed during RF)

Coolant

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

Brake Oil

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

Hose Pipe

Condition : **Excellent**

Good condition

Alternator Drive Belt

Condition : **Excellent**

Good condition

Water Pump

Condition : **Excellent**

Good Condition & no noise

Tappet Noise

Condition : **Excellent**

No noise

Turbo Charger

Condition : **Excellent**

Good condition

Heater Plugs / Spark Plugs

Condition : **Excellent**

Good condition (Changed during refurbishment)

Radiator Fan

Condition : **Excellent**

No noise & smooth Operation (Proper cut-off)

Charcoal Canister

Condition : **Excellent**

No damage & Petrol fume

Ignition Coil (petrol only)

Condition : **Excellent**

Working smoothly

Ignition Wire Harness (petrol only)

Condition : **Excellent**

Wiring & insulation good condition

Engine & Transmission (Continued...)

Fuel Tank and Pipes

Condition : **Excellent**

Good condition

Fuel Filter (Petrol & Diesel)

Condition : **Excellent**

Good condition (Changed during refurbishment)

Fuel Injection Pump (Diesel)

Condition : **Excellent**

No leakage & in good condition

Vehicle Images

Front Side



28 Oct 2022 11:35:19 am

Lat 28.7107067,Long 77.1354833

Front Right Side



28 Oct 2022 11:35:25 am

Lat 28.7113752,Long 77.1358056

Front Right Tyre



28 Oct 2022 11:35:31 am

Lat 28.7125224,Long 77.1368262

Right Side



28 Oct 2022 11:35:29 am

Lat 28.7125224,Long 77.1368262

Rear Right Tyre



28 Oct 2022 11:35:35 am

Lat 28.7126289,Long 77.1370843

Rear Right Side



28 Oct 2022 11:35:38 am

Lat 28.7126668,Long 77.1371734

Back Side



28 Oct 2022 11:35:41 am

Lat 28.7127097,Long 77.1371683

Rear Left Side



28 Oct 2022 11:35:45 am

Lat 28.7127312,Long 77.1371406

[View this car in Website](#)

Rear Left Tyre



28 Oct 2022 11:35:52 am

Lat 28.7127374, Long 77.1371371

Left Side



28 Oct 2022 11:35:49 am

Lat 28.7127334, Long 77.1371373

Front Left Tyre



28 Oct 2022 11:35:54 am

Lat 28.7127375, Long 77.1371378

Front Left Side



28 Oct 2022 11:35:58 am

Lat 28.7127418, Long 77.1371426

Odometer



28 Oct 2022 11:36:17 am

Lat 28.7127419, Long 77.137134