

Mahindra First Choice Wheels Inspection Report



2014 MARUTI SUZUKI ERTIGA(2012-2015) VDI

Moradabad | 64866 km | Diesel | Manual | White Colour | 1st Owner

✔ Assist First Warranty ✔ 200+ Points Inspected



Exterior	Fair
<hr style="border: 1px solid orange;"/>	
Interior	Fair
<hr style="border: 1px solid orange;"/>	
Engine & Transmission	Fair
<hr style="border: 1px solid orange;"/>	

Overall
Fair Buy 🙌

M Mahajan
Head Certification
& Warranty - MFCWL

[Explore this car in website](#)

[View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

MK Motors

Registration Month

August

Registration Year

2014

Color

White

Odometer Reading(km)

64866

Registration Number

DLICXXXXX

No of Owners

1

Chassis Number

MA3FXXXXXXXXXXXXXX

Engine Number

D13AXXXXXXX

Insurance Status

Not available

Accidental / Flooded

Non-Accidental and Non-flooded

CNG Validity Inspection Date

Not Valid

RC Status

Not Available

PUC Certificate

Not Available

Keys Availability

Both Keys Available And One Key Worn Out

Transfer papers availability

Not Available

CNG Hydro Test Validity Certificate

Not Applicable

Vehicle Status

Inspected

Remarks

.

[View in Website](#)

Front Bumper

Condition : **Bad**
Alignment Issue

Grill

Condition : **Excellent**
Good Condition

Emblem

Condition : **Excellent**
Good Condition

Windscreen glass Front

Condition : **Excellent**
Good Condition

Bonnet

Condition : **Bad**
Alignment Issue

Bonnet Functionality

Condition : **Excellent**
Good Condition

RH Side Apron

Condition : **Excellent**
Good Condition

Right Running Board

Condition : **Excellent**
Good Condition

Right Fender

Condition : **Bad**
Dent with Paint Damage

Front Right Door

Condition : **Bad**
Dents With Paint Damage

Right Front Door Functionality

Condition : **Excellent**
Good Condition

Front Right Door handle

Condition : **Excellent**
Good Condition

Front Right Window Glass

Condition : **Excellent**
Good Condition/Same Make

Rear Right Door

Condition : **Bad**
Dents With Paint Damage

Right Rear Door Functionality

Condition : **Excellent**
Good Condition

Rear Right Door handle

Condition : **Excellent**
Good Condition

Rear Right Window Glass

Condition : **Excellent**
Good Condition/Same Make

RH A Pillars

Condition : **Excellent**
Good Condition

Exterior (Continued...)

RH B Pillars

Condition : **Excellent**

Good Condition

RH C Pillars

Condition : **Excellent**

Good Condition

Right Quarter Panel

Condition : **Bad**

Spot Welding Removed

Right Side View Mirror + Casing

Condition : **Excellent**

Good Condition

Right Side Power Mirror + Casing

Condition : **Excellent**

Good Condition

Front right tyre

Condition : **Bad**

Less than 20%

Steel Wheel Rim Front RHS

Condition : **Satisfactory**

Rust

Alloy Wheels Front RHS

Condition : **Excellent**

Not Applicable

Rear right tyre

Condition : **Bad**

Less than 20%

Steel Wheel Rim Rear RHS

Condition : **Satisfactory**

Rust

Alloy Wheels Rear RHS

Condition : **Excellent**

Not Applicable

Windscreen glass Back

Condition : **Excellent**

Good Condition

Trunk

Condition : **Bad**

Repaired/Screw Fitting

Trunk Functionality

Condition : **Excellent**

Good Condition

Rear Bumper

Condition : **Bad**

Alignment Issue

Dickey Shock absorber

Condition : **Excellent**

Good Condition

Spare tyre (stephney)

Condition : **Bad**

Different Make/ Cut Marks/
Bulge /< 30% life

Spare Wheel / Cover

Condition : **Excellent**

Good Condition

[View this car in Website](#)

Exterior (Continued...)

Number Plate (Front & Rear)

Condition : **Excellent**

RTO Format

LH A Pillars

Condition : **Excellent**

Good Condition

LH B Pillars

Condition : **Excellent**

Good Condition

LH C Pillars

Condition : **Excellent**

Good Condition

Left Running Board

Condition : **Good**

Visible Repaint

Left Fender

Condition : **Bad**

Dent with Paint Damage

Left Front Door

Condition : **Bad**

Deep/long Scratches-2 & Above

Front Left Door Functionality

Condition : **Excellent**

Good Condition

Front Left Door handle

Condition : **Excellent**

Good Condition

Front Left Window Glass

Condition : **Excellent**

Good Condition/Same Make

Left Side View Mirror + Casing

Condition : **Excellent**

Good Condition

Left Side Power Mirror + Casing

Condition : **Excellent**

Good Condition

Rear Left Door

Condition : **Good**

Visible Repaint

Rear Left Door Functionality

Condition : **Excellent**

Good Condition

Rear Left Door handle

Condition : **Excellent**

Good Condition

Left Quarter Panel

Condition : **Bad**

Spot Welding Removed

Rear Left Window Glass

Condition : **Excellent**

Good Condition/Same Make

Fuel Cap

Condition : **Excellent**

Working Properly

[View this car in Website](#)

Exterior (Continued...)

Front Left tyre

Condition : **Bad**

Less than 20%

Steel Wheel Rim Front LHS

Condition : **Satisfactory**

Rust

Alloy Wheels Front LHS

Condition : **Excellent**

Not Applicable

Rear Left tyre

Condition : **Bad**

Less than 20%

Steel Wheel Rim Rear LHS

Condition : **Satisfactory**

Rust

Alloy Wheels Rear LHS

Condition : **Excellent**

Not Applicable

LH Side Apron

Condition : **Excellent**

Good Condition

Frame or Underbody

Condition : **Satisfactory**

Panel Rusting

Reverse Camera & Reverse Parking Sensor

Condition : **Excellent**

Not Applicable

Roof

Condition : **Satisfactory**

Dents without paint damage-3

Windscreen Wiper Front

Condition : **Excellent**

All speeds working properly

Windscreen Wiper Rear

Condition : **Excellent**

All speeds working properly

Windscreen Jets

Condition : **Excellent**

Good Condition

Parking Lights Front

Condition : **Excellent**

Good Condition

Parking Lights Rear

Condition : **Excellent**

Good Condition

Right Tail Light

Condition : **Excellent**

Good Condition

Left Tail Light

Condition : **Satisfactory**

cracks

Rear Left Indicator

Condition : **Excellent**

Good Condition

Exterior (Continued...)

Rear Right Indicator

Condition : **Excellent**

Good Condition

Front Left Indicator

Condition : **Excellent**

Good Condition

Front Right Indicator

Condition : **Excellent**

Good Condition

Left Headlight (Both Points)

Condition : **Satisfactory**

NON OEM High Power Lamps

Right Headlight (Both Points)

Condition : **Satisfactory**

NON OEM High Power Lamps

Fog lamps

Condition : **Excellent**



Good Condition

Wheel Cap

Condition : **Excellent**

Available

Interior Rating - **Fair**

 53 Good  8 Issues

RHS Front Door Trim

Condition : **Bad**

Noise

RHS Rear Door Trim

Condition : **Bad**

Noise

Rubber Beading Front RHS

Condition : **Satisfactory**

Loose

Rubber Beading Rear RHS

Condition : **Satisfactory**

Loose

LHS Front Door Trim

Condition : **Bad**

Noise

LHS Rear Door Trim

Condition : **Bad**

Noise

[View this car in Website](#)

Rubber Beading Front LHS

Condition : **Satisfactory**

Loose

Rubber Beading Rear LHS

Condition : **Satisfactory**

Loose

Carpets

Condition : **Excellent**

Good Condition

Roof Inside

Condition : **Excellent**

Good Condition

Driver Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

Driver Seat recliner

Condition : **Excellent**

Good Condition

Driver Seat Up Down

Condition : **Excellent**

Good Condition

Passenger Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

Passenger Seat recliner

Condition : **Excellent**

Good Condition

Passenger Seat Up Down

Condition : **Excellent**

Good Condition

Safety belts inertia locking system Driver Seat

Condition : **Bad**

Not Functional

Safety belts inertia locking system Passenger

Condition : **Bad**

Not Functional

Dash Board

Condition : **Bad**

Mismatched

Sunroof System

Condition : **Excellent**

Not Applicable

Front Right Window Type

Power Windows

Front Right Window Function

Condition : **Excellent**

Smooth Operation

Front Left Window Type

Power Windows

Front Left Window Function

Condition : **Excellent**

Smooth Operation

Interior (Continued...)

Rear Right Window Type

Power Windows

Rear Right Window Function

Condition : **Excellent**

Smooth Operation

Rear Left Window Type

Power Windows

Rear Left Window Function

Condition : **Excellent**

Smooth Operation

Steering Mounted Controls

Condition : **Excellent**

Not Applicable

Inside Rear View mirror

Condition : **Excellent**

Good Condition

Driver Seat Condition

Condition : **Excellent**

Good Condition

Passenger Seat Condition

Condition : **Excellent**

Good Condition

Rear Seat Condition

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Odometer**

Condition : **Excellent**

Good Condition

**Instrument panel Warning
Lights**

Condition : **Excellent**

Warning Lights Off - Good

Instrument panel gauges: Fuel

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Tachometer**

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Temperature**

Condition : **Excellent**

Good Condition

Horn

Condition : **Excellent**

Good Condition

Combination Switch

Condition : **Excellent**

Good Condition

Stereo Controls

Condition : **Excellent**

Good Condition

Charger/USB Port

Condition : **Excellent**

Good Condition

Interior (Continued...)

Interior lights

Condition : **Excellent**

Good Condition

Hazard lights

Condition : **Excellent**

Good Condition

Trunk Light

Condition : **Excellent**

Good Condition

Music System

Condition : **Excellent**

Good Condition

Music system type

Dashboard Mounted Music
Control-Buttons

Speakers

Condition : **Excellent**

Good Condition

Defogger

Condition : **Excellent**

Not Applicable

Central Locking System

Condition : **Excellent**

Good Condition

**AC cooling (Check
undershade)**

Condition : **Excellent**

Good Condition

Heating

Condition : **Excellent**

Good Condition

Air distribution (AC Vents)

Condition : **Excellent**

Good Condition

Recirculation/ Fresh air

Condition : **Excellent**

Good Condition

Steering Type

Power Steering

Power Steering Type

Electronic

Steering condition

Condition : **Bad**

Noise

Air Bags

Condition : **Excellent**

Not Applicable

Hand Brake

Condition : **Good**

Working more than 4 notches

**CNG/LPG kit -
OEM/Aftermarket**

Condition : **Excellent**

No

[View this car in Website](#)



Interior (Continued...)

Jack And Tommy (Tool Kit)

Condition : **Excellent**

Available

Engine & Transmission Rating - Fair

 48 Good  8 Issues

Battery

Condition : **Satisfactory**

Age above 3 years

Alternator

Condition : **Excellent**

Good Condition

Starter Motor

Condition : **Excellent**

Good Condition

Fuel Pump

Condition : **Excellent**

Good Condition

AC Compressor

Condition : **Satisfactory**

Noise

Condenser Fan

Condition : **Satisfactory**

Noise

Blower motor

Condition : **Excellent**

Good Condition

**Steering / Column with motor
Rattling Noise**

Condition : **Excellent**

Working Properly

Suspension Arms

Condition : **Good**

Bushing condition Worn Out

Front struts (Shock Absorber)

Condition : **Excellent**

No Leakage & Rubber boots ok

Rear Shock Absorber/Spring

Condition : **Excellent**

No Leakage & Rubber boots ok

Stabiliser Bar & Other bushes

Condition : **Bad**

Bushing condition Bad or Noise

[View this car in Website](#)

Engine & Transmission (Continued...)

Link Rods (Ball joints)

Condition : **Bad**

Noise or Wheel wobbling

ABS

Condition : **Excellent**

Working

Brake Pedal

Condition : **Excellent**

Operating Properly

Accelerator

Condition : **Excellent**

Working Properly

Check Front Brake Efficiency

Condition : **Bad**

Operating with noise

Check Rear Brake Efficiency

Condition : **Bad**

Operating with noise

Master Cylinder & Booster

Condition : **Excellent**

Good Condition

**Gearshift lever
Automatic/Manual**

Condition : **Excellent**

Good Condition

Clutch Engagement

Condition : **Satisfactory**

Juddering/Vibration

Axle Noise

Condition : **Excellent**

No noise & Boot okay

Front Wheel bearings

Condition : **Excellent**

Good Condition

Rear Wheel bearings

Condition : **Excellent**

Good Condition

Differential

Condition : **Excellent**

Good Condition

Alignment

Condition : **Satisfactory**

Pulling

Balancing

Condition : **Satisfactory**

Wobbling

**Transmission Oil (Manual/
Automatic)**

Condition : **Satisfactory**

Not OK

**Engine and transmission
mountings**

Condition : **Bad**

Vibration

Abnormal Engine Noise

Condition : **Excellent**

No Noise

[View this car in Website](#)

Engine & Transmission (Continued...)

Back Compression

Condition : **Excellent**

Back Compression Not Present

Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

Gasket - tappet cover

Condition : **Excellent**

Good Condition

Engine oil leaks From Bottom/Oil Sump

Condition : **Excellent**

Good Condition

Silencer

Condition : **Excellent**

Good Condition

Catalytic Converter

Condition : **Excellent**

Good Condition

Engine Smoke Colour

Condition : **Excellent**

No colour

Air Filter

Condition : **Bad**

Not Replaced or Not Cleaned

Radiator

Condition : **Bad**

Leakage

Condenser

Condition : **Excellent**

Good Condition

Engine oil & Oil Filter

Condition : **Excellent**

Good Condition

Coolant

Condition : **Excellent**

Good Condition

Brake Oil

Condition : **Satisfactory**

Low Fluid

Hose Pipe

Condition : **Excellent**

Good Condition

Alternator Drive Belt

Condition : **Excellent**

Good Condition

Water Pump

Condition : **Excellent**

Good Condition

Tappet Noise

Condition : **Bad**

Noise

Turbo Charger

Condition : **Excellent**

Good Condition

[View this car in Website](#)

Engine & Transmission (Continued...)

Heater Plugs (in Diesel)

Condition : **Excellent**

Good Condition

Spark Plugs (in Petrol)

Condition : **Excellent**

Not Applicable

Radiator Fan

Condition : **Excellent**

Temperature Sensor Working

Ignition Coil (petrol only)

Condition : **Excellent**

Not Applicable

Ignition Wire Harness (petrol only)

Condition : **Excellent**

Not Applicable

Fuel Tank and Pipes

Condition : **Excellent**

Good Condition

Fuel Filter (Petrol & Diesel)

Condition : **Excellent**

Good Condition

Fuel Injectors

Condition : **Excellent**

Working Smoothly

[View this car in Website](#)

Vehicle Images

Front Side



7 Dec 2022 3:07:34 pm

Lat 29.1951931, Long 78.8730872

Front Right Side



7 Dec 2022 3:07:44 pm

Lat 29.1950946, Long 78.8727364

Front Right Tyre



7 Dec 2022 3:08:04 pm

Lat 29.194931, Long 78.872762

Right Side



7 Dec 2022 3:08:16 pm

Lat 29.1949238, Long 78.8727625

Rear Right Tyre



7 Dec 2022 3:08:38 pm

Lat 29.1948198, Long 78.8727796

Rear Right Side



7 Dec 2022 3:08:50 pm

Lat 29.1949658, Long 78.8727483

Back Side



7 Dec 2022 3:09:03 pm

Lat 29.1950011, Long 78.8727533

Spare Tyre



7 Dec 2022 3:09:16 pm

Lat 29.1950436, Long 78.8728202

[View this car in Website](#)

Rear Left Side



7 Dec 2022 3:09:25 pm

Lat 29.195072, Long 78.8727649

Rear Left Tyre



7 Dec 2022 3:09:39 pm

Lat 29.1950931, Long 78.8726795

Left Side



7 Dec 2022 3:09:55 pm

Lat 29.1949786, Long 78.872805

Front Left Tyre



7 Dec 2022 3:10:07 pm

Lat 29.1951338, Long 78.8727504


Front Left Side



7 Dec 2022 3:10:16 pm

Lat 29.195046, Long 78.8727816

Chassis Imprint



7 Dec 2022 3:03:46 pm

Lat 29.1949018, Long 78.8727302

Odometer



7 Dec 2022 3:04:31 pm

Lat 29.194933, Long 78.8727686

Top Side



7 Dec 2022 3:06:45 pm

Lat 29.1947408, Long 78.8725702

[View this car in Website](#)

Front 2 seats



7 Dec 2022 3:05:09 pm

Lat 29.1949385,Long 78.8727953

Rear 2 seats



7 Dec 2022 3:04:58 pm

Lat 29.1949328,Long 78.8727906

Insurance

7 Dec,2022 3:18:24 pm
GPS - 29.194933 , 78.872642

[Mask](#)

Vehicle Model ERTIGA VDI BS 4 Check Price	Vehicle Maker MARUTI SUZUKI INDIA LTD
Vehicle Financier ICICI BANK LTD.	Vehicle Class, Body Type Motor Car(LMV), SALOON
RC Status ACTIVE	Ownership First Owner
RC Valid Upto 29-Aug-2029 (6 years, 8 months, 22 days)	RC Issue Date 30-Aug-2014 (8 years, 3 months, 7 days)
Pollution Cert Valid Upto 07-Oct-2022 (Expired)	Pollution Cert No NA.
Insurance Valid Upto 03-Oct-2022 (Expired)	Insurance Policy No NA. (Royal Sundaram General Insurance Co. Ltd)
Seat Capacity 7 (Including Driver)	Engine Capacity 1248.0 CC

7 Dec 2022 3:18:24 pm

Lat 29.1948996,Long 78.8726425

Videos

Car Exterior Video

https://chnimgs3bkt.s3.amazonaws.com/autoinspekt/2022/12/07/294715591/original/1670405389778_1670405312615.mp4

Car Engine Video

https://chnimgs3bkt.s3.amazonaws.com/autoinspekt/2022/12/07/294715591/original/1670405457538_1670405415765.mp4

[View this car in Website](#)