

### Mahindra First Choice Wheels Certification Report



## 2016 MARUTI SUZUKI CIAZ(2014-2017) ZDI PLUS

Dadra & Nagar Haveli | 67644 km | Diesel | Manual | White Colour | 2nd Owner

- ✔ Eligible for Warranty
- ✔ 140+ Points Inspected



Exterior	Fair
<hr style="border: 1px solid orange;"/>	
Interior	Fair
<hr style="border: 1px solid orange;"/>	
Engine & Transmission	Fair
<hr style="border: 1px solid orange;"/>	

Overall  
**Fair Buy** 🍀



Explore this car in website [View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **140+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

## Vehicle Details

Owner Name

**Chawla Motors**

Registration Month

**February**

Registration Year

**2017**

Color

**White**

Odometer Reading(km)

**67644**

Registration Number

**DN09XXXXX**

No of Owners

**2**

Insurance Status

**Not available**

Chassis Number

**MAINXXXXXXXXXXXXX**

Engine Number

**SMG6XXXXXX**

Remarks

**Service Required.**

Remarks

**Service Required.**

RC Status

**RC Not Available**

PUC Certificate

**Available**

Keys Availability

**Worn Out**

Transfer Papers Availability

**All Papers available**

Vehicle Status

**Certified**

[View in Website](#)

**Front Bumper**

Condition : **Excellent**

No damage

**Grill / Emblem**

Condition : **Excellent**

No scratch & in good condition

**Windscreen glass**

Condition : **Excellent**

Clean, No marks

**Right Running Board**

Condition : **Excellent**

No dents & scratches

**Right Quarter Panel**

Condition : **Good**

1-2 minor dents & minimal scratches

**Right Fender**

Condition : **Good**

1-2 minor dents & minimal scratches

**Front Right Door**

Condition : **Good**

1-2 minor dents & minimal scratches

**Rear Right Indicator**

Condition : **Excellent**

Working & in good condition

**Rear Right Indicator**

Condition : **Excellent**

Working & in good condition

**Right Doors Functionality**

Condition : **Excellent**

Smooth to operate

**RH Side All Pillars**

Condition : **Excellent**

Spot welding original

**Right Side View Mirror**

Condition : **Excellent**

Operating smoothly & no scratches

**Windscreen Washer and Jets**

Condition : **Excellent**

Smooth operations

**Trunk**

Condition : **Excellent**

No dents or scratches

**Bonnet**

Condition : **Excellent**

No dents or scratches

**Front Right Tyre**

Condition : **Good**

Same Make/ Good & > 60% life

**Rear Right Tyre**

Condition : **Good**

Same Make/ Good & > 60% life

**Trunk, Bonnet and Hood functionality**

Condition : **Excellent**

Operating smoothly

Exterior (Continued...)

**Rear Bumper**

Condition : **Excellent**

No damage

**Spare Tyre**

Condition : **Good**

Same Make/ Good & > 60% life

**Number Plate (Front & Rear)**

Condition : **Excellent**

Good condition

**Left Running Board**

Condition : **Excellent**

No dents or scratches

**Left Quarter Panel**

Condition : **Excellent**

No dents or scratches

**Left Fender**

Condition : **Good**

1-2 minor dents & minimal scratches

**Front Left Door**

Condition : **Good**

1-2 minor dents & minimal scratches

**Rear Left Door**

Condition : **Excellent**

No dents or scratches

**Left Doors Functionality**

Condition : **Excellent**

Smooth to operate

**LH Side All Pillars**

Condition : **Excellent**

Spot welding original

**Left Side View Mirror**

Condition : **Excellent**

Operating smoothly & no scratches

**Fuel Cap - Check Operation/ Noise**

Condition : **Excellent**

Operating smoothly

**Front Left Tyre**

Condition : **Excellent**

Same Make/ Good & > 80% life

**Rear Left Tyre**

Condition : **Good**

Same Make/ Good & > 60% life

**Frame or Underbody**

Condition : **Good**

1-2 panels changed

**Paint, Polishing and Gloss**

Condition : **Good**

1 panel has color difference

**Parking lights Front & Rear**

Condition : **Excellent**

Working & in good condition

**Right Taillight**

Condition : **Excellent**

Working & in good condition

Exterior (Continued...)

**Left Taillight**

Condition : **Excellent**

Working & in good condition

**Rear Left Indicator**

Condition : **Excellent**

Working & in good condition

**Front Left Indicator**

Condition : **Excellent**

Working & in good condition

**Front Right Indicator**

Condition : **Excellent**

Working & in good condition

**Left Headlight (Both Points)**

Condition : **Excellent**

Working & in good condition

**Right Headlight (Both Points)**

Condition : **Excellent**

Working & in good condition

**Wheel Rim (Steel / Alloy)  
(Including Spare Wheel)**

Condition : **Excellent**

Good condition

**Spare Wheel Cover**

Condition : **Excellent**

Good condition

**Fog lamps**

Condition : **Excellent**

Operating & in good condition

**Alloy Wheels**

Condition : **Excellent**

Good condition

**Wheel Cap**

Condition : **NA**

Not Applicable

**Carpet - Cleanliness, torn off, proper size**

Condition : **Good**

Ok but some stains

**All Door Trim**

Condition : **Excellent**

Clean & no rattling noise

**Seat Adjustment**

Condition : **Excellent**

Working smoothly

**Safety Belts Inertia Locking System**

Condition : **Excellent**

Smooth to operate

**Dashboard**

Condition : **Excellent**

Clean & no rattling noise

**Rubber Beading (All)**

Condition : **Excellent**

Clean & No wear & tear marks

**Window Mechanisms**

Condition : **Excellent**

Operating smoothly (All 4)

**Inside Rear View Mirror**

Condition : **Excellent**

Operating smoothly & no scratches

**Seat Condition**

Condition : **Excellent**

Seat cover is in good condition

**Instrument Panel Gauges**

Condition : **Excellent**

Operations & Visibility good

**Instrument Panel Warning Lights**

Condition : **Excellent**

Operating

**Horns**

Condition : **Excellent**

Operating

**Wipers (all speeds)**

Condition : **Excellent**

Smooth to operate

**Combination Switch**

Condition : **Excellent**

Operating smoothly & not faded

**Clock / Stereo controls / Power windows & other electrical controls**

Condition : **Satisfactory**

Working but some wear & tear marks

**Cigarette Lighter / Charger / USB Port**

Condition : **Excellent**

Working & in good condition

**Interior lights**

Condition : **Excellent**

Working smoothly

**Hazard lights**

Condition : **Excellent**

Working & in good condition

Interior (Continued...)

**Trunk Light**

Condition : **Excellent**

Working & in good condition

**AC Cooling**

Condition : **Good**

Good

**Heating**

Condition : **Excellent**

Working

**Air distribution (AC Vents)**

Condition : **Excellent**

Operating & in good condition

**Recirculation/ Fresh air**

Condition : **Excellent**

Operating Smoothly

**Manual / Power Steering  
(Electronic/Hydraulic)**

Condition : **Excellent**

Operations are smooth & no noise/ play observed

**Hand Brake**

Condition : **Excellent**

Smooth operations

**Music System**

Condition : **Good**

Ok but some wear & tear marks

**Speakers**

Condition : **Good**

Ok but sound quality ok

**Defogger**

Condition : **Excellent**

Operating & in good condition

**CNG/LPG kit**

Condition : **NA**

Not Applicable

**Central Locking System**

Condition : **Excellent**

In good condition & smooth operation

**Jack And Tommy (Tool Kit)**

Condition : **Excellent**

Available & in very good condition

**Dickey Shock Absorber**

Condition : **Good**

Ok with No leakage marks /  
Operation slightly weak

**Battery - Specification /  
Voltage check / Check  
Petroleum Jelly Application**

Condition : **Excellent**

Operating smooth & < 2 years  
old

**Alternator**

Condition : **Excellent**

Smooth Operations

**Starter Motor**

Condition : **Excellent**

Smooth Operations

**Fuel Pump ( Petrol)**

Condition : **Excellent**

Smooth operations

**AC Compressor**

Condition : **Satisfactory**

Working but low noise  
observed

**Condenser Fan**

Condition : **Excellent**

No noise & smooth operation  
(Proper cut-off)

**Blower motor**

Condition : **Excellent**

Smooth operations

**Steering Rattling Noise**

Condition : **Excellent**

Smooth & no noise

**Suspension Arms**

Condition : **Excellent**

Working smoothly

**Front struts (Shock absorber)**

Condition : **Excellent**

No noise, Smooth Operation

**Rear Shock Absorber/Spring**

Condition : **Excellent**

No noise & smooth Operation

**Stabiliser Bar & Other Bushes**

Condition : **Excellent**

No noise & smooth operation

**ABS**

Condition : **Excellent**

Smooth Operation (High Speed  
Pedal Vibration)

**Brake Pedal**

Condition : **Excellent**

Smooth Operation & Play

**Check Front Brake**

Condition : **Excellent**

Smooth operation & braking  
efficiency

**Check Rear Brake**

Condition : **Excellent**

Smooth operation & braking  
efficiency

**Master Cylinder / Wheel  
Cylinder**

Condition : **Excellent**

Smooth operation

Engine & Transmission (Continued...)

**Braking Efficiency**

Condition : **Excellent**  
Operating smoothly

**Gearshift level (Gear Engagement)**

Condition : **Excellent**  
Smooth operation

**Gear Lever Play**

Condition : **Excellent**  
Smooth operation

**Clutch Engagement**

Condition : **Excellent**  
Smooth operation

**Clutch Pedal / Cable Operation**

Condition : **Excellent**  
Smooth

**Axle Noise/Drive Shaft Boot Damage**

Condition : **Excellent**  
No noise

**Front & Rear Wheel Bearings**

Condition : **Excellent**  
No noise

**Differential**

Condition : **Excellent**  
Smooth operations

**Alignment/Balancing**

Condition : **Excellent**  
No pulling

**Transmission Oil (Manual/ Automatic)**

Condition : **Excellent**  
No Leakage/ Good condition  
(Changed during Refurbishment)

**Engine and Transmission Mountings**

Condition : **Excellent**  
No Noise/Vibrations

**Abnormal Engine Noise/ Back Compression**

Condition : **Excellent**  
No noise (Tappet as well as Knocking noise)

**Engine Oil Leaks: Cylinder Head Gasket**

Condition : **Excellent**  
No leakage/ Good condition  
(Changed during refurbishment)

**Gasket: Tappet Cover**

Condition : **Excellent**  
No leakage

**Engine Oil Leaks: Crankcase Oil Seals/ Camshaft**

Condition : **Excellent**  
No leakage

**Engine Oil Leaks: Sump Gasket**

Condition : **Excellent**  
No leakage

**Engine Oil Leaks: Sump Damage**

Condition : **Excellent**  
No leakage/ Damage

**Exhaust system**

Condition : **Excellent**  
No noise, No rusting sign & smooth Operation

Engine & Transmission (Continued...)

**Smoke Color (Blue)**

Condition : **Excellent**

No Color

**Smoke Color (Black)**

Condition : **Excellent**

No Color

**Smoke Color (White)**

Condition : **Excellent**

No Color

**Air Filter**

Condition : **Excellent**

Good condition (Changed during refurbishment)

**Radiator /Condenser**

Condition : **Excellent**

Good Condition & no damage/rusting sign

**Engine oil**

Condition : **Excellent**

No Leakage/ Good condition (Changed during RF)

**Coolant**

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

**Brake Oil**

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

**Hose Pipe**

Condition : **Excellent**

Good condition

**Alternator Drive Belt**

Condition : **Excellent**

Good condition

**Water Pump**

Condition : **Excellent**

Good Condition & no noise

**Tappet Noise**

Condition : **Bad**

Noise

**Turbo Charger**

Condition : **Excellent**

Good condition

**Heater Plugs / Spark Plugs**

Condition : **Excellent**

Good condition (Changed during refurbishment)

**Radiator Fan**

Condition : **Excellent**

No noise & smooth Operation (Proper cut-off)

**Charcoal Canister**

Condition : **Excellent**

No damage & Petrol fume

**Ignition Coil (petrol only)**

Condition : **Excellent**

Working smoothly

**Ignition Wire Harness (petrol only)**

Condition : **Excellent**

Wiring & insulation good condition

Engine & Transmission (Continued...)

**Fuel Tank and Pipes**

Condition : **Excellent**

Good condition

**Fuel Filter (Petrol & Diesel)**

Condition : **Excellent**

Good condition (Changed during refurbishment)

**Fuel Injection Pump (Diesel)**

Condition : **Excellent**

No leakage & in good condition

## Vehicle Images

### Front Side



Nov 6, 2022 14:33:59

Lat 21.8311165, Long 75.6159131

### Front Right Side



Nov 6, 2022 14:34:54

Lat 21.831089, Long 75.615937

### Front Right Tyre



Nov 6, 2022 14:35:24  
GPS - 21.83107, 75.61592

Nov 6, 2022 14:35:24

Lat 21.8310696, Long 75.6159204

### Right Side



Nov 6, 2022 14:35:15  
GPS - 21.831069, 75.615937

Nov 6, 2022 14:35:14

Lat 21.8310694, Long 75.6159389

### Rear Right Tyre



Nov 6, 2022 14:35:56  
GPS - 21.831075, 75.615961

Nov 6, 2022 14:35:56

Lat 21.8310747, Long 75.6159611

### Rear Right Side



Nov 6, 2022 14:35:47  
GPS - 21.831067, 75.615946

Nov 6, 2022 14:35:47

Lat 21.8310666, Long 75.6159462

### Back Side



Nov 6, 2022 14:36:10  
GPS - 21.831082, 75.615952

Nov 6, 2022 14:36:10

Lat 21.8310856, Long 75.6159618

### Rear Left Side



Nov 6, 2022 14:36:50  
GPS - 21.831153, 75.615928

Nov 6, 2022 14:36:50

Lat 21.8311534, Long 75.6159087

[View this car in Website](#)

**Rear Left Tyre**



Nov 6, 2022 14:37:06  
GPS - 21.831121 , 75.615909

Nov 6, 2022 14:37:06

Lat 21.8311206, Long 75.6159093

**Left Side**



Nov 6, 2022 14:37:18  
GPS - 21.831126 , 75.615905

Nov 6, 2022 14:37:18

Lat 21.831126, Long 75.6159055

**Front Left Tyre**



Nov 6, 2022 14:37:27  
GPS - 21.831132 , 75.615893

Nov 6, 2022 14:37:27

Lat 21.8311323, Long 75.6158933

**Front Left Side**



Nov 6, 2022 14:37:41  
GPS - 21.831135 , 75.615907

Nov 6, 2022 14:37:41

Lat 21.8311355, Long 75.6159076

**Odometer**



Nov 6, 2022 14:39:20  
GPS - 21.831134 , 75.61588

Nov 6, 2022 14:39:20

Lat 21.8311345, Long 75.6158799

**Top Side**



Nov 6, 2022 14:41:29  
GPS - 21.831085 , 75.615929

Nov 6, 2022 14:41:29

Lat 21.831085, Long 75.6159287

**Front 2 seats**



Nov 6, 2022 14:40:36  
GPS - 21.831113 , 75.615977

Nov 6, 2022 14:40:36

Lat 21.8311129, Long 75.6159766

**Rear 2 seats**



Nov 6, 2022 14:40:46  
GPS - 21.831089 , 75.61597

Nov 6, 2022 14:40:46

Lat 21.8310892, Long 75.61597