

Report ID: 4WCAN294892589 Stock ID: 542814

Mahindra First Choice Wheels Certification Report





2014 HONDA MOBILIO (2014-2017) S PETROL

Thane | 48987 km | Petrol | Manual | Others Colour | 1st Owner

Eligible for Warranty
200+ Points Inspected



Exterior Fair Interior Fair Engine & Transmission Fair

Overall Fair Buy 🎳



Explore this car in website

View in Website

Overall rating is the 'quality score' of a vehicle derived from a 200+ point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details		
Owner Name	Registration Month	Registration Year
Thane Motor Pvt Ltd	October	2014
Color	Odometer Reading(km)	Registration Number
Others	48987	MH02XXXXXX
No of Owners	Chassis Number	Engine Number
1	MAKDXXXXXXXXXXXX	L15ZXXXXXXXX
Insurance Status	Accidental / Flooded	CNG Validity Inspection Date
Not available	Non-Accidental and Non- flooded	Not Applicable
RC Status	PUC Certificate	Keys Availability
Available	Not Available	Two Keys Available And Both Worn Out
Transfer papers availability	CNG Hydro Test Validity Certificate Not Applicable	Vehicle Status
Available		Certified
Remarks		
certified		

View in Website



Front Bumper

Condition: Excellent

Light/Short Scratches-under 2

Grill

Condition: Excellent

Good Condition

Emblem

Condition: Excellent

Good Condition

Windscreen glass Front

Condition: Excellent

Good Condition

Bonnet

Condition: Excellent

Light/Short Scratches-under 2

Bonnet Functionality

Condition: Excellent

Good Condition

RH Side Apron

Condition: Excellent

Good Condition

Right Running Board

Condition: Excellent

Good Condition

Right Fender

Condition: Excellent

Light/Short Scratches-under 3

Front Right Door

Condition: Excellent

Light/Short Scratches-under 2

Right Front Door Functionality

Condition: Good

Not Smooth

Front Right Door handle

Condition: Excellent

Good Condition

Front Right Window Glass

Condition: Excellent

Light/Short Scratches-under 3

Rear Right Door

Condition: Excellent

Light/Short Scratches-under 2

Right Rear Door Functionality

Condition: Excellent

Good Condition

Rear Right Door handle

Condition: Excellent

Good Condition

Rear Right Window Glass

Condition: Excellent

Good Condition/Same Make

RH A Pillars

Condition: Excellent

RH B Pillars

Condition: Excellent

Good Condition

RH C Pillars

Condition: Excellent

Good Condition

Right Quarter Panel

Condition: Excellent

Good Condition

Right Side View Mirror + Casing

Condition: Excellent

Good Condition

Right Side Power Mirror + Casing

Condition: Excellent

Good Condition

Front right tyre

Condition: Good

60%-80%

Steel Wheel Rim Front RHS

Condition: Excellent

Not Applicable

Alloy Wheels Front RHS

Condition: Excellent

Good Condition

Rear right tyre

Condition: Good

60%-80%

Steel Wheel Rim Rear RHS

Condition: Excellent

Not Applicable

Alloy Wheels Rear RHS

Condition: Excellent

Good Condition

Windscreen glass Back

Condition: Excellent

Good Condition

Trunk

Condition: Excellent

Light/Short Scratches-under 2

Trunk Functionality

Condition: Excellent

Good Condition

Rear Bumper

Condition: Excellent

Light/Short Scratches-under 2

Dickey Shock absorber

Condition: Excellent

Good Condition

Spare tyre (stephney)

Condition: Good

Same Make/ Good & > 60% life

Spare Wheel / Cover

Condition: Excellent

Number Plate (Front & Rear)

Condition: Excellent

RTO Format

LH A Pillars

Condition: Excellent

Good Condition

LH B Pillars

Condition: Excellent

Good Condition

LH C Pillars

Condition: Excellent

Good Condition

Left Running Board

Condition: Satisfactory

Deep/long Scratches

Left Fender

Condition: Excellent

Light/Short Scratches-under 3

Left Front Door

Condition: Excellent

Light/Short Scratches-under 2

Front Left Door Functionality

Condition: Excellent

Good Condition

Front Left Door handle

Condition: Excellent

Good Condition

Front Left Window Glass

Condition: Excellent

Good Condition/Same Make

Left Side View Mirror + Casing

Condition: Excellent

Good Condition

Left Side Power Mirror +

Casing

Condition: Excellent

Good Condition

Rear Left Door

Condition: Excellent

Light/Short Scratches-under 2

Rear Left Door Functionality

Condition: Excellent

Good Condition

Rear Left Door handle

Condition: Excellent

Good Condition

Left Quarter Panel

Condition: Good

Light/Short Scratches

Rear Left Window Glass

Condition: Excellent

Good Condition/Same Make

Fuel Cap

Condition: Excellent

Working Properly

Front Left tyre

Condition: Good

60%-80%

Steel Wheel Rim Front LHS

Condition: Excellent

Not Applicable

Alloy Wheels Front LHS

Condition: Excellent

Good Condition

Rear Left tyre

Condition: Good

60%-80%

Steel Wheel Rim Rear LHS

Condition: Excellent

Not Applicable

Alloy Wheels Rear LHS

Condition: Excellent

Good Condition

LH Side Apron

Condition: Excellent

Good Condition

Frame or Underbody

Condition: Excellent

No panel Replaced

Reverse Camera & Reverse Parking Sensor

Condition: Excellent

Functional

Roof

Condition: Good

Light/Short Scratches-3

Windscreen Wiper Front

Condition: Excellent

All speeds working properly

Windscreen Wiper Rear

Condition: Excellent

Not Applicable

Windscreen Jets

Condition: Excellent

Good Condition

Parking Lights Front

Condition: Excellent

Good Condition

Parking Lights Rear

Condition: Excellent

Good Condition

Right Tail Light

Condition: Excellent

Good Condition

Left Tail Light

Condition: Excellent

Good Condition

Rear Left Indicator

Condition: Excellent

Rear Right Indicator

Condition: Excellent

Good Condition

Front Left Indicator

Condition: Excellent

Good Condition

Front Right Indicator

Condition: Excellent

Good Condition

Left Headlight (Both Points)

Condition: Excellent

Good Condition

Right Headlight (Both Points)

Condition: Excellent

Good Condition

Fog lamps

Condition: Excellent

Not Applicable

Wheel Cap

Condition: Excellent

Not Applicable

Interior Rating - Fair

RHS Front Door Trim

Condition: Excellent

Good Condition

RHS Rear Door Trim

Condition: Excellent

Good Condition

Rubber Beading Front RHS

O 60 Good

O 1 Issues

Condition : Excellent

Good Condition

Rubber Beading Rear RHS

Condition: Excellent

Good Condition

LHS Front Door Trim

Condition: Excellent

Good Condition

LHS Rear Door Trim

Condition: Excellent

Rubber Beading Front LHS

Condition: Excellent

Good Condition/Same Make

Rubber Beading Rear LHS

Condition: Excellent

Good Condition/Same Make

Carpets

Condition: Excellent

Good Condition

Roof Inside

Condition: Excellent

Good Condition

Driver Seat Sliding Front to Back

Condition: Excellent

Good Condition

Driver Seat recliner

Condition: Excellent

Good Condition

Driver Seat Up Down

Condition: Excellent

Good Condition

Passenger Seat Sliding Front to Back

Condition: Excellent

Good Condition

Passenger Seat recliner

Condition: Excellent

Good Condition

Passenger Seat Up Down

Condition: Excellent

Not Applicable

Safety belts inertia locking system Driver Seat

Condition: Excellent

Good Condition

Safety belts inertia locking system Passenger

Condition: Excellent

Good Condition

Dash Board

Condition: Excellent

Good Condition

Sunroof System

Condition: Excellent

Not Applicable

Front Right Window Type

Power Windows

Front Right Window Function

Condition: Bad

Bounced Back

Front Left Window Type

Power Windows

Front Left Window Function

Condition: Satisfactory

Noisy

Interior (Continued...)

Rear Right Window Type

Power Windows

Rear Right Window Function

Condition: Satisfactory

Noisy

Rear Left Window Type

Power Windows

Rear Left Window Function

Condition: Satisfactory

Noisy

Steering Mounted Controls

Condition: Excellent

Good Condition

Inside Rear View mirror

Condition: Excellent

Good Condition

Driver Seat Condition

Condition: Excellent

Good Condition

Passenger Seat Condition

Condition: Excellent

Good Condition

Rear Seat Condition

Condition: Excellent

Good Condition

Instrument panel gauges: Odometer

Condition: Excellent

Good Condition

Instrument panel Warning Lights

Condition: Excellent

Warning Lights Off - Good

Instrument panel gauges: Fuel

Condition: Excellent

Good Condition

Instrument panel gauges: Tachometer

Condition : Excellent

Condition . Excellent

Good Condition

Instrument panel gauges: Temperature

ciliperature

Condition: Excellent

Good Condition

Horn

Condition: Excellent

Good Condition

Combination Switch

Condition: Excellent

Good Condition

Stereo Controls

Condition: Excellent

Good Condition

Charger/USB Port

Condition: Excellent

Interior (Continued...)

Interior lights

Condition: Excellent

Good Condition

Hazard lights

Condition: Excellent

Good Condition

Trunk Light

Condition: Excellent

Good Condition

Music System

Condition: Excellent

Good Condition

Music system type

Steering Wheel Mounted Music

Control

Speakers

Condition: Excellent

Good Condition

Defogger

Condition: Excellent

Good Condition

Central Locking System

Condition: Excellent

Good Condition

AC cooling (Check undershade)

Condition: Excellent

Good Condition

Heating

Condition: Excellent

Good Condition

Air distribution (AC Vents)

Condition: Excellent

Good Condition

Recirculation/ Fresh air

Condition: Excellent

Good Condition

Steering Type

Power Steering

Power Steering Type

Electronic

Steering condition

Condition: Excellent

Good Condition

Air Bags

Condition: Excellent

Not Applicable

Hand Brake

Condition: Excellent

Working less than 4 notches

CNG/LPG kit -OEM/Aftermarket

Condition: Excellent

No

Jack And Tommy (Tool Kit)

Condition: Excellent

Available

Engine & Transmission Rating - Fair

O 56 Good

O Issues

Battery

Condition: Excellent

Good Condition

Alternator

Condition: Excellent

Good Condition

Starter Motor

Condition: Excellent

Good Condition

Fuel Pump

Condition: Excellent

Good Condition

AC Compressor

Condition: Excellent

Good Condition

Condenser Fan

Condition: Excellent

Good Condition

Blower motor

Condition: Excellent

Good Condition

Steering / Column with motor **Rattling Noise**

Condition: Excellent

Working Properly

Suspension Arms

Condition: Excellent

All rubber boot & bushing ok

Front struts (Shock Absorber)

Condition: Excellent

No Leakage & Rubber boots ok

Rear Shock Absorber/Spring

Condition: Excellent

No Leakage & Rubber boots ok

Stabiliser Bar & Other bushes

Condition: Excellent

Link Rods (Ball joints)

Condition: Excellent

No Noise & Rubber boots ok

ABS

Condition: Excellent

Not Applicable

Brake Pedal

Condition: Excellent

Operating Properly

Accelarator

Condition: Excellent

Working Properly

Check Front Brake Efficiency

Condition: Excellent

Operating Efficiently

Check Rear Brake Efficiency

Condition: Excellent

Operating Efficiently

Master Cylinder & Booster

Condition: Excellent

Good Condition

Gearshift lever Automatic/Manual

Condition: Excellent

Good Condition

Clutch Engagement

Condition: Excellent

More than 50% life

Axle Noise

Condition: Excellent

No noise & Boot okay

Front Wheel bearings

Condition: Excellent

Good Condition

Rear Wheel bearings

Condition: Excellent

Good Condition

Differential

Condition: Excellent

Good Condition

Alignment

Condition: Excellent

Good Condition

Balancing

Condition: Excellent

Good Condition

Transmission Oil (Manual/ Automatic)

Condition: Excellent

Oil Level Condition OK

Engine and transmission mountings

Condition: Excellent

Good Condition

Abnormal Engine Noise

Condition: Excellent

No Noise

Back Compression

Condition: Excellent

Back Compression Not Present

Head Gasket leakage/replaced

Condition: Excellent

Good Condition

Gasket - tappet cover

Condition: Excellent

Good Condition

Engine oil leaks From Bottom/Oil Sump

Condition: Excellent

Good Condition

Silencer

Condition: Excellent

Good Condition

Catalytic Converter

Condition: Excellent

Good Condition

Engine Smoke Colour

Condition: Excellent

No colour

Air Filter

Condition: Excellent

Cleaned/Replaced

Radiator

Condition: Excellent

Good Condition

Condenser

Condition: Excellent

Good Condition

Engine oil & Oil Filter

Condition: Excellent

Good Condition

Coolant

Condition: Excellent

Good Condition

Brake Oil

Condition: Excellent

Good Condition

Hose Pipe

Condition: Excellent

Good Condition

Alternator Drive Belt

Condition: Excellent

Good Condition

Water Pump

Condition: Excellent

Good Condition

Tappet Noise

Condition: Excellent

Working Smoothly

Turbo Charger

Condition: Excellent

Not Applicable

Heater Plugs (in Diesel)

Condition: Excellent

Not Applicable

Spark Plugs (in Petrol)

Condition: Excellent

Good Condition

Radiator Fan

Condition: Excellent

Temperature Sensor Working

Ignition Coil (petrol only)

Condition: Excellent

Good Condition

Ignition Wire Harness (petrol only)

Condition: Excellent

Good Condition

Fuel Tank and Pipes

Condition: Excellent

Good Condition

Fuel Filter (Petrol & Diesel)

Condition: Excellent

Good Condition

Fuel Injectors

Condition: Excellent

Working Smoothly

Front Side



23 Nov 2022 12:45:02 pm

Lat 19.2175469,Long 72.9902303

Front Right Side



23 Nov 2022 12:45:11 pm

Lat 19.2175074,Long 72.9900325

Front Right Tyre



23 Nov 2022 12:45:42 pm

Lat 19.21723,Long 72.9908513

Right Side



23 Nov 2022 12:45:53 pm

Lat 19.2174948,Long 72.9900221

Rear Right Tyre



23 Nov 2022 12:46:01 pm

Lat 19.2174814,Long 72.9900231

Rear Right Side



23 Nov 2022 12:46:18 pm

Lat 19.2161603,Long 72.9902093

Back Side



23 Nov 2022 12:46:27 pm

Lat 19.2177319,Long 72.9899674

Rear Left Side



23 Nov 2022 12:46:38 pm

Lat 19.2174695,Long 72.990013

Rear Left Tyre



23 Nov 2022 12:47:05 pm

Lat 19.2175431,Long 72.9900068

Left Side



23 Nov 2022 12:47:25 pm

Lat 19.2174809,Long 72.9900181

Front Left Tyre



23 Nov 2022 12:47:34 pm

Lat 19.2174858,Long 72.9900194

Front Left Side



23 Nov 2022 12:47:44 pm

Lat 19.21749,Long 72.9900247

Odometer



23 Nov 2022 12:48:45 pm

Lat 19.2174943,Long 72.9900325

Videos

Car Exterior Video

https://tinyurl.com/2n6dgw2a

Car Engine Video

https://tinyurl.com/2jzcbowz