

Mahindra First Choice Wheels Inspection Report



2010 HYUNDAI SONATA TRANSFORM(2009-2011) 2.0 CRDI AT

Ghaziabad | 72566 km | Diesel | Automatic | Black Colour | 1st Owner

- ✔ Assist First Warranty
- ✔ 200+ Points Inspected



Exterior	<div style="width: 70%;"></div>	Fair
Interior	<div style="width: 80%;"></div>	Fair
Engine & Transmission	<div style="width: 85%;"></div>	Fair

Overall
Fair Buy 🍏

M Mahajan
Head Certification & Warranty - MFCWL

[Explore this car in website](#) [View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

Bharat Cars-Ghaziabad

Registration Month

February

Registration Year

2010

Color

Black

Odometer Reading(km)

72566

Registration Number

DL3CXXXXX

No of Owners

1

Chassis Number

9638XXX

Engine Number

5877XXX

Insurance Status

Not available

Accidental / Flooded

Non-Accidental and Non-flooded

CNG Validity Inspection Date

Not Valid

RC Status

Not Available

PUC Certificate

Not Available

Keys Availability

One Key Available And Good

Transfer papers availability

Available

CNG Hydro Test Validity Certificate

Not Applicable

Vehicle Status

Inspected

Remarks

ten year old

[View in Website](#)

Front Bumper

Condition : Good

Dents With Paint Damage

Grill

Condition : Bad

Broken/missing

Emblem

Condition : Bad

Broken/missing

Windscreen glass Front

Condition : Satisfactory

Cracks

Bonnet

Condition : Good

Dents without paint damage-2 & Above

Bonnet Functionality

Condition : Good

Not Smooth

RH Side Apron

Condition : Excellent

Good Condition

Right Running Board

Condition : Satisfactory

Deep/long Scratches

Right Fender

Condition : Satisfactory

Deep/long Scratches-2 to 5

Front Right Door

Condition : Good

Dents With Paint Damage

Right Front Door Functionality

Condition : Excellent

Good Condition

Front Right Door handle

Condition : Excellent

Good Condition

Front Right Window Glass

Condition : Excellent

Deep/long Scratches-1

Rear Right Door

Condition : Good

Dents With Paint Damage

Right Rear Door Functionality

Condition : Satisfactory

Functional with Noise

Rear Right Door handle

Condition : Good

Misaligned

Rear Right Window Glass

Condition : Satisfactory

Deep/long Scratches

RH A Pillars

Condition : Good

Scratches-under 2

Exterior (Continued...)

RH B Pillars

Condition : **Good**

Scratches-under 2

RH C Pillars

Condition : **Good**

Scratches-under 2

Right Quarter Panel

Condition : **Bad**

Dent with Paint Damage

Right Side View Mirror + Casing

Condition : **Excellent**

Good Condition

Right Side Power Mirror + Casing

Condition : **Satisfactory**

Light/Short Scratches

Front right tyre

Condition : **Bad**

Less than 20%

Steel Wheel Rim Front RHS

Condition : **Excellent**

Not Applicable

Alloy Wheels Front RHS

Condition : **Satisfactory**

Scratches

Rear right tyre

Condition : **Bad**

Less than 20%

Steel Wheel Rim Rear RHS

Condition : **Excellent**

Not Applicable

Alloy Wheels Rear RHS

Condition : **Satisfactory**

Scratches

Windscreen glass Back

Condition : **Satisfactory**

Light/Short Scratches

Trunk

Condition : **Good**

Dents With Paint Damage

Trunk Functionality

Condition : **Excellent**

Good Condition

Rear Bumper

Condition : **Good**

Dents without paint damage-2 & Above

Dickey Shock absorber

Condition : **Excellent**

Not Applicable

Spare tyre (stephney)

Condition : **Bad**

Different Make/ Cut Marks/
Bulge /< 30% life

Spare Wheel / Cover

Condition : **Bad**

Crack

[View this car in Website](#)

Exterior (Continued...)

Number Plate (Front & Rear)

Condition : **Excellent**

RTO Format

LH A Pillars

Condition : **Satisfactory**

Scratches-2 & Above

LH B Pillars

Condition : **Good**

Dents-1

LH C Pillars

Condition : **Good**

Dents-1

Left Running Board

Condition : **Satisfactory**

Deep/long Scratches

Left Fender

Condition : **Bad**

Dent with Paint Damage

Left Front Door

Condition : **Good**

Dents With Paint Damage

Front Left Door Functionality

Condition : **Excellent**

Good Condition

Front Left Door handle

Condition : **Excellent**

Good Condition

Front Left Window Glass

Condition : **Satisfactory**

Deep/long Scratches

Left Side View Mirror + Casing

Condition : **Satisfactory**

Light/Short Scratches

Left Side Power Mirror + Casing

Condition : **Satisfactory**

Light/Short Scratches

Rear Left Door

Condition : **Good**

Dents With Paint Damage

Rear Left Door Functionality

Condition : **Excellent**

Good Condition

Rear Left Door handle

Condition : **Excellent**

Good Condition

Left Quarter Panel

Condition : **Bad**

Dent with Paint Damage

Rear Left Window Glass

Condition : **Satisfactory**

Deep/long Scratches

Fuel Cap

Condition : **Bad**

Not Working Properly/Missing

[View this car in Website](#)

Exterior (Continued...)

Front Left tyre

Condition : **Bad**

Less than 20%

Steel Wheel Rim Front LHS

Condition : **Excellent**

Not Applicable

Alloy Wheels Front LHS

Condition : **Satisfactory**

Scratches

Rear Left tyre

Condition : **Bad**

Less than 20%

Steel Wheel Rim Rear LHS

Condition : **Excellent**

Not Applicable

Alloy Wheels Rear LHS

Condition : **Satisfactory**

Scratches

LH Side Apron

Condition : **Good**

Dents without paint damage

Frame or Underbody

Condition : **Satisfactory**

Panel Rusting

Reverse Camera & Reverse Parking Sensor

Condition : **Excellent**

Not Applicable

Roof

Condition : **Good**

Dents without paint damage-2

Windscreen Wiper Front

Condition : **Excellent**

All speeds working properly

Windscreen Wiper Rear

Condition : **Excellent**

All speeds working properly

Windscreen Jets

Condition : **Excellent**

Good Condition

Parking Lights Front

Condition : **Satisfactory**

Cracks

Parking Lights Rear

Condition : **Satisfactory**

cracks

Right Tail Light

Condition : **Satisfactory**

Cracks

Left Tail Light

Condition : **Satisfactory**

cracks

Rear Left Indicator

Condition : **Satisfactory**

Cracks

[View this car in Website](#)

Exterior (Continued...)

Rear Right Indicator

Condition : **Satisfactory**

Cracks

Front Left Indicator

Condition : **Satisfactory**

Cracks

Front Right Indicator

Condition : **Satisfactory**

Cracks

Left Headlight (Both Points)

Condition : **Excellent**

Good Condition

Right Headlight (Both Points)

Condition : **Satisfactory**

NON OEM High Power Lamps

Fog lamps

Condition : **Excellent**



Good Condition

Wheel Cap

Condition : **Excellent**

Not Applicable

Interior Rating - **Fair**

 48 Good  13 Issues

RHS Front Door Trim

Condition : **Satisfactory**

Unclean

RHS Rear Door Trim

Condition : **Satisfactory**

Unclean

Rubber Beading Front RHS

Condition : **Satisfactory**

Loose

Rubber Beading Rear RHS

Condition : **Satisfactory**

Loose

LHS Front Door Trim

Condition : **Satisfactory**

Unclean

LHS Rear Door Trim

Condition : **Satisfactory**

Unclean

[View this car in Website](#)

Rubber Beading Front LHS

Condition : **Satisfactory**

Loose

Rubber Beading Rear LHS

Condition : **Bad**

Broken

Carpets

Condition : **Satisfactory**

Unclean

Roof Inside

Condition : **Satisfactory**

Unclean

Driver Seat Sliding Front to Back

Condition : **Bad**

Not Functional

Driver Seat recliner

Condition : **Bad**

Not Functional

Driver Seat Up Down

Condition : **Bad**

Not Functional

Passenger Seat Sliding Front to Back

Condition : **Bad**

Not Functional

Passenger Seat recliner

Condition : **Bad**

Not Functional

Passenger Seat Up Down

Condition : **Excellent**

Not Applicable

Safety belts inertia locking system Driver Seat

Condition : **Bad**

Not Functional

Safety belts inertia locking system Passenger

Condition : **Bad**

Not Functional

Dash Board

Condition : **Satisfactory**

Scratches

Sunroof System

Condition : **Bad**

Broken/Not Functional

Front Right Window Type

Power Windows

Front Right Window Function

Condition : **Excellent**

Smooth Operation

Front Left Window Type

Power Windows

Front Left Window Function

Condition : **Excellent**

Smooth Operation

Interior (Continued...)

Rear Right Window Type

Power Windows

Rear Right Window Function

Condition : **Excellent**

Smooth Operation

Rear Left Window Type

Power Windows

Rear Left Window Function

Condition : **Excellent**

Smooth Operation

Steering Mounted Controls

Condition : **Excellent**

Good Condition

Inside Rear View mirror

Condition : **Excellent**

Good Condition

Driver Seat Condition

Condition : **Excellent**

Good Condition

Passenger Seat Condition

Condition : **Excellent**

Good Condition

Rear Seat Condition

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Odometer**

Condition : **Excellent**

Good Condition

**Instrument panel Warning
Lights**

Condition : **Bad**

Warning Lights On - Bad

Instrument panel gauges: Fuel

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Tachometer**

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Temperature**

Condition : **Excellent**

Good Condition

Horn

Condition : **Excellent**

Good Condition

Combination Switch

Condition : **Excellent**

Good Condition

Stereo Controls

Condition : **Excellent**

Good Condition

Charger/USB Port

Condition : **Excellent**

Good Condition

[View this car in Website](#)

Interior (Continued...)

Interior lights

Condition : **Excellent**

Good Condition

Hazard lights

Condition : **Excellent**

Good Condition

Trunk Light

Condition : **Excellent**

Good Condition

Music System

Condition : **Excellent**

Not Applicable

Music system type

Not Applicable

Speakers

Condition : **Excellent**

Good Condition

Defogger

Condition : **Bad**

Not Working

Central Locking System

Condition : **Excellent**

Good Condition

**AC cooling (Check
undershade)**

Condition : **Excellent**

Not Applicable

Heating

Condition : **Excellent**

Not Applicable

Air distribution (AC Vents)

Condition : **Excellent**

Not Applicable

Recirculation/ Fresh air

Condition : **Excellent**

Not Applicable

Steering Type

Power Steering

Power Steering Type

Hydraulic

Steering condition

Condition : **Bad**

Not Working

Air Bags

Condition : **Excellent**

Functional

Hand Brake

Condition : **Good**

Working more than 4 notches

**CNG/LPG kit -
OEM/Aftermarket**

Condition : **Excellent**

No

[View this car in Website](#)



Interior (Continued...)

Jack And Tommy (Tool Kit)

Condition : **Bad**

Not Available

Engine & Transmission Rating - Fair

 38 Good  18 Issues

Battery

Condition : **Satisfactory**

Age above 3 years

Alternator

Condition : **Satisfactory**

Noise

Starter Motor

Condition : **Excellent**

Good Condition

Fuel Pump

Condition : **Excellent**

Good Condition

AC Compressor

Condition : **Excellent**

Not Applicable

Condenser Fan

Condition : **Excellent**

Not Applicable

Blower motor

Condition : **Excellent**

Not Applicable

**Steering / Column with motor
Rattling Noise**

Condition : **Bad**

Not Functional

Suspension Arms

Condition : **Good**

Bushing condition Worn Out

Front struts (Shock Absorber)

Condition : **Satisfactory**

Rubber boot damage

Rear Shock Absorber/Spring

Condition : **Satisfactory**

Rubber boot damage

Stabiliser Bar & Other bushes

Condition : **Bad**

Bushing condition Bad or Noise

[View this car in Website](#)

Engine & Transmission (Continued...)

Link Rods (Ball joints)

Condition : **Good**

Rubber boot damage

ABS

Condition : **Excellent**

Working

Brake Pedal

Condition : **Bad**

Pumping Required

Accelerator

Condition : **Satisfactory**

Excessive Play

Check Front Brake Efficiency

Condition : **Bad**

Operating with noise

Check Rear Brake Efficiency

Condition : **Bad**

Operating with noise

Master Cylinder & Booster

Condition : **Bad**

Leakage

**Gearshift lever
Automatic/Manual**

Condition : **Satisfactory**

Not Smooth

Clutch Engagement

Condition : **Satisfactory**

Juddering/Vibration

Axle Noise

Condition : **Bad**

Boot torn out

Front Wheel bearings

Condition : **Bad**

Bad Condition

Rear Wheel bearings

Condition : **Satisfactory**

Noise

Differential

Condition : **Satisfactory**

Humming Noise

Alignment

Condition : **Satisfactory**

Pulling

Balancing

Condition : **Satisfactory**

Wobbling

**Transmission Oil (Manual/
Automatic)**

Condition : **Excellent**

Oil Level Condition OK

**Engine and transmission
mountings**

Condition : **Satisfactory**

Noise

Abnormal Engine Noise

Condition : **Bad**

Timing Belt Noise

[View this car in Website](#)

Engine & Transmission (Continued...)

Back Compression

Condition : **Excellent**

Back Compression Not Present

Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

Gasket - tappet cover

Condition : **Excellent**

Good Condition

Engine oil leaks From Bottom/Oil Sump

Condition : **Excellent**

Good Condition

Silencer

Condition : **Excellent**

Good Condition

Catalytic Converter

Condition : **Excellent**

Good Condition

Engine Smoke Colour

Condition : **Excellent**

No colour

Air Filter

Condition : **Bad**

Not Replaced or Not Cleaned

Radiator

Condition : **Bad**

Leakage

Condenser

Condition : **Bad**

Damage

Engine oil & Oil Filter

Condition : **Satisfactory**

Not Replaced

Coolant

Condition : **Satisfactory**

Discolouration

Brake Oil

Condition : **Bad**

Leakage

Hose Pipe

Condition : **Satisfactory**

Misaligned

Alternator Drive Belt

Condition : **Bad**

Cracks

Water Pump

Condition : **Bad**

Noise

Tappet Noise

Condition : **Bad**

Noise

Turbo Charger

Condition : **Satisfactory**

Smoky exhaust on acceleration

[View this car in Website](#)

Engine & Transmission (Continued...)

Heater Plugs (in Diesel)

Condition : **Excellent**

Not Applicable

Spark Plugs (in Petrol)

Condition : **Excellent**

Not Applicable

Radiator Fan

Condition : **Bad**

Not Working

Ignition Coil (petrol only)

Condition : **Excellent**

Not Applicable

Ignition Wire Harness (petrol only)

Condition : **Bad**

Broken/Cracked

Fuel Tank and Pipes

Condition : **Excellent**

Good Condition

Fuel Filter (Petrol & Diesel)

Condition : **Satisfactory**

Not Cleaned

Fuel Injectors

Condition : **Excellent**

Working Smoothly

[View this car in Website](#)

Vehicle Images

Front Side



Nov 26, 2022 10:52:28 AM

Lat 28.6638765, Long 77.3240056

Front Right Side



Nov 26, 2022 10:52:35 AM

Lat 28.6638441, Long 77.3239624

Front Right Tyre



Nov 26, 2022 10:52:39 AM

Lat 28.6637651, Long 77.3239829

Right Side



Nov 26, 2022 10:52:46 AM

Lat 28.663784, Long 77.323984

Rear Right Tyre



Nov 26, 2022 10:52:52 AM

Lat 28.6638355, Long 77.3239858

Rear Right Side



Nov 26, 2022 10:52:59 AM

Lat 28.6638549, Long 77.3239753

Back Side



Nov 26, 2022 10:53:06 AM

Lat 28.663853, Long 77.3239761

Rear Left Side



Nov 26, 2022 10:53:13 AM

Lat 28.6638568, Long 77.323976

[View this car in Website](#)

Rear Left Tyre



Nov 26, 2022 10:53:18 AM

Lat 28.663864, Long 77.3240104

Left Side



Nov 26, 2022 10:53:26 AM

Lat 28.6638643, Long 77.3240088

Front Left Tyre



Nov 26, 2022 10:53:31 AM

Lat 28.6638639, Long 77.3239302

Front Left Side



Nov 26, 2022 10:53:39 AM

Lat 28.6638705, Long 77.3239405

Odometer



Nov 26, 2022 10:54:19 AM

Lat 28.6638331, Long 77.3240371

[View this car in Website](#)

Videos

Car Exterior Video

https://chnimgs3bkt.s3.amazonaws.com/autoinspekt/2022/11/26/294933431/original/1669440067562_1669439990627.m

Car Engine Video

https://chnimgs3bkt.s3.amazonaws.com/autoinspekt/2022/11/26/294933431/original/1669440134004_1669440092239.m

[View this car in Website](#)