Mahindra First Choice Wheels Certification Report




2015 RENAULT DUSTER(2015-2016) 85 PS RXL

Bangalore | 71673 km | Diesel | Manual | White Colour | 1st Owner

🧟 Eligible for Warranty 🛛 🧕 200+ Points Inspected



Exterior	Fair
Interior	Fair
Engine & Transmission	Fair





Explore this car in website

View in Website

Overall rating is the 'quality score' of a vehicle derived from a **200**+ point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

India Garage Bangalore

Color

White

No of Owners

1

Insurance Status

Available

RC Status

Available

Transfer papers availability

Available

Remarks

.

Registration Month

April

Odometer Reading(km)

71673

Chassis Number

F108XXXX

Accidental / Flooded

Non-Accidental and Nonflooded

PUC Certificate

Available

CNG Hydro Test Validity Certificate

Not Applicable

Registration Year

2015

Registration Number

KA04XXXXXX

Engine Number

E004XXX

CNG Validity Inspection Date

Not Valid

Keys Availability

One Key Available And Good

Vehicle Status

Certified

View in Website

Exterior Rating - Fair

Front Bumper Condition : Excellent Good Condition

Windscreen glass Front

Condition : Excellent

Good Condition

Grill Condition : Excellent Good Condition

Bonnet Condition : Excellent Good Condition

RH Side Apron Condition : Excellent Good Condition

Front Right Door Condition : Excellent Good Condition

Right Front Door Functionality Condition : Excellent Good Condition

Front Right Window Glass Condition : Excellent Good Condition/Same Make **Rear Right Door Condition : Excellent** Good Condition

Rear Right Door handle Condition : Excellent Good Condition

Rear Right Window Glass Condition : Excellent Good Condition/Same Make Emblem Condition : Excellent Good Condition

Bonnet Functionality Condition : Excellent Good Condition

Right Fender Condition : Excellent Good Condition

Front Right Door handle Condition : Excellent Good Condition

Right Rear Door Functionality Condition : Excellent Good Condition

RH A Pillars Condition : Excellent Good Condition

Right Running Board Condition : Excellent Good Condition

O lssues O 79 Good

RH B Pillars Condition : Excellent Good Condition

Right Side View Mirror + Casing Condition : Excellent Good Condition RH C Pillars Condition : Excellent Good Condition

Right Side Power Mirror + Casing Condition : Excellent Good Condition

Alloy Wheels Front RHS

Condition : Excellent

Not Applicable

Steel Wheel Rim Front RHS Condition : Excellent Good Condition

Steel Wheel Rim Rear RHS Condition : Excellent Good Condition Alloy Wheels Rear RHS Condition : Excellent Not Applicable

Trunk Functionality Condition : Excellent Good Condition

Dickey Shock absorber Condition : Excellent Good Condition

Condition : Excellent

Good Condition

Trunk

Spare tyre (stephney) Condition : Satisfactory Same Make/ Good & > 40% life **Right Quarter Panel** Condition : Excellent Good Condition

Front right tyre Condition : Satisfactory 40%-60%

Rear right tyre Condition : Satisfactory 40%-60%

Windscreen glass Back Condition : Excellent Good Condition

Rear Bumper Condition : Excellent Good Condition

Spare Wheel / Cover Condition : Excellent Good Condition

Number Plate (Front & Rear) Condition : Excellent **RTO Format**

LH A Pillars Condition : Excellent Good Condition

Left Running Board Condition : Excellent Good Condition

Left Front Door Condition : Excellent Good Condition

LH C Pillars

Condition : Excellent

Good Condition

Front Left Window Glass Condition : Excellent Good Condition/Same Make Left Side View Mirror + Casing **Condition : Excellent** Good Condition

Front Left Door Functionality

Condition : Excellent

Good Condition

Rear Left Door Condition : Excellent Good Condition

Rear Left Door Functionality Condition : Excellent Good Condition

Rear Left Door handle Condition : Excellent

Left Quarter Panel **Condition : Excellent** Good Condition

Rear Left Window Glass Condition : Excellent Good Condition/Same Make **Condition : Excellent** Good Condition

LH B Pillars

Left Fender **Condition : Excellent** Good Condition

Front Left Door handle **Condition : Excellent** Good Condition

Left Side Power Mirror + Casing **Condition : Excellent** Good Condition

Good Condition

Fuel Cap Condition : Excellent Working Properly

Front Left tyre **Condition : Satisfactory** 40%-60%

Steel Wheel Rim Front LHS Condition : Excellent Good Condition

Rear Left tyre Condition : Satisfactory

Steel Wheel Rim Rear LHS Condition : Excellent Good Condition

LH Side Apron **Condition : Excellent** Good Condition

Condition : Excellent

Good Condition

40%-60%

Roof

Frame or Underbody Condition : Excellent No panel Replaced

Windscreen Wiper Front **Condition : Excellent** All speeds working properly

Windscreen Jets **Condition : Excellent** Good Condition

Parking Lights Front Condition : Excellent Good Condition

Right Tail Light Condition : Excellent Good Condition

Left Tail Light **Condition : Excellent** Good Condition

Alloy Wheels Front LHS **Condition : Excellent** Not Applicable

Alloy Wheels Rear LHS Condition : Excellent Not Applicable

Reverse Camera & Reverse Parking Sensor **Condition : Excellent** Functional

Windscreen Wiper Rear **Condition : Excellent** All speeds working properly

Parking Lights Rear Condition : Excellent Good Condition

Rear Left Indicator Condition : Excellent Good Condition

Rear Right Indicator Condition : Excellent Good Condition Front Left Indicator Condition : Excellent Good Condition Front Right Indicator Condition : Excellent Good Condition

Left Headlight (Both Points) Condition : Excellent Good Condition Right Headlight (Both Points) Condition : Excellent Good Condition Fog lamps Condition : Excellent Good Condition

Wheel Cap Condition : Excellent Available

Interior Rating - Fair

RHS Front Door Trim Condition : Excellent Good Condition RHS Rear Door Trim Condition : Excellent Good Condition

Rubber Beading Rear RHS Condition : Excellent Good Condition LHS Front Door Trim Condition : Excellent Good Condition O 61 Good O lssues

Rubber Beading Front RHS Condition : Excellent Good Condition

LHS Rear Door Trim Condition : Excellent Good Condition Rubber Beading Front LHS Condition : Excellent Good Condition/Same Make

Roof Inside Condition : Excellent Good Condition Rubber Beading Rear LHS Condition : Excellent Good Condition/Same Make

Driver Seat Sliding Front to Back Condition : Excellent Good Condition

Passenger Seat Sliding Front

Condition : Excellent

Good Condition

to Back

Driver Seat Up Down Condition : Excellent Good Condition

Passenger Seat Up Down Condition : Excellent Good Condition Safety belts inertia locking system Driver Seat Condition : Excellent Good Condition

Dash Board Condition : Excellent Good Condition Sunroof System Condition : Excellent Not Applicable

Front Right Window Function Condition : Excellent Smooth Operation Front Left Window Type
Power Windows

Carpets Condition : Excellent Good Condition

Driver Seat recliner Condition : Excellent Good Condition

Passenger Seat recliner Condition : Excellent Good Condition

Safety belts inertia locking system Passenger Condition : Excellent Good Condition

Front Right Window Type
Power Windows

Front Left Window Function Condition : Excellent Smooth Operation Rear Right Window Type
Power Windows

Rear Right Window Function Condition : Excellent Smooth Operation

Rear Left Window Function Condition : Excellent Smooth Operation Steering Mounted Controls Condition : Excellent Good Condition

Driver Seat Condition Condition : Excellent Good Condition

Instrument panel gauges:

Condition : Excellent

Good Condition

Odometer

Passenger Seat Condition Condition : Excellent Good Condition

Instrument panel Warning Lights Condition : Excellent Warning Lights Off - Good

Instrument panel gauges: Tachometer

Condition : Excellent Good Condition

Combination Switch Condition : Excellent Good Condition Instrument panel gauges: Temperature Condition : Excellent

Good Condition

Stereo Controls Condition : Excellent Good Condition Rear Left Window Type
Power Windows

Inside Rear View mirror Condition : Excellent Good Condition

Rear Seat Condition Condition : Excellent Good Condition

Instrument panel gauges: Fuel Condition : Excellent Good Condition

Horn Condition : Excellent Good Condition

Charger/USB Port Condition : Excellent Good Condition Interior lights Condition : Excellent Good Condition

Music System

Good Condition

Condition : Excellent

Hazard lights Condition : Excellent Good Condition

Music system type Dashboard Mounted Music Control-Buttons

Defogger Condition : Excellent Good Condition

Condition : Excellent

Good Condition

Condition : Excellent Good Condition

Central Locking System

Air distribution (AC Vents) Condition : Excellent Good Condition

Steering Type Manual Steering

Heating

Power Steering Type Electronic Trunk Light Condition : Excellent Good Condition

Speakers Condition : Excellent Good Condition

AC cooling (Check undershade) Condition : Excellent Good Condition

Recirculation/ Fresh air Condition : Excellent Good Condition

Steering condition Condition : Excellent Good Condition

Air Bags Condition : Excellent Functional Hand Brake Condition : Excellent Working less than 4 notches CNG/LPG kit -OEM/Aftermarket Condition : Excellent

No

Jack And Tommy (Tool Kit) Condition : Excellent Available

Engine & Transmission Rating - Fair

Battery Condition : Excellent Good Condition

Fuel Pump

Alternator Condition : Excellent Good Condition

AC Compressor Condition : Excellent Good Condition

Blower motor Condition : Excellent Good Condition

Condition : Excellent

Good Condition

Steering / Column with motor Rattling Noise Condition : Excellent Working Properly

Front struts (Shock Absorber) Condition : Excellent No Leakage & Rubber boots ok Rear Shock Absorber/Spring Condition : Excellent No Leakage & Rubber boots ok Starter Motor Condition : Excellent Good Condition

O 56 Good

O lssues

Condenser Fan Condition : Excellent Good Condition

Suspension Arms Condition : Excellent All rubber boot & bushing ok

Stabiliser Bar & Other bushes Condition : Excellent Good Condition Link Rods (Ball joints) Condition : Excellent No Noise & Rubber boots ok ABS Condition : Excellent Working

Accelarator Condition : Excellent Working Properly Check Front Brake Efficiency Condition : Excellent Operating Efficiently

Master Cylinder & Booster Condition : Excellent Good Condition

Axle Noise Condition : Excellent No noise & Boot okay Front Wheel bearings Condition : Excellent Good Condition

Gearshift lever

Good Condition

Automatic/Manual

Condition : Excellent

Differential Condition : Excellent Good Condition Alignment Condition : Excellent Good Condition

Transmission Oil (Manual/ Automatic) Condition : Excellent Oil Level Condition OK Engine and transmission mountings Condition : Excellent Good Condition Brake Pedal Condition : Excellent Operating Properly

Check Rear Brake Efficiency Condition : Excellent Operating Efficiently

Clutch Engagement Condition : Excellent More than 50% life

Rear Wheel bearings Condition : Excellent Good Condition

Balancing Condition : Excellent Good Condition

Abnormal Engine Noise Condition : Excellent No Noise Back Compression Condition : Excellent Back Compression Not Present Head Gasket leakage/replaced Condition : Excellent Good Condition

Silencer Condition : Excellent Good Condition

Engine Smoke Colour Condition : Excellent No colour

Engine oil leaks From

Bottom/Oil Sump

Good Condition

Condition : Excellent

Condenser Condition : Excellent Good Condition

Brake Oil

Condition : Excellent Cleaned/Replaced

Air Filter

Engine oil & Oil Filter Condition : Excellent Good Condition

Hose Pipe Condition : Excellent Good Condition

Water Pump Condition : Excellent Good Condition

Condition : Excellent

Good Condition

Tappet Noise Condition : Excellent Working Smoothly **Gasket - tappet cover Condition : Excellent** Good Condition

Catalytic Converter Condition : Excellent Good Condition

Radiator Condition : Excellent Good Condition

Coolant Condition : Excellent Good Condition

Alternator Drive Belt Condition : Excellent Good Condition

Turbo Charger Condition : Excellent Good Condition

Heater Plugs (in Diesel) Condition : Excellent Good Condition

Ignition Coil (petrol only)

Condition : Excellent

Not Applicable

Spark Plugs (in Petrol) Condition : Excellent Not Applicable

Ignition Wire Harness (petrol only) Condition : Excellent Not Applicable

Fuel Filter (Petrol & Diesel) Condition : Excellent Good Condition

Fuel Injectors Condition : Excellent Working Smoothly Radiator Fan Condition : Excellent Temperature Sensor Working

Fuel Tank and Pipes Condition : Excellent Good Condition

Front Side



Nov 26, 2022 10:44:00 AM

Lat 12.9951708,Long 77.7316189

Front Right Tyre



Nov 26, 2022 10:44:15 AM

Lat 12.9951016,Long 77.731452

Rear Right Tyre



Nov 26, 2022 10:44:39 AM

Lat 12.9951392,Long 77.731432

Back Side



Nov 26, 2022 10:44:57 AM

Lat 12.9951252,Long 77.731476

Front Right Side



Nov 26, 2022 10:44:08 AM

Lat 12.9951183,Long 77.7314904



Nov 26, 2022 10:44:22 AM

Lat 12.9951017,Long 77.7314483

Rear Right Side



Nov 26, 2022 10:44:49 AM

Lat 12.995143,Long 77.7314061





Nov 26, 2022 10:45:34 AM

Lat 12.9951476,Long 77.7316948

Rear Left Side



Nov 26, 2022 10:45:47 AM

Lat 12.9951499,Long 77.7317481

Left Side



Nov 26, 2022 10:46:06 AM

Lat 12.9951625,Long 77.7317367

Front Left Side



Nov 26, 2022 10:46:28 AM

Lat 12.9951212,Long 77.731757

Rear Left Tyre



Nov 26, 2022 10:45:55 AM

Lat 12.9951498,Long 77.7317508

Front Left Tyre



Nov 26, 2022 10:46:15 AM

Lat 12.9951672,Long 77.7317285

Odometer



Nov 26, 2022 10:55:50 AM

Lat 12.9951477,Long 77.7316978

Videos

Car Exterior Video

https://tinyurl.com/2hopt2w5

Car Engine Video

https://tinyurl.com/2g8yrd7u