

Mahindra First Choice Wheels Certification Report

**2017 FORD ECOSPORT(2015-2017) TITANIUM 1.5L TDCI**

Chaziabad | 73966 km | Diesel | Manual | White Colour | 1st Owner

✓ Eligible for Warranty ✓ 200+ Points InspectedExterior FairInterior ExcellentEngine & Transmission Excellent

Overall
Excellent Buy 🙌



M R Mahajan
M Mahajan
Head Certification
& Warranty - MFCWL

[Explore this car in website](#)[View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

Car Veda

Registration Month

July

Registration Year

2018

Color

White

Odometer Reading(km)

73966

Registration Number

UP13XXXXXX

No of Owners

1

Chassis Number

XXXXXXX

Engine Number

XXXXXXX

Insurance Status

Not available

Accidental / Flooded

Non-Accidental and Non-flooded

CNG Validity Inspection Date

Not Valid

RC Status

Available

PUC Certificate

Available

Keys Availability

One Key Available And Good

Transfer papers availability

Available

CNG Hydro Test Validity Certificate

Not Applicable

Vehicle Status

Certified

Remarks

ok

[View in Website](#)

<div><div>Front Bumper</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Grill</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Emblem</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Windscreen glass Front</div><div>Condition : Satisfactory</div><div>Cracks</div></div>	<div><div>Bonnet</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Bonnet Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>RH Side Apron</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Running Board</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Fender</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Front Right Door</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Front Door Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Front Right Door handle</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Front Right Window Glass</div><div>Condition : Excellent</div><div>Good Condition/Same Make</div></div>	<div><div>Rear Right Door</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Rear Door Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Rear Right Door handle</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Rear Right Window Glass</div><div>Condition : Excellent</div><div>Good Condition/Same Make</div></div>	<div><div>RH A Pillars</div><div>Condition : Excellent</div><div>Good Condition</div></div>

Exterior (Continued...)

RH B Pillars

Condition : **Excellent**

Good Condition

RH C Pillars

Condition : **Excellent**

Good Condition

Right Quarter Panel

Condition : **Excellent**

Good Condition

Right Side View Mirror + Casing

Condition : **Excellent**

Good Condition

Right Side Power Mirror + Casing

Condition : **Excellent**

Good Condition

Front right tyre

Condition : **Good**

60%-80%

Steel Wheel Rim Front RHS

Condition : **Excellent**

Not Applicable

Alloy Wheels Front RHS

Condition : **Excellent**

Good Condition

Rear right tyre

Condition : **Good**

60%-80%

Steel Wheel Rim Rear RHS

Condition : **Excellent**

Not Applicable

Alloy Wheels Rear RHS

Condition : **Excellent**

Good Condition

Windscreen glass Back

Condition : **Excellent**

Good Condition

Trunk

Condition : **Excellent**

Good Condition

Trunk Functionality

Condition : **Excellent**

Good Condition

Rear Bumper

Condition : **Excellent**

Good Condition

Dickey Shock absorber

Condition : **Excellent**

Good Condition

Spare tyre (stephney)

Condition : **Good**

Same Make/ Good & > 60% life

Spare Wheel / Cover

Condition : **Excellent**

Not Applicable

Exterior (Continued...)

Number Plate (Front & Rear)

Condition : **Excellent**

RTO Format

LH A Pillars

Condition : **Excellent**

Good Condition

LH B Pillars

Condition : **Excellent**

Good Condition

LH C Pillars

Condition : **Excellent**

Good Condition

Left Running Board

Condition : **Excellent**

Good Condition

Left Fender

Condition : **Excellent**

Good Condition

Left Front Door

Condition : **Excellent**

Good Condition

Front Left Door Functionality

Condition : **Excellent**

Good Condition

Front Left Door handle

Condition : **Excellent**

Good Condition

Front Left Window Glass

Condition : **Excellent**

Good Condition/Same Make

Left Side View Mirror + Casing

Condition : **Excellent**

Good Condition

Left Side Power Mirror + Casing

Condition : **Excellent**

Good Condition

Rear Left Door

Condition : **Excellent**

Good Condition

Rear Left Door Functionality

Condition : **Excellent**

Good Condition

Rear Left Door handle

Condition : **Excellent**

Good Condition

Left Quarter Panel

Condition : **Excellent**

Good Condition

Rear Left Window Glass

Condition : **Excellent**

Good Condition/Same Make

Fuel Cap

Condition : **Excellent**

Working Properly

Exterior (Continued...)

Front Left tyre

Condition : **Good**

60%-80%

Steel Wheel Rim Front LHS

Condition : **Excellent**

Not Applicable

Alloy Wheels Front LHS

Condition : **Excellent**

Good Condition

Rear Left tyre

Condition : **Good**

60%-80%

Steel Wheel Rim Rear LHS

Condition : **Excellent**

Not Applicable

Alloy Wheels Rear LHS

Condition : **Excellent**

Good Condition

LH Side Apron

Condition : **Excellent**

Good Condition

Frame or Underbody

Condition : **Excellent**

No panel Replaced

Reverse Camera & Reverse Parking Sensor

Condition : **Excellent**

Functional

Roof

Condition : **Excellent**

Good Condition

Windscreen Wiper Front

Condition : **Excellent**

All speeds working properly

Windscreen Wiper Rear

Condition : **Excellent**

All speeds working properly

Windscreen Jets

Condition : **Excellent**

Good Condition

Parking Lights Front

Condition : **Excellent**

Good Condition

Parking Lights Rear

Condition : **Excellent**

Good Condition

Right Tail Light

Condition : **Excellent**

Good Condition

Left Tail Light

Condition : **Excellent**

Good Condition

Rear Left Indicator

Condition : **Excellent**

Good Condition

Exterior (Continued...)

Rear Right Indicator
Condition : Excellent
Good Condition

Front Left Indicator
Condition : Excellent
Good Condition

Front Right Indicator
Condition : Excellent
Good Condition

Left Headlight (Both Points)
Condition : Excellent
Good Condition

Right Headlight (Both Points)
Condition : Excellent
Good Condition

Fog lamps
Condition : Excellent
Good Condition

Wheel Cap
Condition : Excellent
Available

Interior Rating - Excellent

61 Good 0 Issues

RHS Front Door Trim
Condition : Excellent
Good Condition

RHS Rear Door Trim
Condition : Excellent
Good Condition

Rubber Beading Front RHS
Condition : Excellent
Good Condition

Rubber Beading Rear RHS
Condition : Excellent
Good Condition

LHS Front Door Trim
Condition : Excellent
Good Condition

LHS Rear Door Trim
Condition : Excellent
Good Condition

Interior (Continued...)

Rubber Beading Front LHS

Condition : **Excellent**

Good Condition/Same Make

Rubber Beading Rear LHS

Condition : **Excellent**

Good Condition/Same Make

Carpets

Condition : **Excellent**

Good Condition

Roof Inside

Condition : **Excellent**

Good Condition

Driver Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

Driver Seat recliner

Condition : **Excellent**

Good Condition

Driver Seat Up Down

Condition : **Excellent**

Good Condition

Passenger Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

Passenger Seat recliner

Condition : **Excellent**

Good Condition

Passenger Seat Up Down

Condition : **Excellent**

Good Condition

Safety belts inertia locking system Driver Seat

Condition : **Excellent**

Good Condition

Safety belts inertia locking system Passenger

Condition : **Excellent**

Good Condition

Dash Board

Condition : **Excellent**

Good Condition

Sunroof System

Condition : **Excellent**

Good Condition

Front Right Window Type

Power Windows

Front Right Window Function

Condition : **Excellent**

Smooth Operation

Front Left Window Type

Power Windows

Front Left Window Function

Condition : **Excellent**

Smooth Operation

Interior (Continued...)

Rear Right Window Type

Power Windows

Rear Right Window Function

Condition : **Excellent**

Smooth Operation

Rear Left Window Type

Power Windows

Rear Left Window Function

Condition : **Excellent**

Smooth Operation

Steering Mounted Controls

Condition : **Excellent**

Good Condition

Inside Rear View mirror

Condition : **Excellent**

Good Condition

Driver Seat Condition

Condition : **Excellent**

Good Condition

Passenger Seat Condition

Condition : **Excellent**

Good Condition

Rear Seat Condition

Condition : **Excellent**

Good Condition

Instrument panel gauges: Odometer

Condition : **Excellent**

Good Condition

Instrument panel Warning Lights

Condition : **Excellent**

Warning Lights Off - Good

Instrument panel gauges: Fuel

Condition : **Excellent**

Good Condition

Instrument panel gauges: Tachometer

Condition : **Excellent**

Good Condition

Instrument panel gauges: Temperature

Condition : **Excellent**

Good Condition

Horn

Condition : **Excellent**

Good Condition

Combination Switch

Condition : **Excellent**

Good Condition

Stereo Controls

Condition : **Excellent**

Good Condition

Charger/USB Port

Condition : **Excellent**

Good Condition

Interior (Continued...)

Interior lights

Condition : **Excellent**

Good Condition

Hazard lights

Condition : **Excellent**

Good Condition

Trunk Light

Condition : **Excellent**

Good Condition

Music System

Condition : **Excellent**

Good Condition

Music system type

Steering Wheel Mounted Music Control

Speakers

Condition : **Excellent**

Good Condition

Defogger

Condition : **Excellent**

Good Condition

Central Locking System

Condition : **Excellent**

Good Condition

AC cooling (Check undershade)

Condition : **Excellent**

Good Condition

Heating

Condition : **Excellent**

Good Condition

Air distribution (AC Vents)

Condition : **Excellent**

Good Condition

Recirculation/ Fresh air

Condition : **Excellent**

Good Condition

Steering Type

Power Steering

Power Steering Type

Electronic

Steering condition

Condition : **Excellent**

Good Condition

Air Bags

Condition : **Excellent**

Functional

Hand Brake

Condition : **Excellent**

Working less than 4 notches

CNG/LPG kit - OEM/Aftermarket

Condition : **Excellent**

No

Jack And Tommy (Tool Kit)
Condition : Excellent
Available

Engine & Transmission Rating - Excellent

56 Good

0 Issues

Battery
Condition : Excellent
Good Condition

Alternator
Condition : Excellent
Good Condition

Starter Motor
Condition : Excellent
Good Condition

Fuel Pump
Condition : Excellent
Good Condition

AC Compressor
Condition : Excellent
Good Condition

Condenser Fan
Condition : Excellent
Good Condition

Blower motor
Condition : Excellent
Good Condition

Steering / Column with motor Rattling Noise
Condition : Excellent
Working Properly

Suspension Arms
Condition : Excellent
All rubber boot & bushing ok

Front struts (Shock Absorber)
Condition : Excellent
No Leakage & Rubber boots ok

Rear Shock Absorber/Spring
Condition : Excellent
No Leakage & Rubber boots ok

Stabiliser Bar & Other bushes
Condition : Excellent
Good Condition

Engine & Transmission (Continued...)

Link Rods (Ball joints)

Condition : **Excellent**

No Noise & Rubber boots ok

ABS

Condition : **Excellent**

Working

Brake Pedal

Condition : **Excellent**

Operating Properly

Accelerator

Condition : **Excellent**

Working Properly

Check Front Brake Efficiency

Condition : **Excellent**

Operating Efficiently

Check Rear Brake Efficiency

Condition : **Excellent**

Operating Efficiently

Master Cylinder & Booster

Condition : **Excellent**

Good Condition

Gearshift lever Automatic/Manual

Condition : **Excellent**

Good Condition

Clutch Engagement

Condition : **Satisfactory**

Less than 50% life

Axle Noise

Condition : **Excellent**

No noise & Boot okay

Front Wheel bearings

Condition : **Excellent**

Good Condition

Rear Wheel bearings

Condition : **Excellent**

Good Condition

Differential

Condition : **Excellent**

Good Condition

Alignment

Condition : **Excellent**

Good Condition

Balancing

Condition : **Excellent**

Good Condition

Transmission Oil (Manual/ Automatic)

Condition : **Excellent**

Oil Level Condition OK

Engine and transmission mountings

Condition : **Excellent**

Good Condition

Abnormal Engine Noise

Condition : **Excellent**

No Noise

Engine & Transmission (Continued...)

Back Compression

Condition : **Excellent**

Back Compression Not Present

Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

Gasket - tappet cover

Condition : **Excellent**

Good Condition

Engine oil leaks From Bottom/Oil Sump

Condition : **Excellent**

Good Condition

Silencer

Condition : **Excellent**

Good Condition

Catalytic Converter

Condition : **Excellent**

Good Condition

Engine Smoke Colour

Condition : **Excellent**

No colour

Air Filter

Condition : **Excellent**

Cleaned/Replaced

Radiator

Condition : **Excellent**

Good Condition

Condenser

Condition : **Excellent**

Good Condition

Engine oil & Oil Filter

Condition : **Excellent**

Good Condition

Coolant

Condition : **Excellent**

Good Condition

Brake Oil

Condition : **Excellent**

Good Condition

Hose Pipe

Condition : **Excellent**

Good Condition

Alternator Drive Belt

Condition : **Excellent**

Good Condition

Water Pump

Condition : **Excellent**

Good Condition

Tappet Noise

Condition : **Excellent**

Working Smoothly

Turbo Charger

Condition : **Excellent**

Good Condition

Heater Plugs (in Diesel)
Condition : **Excellent**
Good Condition

Spark Plugs (in Petrol)
Condition : **Excellent**
Not Applicable

Radiator Fan
Condition : **Excellent**
Temperature Sensor Working

Ignition Coil (petrol only)
Condition : **Excellent**
Not Applicable

Ignition Wire Harness (petrol only)
Condition : **Excellent**
Not Applicable

Fuel Tank and Pipes
Condition : **Excellent**
Good Condition

Fuel Filter (Petrol & Diesel)
Condition : **Excellent**
Good Condition

Fuel Injectors
Condition : **Excellent**
Working Smoothly

Vehicle Images

Front Side



Nov 29, 2022 11:50:47 AM

Lat 28.6774861, Long 77.4293278

Front Right Side



Nov 29, 2022 11:50:53 AM

Lat 28.6774917, Long 77.4293171

Front Right Tyre



Nov 29, 2022 11:50:58 AM

Lat 28.677495, Long 77.429306

Right Side



Nov 29, 2022 11:51:06 AM

Lat 28.6774643, Long 77.429312

Rear Right Tyre



Nov 29, 2022 11:51:12 AM

Lat 28.677439, Long 77.4293227

Rear Right Side



Nov 29, 2022 11:51:19 AM

Lat 28.6774299, Long 77.4293015

Back Side



Nov 29, 2022 11:51:25 AM

Lat 28.677416, Long 77.4293016

Rear Left Side



Nov 29, 2022 11:51:32 AM

Lat 28.677405, Long 77.4293015

[View this car in Website](#)

Rear Left Tyre



Nov 29, 2022 11:51:37 AM

GPS - 28.677413 , 77.429299

Front Left Tyre



Nov 29, 2022 11:51:50 AM

GPS - 28.677481 , 77.429304

Odometer



Nov 29, 2022 11:53:09 AM

GPS - 28.677474 , 77.429314

Left Side



Nov 29, 2022 11:51:44 AM

Lat 28.6774832,Long 77.4293044

Front Left Side



Nov 29, 2022 11:51:57 AM

Lat 28.6774887,Long 77.4293134

Videos

Car Exterior Video

<https://tinyurl.com/2ononkpn>

Car Engine Video

<https://tinyurl.com/2ostfrmh>