


Mahindra First Choice Wheels Certification Report



2017 TATA TIAGO(2016-2019) REVOTRON XZ

Kozhikode | 72408 km | Petrol | Manual | Others Colour | 1st Owner

- ✔ Eligible for Warranty
- ✔ 200+ Points Inspected



Overall
Excellent Buy 🙌

VERIFIED
M Mahajan
Head Certification & Warranty - MFCWL

Explore this car in website [View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

Registration Month

Registration Year

Car Zone

Jan

2018

Color

Odometer Reading(km)

Registration Number

Others

72408

KL48XXXXX

No of Owners

Chassis Number

Engine Number

1

MAT6XXXXXXXXXXXXXX

REVTXXXXXXXXXXXXXX

Insurance Status

Accidental / Flooded

CNG Validity Inspection Date

Not available

Non-Accidental and Non-flooded

Not Applicable

RC Status

Keys Availability

CNG Hydro Test Validity Certificate

Available

One Key Available And Good

Not Applicable

Vehicle Status

Remarks

Certified

certifirstplus

[View in Website](#)

Front Bumper

Condition : **Good**

Visible Repaint

Grill

Condition : **Excellent**

Good Condition

Emblem

Condition : **Excellent**

Good Condition

Windscreen glass Front

Condition : **Excellent**

Good Condition

Bonnet

Condition : **Excellent**

Bonnet Functionality

Condition : **Excellent**

Good Condition

RH Side Apron

Condition : **Excellent**

Good Condition

Right Running Board

Condition : **Excellent**

Right Fender

Condition : **Excellent**

Front Right Door

Condition : **Excellent**

Right Front Door Functionality

Condition : **Excellent**

Good Condition

Front Right Door handle

Condition : **Excellent**

Good Condition

Front Right Window Glass

Condition : **Excellent**

Good Condition/Same Make

Rear Right Door

Condition : **Excellent**

Right Rear Door Functionality

Condition : **Excellent**

Good Condition

Rear Right Door handle

Condition : **Excellent**

Good Condition

Rear Right Window Glass

Condition : **Excellent**

Good Condition/Same Make

RH A Pillars

Condition : **Excellent**

Good Condition

Exterior (Continued...)

RH B Pillars

Condition : **Excellent**
Good Condition

RH C Pillars

Condition : **Excellent**
Good Condition

Right Quarter Panel

Condition : **Excellent**

Right Side View Mirror + Casing

Condition : **Excellent**

Right Side Power Mirror + Casing

Condition : **Satisfactory**
Light/Short Scratches

Front right tyre

Condition : **Satisfactory**

Steel Wheel Rim Front RHS

Condition : **Excellent**
Good Condition

Alloy Wheels Front RHS

Condition : **Excellent**
Not Applicable

Rear right tyre

Condition : **Satisfactory**

Steel Wheel Rim Rear RHS

Condition : **Excellent**
Good Condition

Alloy Wheels Rear RHS

Condition : **Excellent**
Not Applicable

Windscreen glass Back

Condition : **Excellent**
Good Condition

Trunk

Condition : **Excellent**

Trunk Functionality

Condition : **Excellent**
Good Condition

Rear Bumper

Condition : **Satisfactory**

Dickey Shock absorber

Condition : **Excellent**

Spare tyre (stephney)

Condition : **Good**

Spare Wheel / Cover

Condition : **Excellent**

Exterior (Continued...)

Number Plate (Front & Rear)

Condition : **Bad**

LH A Pillars

Condition : **Excellent**

Good Condition

LH B Pillars

Condition : **Excellent**

Good Condition

LH C Pillars

Condition : **Excellent**

Good Condition

Left Running Board

Condition : **Excellent**

Left Fender

Condition : **Excellent**

Left Front Door

Condition : **Good**

Front Left Door Functionality

Condition : **Excellent**

Good Condition

Front Left Door handle

Condition : **Excellent**

Good Condition

Front Left Window Glass

Condition : **Excellent**

Good Condition/Same Make

Left Side View Mirror + Casing

Condition : **Excellent**

Left Side Power Mirror + Casing

Condition : **Satisfactory**

Light/Short Scratches

Rear Left Door

Condition : **Excellent**

Rear Left Door Functionality

Condition : **Excellent**

Good Condition

Rear Left Door handle

Condition : **Excellent**

Good Condition

Left Quarter Panel

Condition : **Excellent**

Rear Left Window Glass

Condition : **Excellent**

Good Condition/Same Make

Fuel Cap

Condition : **Excellent**

Exterior (Continued...)

Front Left tyre

Condition : **Satisfactory**

Steel Wheel Rim Front LHS

Condition : **Excellent**

Good Condition

Alloy Wheels Front LHS

Condition : **Excellent**

Not Applicable

Rear Left tyre

Condition : **Satisfactory**

Steel Wheel Rim Rear LHS

Condition : **Excellent**

Good Condition

Alloy Wheels Rear LHS

Condition : **Excellent**

Not Applicable

LH Side Apron

Condition : **Excellent**

Good Condition

Frame or Underbody

Condition : **Excellent**

Reverse Camera & Reverse Parking Sensor

Condition : **Excellent**

Not Applicable

Roof

Condition : **Excellent**

Good Condition

Windscreen Wiper Front

Condition : **Satisfactory**

Wiper Blade Rubber Damage

Windscreen Wiper Rear

Condition : **Satisfactory**

Wiper Blade Rubber Damage

Windscreen Jets

Condition : **Excellent**

Parking Lights Front

Condition : **Excellent**

Good Condition

Parking Lights Rear

Condition : **Excellent**

Good Condition

Right Tail Light

Condition : **Excellent**

Left Tail Light

Condition : **Excellent**

Rear Left Indicator

Condition : **Excellent**

Exterior (Continued...)

Rear Right Indicator

Condition : **Excellent**

Front Left Indicator

Condition : **Excellent**

Front Right Indicator

Condition : **Excellent**

Left Headlight (Both Points)

Condition : **Excellent**

Right Headlight (Both Points)

Condition : **Excellent**

Fog lamps

Condition : **Bad**

Wheel Cap

Condition : **Bad**

Interior Rating - **Fair**

 51 Good  10 Issues

RHS Front Door Trim

Condition : **Excellent**

Good Condition

RHS Rear Door Trim

Condition : **Excellent**

Good Condition

Rubber Beading Front RHS

Condition : **Excellent**

Good Condition

Rubber Beading Rear RHS

Condition : **Excellent**

Good Condition

LHS Front Door Trim

Condition : **Excellent**

Good Condition

LHS Rear Door Trim

Condition : **Excellent**

Good Condition

[View this car in Website](#)

Interior (Continued...)

Rubber Beading Front LHS

Condition : **Excellent**

Good Condition/Same Make

Rubber Beading Rear LHS

Condition : **Excellent**

Good Condition/Same Make

Carpets

Condition : **Bad**

Roof Inside

Condition : **Excellent**

Good Condition

Driver Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

Driver Seat recliner

Condition : **Excellent**

Good Condition

Driver Seat Up Down

Condition : **Excellent**

Good Condition

Passenger Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

Passenger Seat recliner

Condition : **Excellent**

Good Condition

Passenger Seat Up Down

Condition : **Excellent**

Not Applicable

Safety belts inertia locking system Driver Seat

Condition : **Excellent**

Good Condition

Safety belts inertia locking system Passenger

Condition : **Excellent**

Good Condition

Dash Board

Condition : **Bad**

Sunroof System

Condition : **Excellent**

Not Applicable

Front Right Window Type

Power Windows

Front Right Window Function

Condition : **Excellent**

Smooth Operation

Front Left Window Type

Power Windows

Front Left Window Function

Condition : **Excellent**

Smooth Operation

Interior (Continued...)

Rear Right Window Type

Power Windows

Rear Right Window Function

Condition : **Excellent**
Smooth Operation

Rear Left Window Type

Power Windows

Rear Left Window Function

Condition : **Excellent**
Smooth Operation

Steering Mounted Controls

Condition : **Excellent**
Good Condition

Inside Rear View mirror

Condition : **Bad**

Driver Seat Condition

Condition : **Satisfactory**
Faded

Passenger Seat Condition

Condition : **Satisfactory**
Faded

Rear Seat Condition

Condition : **Satisfactory**
Faded

**Instrument panel gauges:
Odometer**

Condition : **Excellent**

**Instrument panel Warning
Lights**

Condition : **Bad**

Instrument panel gauges: Fuel

Condition : **Excellent**
Good Condition

**Instrument panel gauges:
Tachometer**

Condition : **Excellent**
Good Condition

**Instrument panel gauges:
Temperature**

Condition : **Excellent**
Good Condition

Horn

Condition : **Excellent**
Good Condition

Combination Switch

Condition : **Bad**

Stereo Controls

Condition : **Excellent**
Good Condition

Charger/USB Port

Condition : **Excellent**
Good Condition

Interior (Continued...)

Interior lights

Condition : **Bad**

Hazard lights

Condition : **Bad**

Trunk Light

Condition : **Excellent**

Not Applicable

Music System

Condition : **Excellent**

Music system type

Steering Wheel Mounted Music Control

Speakers

Condition : **Excellent**

Defogger

Condition : **Excellent**

Central Locking System

Condition : **Excellent**

AC cooling (Check undershade)

Condition : **Excellent**

Heating

Condition : **Excellent**

Air distribution (AC Vents)

Condition : **Bad**

Recirculation/ Fresh air

Condition : **Excellent**

Steering Type

Power Steering

Power Steering Type

Electronic

Steering condition

Condition : **Satisfactory**

Noise

Air Bags

Condition : **Excellent**

Functional

Hand Brake

Condition : **Excellent**

CNG/LPG kit - OEM/Aftermarket



Condition : **Bad**

Interior (Continued...)

Jack And Tommy (Tool Kit)

Condition : **Bad**

Engine & Transmission Rating - Fair

 48 Good  8 Issues

Battery

Condition : **Excellent**

Alternator

Condition : **Excellent**

Starter Motor

Condition : **Excellent**

Fuel Pump

Condition : **Excellent**

AC Compressor

Condition : **Excellent**

Condenser Fan

Condition : **Excellent**

Blower motor

Condition : **Excellent**

**Steering / Column with motor
Rattling Noise**

Condition : **Excellent**

Suspension Arms

Condition : **Satisfactory**
Noise

Front struts (Shock Absorber)

Condition : **Bad**

Rear Shock Absorber/Spring

Condition : **Excellent**

Stabiliser Bar & Other bushes

Condition : **Excellent**

[View this car in Website](#)

Engine & Transmission (Continued...)

Link Rods (Ball joints)

Condition : **Satisfactory**

Noise or Wheel wobbling

ABS

Condition : **Excellent**

Brake Pedal

Condition : **Excellent**

Accelerator

Condition : **Excellent**

Working Properly

Check Front Brake Efficiency

Condition : **Excellent**

Check Rear Brake Efficiency

Condition : **Bad**

Master Cylinder & Booster

Condition : **Excellent**

**Gearshift lever
Automatic/Manual**

Condition : **Excellent**

Clutch Engagement

Condition : **Bad**

Axle Noise

Condition : **Excellent**

Front Wheel bearings

Condition : **Excellent**

Good Condition

Rear Wheel bearings

Condition : **Excellent**

Good Condition

Differential

Condition : **Excellent**

Alignment

Condition : **Excellent**

Balancing

Condition : **Excellent**

Good Condition

**Transmission Oil (Manual/
Automatic)**

Condition : **Excellent**

**Engine and transmission
mountings**

Condition : **Excellent**

Abnormal Engine Noise

Condition : **Excellent**

Engine & Transmission (Continued...)

Back Compression

Condition : **Excellent**

Back Compression Not Present

Head Gasket leakage/replaced

Condition : **Bad**

Gasket - tappet cover

Condition : **Bad**

Engine oil leaks From Bottom/Oil Sump

Condition : **Bad**

Silencer

Condition : **Excellent**

Good Condition

Catalytic Converter

Condition : **Excellent**

Good Condition

Engine Smoke Colour

Condition : **Excellent**

No colour

Air Filter

Condition : **Excellent**

Radiator

Condition : **Excellent**

Good Condition

Condenser

Condition : **Excellent**

Good Condition

Engine oil & Oil Filter

Condition : **Excellent**

Coolant

Condition : **Excellent**

Brake Oil

Condition : **Excellent**

Hose Pipe

Condition : **Excellent**

Alternator Drive Belt

Condition : **Bad**

Water Pump

Condition : **Excellent**

Tappet Noise

Condition : **Excellent**

Turbo Charger

Condition : **Excellent**

Engine & Transmission (Continued...)

Heater Plugs (in Diesel)

Condition : **Excellent**

Spark Plugs (in Petrol)

Condition : **Excellent**

Good Condition

Radiator Fan

Condition : **Excellent**

Ignition Coil (petrol only)

Condition : **Excellent**

Good Condition

Ignition Wire Harness (petrol only)

Condition : **Bad**

Fuel Tank and Pipes

Condition : **Excellent**

Fuel Filter (Petrol & Diesel)

Condition : **Excellent**

Fuel Injectors

Condition : **Excellent**

Vehicle Images

Front Side



12 Dec 2022 4:07:51 pm

Lat 11.297756, Long 75.763838

Front Right Side



12 Dec 2022 4:08:08 pm

Lat 11.2977445, Long 75.7639243

Front Right Tyre



12 Dec 2022 4:08:24 pm

Lat 11.2977233, Long 75.7639151

Right Side



12 Dec 2022 4:10:12 pm

Lat 11.2977164, Long 75.7639029

Rear Right Tyre



12 Dec 2022 4:10:21 pm

Lat 11.2976884, Long 75.7639504

Rear Right Side



12 Dec 2022 4:10:36 pm

Lat 11.2977001, Long 75.7639299

Back Side



12 Dec 2022 4:10:50 pm

Lat 11.2976998, Long 75.7639217

Rear Left Side



12 Dec 2022 4:11:01 pm

Lat 11.2976978, Long 75.7639219

[View this car in Website](#)

Rear Left Tyre



12 Dec 2022 4:11:08 pm
GPS - 11.29769, 75.763917

12 Dec 2022 4:11:08 pm

Lat 11.2976895,Long 75.7639172

Left Side



12 Dec 2022 4:11:28 pm
GPS - 11.2976914, 75.7639107

12 Dec 2022 4:11:28 pm

Lat 11.2976914,Long 75.7639107

Front Left Tyre



12 Dec 2022 4:11:39 pm
GPS - 11.297696, 75.76391

12 Dec 2022 4:11:39 pm

Lat 11.2976958,Long 75.7639099

Front Left Side



12 Dec 2022 4:11:56 pm
GPS - 11.2976985, 75.7639112

12 Dec 2022 4:11:56 pm

Lat 11.2976985,Long 75.7639112

Odometer



12 Dec 2022 4:12:19 pm
GPS - 11.297701, 75.763911

12 Dec 2022 4:12:19 pm

Lat 11.2977012,Long 75.7639107

Videos

Car Exterior Video

<https://tinyurl.com/2mcbmk87>

Car Engine Video

<https://tinyurl.com/2ns7ejrg>