

## Mahindra First Choice Wheels Certification Report

**2017 MARUTI SUZUKI ALTO 800(2016-2019) LXI**

Moradabad | 7652 km | Petrol | Manual | Silver Colour | 1st Owner

✔ Eligible for Warranty ✔ 200+ Points InspectedOverall  
**Fair Buy** 🍏Exterior FairInterior FairEngine & Transmission Fair  
M Mahajan  
Head Certification  
& Warranty - MFCWL[Explore this car in website](#)[View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

## Vehicle Details

Owner Name

**RN Motors**

Registration Month

**September**

Registration Year

**2017**

Color

**Silver**

Odometer Reading(km)

**7652**

Registration Number

**UP80XXXXXX**

No of Owners

**1**

Chassis Number

**XXXXXXX**

Engine Number

**XXXXXXX**

Insurance Status

**Not available**

Accidental / Flooded

**Non-Accidental and Non-flooded**

CNG Validity Inspection Date

**Not Applicable**

RC Status

**Available**

PUC Certificate

**Not Available**

Keys Availability

**One Key Available And Good**

Transfer papers availability

**Available**

CNG Hydro Test Validity Certificate

**Not Applicable**

Vehicle Status

**Certified**

Remarks

•

[View in Website](#)

<div><div>Front Bumper</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Grill</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Emblem</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Windscreen glass Front</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Bonnet</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Bonnet Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>RH Side Apron</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Running Board</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Fender</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Front Right Door</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Front Door Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Front Right Door handle</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Front Right Window Glass</div><div>Condition : Excellent</div><div>Good Condition/Same Make</div></div>	<div><div>Rear Right Door</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Rear Door Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Rear Right Door handle</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Rear Right Window Glass</div><div>Condition : Excellent</div><div>Good Condition/Same Make</div></div>	<div><div>RH A Pillars</div><div>Condition : Excellent</div><div>Good Condition</div></div>

Exterior (Continued...)

**RH B Pillars**

Condition : **Excellent**

Good Condition

**RH C Pillars**

Condition : **Excellent**

Not Applicable

**Right Quarter Panel**

Condition : **Excellent**

Good Condition

**Right Side View Mirror + Casing**

Condition : **Excellent**

Good Condition

**Right Side Power Mirror + Casing**

Condition : **Excellent**

Not Applicable

**Front right tyre**

Condition : **Satisfactory**

40%-60%

**Steel Wheel Rim Front RHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Front RHS**

Condition : **Excellent**

Not Applicable

**Rear right tyre**

Condition : **Satisfactory**

40%-60%

**Steel Wheel Rim Rear RHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Rear RHS**

Condition : **Excellent**

Not Applicable

**Windscreen glass Back**

Condition : **Excellent**

Good Condition

**Trunk**

Condition : **Excellent**

Good Condition

**Trunk Functionality**

Condition : **Excellent**

Good Condition

**Rear Bumper**

Condition : **Excellent**

Good Condition

**Dickey Shock absorber**

Condition : **Excellent**

Good Condition

**Spare tyre (stephney)**

Condition : **Excellent**

Same Make/ Good & > 80% life

**Spare Wheel / Cover**

Condition : **Excellent**

Not Applicable

Exterior (Continued...)

**Number Plate (Front & Rear)**

Condition : **Excellent**

RTO Format

**LH A Pillars**

Condition : **Excellent**

Good Condition

**LH B Pillars**

Condition : **Excellent**

Good Condition

**LH C Pillars**

Condition : **Excellent**

Good Condition

**Left Running Board**

Condition : **Excellent**

Good Condition

**Left Fender**

Condition : **Excellent**

Good Condition

**Left Front Door**

Condition : **Excellent**

Good Condition

**Front Left Door Functionality**

Condition : **Excellent**

Good Condition

**Front Left Door handle**

Condition : **Excellent**

Good Condition

**Front Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Left Side View Mirror + Casing**

Condition : **Excellent**

Good Condition

**Left Side Power Mirror + Casing**

Condition : **Excellent**

Good Condition

**Rear Left Door**

Condition : **Excellent**

Good Condition

**Rear Left Door Functionality**

Condition : **Excellent**

Good Condition

**Rear Left Door handle**

Condition : **Excellent**

Good Condition

**Left Quarter Panel**

Condition : **Excellent**

Good Condition

**Rear Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Fuel Cap**

Condition : **Excellent**

Working Properly

Exterior (Continued...)

**Front Left tyre**

Condition : **Satisfactory**

40%-60%

**Steel Wheel Rim Front LHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Front LHS**

Condition : **Excellent**

Not Applicable

**Rear Left tyre**

Condition : **Satisfactory**

40%-60%

**Steel Wheel Rim Rear LHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Rear LHS**

Condition : **Excellent**

Not Applicable

**LH Side Apron**

Condition : **Excellent**

Good Condition

**Frame or Underbody**

Condition : **Excellent**

No panel Replaced

**Reverse Camera & Reverse  
Parking Sensor**

Condition : **Excellent**

Not Applicable

**Roof**

Condition : **Excellent**

Good Condition

**Windscreen Wiper Front**

Condition : **Excellent**

All speeds working properly

**Windscreen Wiper Rear**

Condition : **Excellent**

Not Applicable

**Windscreen Jets**

Condition : **Excellent**

Good Condition

**Parking Lights Front**

Condition : **Excellent**

Good Condition

**Parking Lights Rear**

Condition : **Excellent**

Good Condition

**Right Tail Light**

Condition : **Excellent**

Good Condition

**Left Tail Light**

Condition : **Excellent**

Good Condition

**Rear Left Indicator**

Condition : **Excellent**

Good Condition

Exterior (Continued...)

**Rear Right Indicator**  
Condition : Excellent  
Good Condition

**Front Left Indicator**  
Condition : Excellent  
Good Condition

**Front Right Indicator**  
Condition : Excellent  
Good Condition

**Left Headlight (Both Points)**  
Condition : Excellent  
Good Condition

**Right Headlight (Both Points)**  
Condition : Excellent  
Good Condition

**Fog lamps**  
Condition : Excellent  
Not Applicable

**Wheel Cap**  
Condition : Excellent  
Available

Interior Rating - Fair

60 Good 1 Issues

**RHS Front Door Trim**  
Condition : Excellent  
Good Condition

**RHS Rear Door Trim**  
Condition : Excellent  
Good Condition

**Rubber Beading Front RHS**  
Condition : Excellent  
Good Condition

**Rubber Beading Rear RHS**  
Condition : Excellent  
Good Condition

**LHS Front Door Trim**  
Condition : Excellent  
Good Condition

**LHS Rear Door Trim**  
Condition : Excellent  
Good Condition

## Interior (Continued...)

### Rubber Beading Front LHS

Condition : **Excellent**

Good Condition/Same Make

### Rubber Beading Rear LHS

Condition : **Excellent**

Good Condition/Same Make

### Carpets

Condition : **Excellent**

Good Condition

### Roof Inside

Condition : **Excellent**

Good Condition

### Driver Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

### Driver Seat recliner

Condition : **Excellent**

Good Condition

### Driver Seat Up Down

Condition : **Excellent**

Good Condition

### Passenger Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

### Passenger Seat recliner

Condition : **Excellent**

Good Condition

### Passenger Seat Up Down

Condition : **Excellent**

Good Condition

### Safety belts inertia locking system Driver Seat

Condition : **Excellent**

Good Condition

### Safety belts inertia locking system Passenger

Condition : **Excellent**

Good Condition

### Dash Board

Condition : **Excellent**

Good Condition

### Sunroof System

Condition : **Excellent**

Not Applicable

### Front Right Window Type

Power Windows

### Front Right Window Function

Condition : **Excellent**

Smooth Operation

### Front Left Window Type

Power Windows

### Front Left Window Function

Condition : **Excellent**

Smooth Operation



## Interior (Continued...)

### Rear Right Window Type

Manual Windows

### Rear Right Window Function

Condition : **Excellent**

Smooth Operation

### Rear Left Window Type

Manual Windows

### Rear Left Window Function

Condition : **Excellent**

Smooth Operation

### Steering Mounted Controls

Condition : **Excellent**

Not Applicable

### Inside Rear View mirror

Condition : **Excellent**

Good Condition

### Driver Seat Condition

Condition : **Excellent**

Good Condition

### Passenger Seat Condition

Condition : **Excellent**

Good Condition

### Rear Seat Condition

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Odometer

Condition : **Excellent**

Good Condition

### Instrument panel Warning Lights

Condition : **Excellent**

Warning Lights Off - Good

### Instrument panel gauges: Fuel

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Tachometer

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Temperature

Condition : **Excellent**

Good Condition

### Horn

Condition : **Excellent**

Good Condition

### Combination Switch

Condition : **Excellent**

Good Condition

### Stereo Controls

Condition : **Excellent**

Good Condition

### Charger/USB Port

Condition : **Bad**

Not Functional

## Interior (Continued...)

### Interior lights

Condition : **Excellent**

Good Condition

### Hazard lights

Condition : **Excellent**

Good Condition

### Trunk Light

Condition : **Excellent**

Good Condition

### Music System

Condition : **Excellent**

Good Condition

### Music system type

Dashboard Mounted Music  
Control-Buttons

### Speakers

Condition : **Excellent**

Good Condition

### Defogger

Condition : **Excellent**

Not Applicable

### Central Locking System

Condition : **Excellent**

Not Applicable

### AC cooling (Check undershade)

Condition : **Excellent**

Good Condition

### Heating

Condition : **Excellent**

Good Condition

### Air distribution (AC Vents)

Condition : **Excellent**

Good Condition

### Recirculation/ Fresh air

Condition : **Excellent**

Good Condition

### Steering Type

Power Steering

### Power Steering Type

Hydraulic

### Steering condition

Condition : **Excellent**

Good Condition

### Air Bags

Condition : **Excellent**

Not Applicable

### Hand Brake

Condition : **Excellent**

Working less than 4 notches

### CNG/LPG kit - OEM/Aftermarket

Condition : **Excellent**

No

Jack And Tommy (Tool Kit)

Condition : Excellent

Available

Engine & Transmission Rating - Fair

56 Good

0 Issues

Battery

Condition : Excellent

Good Condition

Alternator

Condition : Excellent

Good Condition

Starter Motor

Condition : Excellent

Good Condition

Fuel Pump

Condition : Excellent

Good Condition

AC Compressor

Condition : Excellent

Good Condition

Condenser Fan

Condition : Excellent

Good Condition

Blower motor

Condition : Excellent

Good Condition

Steering / Column with motor  
Rattling Noise

Condition : Excellent

Working Properly

Suspension Arms

Condition : Excellent

All rubber boot & bushing ok

Front struts (Shock Absorber)

Condition : Excellent

No Leakage & Rubber boots ok

Rear Shock Absorber/Spring

Condition : Excellent

No Leakage & Rubber boots ok

Stabiliser Bar & Other bushes

Condition : Excellent

Good Condition

## Engine & Transmission (Continued...)

### Link Rods (Ball joints)

Condition : **Excellent**

No Noise & Rubber boots ok

### ABS

Condition : **Excellent**

Not Applicable

### Brake Pedal

Condition : **Excellent**

Operating Properly

### Accelerator

Condition : **Excellent**

Working Properly

### Check Front Brake Efficiency

Condition : **Excellent**

Operating Efficiently

### Check Rear Brake Efficiency

Condition : **Excellent**

Operating Efficiently

### Master Cylinder & Booster

Condition : **Excellent**

Good Condition

### Gearshift lever Automatic/Manual

Condition : **Excellent**

Good Condition

### Clutch Engagement

Condition : **Excellent**

More than 50% life

### Axle Noise

Condition : **Excellent**

No noise & Boot okay

### Front Wheel bearings

Condition : **Excellent**

Good Condition

### Rear Wheel bearings

Condition : **Excellent**

Good Condition

### Differential

Condition : **Excellent**

Good Condition

### Alignment

Condition : **Excellent**

Good Condition

### Balancing

Condition : **Excellent**

Good Condition

### Transmission Oil (Manual/ Automatic)

Condition : **Excellent**

Oil Level Condition OK

### Engine and transmission mountings

Condition : **Excellent**

Good Condition

### Abnormal Engine Noise

Condition : **Excellent**

No Noise

## Engine & Transmission (Continued...)

### Back Compression

Condition : **Excellent**

Back Compression Not Present

### Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

### Gasket - tappet cover

Condition : **Excellent**

Good Condition

### Engine oil leaks From Bottom/Oil Sump

Condition : **Excellent**

Good Condition

### Silencer

Condition : **Excellent**

Good Condition

### Catalytic Converter

Condition : **Excellent**

Good Condition

### Engine Smoke Colour

Condition : **Excellent**

No colour

### Air Filter

Condition : **Excellent**

Cleaned/Replaced

### Radiator

Condition : **Excellent**

Good Condition

### Condenser

Condition : **Excellent**

Good Condition

### Engine oil & Oil Filter

Condition : **Excellent**

Good Condition

### Coolant

Condition : **Excellent**

Good Condition

### Brake Oil

Condition : **Excellent**

Good Condition

### Hose Pipe

Condition : **Excellent**

Good Condition

### Alternator Drive Belt

Condition : **Excellent**

Good Condition

### Water Pump

Condition : **Excellent**

Good Condition

### Tappet Noise

Condition : **Excellent**

Working Smoothly

### Turbo Charger

Condition : **Excellent**

Not Applicable

**Heater Plugs (in Diesel)**  
Condition : **Excellent**  
Not Applicable

**Spark Plugs (in Petrol)**  
Condition : **Excellent**  
Good Condition

**Radiator Fan**  
Condition : **Excellent**  
Temperature Sensor Working

**Ignition Coil (petrol only)**  
Condition : **Excellent**  
Good Condition

**Ignition Wire Harness (petrol only)**  
Condition : **Excellent**  
Good Condition

**Fuel Tank and Pipes**  
Condition : **Excellent**  
Good Condition

**Fuel Filter (Petrol & Diesel)**  
Condition : **Excellent**  
Good Condition

**Fuel Injectors**  
Condition : **Excellent**  
Working Smoothly



## Vehicle Images

### Front Side



Dec 30, 2022 12:56:37 PM

Lat 28.8354248,Long 78.8194982

### Front Right Side



Dec 30, 2022 12:56:46 PM

Lat 28.8354154,Long 78.8195038

### Front Right Tyre



Dec 30, 2022 1:01:35 PM

Lat 28.8342947,Long 78.8189741

### Right Side



Dec 30, 2022 1:01:46 PM

Lat 28.8354274,Long 78.8194793

### Rear Right Tyre



Dec 30, 2022 1:02:09 PM

Lat 28.8354472,Long 78.819461

### Rear Right Side



Dec 30, 2022 1:02:19 PM

Lat 28.8354667,Long 78.8194683

### Back Side



Dec 30, 2022 1:02:29 PM

Lat 28.8354572,Long 78.8194843

### Rear Left Side



Dec 30, 2022 1:02:43 PM

Lat 28.8354506,Long 78.819486

[View this car in Website](#)



#### Rear Left Tyre



Dec 30, 2022 1:02:52 PM

Lat 28.8354055,Long 78.8195061

#### Front Left Tyre



Dec 30, 2022 1:03:58 PM

Lat 28.8353973,Long 78.8195067

#### Chassis Imprint



Dec 30, 2022 1:10:43 PM

Lat 28.835381,Long 78.8194684

#### Left Side



Dec 30, 2022 1:03:51 PM

Lat 28.8342947,Long 78.8189741

#### Front Left Side



Dec 30, 2022 1:04:09 PM

Lat 28.8354206,Long 78.8195188

#### Odometer



Dec 30, 2022 1:05:49 PM

Lat 28.8354035,Long 78.8195023



## Videos

Car Exterior Video

<https://tinyurl.com/2rxhab9c>

Car Engine Video

<https://tinyurl.com/2lzfjxlo>

[View this car in Website](#)