

Mahindra First Choice Wheels Inspection Report



2011 HYUNDAI EON(2011-2019) MAGNA

Faridabad | 72306 km | Petrol | Manual | Silver Colour | 2nd Owner

- ✔ Assist First Warranty
- ✔ 200+ Points Inspected



Exterior	Fair
<hr style="border: 1px solid orange;"/>	
Interior	Fair
<hr style="border: 1px solid orange;"/>	
Engine & Transmission	Fair
<hr style="border: 1px solid orange;"/>	

Overall
Fair Buy 🙌

M Mahajan
Head Certification & Warranty - MPCWL

[Explore this car in website](#) [View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

Auto Wellness

Registration Month

May

Registration Year

2012

Color

Silver

Odometer Reading(km)

72306

Registration Number

HR29XXXXXX

No of Owners

2

Chassis Number

XXXXXXXX

Engine Number

XXXXXXXX

Insurance Status

Not available

Accidental / Flooded

Non-Accidental and Non-flooded

CNG Validity Inspection Date

Not Valid

RC Status

Available

PUC Certificate

Not Available

Keys Availability

One Key Available And Good

Transfer papers availability

Available

CNG Hydro Test Validity Certificate

Not Applicable

Vehicle Status

Inspected

Remarks

ten year old

[View in Website](#)

Front Bumper

Condition : Good

Dents With Paint Damage

Grill

Condition : Satisfactory

Non-OEM Grill

Emblem

Condition : Excellent

Good Condition

Windscreen glass Front

Condition : Satisfactory

Light/Short Scratches

Bonnet

Condition : Excellent

Dents without paint damage-
under 2

Bonnet Functionality

Condition : Good

Not Smooth

RH Side Apron

Condition : Excellent

Good Condition

Right Running Board

Condition : Satisfactory

Deep/long Scratches

Right Fender

Condition : Good

Dent without Paint Damage-2
to 4

Front Right Door

Condition : Good

Dents With Paint Damage

**Right Front Door
Functionality**

Condition : Satisfactory

Functional with Noise

Front Right Door handle

Condition : Good

Misaligned

Front Right Window Glass

Condition : Excellent

Light/Short Scratches-under 3

Rear Right Door

Condition : Excellent

Dents without paint damage-
under 2

Right Rear Door Functionality

Condition : Satisfactory

Functional with Noise

Rear Right Door handle

Condition : Good

Misaligned

Rear Right Window Glass

Condition : Satisfactory

Deep/long Scratches

RH A Pillars

Condition : Satisfactory

Scratches-2 & Above

Exterior (Continued...)

RH B Pillars

Condition : **Excellent**

Good Condition

RH C Pillars

Condition : **Excellent**

Good Condition

Right Quarter Panel

Condition : **Bad**

Dent with Paint Damage

Right Side View Mirror + Casing

Condition : **Bad**

Deep/Long Scratches

Right Side Power Mirror + Casing

Condition : **Satisfactory**

Light/Short Scratches

Front right tyre

Condition : **Satisfactory**

25-40%

Steel Wheel Rim Front RHS

Condition : **Satisfactory**

Mounting Holes Mismatch

Alloy Wheels Front RHS

Condition : **Excellent**

Not Applicable

Rear right tyre

Condition : **Satisfactory**

25-40%

Steel Wheel Rim Rear RHS

Condition : **Excellent**

Good Condition

Alloy Wheels Rear RHS

Condition : **Excellent**

Not Applicable

Windscreen glass Back

Condition : **Excellent**

Good Condition

Trunk

Condition : **Excellent**

Good Condition

Trunk Functionality

Condition : **Excellent**

Good Condition

Rear Bumper

Condition : **Excellent**

Dents without paint damage-
under 2

Dickey Shock absorber

Condition : **Satisfactory**

Improper Functioning

Spare tyre (stephney)

Condition : **Bad**

Different Make/ Cut Marks/
Bulge /< 30% life

Spare Wheel / Cover

Condition : **Bad**

Crack

Exterior (Continued...)

Number Plate (Front & Rear)

Condition : **Excellent**

RTO Format

LH A Pillars

Condition : **Excellent**

Good Condition

LH B Pillars

Condition : **Excellent**

Good Condition

LH C Pillars

Condition : **Excellent**

Good Condition

Left Running Board

Condition : **Excellent**

Good Condition

Left Fender

Condition : **Bad**

Dent with Paint Damage

Left Front Door

Condition : **Satisfactory**

Alignment Issue

Front Left Door Functionality

Condition : **Excellent**

Good Condition

Front Left Door handle

Condition : **Excellent**

Good Condition

Front Left Window Glass

Condition : **Satisfactory**

Deep/long Scratches

Left Side View Mirror + Casing

Condition : **Satisfactory**

Light/Short Scratches

Left Side Power Mirror + Casing

Condition : **Satisfactory**

Light/Short Scratches

Rear Left Door

Condition : **Satisfactory**

Alignment Issue

Rear Left Door Functionality

Condition : **Excellent**

Good Condition

Rear Left Door handle

Condition : **Good**

Replaced

Left Quarter Panel

Condition : **Good**

Dent without Paint Damage

Rear Left Window Glass

Condition : **Satisfactory**

Deep/long Scratches

Fuel Cap

Condition : **Bad**

Not Working Properly/Missing

Exterior (Continued...)

Front Left tyre

Condition : **Satisfactory**

25-40%

Steel Wheel Rim Front LHS

Condition : **Satisfactory**

Rust

Alloy Wheels Front LHS

Condition : **Excellent**

Not Applicable

Rear Left tyre

Condition : **Satisfactory**

25-40%

Steel Wheel Rim Rear LHS

Condition : **Excellent**

Good Condition

Alloy Wheels Rear LHS

Condition : **Excellent**

Not Applicable

LH Side Apron

Condition : **Satisfactory**

Dents with Paint Damage

Frame or Underbody

Condition : **Excellent**

No panel Replaced

Reverse Camera & Reverse Parking Sensor

Condition : **Excellent**

Not Applicable

Roof

Condition : **Excellent**

Good Condition

Windscreen Wiper Front

Condition : **Satisfactory**

Working at speeds 1/2

Windscreen Wiper Rear

Condition : **Satisfactory**

Working at speeds 1/2

Windscreen Jets

Condition : **Excellent**

Good Condition

Parking Lights Front

Condition : **Excellent**

Good Condition

Parking Lights Rear

Condition : **Excellent**

Good Condition

Right Tail Light

Condition : **Satisfactory**

Cracks

Left Tail Light

Condition : **Excellent**

Good Condition

Rear Left Indicator

Condition : **Excellent**

Good Condition

Exterior (Continued...)

Rear Right Indicator

Condition : **Excellent**

Good Condition

Front Left Indicator

Condition : **Excellent**

Good Condition

Front Right Indicator

Condition : **Excellent**

Good Condition

Left Headlight (Both Points)

Condition : **Excellent**

Good Condition

Right Headlight (Both Points)

Condition : **Excellent**

Good Condition

Fog lamps

Condition : **Excellent**



Not Applicable

Wheel Cap

Condition : **Excellent**

Available

Interior Rating - **Fair**

 58 Good  3 Issues

RHS Front Door Trim

Condition : **Satisfactory**

Unclean

RHS Rear Door Trim

Condition : **Satisfactory**

Unclean

Rubber Beading Front RHS

Condition : **Satisfactory**

Loose

Rubber Beading Rear RHS

Condition : **Satisfactory**

Loose

LHS Front Door Trim

Condition : **Satisfactory**

Unclean

LHS Rear Door Trim

Condition : **Satisfactory**

Unclean

[View this car in Website](#)

Rubber Beading Front LHS

Condition : **Satisfactory**

Loose

Rubber Beading Rear LHS

Condition : **Satisfactory**

Loose

Carpets

Condition : **Satisfactory**

Unclean

Roof Inside

Condition : **Satisfactory**

Unclean

Driver Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

Driver Seat recliner

Condition : **Excellent**

Good Condition

Driver Seat Up Down

Condition : **Excellent**

Good Condition

Passenger Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

Passenger Seat recliner

Condition : **Excellent**

Good Condition

Passenger Seat Up Down

Condition : **Excellent**

Good Condition

Safety belts inertia locking system Driver Seat

Condition : **Excellent**

Good Condition

Safety belts inertia locking system Passenger

Condition : **Bad**

Not Functional

Dash Board

Condition : **Satisfactory**

Scratches

Sunroof System

Condition : **Excellent**

Not Applicable

Front Right Window Type

Power Windows

Front Right Window Function

Condition : **Excellent**

Smooth Operation

Front Left Window Type

Power Windows

Front Left Window Function

Condition : **Excellent**

Smooth Operation

Interior (Continued...)

Rear Right Window Type

Manual Windows

Rear Right Window Function

Condition : **Excellent**

Smooth Operation

Rear Left Window Type

Manual Windows

Rear Left Window Function

Condition : **Excellent**

Smooth Operation

Steering Mounted Controls

Condition : **Excellent**

Not Applicable

Inside Rear View mirror

Condition : **Satisfactory**

Light/Short Scratches

Driver Seat Condition

Condition : **Satisfactory**

Faded

Passenger Seat Condition

Condition : **Satisfactory**

Faded

Rear Seat Condition

Condition : **Satisfactory**

Faded

**Instrument panel gauges:
Odometer**

Condition : **Excellent**

Good Condition

**Instrument panel Warning
Lights**

Condition : **Excellent**

Warning Lights Off - Good

Instrument panel gauges: Fuel

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Tachometer**

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Temperature**

Condition : **Excellent**

Good Condition

Horn

Condition : **Excellent**

Good Condition

Combination Switch

Condition : **Excellent**

Good Condition

Stereo Controls

Condition : **Excellent**

Not Applicable

Charger/USB Port

Condition : **Excellent**

Good Condition

[View this car in Website](#)

Interior (Continued...)

Interior lights

Condition : **Excellent**

Good Condition

Hazard lights

Condition : **Excellent**

Good Condition

Trunk Light

Condition : **Excellent**

Good Condition

Music System

Condition : **Excellent**

Good Condition

Music system type

Dashboard Mounted Music
Control-Buttons

Speakers

Condition : **Excellent**

Good Condition

Defogger

Condition : **Excellent**

Not Applicable

Central Locking System

Condition : **Excellent**

Not Applicable

**AC cooling (Check
undershade)**

Condition : **Bad**

Not Cooling

Heating

Condition : **Excellent**

Not Applicable

Air distribution (AC Vents)

Condition : **Good**

Not Working 2

Recirculation/ Fresh air

Condition : **Excellent**

Not Applicable

Steering Type

Power Steering

Power Steering Type

Electronic

Steering condition

Condition : **Satisfactory**

Noise

Air Bags

Condition : **Excellent**

Not Applicable

Hand Brake

Condition : **Excellent**

Working less than 4 notches

**CNG/LPG kit -
OEM/Aftermarket**

Condition : **Excellent**

No



Interior (Continued...)

Jack And Tommy (Tool Kit)

Condition : **Bad**

Not Available

Engine & Transmission Rating - Fair

 45 Good  11 Issues

Battery

Condition : **Bad**

Not Operational/Discharged

Alternator

Condition : **Excellent**

Good Condition

Starter Motor

Condition : **Excellent**

Good Condition

Fuel Pump

Condition : **Excellent**

Good Condition

AC Compressor

Condition : **Satisfactory**

Noise

Condenser Fan

Condition : **Satisfactory**

Noise

Blower motor

Condition : **Excellent**

Good Condition

**Steering / Column with motor
Rattling Noise**

Condition : **Satisfactory**

Rattling Noise

Suspension Arms

Condition : **Satisfactory**

Damage

Front struts (Shock Absorber)

Condition : **Satisfactory**

Rubber boot damage

Rear Shock Absorber/Spring

Condition : **Satisfactory**

Rubber boot damage

Stabiliser Bar & Other bushes

Condition : **Bad**

Bushing condition Bad or Noise

[View this car in Website](#)

Engine & Transmission (Continued...)

Link Rods (Ball joints)

Condition : **Good**

Rubber boot damage

ABS

Condition : **Excellent**

Not Applicable

Brake Pedal

Condition : **Bad**

Pumping Required

Accelerator

Condition : **Excellent**

Working Properly

Check Front Brake Efficiency

Condition : **Excellent**

Operating Efficiently

Check Rear Brake Efficiency

Condition : **Excellent**

Operating Efficiently

Master Cylinder & Booster

Condition : **Excellent**

Good Condition

**Gearshift lever
Automatic/Manual**

Condition : **Bad**

Slippage

Clutch Engagement

Condition : **Satisfactory**

Juddering/Vibration

Axle Noise

Condition : **Excellent**

No noise & Boot okay

Front Wheel bearings

Condition : **Satisfactory**

Noise

Rear Wheel bearings

Condition : **Excellent**

Good Condition

Differential

Condition : **Excellent**

Good Condition

Alignment

Condition : **Satisfactory**

Pulling

Balancing

Condition : **Satisfactory**

Wobbling

**Transmission Oil (Manual/
Automatic)**

Condition : **Excellent**

Oil Level Condition OK

**Engine and transmission
mountings**

Condition : **Bad**

Vibration

Abnormal Engine Noise

Condition : **Bad**

Cam Shaft Noise

[View this car in Website](#)

Engine & Transmission (Continued...)

Back Compression

Condition : **Bad**

Back Compression Present

Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

Gasket - tappet cover

Condition : **Satisfactory**

Leakage

Engine oil leaks From Bottom/Oil Sump

Condition : **Excellent**

Good Condition

Silencer

Condition : **Satisfactory**

Leakage

Catalytic Converter

Condition : **Excellent**

Good Condition

Engine Smoke Colour

Condition : **Excellent**

No colour

Air Filter

Condition : **Bad**

Not Replaced or Not Cleaned

Radiator

Condition : **Satisfactory**

Radiator Choke Up

Condenser

Condition : **Bad**

Joint O-Ring Leakage

Engine oil & Oil Filter

Condition : **Satisfactory**

Not Replaced

Coolant

Condition : **Satisfactory**

Low Coolant Level

Brake Oil

Condition : **Excellent**

Good Condition

Hose Pipe

Condition : **Excellent**

Good Condition

Alternator Drive Belt

Condition : **Bad**

Cracks

Water Pump

Condition : **Excellent**

Good Condition

Tappet Noise

Condition : **Bad**

Noise

Turbo Charger

Condition : **Excellent**

Not Applicable

Engine & Transmission (Continued...)

Heater Plugs (in Diesel)

Condition : **Excellent**

Not Applicable

Spark Plugs (in Petrol)

Condition : **Excellent**

Good Condition

Radiator Fan

Condition : **Excellent**

Temperature Sensor Working

Ignition Coil (petrol only)

Condition : **Excellent**

Good Condition

Ignition Wire Harness (petrol only)

Condition : **Excellent**

Good Condition

Fuel Tank and Pipes

Condition : **Excellent**

Good Condition

Fuel Filter (Petrol & Diesel)

Condition : **Excellent**

Good Condition

Fuel Injectors

Condition : **Excellent**

Working Smoothly

Vehicle Images

Front Side



Dec 20, 2022 12:01:21 PM

Lat 28.4107062,Long 77.3481571

Front Right Side



Dec 20, 2022 12:01:28 PM

Lat 28.4107578,Long 77.3482324

Front Right Tyre



Dec 20, 2022 12:01:34 PM
GPS - 28.410737, 77.348217

Dec 20, 2022 12:01:34 PM

Lat 28.4107369,Long 77.3482171

Right Side



Dec 20, 2022 12:01:42 PM
GPS - 28.410744, 77.348215

Dec 20, 2022 12:01:42 PM

Lat 28.4107345,Long 77.3482155

Rear Right Tyre



Dec 20, 2022 12:01:49 PM
GPS - 28.410713, 77.348191

Dec 20, 2022 12:01:49 PM

Lat 28.4107129,Long 77.3481906

Rear Right Side



Dec 20, 2022 12:01:59 PM
GPS - 28.410693, 77.348164

Dec 20, 2022 12:01:59 PM

Lat 28.4106963,Long 77.3481684

Back Side



Dec 20, 2022 12:02:05 PM
GPS - 28.410689, 77.348142

Dec 20, 2022 12:02:05 PM

Lat 28.4106896,Long 77.3481496

Rear Left Side



Dec 20, 2022 12:02:12 PM
GPS - 28.410689, 77.348142

Dec 20, 2022 12:02:12 PM

Lat 28.4106887,Long 77.3481424

[View this car in Website](#)

Rear Left Tyre



Dec 20, 2022 12:02:19 PM
GPS - 28.410685 , 77.348143

Dec 20, 2022 12:02:19 PM

Lat 28.410685,Long 77.3481427

Left Side



Dec 20, 2022 12:02:27 PM
GPS - 28.410685 , 77.348143

Dec 20, 2022 12:02:27 PM

Lat 28.4106854,Long 77.3481448

Front Left Tyre



Dec 20, 2022 12:02:34 PM
GPS - 28.410686 , 77.348141

Dec 20, 2022 12:02:34 PM

Lat 28.4106859,Long 77.348141

Front Left Side



Dec 20, 2022 12:02:43 PM
GPS - 28.410691 , 77.3481375

Dec 20, 2022 12:02:43 PM

Lat 28.410691,Long 77.3481375

Odometer



Dec 20, 2022 12:04:05 PM
GPS - 28.410744 , 77.348178

Dec 20, 2022 12:04:05 PM

Lat 28.4107442,Long 77.3481781

[View this car in Website](#)

Videos

Car Exterior Video

https://chnimgs3bkt.s3.amazonaws.com/autoinspekt/2022/12/20/295152933/original/1671517786066_1671517708966.mp4

Car Engine Video

https://chnimgs3bkt.s3.amazonaws.com/autoinspekt/2022/12/20/295152933/original/1671517867562_1671517825437.mp4

[View this car in Website](#)