

Mahindra First Choice Wheels Certification Report



2016 TOYOTA ETIOS(2014-2016) V

Kollam | 27630 km | Petrol | Manual | Silver Colour | 2nd Owner

- ✔ Eligible for Warranty
- ✔ 200+ Points Inspected



Overall Rating

7.9

Exterior	Fair
Interior	Fair
Engine & Transmission	Fair

Overall
Fair Buy 🙌

 *M Mahajan*
M Mahajan
Head Certification & Warranty - MFCWL

[Explore this car in website](#) [View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

Haven Motors

Registration Month

November

Registration Year

2016

Color

Silver

Odometer Reading(km)

27630

Registration Number

KL01XXXXXX

No of Owners

2

Chassis Number

MBJBXXXXXXXXXXXX

Engine Number

2NRDXXXXXX

Insurance Status

Available

Insurance Type

Company

Accidental / Flooded

Non-Accidental and Non-flooded

CNG Validity Inspection Date

Not Valid

RC Status

Available

PUC Certificate

Available

Keys Availability

Both Keys Available And Good

Transfer papers availability

Available

CNG Hydro Test Validity Certificate

Not Applicable

Vehicle Status

Certified

Remarks

ok

[View in Website](#)

Front Bumper

Condition : **Excellent**

Good Condition

Grill

Condition : **Excellent**

Good Condition

Emblem

Condition : **Excellent**

Good Condition

Windscreen glass Front

Condition : **Excellent**

Good Condition

Bonnet

Condition : **Excellent**

Good Condition

Bonnet Functionality

Condition : **Excellent**

Good Condition

RH Side Apron

Condition : **Excellent**

Good Condition

Right Running Board

Condition : **Excellent**

Good Condition

Right Fender

Condition : **Excellent**

Good Condition

Front Right Door

Condition : **Excellent**

Good Condition

**Right Front Door
Functionality**

Condition : **Excellent**

Good Condition

Front Right Door handle

Condition : **Excellent**

Good Condition

Front Right Window Glass

Condition : **Excellent**

Good Condition/Same Make

Rear Right Door

Condition : **Excellent**

Good Condition

Right Rear Door Functionality

Condition : **Excellent**

Good Condition

Rear Right Door handle

Condition : **Excellent**

Good Condition

Rear Right Window Glass

Condition : **Excellent**

Good Condition/Same Make

RH A Pillars

Condition : **Excellent**

Good Condition

Exterior (Continued...)

RH B Pillars

Condition : **Excellent**

Good Condition

RH C Pillars

Condition : **Excellent**

Good Condition

Right Quarter Panel

Condition : **Excellent**

Good Condition

Right Side View Mirror + Casing

Condition : **Excellent**

Good Condition

Right Side Power Mirror + Casing

Condition : **Excellent**

Good Condition

Front right tyre

Condition : **Good**

60%-80%

Steel Wheel Rim Front RHS

Condition : **Excellent**

Good Condition

Alloy Wheels Front RHS

Condition : **Excellent**

Not Applicable

Rear right tyre

Condition : **Good**

60%-80%

Steel Wheel Rim Rear RHS

Condition : **Excellent**

Good Condition

Alloy Wheels Rear RHS

Condition : **Excellent**

Not Applicable

Windscreen glass Back

Condition : **Excellent**

Good Condition

Trunk

Condition : **Excellent**

Good Condition

Trunk Functionality

Condition : **Excellent**

Good Condition

Rear Bumper

Condition : **Excellent**

Good Condition

Dickey Shock absorber

Condition : **Excellent**

Good Condition

Spare tyre (stephney)

Condition : **Excellent**

Same Make/ Good & > 80% life

Spare Wheel / Cover

Condition : **Excellent**

Not Applicable

[View this car in Website](#)

Exterior (Continued...)

Number Plate (Front & Rear)

Condition : **Excellent**

RTO Format

LH A Pillars

Condition : **Excellent**

Good Condition

LH B Pillars

Condition : **Excellent**

Good Condition

LH C Pillars

Condition : **Excellent**

Good Condition

Left Running Board

Condition : **Excellent**

Good Condition

Left Fender

Condition : **Excellent**

Good Condition

Left Front Door

Condition : **Excellent**

Good Condition

Front Left Door Functionality

Condition : **Excellent**

Good Condition

Front Left Door handle

Condition : **Excellent**

Good Condition

Front Left Window Glass

Condition : **Excellent**

Good Condition/Same Make

Left Side View Mirror + Casing

Condition : **Excellent**

Good Condition

Left Side Power Mirror + Casing

Condition : **Excellent**

Good Condition

Rear Left Door

Condition : **Excellent**

Good Condition

Rear Left Door Functionality

Condition : **Excellent**

Good Condition

Rear Left Door handle

Condition : **Excellent**

Good Condition

Left Quarter Panel

Condition : **Excellent**

Good Condition

Rear Left Window Glass

Condition : **Excellent**

Good Condition/Same Make

Fuel Cap

Condition : **Excellent**

Working Properly

[View this car in Website](#)

Exterior (Continued...)

Front Left tyre

Condition : **Good**

60%-80%

Steel Wheel Rim Front LHS

Condition : **Excellent**

Good Condition

Alloy Wheels Front LHS

Condition : **Excellent**

Not Applicable

Rear Left tyre

Condition : **Good**

60%-80%

Steel Wheel Rim Rear LHS

Condition : **Excellent**

Good Condition

Alloy Wheels Rear LHS

Condition : **Excellent**

Not Applicable

LH Side Apron

Condition : **Excellent**

Good Condition

Frame or Underbody

Condition : **Excellent**

No panel Replaced

Reverse Camera & Reverse Parking Sensor

Condition : **Excellent**

Functional

Roof

Condition : **Excellent**

Good Condition

Windscreen Wiper Front

Condition : **Excellent**

All speeds working properly

Windscreen Wiper Rear

Condition : **Excellent**

All speeds working properly

Windscreen Jets

Condition : **Excellent**

Good Condition

Parking Lights Front

Condition : **Excellent**

Good Condition

Parking Lights Rear

Condition : **Excellent**

Good Condition

Right Tail Light

Condition : **Excellent**

Good Condition

Left Tail Light

Condition : **Excellent**

Good Condition

Rear Left Indicator

Condition : **Excellent**

Good Condition

[View this car in Website](#)

Exterior (Continued...)

Rear Right Indicator

Condition : **Excellent**

Good Condition

Front Left Indicator

Condition : **Excellent**

Good Condition

Front Right Indicator

Condition : **Excellent**

Good Condition

Left Headlight (Both Points)

Condition : **Excellent**

Good Condition

Right Headlight (Both Points)

Condition : **Excellent**

Good Condition

Fog lamps

Condition : **Excellent**



Good Condition

Wheel Cap

Condition : **Excellent**

Available

Interior Rating - **Fair**

 61 Good  0 Issues

RHS Front Door Trim

Condition : **Excellent**

Good Condition

RHS Rear Door Trim

Condition : **Excellent**

Good Condition

Rubber Beading Front RHS

Condition : **Excellent**

Good Condition

Rubber Beading Rear RHS

Condition : **Excellent**

Good Condition

LHS Front Door Trim

Condition : **Excellent**

Good Condition

LHS Rear Door Trim

Condition : **Excellent**

Good Condition

[View this car in Website](#)

Rubber Beading Front LHS

Condition : **Excellent**

Good Condition/Same Make

Rubber Beading Rear LHS

Condition : **Excellent**

Good Condition/Same Make

Carpets

Condition : **Excellent**

Good Condition

Roof Inside

Condition : **Excellent**

Good Condition

Driver Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

Driver Seat recliner

Condition : **Excellent**

Good Condition

Driver Seat Up Down

Condition : **Excellent**

Good Condition

Passenger Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

Passenger Seat recliner

Condition : **Excellent**

Good Condition

Passenger Seat Up Down

Condition : **Excellent**

Good Condition

Safety belts inertia locking system Driver Seat

Condition : **Excellent**

Good Condition

Safety belts inertia locking system Passenger

Condition : **Excellent**

Good Condition

Dash Board

Condition : **Excellent**

Good Condition

Sunroof System

Condition : **Excellent**

Not Applicable

Front Right Window Type

Power Windows

Front Right Window Function

Condition : **Excellent**

Smooth Operation

Front Left Window Type

Power Windows

Front Left Window Function

Condition : **Excellent**

Smooth Operation

[View this car in Website](#)

Interior (Continued...)

Rear Right Window Type

Power Windows

Rear Right Window Function

Condition : **Excellent**
Smooth Operation

Rear Left Window Type

Power Windows

Rear Left Window Function

Condition : **Excellent**
Smooth Operation

Steering Mounted Controls

Condition : **Excellent**
Good Condition

Inside Rear View mirror

Condition : **Excellent**
Good Condition

Driver Seat Condition

Condition : **Excellent**
Good Condition

Passenger Seat Condition

Condition : **Excellent**
Good Condition

Rear Seat Condition

Condition : **Excellent**
Good Condition

**Instrument panel gauges:
Odometer**

Condition : **Excellent**
Good Condition

**Instrument panel Warning
Lights**

Condition : **Excellent**
Warning Lights Off - Good

Instrument panel gauges: Fuel

Condition : **Excellent**
Good Condition

**Instrument panel gauges:
Tachometer**

Condition : **Excellent**
Good Condition

**Instrument panel gauges:
Temperature**

Condition : **Excellent**
Good Condition

Horn

Condition : **Excellent**
Good Condition

Combination Switch

Condition : **Excellent**
Good Condition

Stereo Controls

Condition : **Excellent**
Good Condition

Charger/USB Port

Condition : **Excellent**
Good Condition

[View this car in Website](#)

Interior (Continued...)

Interior lights

Condition : **Excellent**

Good Condition

Hazard lights

Condition : **Excellent**

Good Condition

Trunk Light

Condition : **Excellent**

Good Condition

Music System

Condition : **Excellent**

Good Condition

Music system type

Steering Wheel Mounted Music Control

Speakers

Condition : **Excellent**

Good Condition

Defogger

Condition : **Excellent**

Good Condition

Central Locking System

Condition : **Excellent**

Good Condition

AC cooling (Check undershade)

Condition : **Excellent**

Good Condition

Heating

Condition : **Excellent**

Good Condition

Air distribution (AC Vents)

Condition : **Excellent**

Good Condition

Recirculation/ Fresh air

Condition : **Excellent**

Good Condition

Steering Type

Power Steering

Power Steering Type

Electronic

Steering condition

Condition : **Excellent**

Good Condition

Air Bags

Condition : **Excellent**

Functional

Hand Brake

Condition : **Excellent**

Working less than 4 notches

CNG/LPG kit - OEM/Aftermarket

Condition : **Excellent**

No

[View this car in Website](#)

Interior (Continued...)

Jack And Tommy (Tool Kit)

Condition : **Excellent**

Available

Engine & Transmission Rating - Fair

 56 Good

 0 Issues

Battery

Condition : **Excellent**

Good Condition

Alternator

Condition : **Excellent**

Good Condition

Starter Motor

Condition : **Excellent**

Good Condition

Fuel Pump

Condition : **Excellent**

Good Condition

AC Compressor

Condition : **Excellent**

Good Condition

Condenser Fan

Condition : **Excellent**

Good Condition

Blower motor

Condition : **Excellent**

Good Condition

**Steering / Column with motor
Rattling Noise**

Condition : **Excellent**

Working Properly

Suspension Arms

Condition : **Excellent**

All rubber boot & bushing ok

Front struts (Shock Absorber)

Condition : **Excellent**

No Leakage & Rubber boots ok

Rear Shock Absorber/Spring

Condition : **Excellent**

No Leakage & Rubber boots ok

Stabiliser Bar & Other bushes

Condition : **Excellent**

Good Condition

[View this car in Website](#)

Engine & Transmission (Continued...)

Link Rods (Ball joints)

Condition : **Excellent**

No Noise & Rubber boots ok

ABS

Condition : **Excellent**

Working

Brake Pedal

Condition : **Excellent**

Operating Properly

Accelerator

Condition : **Excellent**

Working Properly

Check Front Brake Efficiency

Condition : **Excellent**

Operating Efficiently

Check Rear Brake Efficiency

Condition : **Excellent**

Operating Efficiently

Master Cylinder & Booster

Condition : **Excellent**

Good Condition

**Gearshift lever
Automatic/Manual**

Condition : **Excellent**

Good Condition

Clutch Engagement

Condition : **Excellent**

More than 50% life

Axle Noise

Condition : **Excellent**

No noise & Boot okay

Front Wheel bearings

Condition : **Excellent**

Good Condition

Rear Wheel bearings

Condition : **Excellent**

Good Condition

Differential

Condition : **Excellent**

Good Condition

Alignment

Condition : **Excellent**

Good Condition

Balancing

Condition : **Excellent**

Good Condition

**Transmission Oil (Manual/
Automatic)**

Condition : **Excellent**

Oil Level Condition OK

**Engine and transmission
mountings**

Condition : **Excellent**

Good Condition

Abnormal Engine Noise

Condition : **Excellent**

No Noise

[View this car in Website](#)

Engine & Transmission (Continued...)

Back Compression

Condition : **Excellent**

Back Compression Not Present

Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

Gasket - tappet cover

Condition : **Excellent**

Good Condition

Engine oil leaks From Bottom/Oil Sump

Condition : **Excellent**

Good Condition

Silencer

Condition : **Excellent**

Good Condition

Catalytic Converter

Condition : **Excellent**

Good Condition

Engine Smoke Colour

Condition : **Excellent**

No colour

Air Filter

Condition : **Excellent**

Cleaned/Replaced

Radiator

Condition : **Excellent**

Good Condition

Condenser

Condition : **Excellent**

Good Condition

Engine oil & Oil Filter

Condition : **Excellent**

Good Condition

Coolant

Condition : **Excellent**

Good Condition

Brake Oil

Condition : **Excellent**

Good Condition

Hose Pipe

Condition : **Excellent**

Good Condition

Alternator Drive Belt

Condition : **Excellent**

Good Condition

Water Pump

Condition : **Excellent**

Good Condition

Tappet Noise

Condition : **Excellent**

Working Smoothly

Turbo Charger

Condition : **Excellent**

Not Applicable

[View this car in Website](#)

Engine & Transmission (Continued...)

Heater Plugs (in Diesel)

Condition : **Excellent**

Not Applicable

Spark Plugs (in Petrol)

Condition : **Excellent**

Good Condition

Radiator Fan

Condition : **Excellent**

Temperature Sensor Working

Ignition Coil (petrol only)

Condition : **Excellent**

Good Condition

Ignition Wire Harness (petrol only)

Condition : **Excellent**

Good Condition

Fuel Tank and Pipes

Condition : **Excellent**

Good Condition

Fuel Filter (Petrol & Diesel)

Condition : **Excellent**

Good Condition

Fuel Injectors

Condition : **Excellent**

Working Smoothly

[View this car in Website](#)

Vehicle Images

Front Side



Jan 9, 2023 3:16:38 PM

Lat 8.8395391,Long 76.7375886

Front Right Side



Jan 9, 2023 3:17:51 PM

Lat 8.8395189,Long 76.7376097

Front Right Tyre



Jan 9, 2023 3:17:40 PM
GPS - 8.839519 , 76.737588

Jan 9, 2023 3:17:40 PM

Lat 8.8395192,Long 76.7375875

Right Side



Jan 9, 2023 3:19:18 PM

Lat 8.8395056,Long 76.7376362

Rear Right Tyre



Jan 9, 2023 3:15:28 PM
GPS - 8.839495 , 76.737572

Jan 9, 2023 3:15:28 PM

Lat 8.8394951,Long 76.7375721

Rear Right Side



Jan 9, 2023 3:15:16 PM

Lat 8.8394668,Long 76.7375544

Back Side



Jan 9, 2023 3:14:28 PM

Lat 8.8394295,Long 76.7375284

Rear Left Side



Jan 9, 2023 3:15:01 PM

Lat 8.8394583,Long 76.7375483

[View this car in Website](#)

Rear Left Tyre



Jan 9, 2023 3:15:47 PM

Lat 8.8394572, Long 76.7375335

Left Side



Jan 9, 2023 3:16:12 PM

Lat 8.8396052, Long 76.7375343

Front Left Tyre



Jan 9, 2023 3:16:22 PM

Lat 8.8395504, Long 76.7375779

Front Left Side



Jan 9, 2023 3:16:56 PM

Lat 8.8395534, Long 76.7376047

Odometer



Jan 9, 2023 3:23:41 PM

Lat 8.8395343, Long 76.7376074

[View this car in Website](#)

Videos

Car Exterior Video

https://chnimgs3bkt.s3.amazonaws.com/autoinspekt/2023/01/09/295272084/original/1673257991669_1673257955946.m

Car Engine Video

https://chnimgs3bkt.s3.amazonaws.com/autoinspekt/2023/01/09/295272084/original/1673257921540_1673257902635.m

[View this car in Website](#)