

Mahindra First Choice Wheels Certification Report



2015 DATSUN GO PLUS(2014-2018) T

Kannur | 55615 km | Petrol | Manual | Grey Colour | 1st Owner

- Eligible for Warranty
- 200+ Points Inspected



Exterior	Fair
Interior	Fair
Engine & Transmission	Fair

Overall  
**Fair Buy**

**VERIFIED**  
M Mahajan  
Head Certification & Warranty - MFCWL

Explore this car in website [View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

## Vehicle Details

Owner Name

**Autobot Kannur**

Registration Month

**March**

Registration Year

**2016**

Color

**Grey**

Odometer Reading(km)

**55615**

Registration Number

**KL59XXXXX**

No of Owners

**1**

Chassis Number

**XXXXXXXX**

Engine Number

**XXXXXXXX**

Insurance Status

**Available**

Accidental / Flooded

**Non-Accidental and Non-flooded**

CNG Validity Inspection Date

**Not Applicable**

RC Status

**Available**

PUC Certificate

**Available**

Keys Availability

**One Key Available And Good**

Transfer papers availability

**Available**

CNG Hydro Test Validity Certificate

**Not Applicable**

Vehicle Status

**Certified**

Remarks

**certifirstplus**

[View in Website](#)

**Front Bumper**

Condition : **Bad**

Alignment Issue

**Grill**

Condition : **Excellent**

Good Condition

**Emblem**

Condition : **Excellent**

Good Condition

**Windscreen glass Front**

Condition : **Excellent**

Good Condition

**Bonnet**

Condition : **Excellent**

Light/Short Scratches-under 2

**Bonnet Functionality**

Condition : **Good**

Not Smooth

**RH Side Apron**

Condition : **Excellent**

Good Condition

**Right Running Board**

Condition : **Excellent**

Good Condition

**Right Fender**

Condition : **Bad**

Dent with Paint Damage

**Front Right Door**

Condition : **Satisfactory**

Dents With Paint Damage

**Right Front Door Functionality**

Condition : **Good**

Not Smooth

**Front Right Door handle**

Condition : **Excellent**

Good Condition

**Front Right Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Rear Right Door**

Condition : **Satisfactory**

Dents With Paint Damage

**Right Rear Door Functionality**

Condition : **Excellent**

Good Condition

**Rear Right Door handle**

Condition : **Excellent**

Good Condition

**Rear Right Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**RH A Pillars**

Condition : **Excellent**

Good Condition

Exterior (Continued...)

**RH B Pillars**

Condition : **Excellent**

Good Condition

**RH C Pillars**

Condition : **Excellent**

Good Condition

**Right Quarter Panel**

Condition : **Satisfactory**

Deep/long Scratches

**Right Side View Mirror + Casing**

Condition : **Satisfactory**

Light/Short Scratches

**Right Side Power Mirror + Casing**

Condition : **Excellent**

Not Applicable

**Front right tyre**

Condition : **Satisfactory**

40%-60%

**Steel Wheel Rim Front RHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Front RHS**

Condition : **Excellent**

Not Applicable

**Rear right tyre**

Condition : **Satisfactory**

40%-60%

**Steel Wheel Rim Rear RHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Rear RHS**

Condition : **Excellent**

Not Applicable

**Windscreen glass Back**

Condition : **Excellent**

Good Condition

**Trunk**

Condition : **Good**

Dents With Paint Damage

**Trunk Functionality**

Condition : **Excellent**

Good Condition

**Rear Bumper**

Condition : **Satisfactory**

Dents With Paint Damage

**Dickey Shock absorber**

Condition : **Excellent**

Good Condition

**Spare tyre (stephney)**

Condition : **Bad**

Different Make/ Cut Marks/  
Bulge /< 30% life

**Spare Wheel / Cover**

Condition : **Excellent**

Good Condition

Exterior (Continued...)

**Number Plate (Front & Rear)**

Condition : **Satisfactory**

Not RTO Format

**LH A Pillars**

Condition : **Excellent**

Good Condition

**LH B Pillars**

Condition : **Excellent**

Good Condition

**LH C Pillars**

Condition : **Excellent**

Good Condition

**Left Running Board**

Condition : **Satisfactory**

Deep/long Scratches

**Left Fender**

Condition : **Bad**

Dent with Paint Damage

**Left Front Door**

Condition : **Excellent**

Light/Short Scratches-2 & Above

**Front Left Door Functionality**

Condition : **Excellent**

Good Condition

**Front Left Door handle**

Condition : **Excellent**

Good Condition

**Front Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Left Side View Mirror + Casing**

Condition : **Satisfactory**

Light/Short Scratches

**Left Side Power Mirror + Casing**

Condition : **Excellent**

Not Applicable

**Rear Left Door**

Condition : **Good**

Deep/long Scratches-2 & Above

**Rear Left Door Functionality**

Condition : **Excellent**

Good Condition

**Rear Left Door handle**

Condition : **Excellent**

Good Condition

**Left Quarter Panel**

Condition : **Excellent**

Good Condition

**Rear Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Fuel Cap**

Condition : **Excellent**

Working Properly

Exterior (Continued...)

**Front Left tyre**

Condition : **Satisfactory**

25-40%

**Steel Wheel Rim Front LHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Front LHS**

Condition : **Excellent**

Not Applicable

**Rear Left tyre**

Condition : **Satisfactory**

40%-60%

**Steel Wheel Rim Rear LHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Rear LHS**

Condition : **Excellent**

Not Applicable

**LH Side Apron**

Condition : **Excellent**

Good Condition

**Frame or Underbody**

Condition : **Excellent**

No panel Replaced

**Reverse Camera & Reverse Parking Sensor**

Condition : **Excellent**

Not Applicable

**Roof**

Condition : **Excellent**

Good Condition

**Windscreen Wiper Front**

Condition : **Satisfactory**

Wiper Blade Rubber Damage

**Windscreen Wiper Rear**

Condition : **Excellent**

Not Applicable

**Windscreen Jets**

Condition : **Excellent**

Good Condition

**Parking Lights Front**

Condition : **Excellent**

Good Condition

**Parking Lights Rear**

Condition : **Excellent**

Good Condition

**Right Tail Light**

Condition : **Excellent**

Good Condition

**Left Tail Light**

Condition : **Excellent**

Good Condition

**Rear Left Indicator**

Condition : **Excellent**

Good Condition

Exterior (Continued...)

**Rear Right Indicator**

Condition : **Excellent**

Good Condition

**Front Left Indicator**

Condition : **Excellent**

Good Condition

**Front Right Indicator**

Condition : **Excellent**

Good Condition

**Left Headlight (Both Points)**

Condition : **Excellent**

Good Condition

**Right Headlight (Both Points)**

Condition : **Excellent**

Good Condition

**Fog lamps**

Condition : **Excellent**

Not Applicable

**Wheel Cap**

Condition : **Excellent**

Available

Interior Rating - **Fair**

○ 59 Good ○ 2 Issues

**RHS Front Door Trim**

Condition : **Satisfactory**

Unclean

**RHS Rear Door Trim**

Condition : **Satisfactory**

Unclean

**Rubber Beading Front RHS**

Condition : **Excellent**

Good Condition

**Rubber Beading Rear RHS**

Condition : **Excellent**

Good Condition

**LHS Front Door Trim**

Condition : **Satisfactory**

Unclean

**LHS Rear Door Trim**

Condition : **Satisfactory**

Unclean

Interior (Continued...)

**Rubber Beading Front LHS**

Condition : **Excellent**

Good Condition/Same Make

**Rubber Beading Rear LHS**

Condition : **Excellent**

Good Condition/Same Make

**Carpets**

Condition : **Satisfactory**

Unclean

**Roof Inside**

Condition : **Excellent**

Good Condition

**Driver Seat Sliding Front to Back**

Condition : **Excellent**

Good Condition

**Driver Seat recliner**

Condition : **Excellent**

Good Condition

**Driver Seat Up Down**

Condition : **Excellent**

Not Applicable

**Passenger Seat Sliding Front to Back**

Condition : **Excellent**

Good Condition

**Passenger Seat recliner**

Condition : **Excellent**

Good Condition

**Passenger Seat Up Down**

Condition : **Excellent**

Not Applicable

**Safety belts inertia locking system Driver Seat**

Condition : **Excellent**

Good Condition

**Safety belts inertia locking system Passenger**

Condition : **Excellent**

Good Condition

**Dash Board**

Condition : **Excellent**

Good Condition

**Sunroof System**

Condition : **Excellent**

Not Applicable

**Front Right Window Type**

Power Windows

**Front Right Window Function**

Condition : **Excellent**

Smooth Operation

**Front Left Window Type**

Power Windows

**Front Left Window Function**

Condition : **Excellent**

Smooth Operation

Interior (Continued...)

**Rear Right Window Type**

Manual Windows

**Rear Right Window Function**

Condition : **Excellent**

Smooth Operation

**Rear Left Window Type**

Manual Windows

**Rear Left Window Function**

Condition : **Excellent**

Smooth Operation

**Steering Mounted Controls**

Condition : **Excellent**

Not Applicable

**Inside Rear View mirror**

Condition : **Excellent**

Good Condition

**Driver Seat Condition**

Condition : **Satisfactory**

Faded

**Passenger Seat Condition**

Condition : **Satisfactory**

Faded

**Rear Seat Condition**

Condition : **Satisfactory**

Faded

**Instrument panel gauges:  
Odometer**

Condition : **Excellent**

Good Condition

**Instrument panel Warning  
Lights**

Condition : **Excellent**

Warning Lights Off - Good

**Instrument panel gauges: Fuel**

Condition : **Excellent**

Good Condition

**Instrument panel gauges:  
Tachometer**

Condition : **Excellent**

Not Applicable

**Instrument panel gauges:  
Temperature**

Condition : **Excellent**

Good Condition

**Horn**

Condition : **Excellent**

Good Condition

**Combination Switch**

Condition : **Excellent**

Good Condition

**Stereo Controls**

Condition : **Bad**

Not Functional

**Charger/USB Port**

Condition : **Excellent**

Good Condition

Interior (Continued...)

**Interior lights**

Condition : **Excellent**  
Good Condition

**Hazard lights**

Condition : **Excellent**  
Good Condition

**Trunk Light**

Condition : **Excellent**  
Not Applicable

**Music System**

Condition : **Excellent**  
Good Condition

**Music system type**

Dashboard Mounted Music  
Control-Buttons

**Speakers**

Condition : **Excellent**  
Good Condition

**Defogger**

Condition : **Excellent**  
Not Applicable

**Central Locking System**

Condition : **Excellent**  
Good Condition

**AC cooling (Check  
undershade)**

Condition : **Bad**  
Not Cooling

**Heating**

Condition : **Excellent**  
Good Condition

**Air distribution (AC Vents)**

Condition : **Excellent**  
Good Condition

**Recirculation/ Fresh air**

Condition : **Excellent**  
Good Condition

**Steering Type**

Power Steering

**Power Steering Type**

Electronic

**Steering condition**

Condition : **Satisfactory**  
Noise

**Air Bags**

Condition : **Excellent**  
Not Applicable

**Hand Brake**

Condition : **Excellent**  
Working less than 4 notches

**CNG/LPG kit -  
OEM/Aftermarket**

Condition : **Excellent**  
No



Interior (Continued...)

**Jack And Tommy (Tool Kit)**

Condition : **Excellent**

Available

**Engine & Transmission Rating - Fair**

 54 Good  2 Issues

**Battery**

Condition : **Satisfactory**

Age above 3 years

**Alternator**

Condition : **Excellent**

Good Condition

**Starter Motor**

Condition : **Excellent**

Good Condition

**Fuel Pump**

Condition : **Excellent**

Good Condition

**AC Compressor**

Condition : **Excellent**

Good Condition

**Condenser Fan**

Condition : **Excellent**

Good Condition

**Blower motor**

Condition : **Excellent**

Good Condition

**Steering / Column with motor  
Rattling Noise**

Condition : **Excellent**

Working Properly

**Suspension Arms**

Condition : **Bad**

Noise

**Front struts (Shock Absorber)**

Condition : **Satisfactory**

Rubber boot damage

**Rear Shock Absorber/Spring**

Condition : **Satisfactory**

Rubber boot damage

**Stabiliser Bar & Other bushes**

Condition : **Bad**

Bushing condition Bad or Noise

[View this car in Website](#)

Engine & Transmission (Continued...)

**Link Rods (Ball joints)**

Condition : **Excellent**

Noise or Wheel wobbling

**ABS**

Condition : **Excellent**

Not Applicable

**Brake Pedal**

Condition : **Excellent**

Operating Properly

**Accelerator**

Condition : **Excellent**

Working Properly

**Check Front Brake Efficiency**

Condition : **Excellent**

Operating Efficiently

**Check Rear Brake Efficiency**

Condition : **Excellent**

Operating Efficiently

**Master Cylinder & Booster**

Condition : **Excellent**

Good Condition

**Gearshift lever  
Automatic/Manual**

Condition : **Excellent**

Good Condition

**Clutch Engagement**

Condition : **Excellent**

More than 50% life

**Axle Noise**

Condition : **Excellent**

No noise & Boot okay

**Front Wheel bearings**

Condition : **Excellent**

Good Condition

**Rear Wheel bearings**

Condition : **Excellent**

Good Condition

**Differential**

Condition : **Excellent**

Good Condition

**Alignment**

Condition : **Excellent**

Good Condition

**Balancing**

Condition : **Excellent**

Good Condition

**Transmission Oil (Manual/  
Automatic)**

Condition : **Excellent**

Oil Level Condition OK

**Engine and transmission  
mountings**

Condition : **Excellent**

Good Condition

**Abnormal Engine Noise**

Condition : **Excellent**

No Noise

Engine & Transmission (Continued...)

**Back Compression**

Condition : **Excellent**

Back Compression Not Present

**Head Gasket leakage/replaced**

Condition : **Excellent**

Good Condition

**Gasket - tappet cover**

Condition : **Excellent**

Good Condition

**Engine oil leaks From Bottom/Oil Sump**

Condition : **Excellent**

Good Condition

**Silencer**

Condition : **Excellent**

Good Condition

**Catalytic Converter**

Condition : **Excellent**

Good Condition

**Engine Smoke Colour**

Condition : **Excellent**

No colour

**Air Filter**

Condition : **Excellent**

Cleaned/Replaced

**Radiator**

Condition : **Excellent**

Good Condition

**Condenser**

Condition : **Excellent**

Good Condition

**Engine oil & Oil Filter**

Condition : **Excellent**

Good Condition

**Coolant**

Condition : **Excellent**

Good Condition

**Brake Oil**

Condition : **Excellent**

Good Condition

**Hose Pipe**

Condition : **Excellent**

Good Condition

**Alternator Drive Belt**

Condition : **Excellent**

Good Condition

**Water Pump**

Condition : **Excellent**

Good Condition

**Tappet Noise**

Condition : **Excellent**

Working Smoothly

**Turbo Charger**

Condition : **Excellent**

Not Applicable

Engine & Transmission (Continued...)

**Heater Plugs (in Diesel)**

Condition : **Excellent**

Not Applicable

**Spark Plugs (in Petrol)**

Condition : **Excellent**

Good Condition

**Radiator Fan**

Condition : **Excellent**

Temperature Sensor Working

**Ignition Coil (petrol only)**

Condition : **Excellent**

Good Condition

**Ignition Wire Harness (petrol only)**

Condition : **Excellent**

Good Condition

**Fuel Tank and Pipes**

Condition : **Excellent**

Good Condition

**Fuel Filter (Petrol & Diesel)**

Condition : **Excellent**

Good Condition

**Fuel Injectors**

Condition : **Excellent**

Working Smoothly

## Vehicle Images

### Front Side



3 Feb 2023 1:26:40 pm

Lat 11.8032326, Long 75.4464597

### Front Right Side



3 Feb 2023 1:26:46 pm

Lat 11.8032178, Long 75.4464523

### Front Right Tyre



3 Feb 2023 1:27:01 pm

Lat 11.8032333, Long 75.4464615

### Right Side



3 Feb 2023 1:27:09 pm

Lat 11.8032329, Long 75.4464565

### Rear Right Tyre



3 Feb 2023 1:27:18 pm

Lat 11.8032399, Long 75.4464497

### Rear Right Side



3 Feb 2023 1:27:26 pm

Lat 11.80324, Long 75.446444

### Back Side



3 Feb 2023 1:27:37 pm

Lat 11.8032402, Long 75.4463918

### Rear Left Side



3 Feb 2023 1:27:52 pm

Lat 11.8032536, Long 75.4464219

[View this car in Website](#)

**Rear Left Tyre**



3 Feb 2023 1:28:09 pm

Lat 11.8032538, Long 75.4464015

**Left Side**



3 Feb 2023 1:28:17 pm

Lat 11.8032709, Long 75.4464183

**Front Left Tyre**



3 Feb 2023 1:28:22 pm

Lat 11.8032744, Long 75.4464233

**Front Left Side**



3 Feb 2023 1:28:30 pm

Lat 11.8032726, Long 75.4464226

**Chassis Imprint**



3 Feb 2023 1:26:26 pm

Lat 11.8032247, Long 75.4464424

**Odometer**



3 Feb 2023 1:29:19 pm

Lat 11.803272, Long 75.4464238

## Videos

Car Exterior Video

<https://tinyurl.com/267ks6ns>

Car Engine Video

<https://tinyurl.com/26xpgjh3>