

## Mahindra First Choice Wheels Inspection Report

**2017 ISUZU D-MAX(2015-2019) SINGLE CAB**

Gurgaon | 85848 km | Diesel | Manual | Others Colour | 1st Owner

✔ Assist First Warranty ✔ 200+ Points Inspected

Overall  
**Fair Buy** 🍏

Exterior Fair



Interior Fair



Engine & Transmission Fair



*M R Mahajan*  
M Mahajan  
Head Certification  
& Warranty - MFCWL

[Explore this car in website](#)[View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

## Vehicle Details

Owner Name

**Taneja Fourwheels**

Registration Month

**June**

Registration Year

**2017**

Color

**Others**

Odometer Reading(km)

**85848**

Registration Number

**DL8CXXXXXX**

No of Owners

**1**

Chassis Number

**M3GTXXXXXXXXXXXX**

Engine Number

**XXXXXXX**

Insurance Status

**Available**

Accidental / Flooded

**Non-Accidental and Non-flooded**

CNG Validity Inspection Date

**Not Applicable**

RC Status

**Available**

PUC Certificate

**Not Available**

Keys Availability

**One Key Available And Good**

Transfer papers availability

**Available**

CNG Hydro Test Validity Certificate

**Not Applicable**

Vehicle Status

**Inspected**

Remarks

**tyres need change, service required**

[View in Website](#)

<div><div>Front Bumper</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Grill</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Emblem</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Windscreen glass Front</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Bonnet</div><div>Condition : Good</div><div>Dents With Paint Damage</div></div>	<div><div>Bonnet Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>RH Side Apron</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Running Board</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Fender</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Front Right Door</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Front Door Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Front Right Door handle</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Front Right Window Glass</div><div>Condition : Excellent</div><div>Good Condition/Same Make</div></div>	<div><div>Rear Right Door</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Rear Door Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Rear Right Door handle</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Rear Right Window Glass</div><div>Condition : Excellent</div><div>Good Condition/Same Make</div></div>	<div><div>RH A Pillars</div><div>Condition : Excellent</div><div>Good Condition</div></div>

Exterior (Continued...)

**RH B Pillars**

Condition : **Excellent**

Good Condition

**RH C Pillars**

Condition : **Excellent**

Good Condition

**Right Quarter Panel**

Condition : **Excellent**

Good Condition

**Right Side View Mirror + Casing**

Condition : **Excellent**

Good Condition

**Right Side Power Mirror + Casing**

Condition : **Excellent**

Good Condition

**Front right tyre**

Condition : **Bad**

Less than 20%

**Steel Wheel Rim Front RHS**

Condition : **Excellent**

Not Applicable

**Alloy Wheels Front RHS**

Condition : **Excellent**

Good Condition

**Rear right tyre**

Condition : **Bad**

Less than 20%

**Steel Wheel Rim Rear RHS**

Condition : **Excellent**

Not Applicable

**Alloy Wheels Rear RHS**

Condition : **Excellent**

Good Condition

**Windscreen glass Back**

Condition : **Excellent**

Good Condition

**Trunk**

Condition : **Excellent**

Good Condition

**Trunk Functionality**

Condition : **Excellent**

Good Condition

**Rear Bumper**

Condition : **Excellent**

Good Condition

**Dickey Shock absorber**

Condition : **Excellent**

Not Applicable

**Spare tyre (stephney)**

Condition : **Satisfactory**

Same Make/ Good & > 40% life

**Spare Wheel / Cover**

Condition : **Excellent**

Not Applicable

Exterior (Continued...)

**Number Plate (Front & Rear)**

Condition : **Excellent**

RTO Format

**LH A Pillars**

Condition : **Excellent**

Good Condition

**LH B Pillars**

Condition : **Excellent**

Good Condition

**LH C Pillars**

Condition : **Excellent**

Good Condition

**Left Running Board**

Condition : **Excellent**

Good Condition

**Left Fender**

Condition : **Excellent**

Good Condition

**Left Front Door**

Condition : **Excellent**

Good Condition

**Front Left Door Functionality**

Condition : **Excellent**

Good Condition

**Front Left Door handle**

Condition : **Excellent**

Good Condition

**Front Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Left Side View Mirror + Casing**

Condition : **Excellent**

Good Condition

**Left Side Power Mirror + Casing**

Condition : **Excellent**

Good Condition

**Rear Left Door**

Condition : **Excellent**

Good Condition

**Rear Left Door Functionality**

Condition : **Excellent**

Good Condition

**Rear Left Door handle**

Condition : **Excellent**

Good Condition

**Left Quarter Panel**

Condition : **Excellent**

Good Condition

**Rear Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Fuel Cap**

Condition : **Excellent**

Working Properly

Exterior (Continued...)

**Front Left tyre**

Condition : **Bad**  
Less than 20%

**Steel Wheel Rim Front LHS**

Condition : **Excellent**  
Not Applicable

**Alloy Wheels Front LHS**

Condition : **Excellent**  
Good Condition

**Rear Left tyre**

Condition : **Bad**  
Less than 20%

**Steel Wheel Rim Rear LHS**

Condition : **Excellent**  
Not Applicable

**Alloy Wheels Rear LHS**

Condition : **Excellent**  
Good Condition

**LH Side Apron**

Condition : **Excellent**  
Good Condition

**Frame or Underbody**

Condition : **Excellent**  
No panel Replaced

**Reverse Camera & Reverse Parking Sensor**

Condition : **Excellent**  
Functional

**Roof**

Condition : **Excellent**  
Good Condition

**Windscreen Wiper Front**

Condition : **Excellent**  
All speeds working properly

**Windscreen Wiper Rear**

Condition : **Excellent**  
All speeds working properly

**Windscreen Jets**

Condition : **Excellent**  
Good Condition

**Parking Lights Front**

Condition : **Excellent**  
Good Condition

**Parking Lights Rear**

Condition : **Excellent**  
Good Condition

**Right Tail Light**

Condition : **Excellent**  
Good Condition

**Left Tail Light**

Condition : **Excellent**  
Good Condition

**Rear Left Indicator**

Condition : **Excellent**  
Good Condition

Exterior (Continued...)

<div><div>Rear Right Indicator</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Front Left Indicator</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Front Right Indicator</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Left Headlight (Both Points)</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Headlight (Both Points)</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Fog lamps</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Wheel Cap</div><div>Condition : Excellent</div><div>Not Applicable</div></div>		

Interior Rating - Fair

61 Good 0 Issues

<div><div>RHS Front Door Trim</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>RHS Rear Door Trim</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Rubber Beading Front RHS</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Rubber Beading Rear RHS</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>LHS Front Door Trim</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>LHS Rear Door Trim</div><div>Condition : Excellent</div><div>Good Condition</div></div>

## Interior (Continued...)

### Rubber Beading Front LHS

Condition : **Excellent**

Good Condition/Same Make

### Rubber Beading Rear LHS

Condition : **Excellent**

Good Condition/Same Make

### Carpets

Condition : **Excellent**

Good Condition

### Roof Inside

Condition : **Excellent**

Good Condition

### Driver Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

### Driver Seat recliner

Condition : **Excellent**

Good Condition

### Driver Seat Up Down

Condition : **Excellent**

Good Condition

### Passenger Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

### Passenger Seat recliner

Condition : **Excellent**

Good Condition

### Passenger Seat Up Down

Condition : **Excellent**

Good Condition

### Safety belts inertia locking system Driver Seat

Condition : **Excellent**

Good Condition

### Safety belts inertia locking system Passenger

Condition : **Excellent**

Good Condition

### Dash Board

Condition : **Excellent**

Good Condition

### Sunroof System

Condition : **Excellent**

Not Applicable

### Front Right Window Type

Power Windows

### Front Right Window Function

Condition : **Excellent**

Smooth Operation

### Front Left Window Type

Power Windows

### Front Left Window Function

Condition : **Excellent**

Smooth Operation



## Interior (Continued...)

### Rear Right Window Type

Power Windows

### Rear Right Window Function

Condition : **Excellent**

Smooth Operation

### Rear Left Window Type

Power Windows

### Rear Left Window Function

Condition : **Excellent**

Smooth Operation

### Steering Mounted Controls

Condition : **Excellent**

Good Condition

### Inside Rear View mirror

Condition : **Excellent**

Good Condition

### Driver Seat Condition

Condition : **Excellent**

Good Condition

### Passenger Seat Condition

Condition : **Excellent**

Good Condition

### Rear Seat Condition

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Odometer

Condition : **Excellent**

Good Condition

### Instrument panel Warning Lights

Condition : **Excellent**

Warning Lights Off - Good

### Instrument panel gauges: Fuel

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Tachometer

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Temperature

Condition : **Excellent**

Good Condition

### Horn

Condition : **Excellent**

Good Condition

### Combination Switch

Condition : **Excellent**

Good Condition

### Stereo Controls

Condition : **Excellent**

Good Condition

### Charger/USB Port

Condition : **Excellent**

Good Condition

## Interior (Continued...)

### Interior lights

Condition : **Excellent**

Good Condition

### Hazard lights

Condition : **Excellent**

Good Condition

### Trunk Light

Condition : **Excellent**

Good Condition

### Music System

Condition : **Excellent**

Good Condition

### Music system type

Steering Wheel Mounted Music Control

### Speakers

Condition : **Excellent**

Good Condition

### Defogger

Condition : **Excellent**

Good Condition

### Central Locking System

Condition : **Excellent**

Good Condition

### AC cooling (Check undershade)

Condition : **Excellent**

Good Condition

### Heating

Condition : **Excellent**

Good Condition

### Air distribution (AC Vents)

Condition : **Excellent**

Good Condition

### Recirculation/ Fresh air

Condition : **Excellent**

Good Condition

### Steering Type

Power Steering

### Power Steering Type

Hydraulic

### Steering condition

Condition : **Satisfactory**

Noise

### Air Bags

Condition : **Excellent**

Functional

### Hand Brake

Condition : **Excellent**

Working less than 4 notches

### CNG/LPG kit - OEM/Aftermarket

Condition : **Excellent**

No

Jack And Tommy (Tool Kit)

Condition : Excellent

Available

Engine & Transmission Rating - Fair

55 Good

1 Issues

Battery

Condition : Excellent

Good Condition

Alternator

Condition : Excellent

Good Condition

Starter Motor

Condition : Excellent

Good Condition

Fuel Pump

Condition : Excellent

Good Condition

AC Compressor

Condition : Excellent

Good Condition

Condenser Fan

Condition : Excellent

Good Condition

Blower motor

Condition : Excellent

Good Condition

Steering / Column with motor  
Rattling Noise

Condition : Satisfactory

Rattling Noise

Suspension Arms

Condition : Satisfactory

Noise

Front struts (Shock Absorber)

Condition : Excellent

No Leakage & Rubber boots ok

Rear Shock Absorber/Spring

Condition : Excellent

No Leakage & Rubber boots ok

Stabiliser Bar & Other bushes

Condition : Excellent

Good Condition

## Engine & Transmission (Continued...)

### Link Rods (Ball joints)

Condition : **Excellent**

No Noise & Rubber boots ok

### ABS

Condition : **Excellent**

Working

### Brake Pedal

Condition : **Excellent**

Operating Properly

### Accelerator

Condition : **Excellent**

Working Properly

### Check Front Brake Efficiency

Condition : **Excellent**

Operating Efficiently

### Check Rear Brake Efficiency

Condition : **Excellent**

Operating Efficiently

### Master Cylinder & Booster

Condition : **Excellent**

Good Condition

### Gearshift lever Automatic/Manual

Condition : **Excellent**

Good Condition

### Clutch Engagement

Condition : **Excellent**

More than 50% life

### Axle Noise

Condition : **Excellent**

No noise & Boot okay

### Front Wheel bearings

Condition : **Excellent**

Good Condition

### Rear Wheel bearings

Condition : **Excellent**

Good Condition

### Differential

Condition : **Excellent**

Good Condition

### Alignment

Condition : **Excellent**

Good Condition

### Balancing

Condition : **Excellent**

Good Condition

### Transmission Oil (Manual/ Automatic)

Condition : **Excellent**

Oil Level Condition OK

### Engine and transmission mountings

Condition : **Excellent**

Good Condition

### Abnormal Engine Noise

Condition : **Excellent**

No Noise

## Engine & Transmission (Continued...)

### Back Compression

Condition : **Excellent**

Back Compression Not Present

### Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

### Gasket - tappet cover

Condition : **Excellent**

Good Condition

### Engine oil leaks From Bottom/Oil Sump

Condition : **Excellent**

Good Condition

### Silencer

Condition : **Excellent**

Good Condition

### Catalytic Converter

Condition : **Excellent**

Good Condition

### Engine Smoke Colour

Condition : **Excellent**

No colour

### Air Filter

Condition : **Bad**

Not Replaced or Not Cleaned

### Radiator

Condition : **Excellent**

Good Condition

### Condenser

Condition : **Excellent**

Good Condition

### Engine oil & Oil Filter

Condition : **Satisfactory**

Not Replaced

### Coolant

Condition : **Satisfactory**

Discolouration

### Brake Oil

Condition : **Excellent**

Good Condition

### Hose Pipe

Condition : **Excellent**

Good Condition

### Alternator Drive Belt

Condition : **Excellent**

Good Condition

### Water Pump

Condition : **Excellent**

Good Condition

### Tappet Noise

Condition : **Excellent**

Working Smoothly

### Turbo Charger

Condition : **Excellent**

Good Condition

**Heater Plugs (in Diesel)**  
Condition : **Excellent**  
Good Condition

**Spark Plugs (in Petrol)**  
Condition : **Excellent**  
Not Applicable

**Radiator Fan**  
Condition : **Excellent**  
Temperature Sensor Working

**Ignition Coil (petrol only)**  
Condition : **Excellent**  
Not Applicable

**Ignition Wire Harness (petrol only)**  
Condition : **Excellent**  
Not Applicable

**Fuel Tank and Pipes**  
Condition : **Excellent**  
Good Condition

**Fuel Filter (Petrol & Diesel)**  
Condition : **Excellent**  
Good Condition

**Fuel Injectors**  
Condition : **Excellent**  
Working Smoothly

## Vehicle Images

### Front Side



14 Feb 2023 5:36:48 pm

Lat 28.4866769,Long 77.053358

### Front Right Side



14 Feb 2023 5:36:51 pm

Lat 28.4868028,Long 77.0535541

### Front Right Tyre



14 Feb 2023 5:36:58 pm

Lat 28.4868052,Long 77.0535333

### Right Side



14 Feb 2023 5:36:55 pm

Lat 28.4868036,Long 77.0535393

### Rear Right Tyre



14 Feb 2023 5:37:03 pm

Lat 28.4868064,Long 77.0535416

### Rear Right Side



14 Feb 2023 5:37:06 pm

Lat 28.4868072,Long 77.0535373

### Back Side



14 Feb 2023 5:37:10 pm

Lat 28.4868027,Long 77.0535452

### Rear Left Side



14 Feb 2023 5:37:14 pm

Lat 28.4867405,Long 77.0534862

[View this car in Website](#)



Rear Left Tyre



14 Feb 2023 5:37:24 pm

Lat 28.4867752,Long 77.0534458

Front Left Tyre



14 Feb 2023 5:37:29 pm

Lat 28.4867782,Long 77.0534541

Odometer



14 Feb 2023 5:39:59 pm

Lat 28.4865452,Long 77.0532831

Left Side



14 Feb 2023 5:37:20 pm

Lat 28.4867371,Long 77.0534714

Front Left Side



14 Feb 2023 5:37:33 pm

Lat 28.4868028,Long 77.0534906



## Videos

Car Exterior Video

<https://tinyurl.com/2k2am6br>

Car Engine Video

<https://tinyurl.com/2pecczf2>