

## Mahindra First Choice Wheels Certification Report



## 2013 MAHINDRA BOLERO(2011-2016) ZLX BS IV

West Champaran | 78394 km | Diesel | Manual | White Colour | 2nd Owner

✓ Eligible for Warranty ✓ 200+ Points Inspected

Overall  
Fair Buy 🤝

Exterior Fair



Interior Fair



Engine & Transmission Fair



M R Mahajan  
Head Certification  
& Warranty - MFCWL

[Explore this car in website](#)[View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

## Vehicle Details

Owner Name

**Sonakshi Automobiles**

Registration Month

**August**

Registration Year

**2013**

Color

**White**

Odometer Reading(km)

**78394**

Registration Number

**BR03XXXXX**

No of Owners

**2**

Chassis Number

**MAIXXXXXXXXXXXXXX**

Engine Number

**GPD4XXXXXX**

Insurance Status

**Not available**

Accidental / Flooded

**Non-Accidental and Non-flooded**

CNG Validity Inspection Date

**Not Applicable**

RC Status

**Available**

PUC Certificate

**Not Available**

Keys Availability

**One Key Available And Good**

Transfer papers availability

**Available**

CNG Hydro Test Validity Certificate

**Not Applicable**

Vehicle Status

**Certified**

Remarks

•

[View in Website](#)

|  |   |   |
|--|---|---|
| <div>Front Bumper</div> <div>Condition : Excellent</div> <div>Good Condition</div>                       | <div>Grill</div> <div>Condition : Excellent</div> <div>Good Condition</div>                             | <div>Emblem</div> <div>Condition : Excellent</div> <div>Good Condition</div>                        |
| <div>Windscreen glass Front</div> <div>Condition : Excellent</div> <div>Good Condition</div>             | <div>Bonnet</div> <div>Condition : Excellent</div> <div>Good Condition</div>                            | <div>Bonnet Functionality</div> <div>Condition : Excellent</div> <div>Good Condition</div>          |
| <div>RH Side Apron</div> <div>Condition : Excellent</div> <div>Good Condition</div>                      | <div>Right Running Board</div> <div>Condition : Excellent</div> <div>Good Condition</div>               | <div>Right Fender</div> <div>Condition : Excellent</div> <div>Good Condition</div>                  |
| <div>Front Right Door</div> <div>Condition : Excellent</div> <div>Good Condition</div>                   | <div>Right Front Door Functionality</div> <div>Condition : Excellent</div> <div>Good Condition</div>    | <div>Front Right Door handle</div> <div>Condition : Excellent</div> <div>Good Condition</div>       |
| <div>Front Right Window Glass</div> <div>Condition : Excellent</div> <div>Good Condition/Same Make</div> | <div>Rear Right Door</div> <div>Condition : Excellent</div> <div>Good Condition</div>                   | <div>Right Rear Door Functionality</div> <div>Condition : Excellent</div> <div>Good Condition</div> |
| <div>Rear Right Door handle</div> <div>Condition : Excellent</div> <div>Good Condition</div>             | <div>Rear Right Window Glass</div> <div>Condition : Excellent</div> <div>Good Condition/Same Make</div> | <div>RH A Pillars</div> <div>Condition : Satisfactory</div> <div>Corrosion</div>                    |

Exterior (Continued...)

**RH B Pillars**

Condition : **Excellent**

Good Condition

**RH C Pillars**

Condition : **Excellent**

Good Condition

**Right Quarter Panel**

Condition : **Excellent**

Good Condition

**Right Side View Mirror + Casing**

Condition : **Excellent**

Good Condition

**Right Side Power Mirror + Casing**

Condition : **Excellent**

Good Condition

**Front right tyre**

Condition : **Satisfactory**

25-40%

**Steel Wheel Rim Front RHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Front RHS**

Condition : **Excellent**

Not Applicable

**Rear right tyre**

Condition : **Satisfactory**

25-40%

**Steel Wheel Rim Rear RHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Rear RHS**

Condition : **Excellent**

Not Applicable

**Windscreen glass Back**

Condition : **Excellent**

Good Condition

**Trunk**

Condition : **Excellent**

Good Condition

**Trunk Functionality**

Condition : **Excellent**

Good Condition

**Rear Bumper**

Condition : **Excellent**

Good Condition

**Dickey Shock absorber**

Condition : **Excellent**

Good Condition

**Spare tyre (stephney)**

Condition : **Bad**

Different Make/ Cut Marks/  
Bulge /< 30% life

**Spare Wheel / Cover**

Condition : **Excellent**

Not Applicable

Exterior (Continued...)

**Number Plate (Front & Rear)**

Condition : **Excellent**

RTO Format

**LH A Pillars**

Condition : **Satisfactory**

Corrosion

**LH B Pillars**

Condition : **Excellent**

Good Condition

**LH C Pillars**

Condition : **Excellent**

Good Condition

**Left Running Board**

Condition : **Excellent**

Good Condition

**Left Fender**

Condition : **Excellent**

Good Condition

**Left Front Door**

Condition : **Excellent**

Good Condition

**Front Left Door Functionality**

Condition : **Excellent**

Good Condition

**Front Left Door handle**

Condition : **Excellent**

Good Condition

**Front Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Left Side View Mirror + Casing**

Condition : **Excellent**

Good Condition

**Left Side Power Mirror + Casing**

Condition : **Excellent**

Good Condition

**Rear Left Door**

Condition : **Excellent**

Good Condition

**Rear Left Door Functionality**

Condition : **Excellent**

Good Condition

**Rear Left Door handle**

Condition : **Excellent**

Good Condition

**Left Quarter Panel**

Condition : **Excellent**

Good Condition

**Rear Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Fuel Cap**

Condition : **Excellent**

Working Properly

## Exterior (Continued...)

### Front Left tyre

Condition : **Satisfactory**

25-40%

### Steel Wheel Rim Front LHS

Condition : **Excellent**

Good Condition

### Alloy Wheels Front LHS

Condition : **Excellent**

Not Applicable

### Rear Left tyre

Condition : **Satisfactory**

25-40%

### Steel Wheel Rim Rear LHS

Condition : **Excellent**

Good Condition

### Alloy Wheels Rear LHS

Condition : **Excellent**

Not Applicable

### LH Side Apron

Condition : **Excellent**

Good Condition

### Frame or Underbody

Condition : **Excellent**

No panel Replaced

### Reverse Camera & Reverse Parking Sensor

Condition : **Excellent**

Not Applicable

### Roof

Condition : **Excellent**

Good Condition

### Windscreen Wiper Front

Condition : **Excellent**

All speeds working properly

### Windscreen Wiper Rear

Condition : **Excellent**

All speeds working properly

### Windscreen Jets

Condition : **Excellent**

Good Condition

### Parking Lights Front

Condition : **Excellent**

Good Condition

### Parking Lights Rear

Condition : **Excellent**

Good Condition

### Right Tail Light

Condition : **Excellent**

Good Condition

### Left Tail Light

Condition : **Excellent**

Good Condition

### Rear Left Indicator

Condition : **Excellent**

Good Condition

Exterior (Continued...)

**Rear Right Indicator**  
Condition : Excellent  
Good Condition

**Front Left Indicator**  
Condition : Excellent  
Good Condition

**Front Right Indicator**  
Condition : Excellent  
Good Condition

**Left Headlight (Both Points)**  
Condition : Excellent  
Good Condition

**Right Headlight (Both Points)**  
Condition : Excellent  
Good Condition

**Fog lamps**  
Condition : Excellent  
Good Condition

**Wheel Cap**  
Condition : Excellent  
Available

Interior Rating - Fair

61 Good 0 Issues

**RHS Front Door Trim**  
Condition : Excellent  
Good Condition

**RHS Rear Door Trim**  
Condition : Excellent  
Good Condition

**Rubber Beading Front RHS**  
Condition : Excellent  
Good Condition

**Rubber Beading Rear RHS**  
Condition : Excellent  
Good Condition

**LHS Front Door Trim**  
Condition : Excellent  
Good Condition

**LHS Rear Door Trim**  
Condition : Excellent  
Good Condition

## Interior (Continued...)

### Rubber Beading Front LHS

Condition : **Excellent**

Good Condition/Same Make

### Rubber Beading Rear LHS

Condition : **Excellent**

Good Condition/Same Make

### Carpets

Condition : **Excellent**

Good Condition

### Roof Inside

Condition : **Excellent**

Good Condition

### Driver Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

### Driver Seat recliner

Condition : **Excellent**

Good Condition

### Driver Seat Up Down

Condition : **Excellent**

Good Condition

### Passenger Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

### Passenger Seat recliner

Condition : **Excellent**

Good Condition

### Passenger Seat Up Down

Condition : **Excellent**

Good Condition

### Safety belts inertia locking system Driver Seat

Condition : **Excellent**

Good Condition

### Safety belts inertia locking system Passenger

Condition : **Excellent**

Good Condition

### Dash Board

Condition : **Excellent**

Good Condition

### Sunroof System

Condition : **Excellent**

Not Applicable

### Front Right Window Type

Power Windows

### Front Right Window Function

Condition : **Excellent**

Smooth Operation

### Front Left Window Type

Power Windows

### Front Left Window Function

Condition : **Excellent**

Smooth Operation



## Interior (Continued...)

### Rear Right Window Type

Power Windows

### Rear Right Window Function

Condition : **Excellent**

Smooth Operation

### Rear Left Window Type

Power Windows

### Rear Left Window Function

Condition : **Excellent**

Smooth Operation

### Steering Mounted Controls

Condition : **Excellent**

Not Applicable

### Inside Rear View mirror

Condition : **Excellent**

Good Condition

### Driver Seat Condition

Condition : **Excellent**

Good Condition

### Passenger Seat Condition

Condition : **Excellent**

Good Condition

### Rear Seat Condition

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Odometer

Condition : **Excellent**

Good Condition

### Instrument panel Warning Lights

Condition : **Excellent**

Warning Lights Off - Good

### Instrument panel gauges: Fuel

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Tachometer

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Temperature

Condition : **Excellent**

Good Condition

### Horn

Condition : **Excellent**

Good Condition

### Combination Switch

Condition : **Excellent**

Good Condition

### Stereo Controls

Condition : **Excellent**

Good Condition

### Charger/USB Port

Condition : **Excellent**

Good Condition

**Interior lights**

Condition : **Excellent**

Good Condition

**Hazard lights**

Condition : **Excellent**

Good Condition

**Trunk Light**

Condition : **Excellent**

Good Condition

**Music System**

Condition : **Excellent**

Good Condition

**Music system type**

Dashboard Mounted Music  
Control-Buttons

**Speakers**

Condition : **Excellent**

Good Condition

**Defogger**

Condition : **Excellent**

Not Applicable

**Central Locking System**

Condition : **Excellent**

Good Condition

**AC cooling (Check  
undershade)**

Condition : **Excellent**

Good Condition

**Heating**

Condition : **Excellent**

Good Condition

**Air distribution (AC Vents)**

Condition : **Excellent**

Good Condition

**Recirculation/ Fresh air**

Condition : **Excellent**

Good Condition

**Steering Type**

Manual Steering

**Power Steering Type**

Hydraulic

**Steering condition**

Condition : **Satisfactory**

Not Smooth

**Air Bags**

Condition : **Excellent**

Not Applicable

**Hand Brake**

Condition : **Excellent**

Working less than 4 notches

**CNG/LPG kit -  
OEM/Aftermarket**

Condition : **Excellent**

No

**Jack And Tommy (Tool Kit)**  
Condition : Excellent  
Available

Engine & Transmission Rating - Fair

55 Good

1 Issues

**Battery**  
Condition : Bad  
Not Operational/Discharged

**Alternator**  
Condition : Excellent  
Good Condition

**Starter Motor**  
Condition : Excellent  
Good Condition

**Fuel Pump**  
Condition : Excellent  
Good Condition

**AC Compressor**  
Condition : Excellent  
Good Condition

**Condenser Fan**  
Condition : Excellent  
Good Condition

**Blower motor**  
Condition : Excellent  
Good Condition

**Steering / Column with motor  
Rattling Noise**  
Condition : Excellent  
Working Properly

**Suspension Arms**  
Condition : Excellent  
All rubber boot & bushing ok

**Front struts (Shock Absorber)**  
Condition : Excellent  
No Leakage & Rubber boots ok

**Rear Shock Absorber/Spring**  
Condition : Excellent  
No Leakage & Rubber boots ok

**Stabiliser Bar & Other bushes**  
Condition : Excellent  
Good Condition

## Engine & Transmission (Continued...)

### Link Rods (Ball joints)

Condition : **Excellent**

No Noise & Rubber boots ok

### ABS

Condition : **Excellent**

Not Applicable

### Brake Pedal

Condition : **Excellent**

Operating Properly

### Accelerator

Condition : **Excellent**

Working Properly

### Check Front Brake Efficiency

Condition : **Excellent**

Operating Efficiently

### Check Rear Brake Efficiency

Condition : **Excellent**

Operating Efficiently

### Master Cylinder & Booster

Condition : **Excellent**

Good Condition

### Gearshift lever Automatic/Manual

Condition : **Excellent**

Good Condition

### Clutch Engagement

Condition : **Satisfactory**

Less than 50% life

### Axle Noise

Condition : **Excellent**

No noise & Boot okay

### Front Wheel bearings

Condition : **Excellent**

Good Condition

### Rear Wheel bearings

Condition : **Excellent**

Good Condition

### Differential

Condition : **Excellent**

Good Condition

### Alignment

Condition : **Excellent**

Good Condition

### Balancing

Condition : **Excellent**

Good Condition

### Transmission Oil (Manual/ Automatic)

Condition : **Excellent**

Oil Level Condition OK

### Engine and transmission mountings

Condition : **Excellent**

Good Condition

### Abnormal Engine Noise

Condition : **Excellent**

No Noise

## Engine & Transmission (Continued...)

### Back Compression

Condition : **Excellent**

Back Compression Not Present

### Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

### Gasket - tappet cover

Condition : **Excellent**

Good Condition

### Engine oil leaks From Bottom/Oil Sump

Condition : **Excellent**

Good Condition

### Silencer

Condition : **Excellent**

Good Condition

### Catalytic Converter

Condition : **Excellent**

Good Condition

### Engine Smoke Colour

Condition : **Excellent**

No colour

### Air Filter

Condition : **Excellent**

Cleaned/Replaced

### Radiator

Condition : **Excellent**

Good Condition

### Condenser

Condition : **Excellent**

Good Condition

### Engine oil & Oil Filter

Condition : **Excellent**

Good Condition

### Coolant

Condition : **Excellent**

Good Condition

### Brake Oil

Condition : **Excellent**

Good Condition

### Hose Pipe

Condition : **Excellent**

Good Condition

### Alternator Drive Belt

Condition : **Excellent**

Good Condition

### Water Pump

Condition : **Excellent**

Good Condition

### Tappet Noise

Condition : **Excellent**

Working Smoothly

### Turbo Charger

Condition : **Excellent**

Good Condition

|   |   |  |
|---|---|--|
| <div><div>Heater Plugs (in Diesel)</div><div>Condition : <span>Excellent</span></div><div>Good Condition</div></div>          | <div><div>Spark Plugs (in Petrol)</div><div>Condition : <span>Excellent</span></div><div>Not Applicable</div></div>             | <div><div>Radiator Fan</div><div>Condition : <span>Excellent</span></div><div>Temperature Sensor Working</div></div> |
| <div><div>Ignition Coil (petrol only)</div><div>Condition : <span>Excellent</span></div><div>Not Applicable</div></div>       | <div><div>Ignition Wire Harness (petrol only)</div><div>Condition : <span>Excellent</span></div><div>Not Applicable</div></div> | <div><div>Fuel Tank and Pipes</div><div>Condition : <span>Excellent</span></div><div>Good Condition</div></div>      |
| <div><div>Fuel Filter (Petrol &amp; Diesel)</div><div>Condition : <span>Excellent</span></div><div>Good Condition</div></div> | <div><div>Fuel Injectors</div><div>Condition : <span>Excellent</span></div><div>Working Smoothly</div></div>                    |  |

## Vehicle Images

### Front Side



Feb 15, 2023 3:21:54 PM

Lat 27.1166919, Long 84.4672348

### Front Right Side



Feb 15, 2023 3:22:00 PM

Lat 27.1166919, Long 84.4672348

### Front Right Tyre



Feb 15, 2023 3:22:05 PM

Lat 27.1166796, Long 84.4672247

### Right Side



Feb 15, 2023 3:22:10 PM

Lat 27.1166768, Long 84.4672325

### Rear Right Tyre



Feb 15, 2023 3:22:17 PM

Lat 27.116679, Long 84.4672494

### Rear Right Side



Feb 15, 2023 3:22:22 PM

Lat 27.1166694, Long 84.4672454

### Back Side



Feb 15, 2023 3:22:30 PM

Lat 27.1166409, Long 84.4672382

### Rear Left Side



Feb 15, 2023 3:22:38 PM

Lat 27.1166477, Long 84.4672409

[View this car in Website](#)



#### Rear Left Tyre



Feb 15, 2023 3:22:45 PM

Lat 27.1166244, Long 84.4672151

#### Front Left Tyre



Feb 15, 2023 3:23:01 PM

Lat 27.1166433, Long 84.467217

#### Chassis Imprint



Feb 15, 2023 3:23:52 PM

Lat 27.1167523, Long 84.4672253

#### Left Side



Feb 15, 2023 3:22:56 PM

Lat 27.1166353, Long 84.467239

#### Front Left Side



Feb 15, 2023 3:23:07 PM

Lat 27.1166433, Long 84.467217

#### Odometer



Feb 15, 2023 3:26:04 PM

Lat 27.1166636, Long 84.467238



## Videos

Car Exterior Video

<https://tinyurl.com/2nyxxayv>

Car Engine Video

<https://tinyurl.com/2lyrlwk8>