

## Mahindra First Choice Wheels Certification Report

**2013 MARUTI SUZUKI SWIFT DZIRE(2011-2015) VXI**

Thane | 42173 km | Petrol | Manual | Others Colour | 1st Owner

✅ Eligible for Warranty ✅ 200+ Points InspectedExterior FairInterior FairEngine & Transmission Fair

Overall  
**Fair Buy** 🍏



*M R Mahajan*  
M Mahajan  
Head Certification  
& Warranty - MFCWL

[Explore this car in website](#)[View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

## Vehicle Details

Owner Name

**Thane Motor Pvt Ltd**

Registration Month

**May**

Registration Year

**2013**

Color

**Others**

Odometer Reading(km)

**42173**

Registration Number

**MH05XXXXXX**

No of Owners

**1**

Chassis Number

**MA3EXXXXXXXXXXXXX**

Engine Number

**K12MXXXXXXXXXX**

Insurance Status

**Available**

Insurance Type

**Company**

Insurance Validity

**2023-05-20**

Accidental / Flooded

**Non-Accidental and Non-flooded**

CNG Validity Inspection Date

**Not Applicable**

RC Status

**Available**

PUC Certificate

**Not Available**

Keys Availability

**Two Keys Available And Both Worn Out**

Transfer papers availability

**Available**

CNG Hydro Test Validity Certificate

**Not Applicable**

Vehicle Status

**Certified**

Remarks

**certified**

[View in Website](#)

<div><div>Front Bumper</div><div>Condition : Good</div><div>Visible Repaint</div></div>	<div><div>Grill</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Emblem</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Windscreen glass Front</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Bonnet</div><div>Condition : Good</div><div>Visible Repaint</div></div>	<div><div>Bonnet Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>RH Side Apron</div><div>Condition : Good</div><div>Visible Repaint</div></div>	<div><div>Right Running Board</div><div>Condition : Good</div><div>Visible Repaint</div></div>	<div><div>Right Fender</div><div>Condition : Good</div><div>Visible Repaint</div></div>
<div><div>Front Right Door</div><div>Condition : Good</div><div>Visible Repaint</div></div>	<div><div>Right Front Door Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Front Right Door handle</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Front Right Window Glass</div><div>Condition : Excellent</div><div>Good Condition/Same Make</div></div>	<div><div>Rear Right Door</div><div>Condition : Good</div><div>Visible Repaint</div></div>	<div><div>Right Rear Door Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Rear Right Door handle</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Rear Right Window Glass</div><div>Condition : Excellent</div><div>Good Condition/Same Make</div></div>	<div><div>RH A Pillars</div><div>Condition : Excellent</div><div>Good Condition</div></div>

Exterior (Continued...)

**RH B Pillars**

Condition : **Excellent**

Good Condition

**RH C Pillars**

Condition : **Excellent**

Good Condition

**Right Quarter Panel**

Condition : **Good**

Visible Repaint

**Right Side View Mirror + Casing**

Condition : **Excellent**

Not Applicable

**Right Side Power Mirror + Casing**

Condition : **Excellent**

Good Condition

**Front right tyre**

Condition : **Satisfactory**

40%-60%

**Steel Wheel Rim Front RHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Front RHS**

Condition : **Excellent**

Not Applicable

**Rear right tyre**

Condition : **Bad**

Less than 20%

**Steel Wheel Rim Rear RHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Rear RHS**

Condition : **Excellent**

Not Applicable

**Windscreen glass Back**

Condition : **Excellent**

Good Condition

**Trunk**

Condition : **Good**

Visible Repaint

**Trunk Functionality**

Condition : **Excellent**

Good Condition

**Rear Bumper**

Condition : **Good**

Visible Repaint

**Dickey Shock absorber**

Condition : **Excellent**

Not Applicable

**Spare tyre (stephney)**

Condition : **Satisfactory**

Same Make/ Good & > 40% life

**Spare Wheel / Cover**

Condition : **Excellent**

Good Condition

Exterior (Continued...)

**Number Plate (Front & Rear)**

Condition : **Bad**

Broken/missing

**LH A Pillars**

Condition : **Excellent**

Good Condition

**LH B Pillars**

Condition : **Excellent**

Good Condition

**LH C Pillars**

Condition : **Excellent**

Good Condition

**Left Running Board**

Condition : **Good**

Visible Repaint

**Left Fender**

Condition : **Good**

Visible Repaint

**Left Front Door**

Condition : **Good**

Visible Repaint

**Front Left Door Functionality**

Condition : **Excellent**

Good Condition

**Front Left Door handle**

Condition : **Excellent**

Good Condition

**Front Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Left Side View Mirror + Casing**

Condition : **Excellent**

Not Applicable

**Left Side Power Mirror + Casing**

Condition : **Excellent**

Good Condition

**Rear Left Door**

Condition : **Good**

Visible Repaint

**Rear Left Door Functionality**

Condition : **Excellent**

Good Condition

**Rear Left Door handle**

Condition : **Excellent**

Good Condition

**Left Quarter Panel**

Condition : **Good**

Visible Repaint

**Rear Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Fuel Cap**

Condition : **Excellent**

Working Properly

Exterior (Continued...)

**Front Left tyre**

Condition : **Satisfactory**

25-40%

**Steel Wheel Rim Front LHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Front LHS**

Condition : **Excellent**

Not Applicable

**Rear Left tyre**

Condition : **Bad**

Less than 20%

**Steel Wheel Rim Rear LHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Rear LHS**

Condition : **Excellent**

Not Applicable

**LH Side Apron**

Condition : **Good**

Visible Repaint

**Frame or Underbody**

Condition : **Satisfactory**

Panel Rusting

**Reverse Camera & Reverse  
Parking Sensor**

Condition : **Excellent**

Not Applicable

**Roof**

Condition : **Excellent**

Visible Repaint

**Windscreen Wiper Front**

Condition : **Excellent**

All speeds working properly

**Windscreen Wiper Rear**

Condition : **Excellent**

Not Applicable

**Windscreen Jets**

Condition : **Excellent**

Good Condition

**Parking Lights Front**

Condition : **Excellent**

Good Condition

**Parking Lights Rear**

Condition : **Excellent**

Good Condition

**Right Tail Light**

Condition : **Excellent**

Good Condition

**Left Tail Light**

Condition : **Excellent**

Good Condition

**Rear Left Indicator**

Condition : **Excellent**

Good Condition

Exterior (Continued...)

**Rear Right Indicator**  
Condition : Excellent  
Good Condition

**Front Left Indicator**  
Condition : Excellent  
Good Condition

**Front Right Indicator**  
Condition : Excellent  
Good Condition

**Left Headlight (Both Points)**  
Condition : Excellent  
Good Condition

**Right Headlight (Both Points)**  
Condition : Excellent  
Good Condition

**Fog lamps**  
Condition : Excellent  
Good Condition

**Wheel Cap**  
Condition : Bad  
Not Available

Interior Rating - Fair

61 Good 0 Issues

**RHS Front Door Trim**  
Condition : Excellent  
Good Condition

**RHS Rear Door Trim**  
Condition : Excellent  
Good Condition

**Rubber Beading Front RHS**  
Condition : Excellent  
Good Condition

**Rubber Beading Rear RHS**  
Condition : Excellent  
Good Condition

**LHS Front Door Trim**  
Condition : Excellent  
Good Condition

**LHS Rear Door Trim**  
Condition : Excellent  
Good Condition

## Interior (Continued...)

### Rubber Beading Front LHS

Condition : **Excellent**

Good Condition/Same Make

### Rubber Beading Rear LHS

Condition : **Excellent**

Good Condition/Same Make

### Carpets

Condition : **Excellent**

Good Condition

### Roof Inside

Condition : **Excellent**

Good Condition

### Driver Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

### Driver Seat recliner

Condition : **Excellent**

Good Condition

### Driver Seat Up Down

Condition : **Excellent**

Not Applicable

### Passenger Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

### Passenger Seat recliner

Condition : **Excellent**

Good Condition

### Passenger Seat Up Down

Condition : **Excellent**

Not Applicable

### Safety belts inertia locking system Driver Seat

Condition : **Excellent**

Good Condition

### Safety belts inertia locking system Passenger

Condition : **Excellent**

Good Condition

### Dash Board

Condition : **Excellent**

Good Condition

### Sunroof System

Condition : **Excellent**

Not Applicable

### Front Right Window Type

Power Windows

### Front Right Window Function

Condition : **Excellent**

Smooth Operation

### Front Left Window Type

Power Windows

### Front Left Window Function

Condition : **Excellent**

Smooth Operation



## Interior (Continued...)

### Rear Right Window Type

Power Windows

### Rear Right Window Function

Condition : **Excellent**

Smooth Operation

### Rear Left Window Type

Power Windows

### Rear Left Window Function

Condition : **Excellent**

Smooth Operation

### Steering Mounted Controls

Condition : **Excellent**

Good Condition

### Inside Rear View mirror

Condition : **Excellent**

Good Condition

### Driver Seat Condition

Condition : **Excellent**

Good Condition

### Passenger Seat Condition

Condition : **Excellent**

Good Condition

### Rear Seat Condition

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Odometer

Condition : **Excellent**

Good Condition

### Instrument panel Warning Lights

Condition : **Excellent**

Warning Lights Off - Good

### Instrument panel gauges: Fuel

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Tachometer

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Temperature

Condition : **Excellent**

Good Condition

### Horn

Condition : **Excellent**

Good Condition

### Combination Switch

Condition : **Excellent**

Good Condition

### Stereo Controls

Condition : **Excellent**

Good Condition

### Charger/USB Port

Condition : **Excellent**

Good Condition

## Interior (Continued...)

### Interior lights

Condition : **Excellent**

Good Condition

### Hazard lights

Condition : **Excellent**

Good Condition

### Trunk Light

Condition : **Excellent**

Good Condition

### Music System

Condition : **Excellent**

Good Condition

### Music system type

Dashboard Mounted Music  
Control-Buttons

### Speakers

Condition : **Excellent**

Good Condition

### Defogger

Condition : **Excellent**

Not Applicable

### Central Locking System

Condition : **Excellent**

Good Condition

### AC cooling (Check undershade)

Condition : **Excellent**

Good Condition

### Heating

Condition : **Excellent**

Good Condition

### Air distribution (AC Vents)

Condition : **Excellent**

Good Condition

### Recirculation/ Fresh air

Condition : **Excellent**

Good Condition

### Steering Type

Power Steering

### Power Steering Type

Electronic

### Steering condition

Condition : **Excellent**

Good Condition

### Air Bags

Condition : **Excellent**

Not Applicable

### Hand Brake

Condition : **Excellent**

Working less than 4 notches

### CNG/LPG kit - OEM/Aftermarket

Condition : **Excellent**

No

**Jack And Tommy (Tool Kit)**  
Condition : Excellent  
Available

Engine & Transmission Rating - Fair

56 Good

0 Issues

**Battery**  
Condition : Satisfactory  
Age above 3 years

**Alternator**  
Condition : Excellent  
Good Condition

**Starter Motor**  
Condition : Excellent  
Good Condition

**Fuel Pump**  
Condition : Excellent  
Good Condition

**AC Compressor**  
Condition : Excellent  
Good Condition

**Condenser Fan**  
Condition : Excellent  
Good Condition

**Blower motor**  
Condition : Excellent  
Good Condition

**Steering / Column with motor Rattling Noise**  
Condition : Excellent  
Working Properly

**Suspension Arms**  
Condition : Excellent  
All rubber boot & bushing ok

**Front struts (Shock Absorber)**  
Condition : Excellent  
No Leakage & Rubber boots ok

**Rear Shock Absorber/Spring**  
Condition : Excellent  
No Leakage & Rubber boots ok

**Stabiliser Bar & Other bushes**  
Condition : Excellent  
Good Condition

## Engine & Transmission (Continued...)

### Link Rods (Ball joints)

Condition : **Excellent**

No Noise & Rubber boots ok

### ABS

Condition : **Excellent**

Not Applicable

### Brake Pedal

Condition : **Excellent**

Operating Properly

### Accelerator

Condition : **Excellent**

Working Properly

### Check Front Brake Efficiency

Condition : **Excellent**

Operating Efficiently

### Check Rear Brake Efficiency

Condition : **Excellent**

Operating Efficiently

### Master Cylinder & Booster

Condition : **Excellent**

Good Condition

### Gearshift lever Automatic/Manual

Condition : **Excellent**

Good Condition

### Clutch Engagement

Condition : **Excellent**

More than 50% life

### Axle Noise

Condition : **Excellent**

No noise & Boot okay

### Front Wheel bearings

Condition : **Excellent**

Good Condition

### Rear Wheel bearings

Condition : **Excellent**

Good Condition

### Differential

Condition : **Excellent**

Good Condition

### Alignment

Condition : **Excellent**

Good Condition

### Balancing

Condition : **Excellent**

Good Condition

### Transmission Oil (Manual/ Automatic)

Condition : **Excellent**

Oil Level Condition OK

### Engine and transmission mountings

Condition : **Excellent**

Good Condition

### Abnormal Engine Noise

Condition : **Excellent**

No Noise

## Engine & Transmission (Continued...)

### Back Compression

Condition : **Excellent**

Back Compression Not Present

### Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

### Gasket - tappet cover

Condition : **Excellent**

Good Condition

### Engine oil leaks From Bottom/Oil Sump

Condition : **Excellent**

Good Condition

### Silencer

Condition : **Excellent**

Good Condition

### Catalytic Converter

Condition : **Excellent**

Good Condition

### Engine Smoke Colour

Condition : **Excellent**

No colour

### Air Filter

Condition : **Excellent**

Cleaned/Replaced

### Radiator

Condition : **Excellent**

Good Condition

### Condenser

Condition : **Excellent**

Good Condition

### Engine oil & Oil Filter

Condition : **Excellent**

Good Condition

### Coolant

Condition : **Excellent**

Good Condition

### Brake Oil

Condition : **Excellent**

Good Condition

### Hose Pipe

Condition : **Excellent**

Good Condition

### Alternator Drive Belt

Condition : **Excellent**

Good Condition

### Water Pump

Condition : **Excellent**

Good Condition

### Tappet Noise

Condition : **Excellent**

Working Smoothly

### Turbo Charger

Condition : **Excellent**

Not Applicable

**Heater Plugs (in Diesel)**  
Condition : **Excellent**  
Not Applicable

**Spark Plugs (in Petrol)**  
Condition : **Excellent**  
Good Condition

**Radiator Fan**  
Condition : **Excellent**  
Temperature Sensor Working

**Ignition Coil (petrol only)**  
Condition : **Excellent**  
Good Condition

**Ignition Wire Harness (petrol only)**  
Condition : **Excellent**  
Good Condition

**Fuel Tank and Pipes**  
Condition : **Excellent**  
Good Condition

**Fuel Filter (Petrol & Diesel)**  
Condition : **Excellent**  
Good Condition

**Fuel Injectors**  
Condition : **Excellent**  
Working Smoothly

## Vehicle Images

### Front Side



Feb 24, 2023 1:30:28 PM

Lat 19.22403,Long 72.98467

### Front Right Side



Feb 24, 2023 1:30:36 PM

Lat 19.2238963,Long 72.9846557

### Front Right Tyre



Feb 24, 2023 1:30:40 PM

Lat 19.2238642,Long 72.9846708

### Right Side



Feb 24, 2023 1:30:47 PM

Lat 19.2238398,Long 72.9846899

### Rear Right Tyre



Feb 24, 2023 1:30:54 PM

Lat 19.2238879,Long 72.9847109

### Rear Right Side



Feb 24, 2023 1:31:53 PM

Lat 19.2239125,Long 72.9846876

### Back Side



Feb 24, 2023 1:32:00 PM

Lat 19.2238785,Long 72.9846335

### Spare Tyre



Feb 24, 2023 1:31:20 PM

Lat 19.2238717,Long 72.9847048

[View this car in Website](#)



#### Rear Left Side



Feb 24, 2023 1:32:08 PM

Lat 19.2239092,Long 72.9846394

#### Rear Left Tyre



Feb 24, 2023 1:32:14 PM

Lat 19.2239101,Long 72.9846365

#### Left Side



Feb 24, 2023 1:32:23 PM

Lat 19.2238947,Long 72.9846546

#### Front Left Tyre



Feb 24, 2023 1:32:30 PM

Lat 19.2238503,Long 72.9846391

#### Front Left Side



Feb 24, 2023 1:32:38 PM

Lat 19.2238242,Long 72.9846278

#### Odometer



Feb 24, 2023 1:35:54 PM

Lat 19.2238349,Long 72.9846328



## Videos

Car Exterior Video

<https://tinyurl.com/2erakwp2>

Car Engine Video

<https://tinyurl.com/2mzr8yly>