

## Mahindra First Choice Wheels Certification Report

**2017 MARUTI SUZUKI CELERIO(2017-2019) VXI AMT**

Kozhikode | 47356 km | Petrol | Amt | Grey Colour | 1st Owner

✓ Eligible for Warranty ✓ 200+ Points InspectedExterior FairInterior FairEngine & Transmission Fair

Overall  
**Fair Buy** 🚗



*M R Mahajan*  
M Mahajan  
Head Certification  
& Warranty - MFCWL

[Explore this car in website](#)[View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

## Vehicle Details

Owner Name

Registration Month

Registration Year

**Car Zone**

**June**

**2017**

Color

Odometer Reading(km)

Registration Number

**Grey**

**47356**

**KL59XXXXX**

No of Owners

Chassis Number

Engine Number

**1**

**MA3EXXXXXXXXXXXXXXX**

**K10BXXXXXXXXX**

Insurance Status

Accidental / Flooded

CNG Validity Inspection Date

**Available**

**Non-Accidental and Non-flooded**

**Not Applicable**

RC Status

PUC Certificate

Keys Availability

**Available**

**Available**

**One Key Available And Good**

Transfer papers availability

CNG Hydro Test Validity Certificate

Vehicle Status

**Available**

**Not Applicable**

**Certified**

Remarks

**WarrantyFirst**

[View in Website](#)

**Front Bumper**

Condition : Good

Deep/long Scratches-2 & Above

**Grill**

Condition : Excellent

Good Condition

**Emblem**

Condition : Excellent

Good Condition

**Windscreen glass Front**

Condition : Excellent

Good Condition

**Bonnet**

Condition : Excellent

Good Condition

**Bonnet Functionality**

Condition : Excellent

Good Condition

**RH Side Apron**

Condition : Excellent

Good Condition

**Right Running Board**

Condition : Excellent

Good Condition

**Right Fender**

Condition : Excellent

Good Condition

**Front Right Door**

Condition : Satisfactory

Replaced - Not Original

**Right Front Door Functionality**

Condition : Excellent

Good Condition

**Front Right Door handle**

Condition : Excellent

Good Condition

**Front Right Window Glass**

Condition : Excellent

Good Condition/Same Make

**Rear Right Door**

Condition : Excellent

Good Condition

**Right Rear Door Functionality**

Condition : Excellent

Good Condition

**Rear Right Door handle**

Condition : Excellent

Good Condition

**Rear Right Window Glass**

Condition : Excellent

Good Condition/Same Make

**RH A Pillars**

Condition : Excellent

Good Condition

Exterior (Continued...)

**RH B Pillars**

Condition : **Excellent**

Good Condition

**RH C Pillars**

Condition : **Excellent**

Good Condition

**Right Quarter Panel**

Condition : **Good**

Light/Short Scratches

**Right Side View Mirror + Casing**

Condition : **Satisfactory**

Light/Short Scratches

**Right Side Power Mirror + Casing**

Condition : **Excellent**

Not Applicable

**Front right tyre**

Condition : **Satisfactory**

25-40%

**Steel Wheel Rim Front RHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Front RHS**

Condition : **Excellent**

Not Applicable

**Rear right tyre**

Condition : **Satisfactory**

40%-60%

**Steel Wheel Rim Rear RHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Rear RHS**

Condition : **Excellent**

Not Applicable

**Windscreen glass Back**

Condition : **Excellent**

Good Condition

**Trunk**

Condition : **Excellent**

Good Condition

**Trunk Functionality**

Condition : **Excellent**

Good Condition

**Rear Bumper**

Condition : **Good**

Deep/long Scratches-2 & Above

**Dickey Shock absorber**

Condition : **Excellent**

Good Condition

**Spare tyre (stephney)**

Condition : **Bad**

Different Make/ Cut Marks/  
Bulge /< 30% life

**Spare Wheel / Cover**

Condition : **Excellent**

Good Condition

Exterior (Continued...)

**Number Plate (Front & Rear)**

Condition : **Excellent**

RTO Format

**LH A Pillars**

Condition : **Excellent**

Good Condition

**LH B Pillars**

Condition : **Excellent**

Good Condition

**LH C Pillars**

Condition : **Excellent**

Good Condition

**Left Running Board**

Condition : **Satisfactory**

Deep/long Scratches

**Left Fender**

Condition : **Bad**

Dent with Paint Damage

**Left Front Door**

Condition : **Excellent**

Light/Short Scratches-2 & Above

**Front Left Door Functionality**

Condition : **Excellent**

Good Condition

**Front Left Door handle**

Condition : **Excellent**

Good Condition

**Front Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Left Side View Mirror + Casing**

Condition : **Satisfactory**

Light/Short Scratches

**Left Side Power Mirror + Casing**

Condition : **Excellent**

Not Applicable

**Rear Left Door**

Condition : **Excellent**

Good Condition

**Rear Left Door Functionality**

Condition : **Excellent**

Good Condition

**Rear Left Door handle**

Condition : **Excellent**

Good Condition

**Left Quarter Panel**

Condition : **Excellent**

Good Condition

**Rear Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Fuel Cap**

Condition : **Excellent**

Working Properly

[View this car in Website](#)

## Exterior (Continued...)

### Front Left tyre

Condition : **Satisfactory**

25-40%

### Steel Wheel Rim Front LHS

Condition : **Excellent**

Good Condition

### Alloy Wheels Front LHS

Condition : **Excellent**

Not Applicable

### Rear Left tyre

Condition : **Satisfactory**

40%-60%

### Steel Wheel Rim Rear LHS

Condition : **Excellent**

Good Condition

### Alloy Wheels Rear LHS

Condition : **Excellent**

Not Applicable

### LH Side Apron

Condition : **Excellent**

Good Condition

### Frame or Underbody

Condition : **Excellent**

No panel Replaced

### Reverse Camera & Reverse Parking Sensor

Condition : **Excellent**

Functional

### Roof

Condition : **Excellent**

Good Condition

### Windscreen Wiper Front

Condition : **Satisfactory**

Wiper Blade Rubber Damage

### Windscreen Wiper Rear

Condition : **Excellent**

Not Applicable

### Windscreen Jets

Condition : **Excellent**

Good Condition

### Parking Lights Front

Condition : **Excellent**

Good Condition

### Parking Lights Rear

Condition : **Excellent**

Good Condition

### Right Tail Light

Condition : **Excellent**

Good Condition

### Left Tail Light

Condition : **Excellent**

Good Condition

### Rear Left Indicator

Condition : **Excellent**

Good Condition

Exterior (Continued...)

**Rear Right Indicator**  
Condition : Excellent  
Good Condition

**Front Left Indicator**  
Condition : Excellent  
Good Condition

**Front Right Indicator**  
Condition : Excellent  
Good Condition

**Left Headlight (Both Points)**  
Condition : Excellent  
Good Condition

**Right Headlight (Both Points)**  
Condition : Excellent  
Good Condition

**Fog lamps**  
Condition : Excellent  
Not Applicable

**Wheel Cap**  
Condition : Excellent  
Available

Interior Rating - Fair

60 Good

1 Issues

**RHS Front Door Trim**  
Condition : Excellent  
Good Condition

**RHS Rear Door Trim**  
Condition : Excellent  
Good Condition

**Rubber Beading Front RHS**  
Condition : Excellent  
Good Condition

**Rubber Beading Rear RHS**  
Condition : Excellent  
Good Condition

**LHS Front Door Trim**  
Condition : Excellent  
Good Condition

**LHS Rear Door Trim**  
Condition : Excellent  
Good Condition

## Interior (Continued...)

### Rubber Beading Front LHS

Condition : **Excellent**

Good Condition/Same Make

### Rubber Beading Rear LHS

Condition : **Excellent**

Good Condition/Same Make

### Carpets

Condition : **Satisfactory**

Unclean

### Roof Inside

Condition : **Bad**

Unclean

### Driver Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

### Driver Seat recliner

Condition : **Excellent**

Good Condition

### Driver Seat Up Down

Condition : **Excellent**

Not Applicable

### Passenger Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

### Passenger Seat recliner

Condition : **Excellent**

Good Condition

### Passenger Seat Up Down

Condition : **Excellent**

Not Applicable

### Safety belts inertia locking system Driver Seat

Condition : **Excellent**

Good Condition

### Safety belts inertia locking system Passenger

Condition : **Excellent**

Good Condition

### Dash Board

Condition : **Excellent**

Good Condition

### Sunroof System

Condition : **Excellent**

Not Applicable

### Front Right Window Type

Power Windows

### Front Right Window Function

Condition : **Excellent**

Smooth Operation

### Front Left Window Type

Power Windows

### Front Left Window Function

Condition : **Excellent**

Smooth Operation



## Interior (Continued...)

### Rear Right Window Type

Power Windows

### Rear Right Window Function

Condition : **Excellent**

Smooth Operation

### Rear Left Window Type

Power Windows

### Rear Left Window Function

Condition : **Excellent**

Smooth Operation

### Steering Mounted Controls

Condition : **Excellent**

Not Applicable

### Inside Rear View mirror

Condition : **Excellent**

Good Condition

### Driver Seat Condition

Condition : **Satisfactory**

Faded

### Passenger Seat Condition

Condition : **Satisfactory**

Faded

### Rear Seat Condition

Condition : **Satisfactory**

Faded

### Instrument panel gauges: Odometer

Condition : **Excellent**

Good Condition

### Instrument panel Warning Lights

Condition : **Excellent**

Warning Lights Off - Good

### Instrument panel gauges: Fuel

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Tachometer

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Temperature

Condition : **Excellent**

Good Condition

### Horn

Condition : **Excellent**

Good Condition

### Combination Switch

Condition : **Excellent**

Good Condition

### Stereo Controls

Condition : **Excellent**

Good Condition

### Charger/USB Port

Condition : **Excellent**

Good Condition

## Interior (Continued...)

### Interior lights

Condition : **Excellent**

Good Condition

### Hazard lights

Condition : **Excellent**

Good Condition

### Trunk Light

Condition : **Excellent**

Good Condition

### Music System

Condition : **Excellent**

Good Condition

### Music system type

Dashboard Mounted Music  
Control-Touch Screen

### Speakers

Condition : **Excellent**

Good Condition

### Defogger

Condition : **Excellent**

Not Applicable

### Central Locking System

Condition : **Excellent**

Good Condition

### AC cooling (Check undershade)

Condition : **Excellent**

Good Condition

### Heating

Condition : **Excellent**

Good Condition

### Air distribution (AC Vents)

Condition : **Excellent**

Good Condition

### Recirculation/ Fresh air

Condition : **Excellent**

Good Condition

### Steering Type

Power Steering

### Power Steering Type

Electronic

### Steering condition

Condition : **Excellent**

Good Condition

### Air Bags

Condition : **Excellent**

Not Applicable

### Hand Brake

Condition : **Excellent**

Working less than 4 notches

### CNG/LPG kit - OEM/Aftermarket

Condition : **Excellent**

No

Jack And Tommy (Tool Kit)

Condition : Excellent

Available

Engine & Transmission Rating - Fair

56 Good

0 Issues

Battery

Condition : Satisfactory

Age above 3 years

Alternator

Condition : Excellent

Good Condition

Starter Motor

Condition : Excellent

Good Condition

Fuel Pump

Condition : Excellent

Good Condition

AC Compressor

Condition : Excellent

Good Condition

Condenser Fan

Condition : Excellent

Good Condition

Blower motor

Condition : Excellent

Good Condition

Steering / Column with motor  
Rattling Noise

Condition : Excellent

Working Properly

Suspension Arms

Condition : Excellent

All rubber boot & bushing ok

Front struts (Shock Absorber)

Condition : Excellent

No Leakage & Rubber boots ok

Rear Shock Absorber/Spring

Condition : Excellent

No Leakage & Rubber boots ok

Stabiliser Bar & Other bushes

Condition : Excellent

Good Condition

## Engine & Transmission (Continued...)

### Link Rods (Ball joints)

Condition : **Excellent**

No Noise & Rubber boots ok

### ABS

Condition : **Excellent**

Not Applicable

### Brake Pedal

Condition : **Excellent**

Operating Properly

### Accelerator

Condition : **Excellent**

Working Properly

### Check Front Brake Efficiency

Condition : **Excellent**

Operating Efficiently

### Check Rear Brake Efficiency

Condition : **Excellent**

Operating Efficiently

### Master Cylinder & Booster

Condition : **Excellent**

Good Condition

### Gearshift lever Automatic/Manual

Condition : **Excellent**

Good Condition

### Clutch Engagement

Condition : **Excellent**

More than 50% life

### Axle Noise

Condition : **Excellent**

No noise & Boot okay

### Front Wheel bearings

Condition : **Excellent**

Good Condition

### Rear Wheel bearings

Condition : **Excellent**

Good Condition

### Differential

Condition : **Excellent**

Good Condition

### Alignment

Condition : **Excellent**

Good Condition

### Balancing

Condition : **Excellent**

Good Condition

### Transmission Oil (Manual/ Automatic)

Condition : **Excellent**

Oil Level Condition OK

### Engine and transmission mountings

Condition : **Excellent**

Good Condition

### Abnormal Engine Noise

Condition : **Excellent**

No Noise

## Engine & Transmission (Continued...)

### Back Compression

Condition : **Excellent**

Back Compression Not Present

### Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

### Gasket - tappet cover

Condition : **Excellent**

Good Condition

### Engine oil leaks From Bottom/Oil Sump

Condition : **Excellent**

Good Condition

### Silencer

Condition : **Excellent**

Good Condition

### Catalytic Converter

Condition : **Excellent**

Good Condition

### Engine Smoke Colour

Condition : **Excellent**

No colour

### Air Filter

Condition : **Excellent**

Cleaned/Replaced

### Radiator

Condition : **Excellent**

Good Condition

### Condenser

Condition : **Excellent**

Good Condition

### Engine oil & Oil Filter

Condition : **Excellent**

Good Condition

### Coolant

Condition : **Excellent**

Good Condition

### Brake Oil

Condition : **Excellent**

Good Condition

### Hose Pipe

Condition : **Excellent**

Good Condition

### Alternator Drive Belt

Condition : **Excellent**

Good Condition

### Water Pump

Condition : **Excellent**

Good Condition

### Tappet Noise

Condition : **Excellent**

Working Smoothly

### Turbo Charger

Condition : **Excellent**

Not Applicable

**Heater Plugs (in Diesel)**  
Condition : **Excellent**  
Not Applicable

**Spark Plugs (in Petrol)**  
Condition : **Excellent**  
Good Condition

**Radiator Fan**  
Condition : **Excellent**  
Temperature Sensor Working

**Ignition Coil (petrol only)**  
Condition : **Excellent**  
Good Condition

**Ignition Wire Harness (petrol only)**  
Condition : **Excellent**  
Good Condition

**Fuel Tank and Pipes**  
Condition : **Excellent**  
Good Condition

**Fuel Filter (Petrol & Diesel)**  
Condition : **Excellent**  
Good Condition

**Fuel Injectors**  
Condition : **Excellent**  
Working Smoothly



## Vehicle Images

### Front Side



2 Mar 2023 1:39:16 pm

Lat 11.2974881, Long 75.7639129

### Front Right Side



2 Mar 2023 1:39:22 pm

Lat 11.2974899, Long 75.7639131

### Front Right Tyre



2 Mar 2023 1:39:27 pm

Lat 11.2975095, Long 75.7639172

### Right Side



2 Mar 2023 1:39:35 pm

Lat 11.2975065, Long 75.7639213

### Rear Right Tyre



2 Mar 2023 1:39:43 pm

Lat 11.2975082, Long 75.7639176

### Rear Right Side



2 Mar 2023 1:39:49 pm

Lat 11.2974725, Long 75.7638874

### Back Side



2 Mar 2023 1:39:57 pm

Lat 11.2974775, Long 75.7638864

### Rear Left Side



2 Mar 2023 1:40:04 pm

Lat 11.2974772, Long 75.7638785

[View this car in Website](#)



Rear Left Tyre



2 Mar 2023 1:40:12 pm

Lat 11.2974797,Long 75.763877

Front Left Tyre



2 Mar 2023 1:40:30 pm

Lat 11.2974874,Long 75.7638776

Odometer



2 Mar 2023 1:33:03 pm

Lat 11.2974764,Long 75.7639162

Left Side



2 Mar 2023 1:40:25 pm

Lat 11.2974866,Long 75.7638775

Front Left Side



2 Mar 2023 1:40:37 pm

Lat 11.2974885,Long 75.7638776



## Videos

Car Exterior Video

<https://tinyurl.com/2lm9fp6x>

Car Engine Video

<https://tinyurl.com/2eglb4kc>