

Mahindra First Choice Wheels Certification Report

**2017 HYUNDAI CRETA(2015-2018) 1.6 SX CRDI**

Pune | 60583 km | Diesel | Manual | White Colour | 1st Owner

Eligible for Warranty 200+ Points Inspected

Exterior FairInterior FairEngine & Transmission Fair

Overall
Fair Buy

M. Mahajan
M Mahajan
Head Certification
& Warranty - MFCWL

[Explore this car in website](#)[View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

Jeen Mata Motors

Registration Month

July

Registration Year

2017

Color

White

Odometer Reading(km)

60583

Registration Number

MH12XXXXXX

No of Owners

1

Chassis Number

MALCXXXXXXXXXXXXXX

Engine Number

D4FBXXXXXXXXXX

Insurance Status

Not available

Accidental / Flooded

Non-Accidental and Non-flooded

CNG Validity Inspection Date

Not Applicable

RC Status

Not Available

PUC Certificate

Not Available

Keys Availability

One Key Available And Good

Transfer papers availability

Available

CNG Hydro Test Validity Certificate

Not Applicable

Vehicle Status

Certified

Remarks

1.Single Key Available

[View in Website](#)

Front Bumper

Condition : **Good**

Visible Repaint

Grill

Condition : **Excellent**

Good Condition

Emblem

Condition : **Excellent**

Good Condition

Windscreen glass Front

Condition : **Excellent**

Good Condition

Bonnet

Condition : **Satisfactory**

Replaced - Not Original

Bonnet Functionality

Condition : **Excellent**

Good Condition

RH Side Apron

Condition : **Excellent**

Good Condition

Right Running Board

Condition : **Excellent**

Good Condition

Right Fender

Condition : **Excellent**

Good Condition

Front Right Door

Condition : **Excellent**

Deep/long Scratches-under 2

Right Front Door Functionality

Condition : **Excellent**

Good Condition

Front Right Door handle

Condition : **Excellent**

Good Condition

Front Right Window Glass

Condition : **Excellent**

Good Condition/Same Make

Rear Right Door

Condition : **Excellent**

Good Condition

Right Rear Door Functionality

Condition : **Excellent**

Good Condition

Rear Right Door handle

Condition : **Excellent**

Good Condition

Rear Right Window Glass

Condition : **Excellent**

Good Condition/Same Make

RH A Pillars

Condition : **Excellent**

Good Condition

Exterior (Continued...)

RH B Pillars

Condition : **Excellent**

Good Condition

RH C Pillars

Condition : **Excellent**

Good Condition

Right Quarter Panel

Condition : **Good**

Dent without Paint Damage

Right Side View Mirror + Casing

Condition : **Excellent**

Not Applicable

Right Side Power Mirror + Casing

Condition : **Excellent**

Good Condition

Front right tyre

Condition : **Excellent**

Above 80% life

Alloy Wheels Present?

Condition : **Yes**

Yes

Wheel Front RHS

Condition : **Excellent**

Good Condition

Rear right tyre

Condition : **Excellent**

Above 80% life

Wheel Rear RHS

Condition : **Excellent**

Good Condition

Windscreen glass Back

Condition : **Excellent**

Good Condition

Trunk

Condition : **Excellent**

Good Condition

Trunk Functionality

Condition : **Excellent**

Good Condition

Rear Bumper

Condition : **Excellent**

Good Condition

Dickey Shock absorber

Condition : **Excellent**

Good Condition

Spare tyre (stephney)

Condition : **Excellent**

Same Make/ Good & > 80% life

Spare Wheel / Cover

Condition : **Excellent**

Good Condition

Number Plate (Front & Rear)

Condition : **Excellent**

RTO Format

[View this car in Website](#)

Exterior (Continued...)

LH A Pillars

Condition : **Excellent**

Good Condition

LH B Pillars

Condition : **Excellent**

Good Condition

LH C Pillars

Condition : **Excellent**

Good Condition

Left Running Board

Condition : **Excellent**

Good Condition

Left Fender

Condition : **Excellent**

Good Condition

Left Front Door

Condition : **Excellent**

Good Condition

Front Left Door Functionality

Condition : **Excellent**

Good Condition

Front Left Door handle

Condition : **Excellent**

Good Condition

Front Left Window Glass

Condition : **Excellent**

Good Condition/Same Make

Left Side View Mirror + Casing

Condition : **Excellent**

Not Applicable

Left Side Power Mirror + Casing

Condition : **Excellent**

Good Condition

Rear Left Door

Condition : **Excellent**

Good Condition

Rear Left Door Functionality

Condition : **Excellent**

Good Condition

Rear Left Door handle

Condition : **Excellent**

Good Condition

Left Quarter Panel

Condition : **Excellent**

Good Condition

Rear Left Window Glass

Condition : **Excellent**

Good Condition/Same Make

Fuel Cap

Condition : **Excellent**

Working Properly

Front Left tyre

Condition : **Excellent**

Above 80% life

[View this car in Website](#)

Exterior (Continued...)

Wheel Front LHS

Condition : **Excellent**
Good Condition

Rear Left tyre

Condition : **Excellent**
Above 80% life

Wheel Rear LHS

Condition : **Excellent**
Good Condition

LH Side Apron

Condition : **Excellent**
Good Condition

Frame or Underbody

Condition : **Excellent**
No panel Replaced

Reverse Camera & Reverse Parking Sensor

Condition : **Excellent**
Functional

Roof

Condition : **Excellent**
Good Condition

Front Windows Type

Condition : **Power Windows**
Power Windows

Front Right Window Function

Condition : **Excellent**
Smooth Operation

Front Left Window Function

Condition : **Excellent**
Smooth Operation

Rear Windows Type

Condition : **Power Windows**
Power Windows

Rear Right Window Function

Condition : **Excellent**
Smooth Operation

Rear Left Window Function

Condition : **Excellent**
Smooth Operation

Windscreen Wiper Front

Condition : **Excellent**
All speeds working properly

Windscreen Wiper Rear

Condition : **Excellent**
All speeds working properly

Windscreen Jets

Condition : **Excellent**
Good Condition

Parking Lights Front

Condition : **Excellent**
Good Condition

Parking Lights Rear

Condition : **Excellent**
Good Condition

[View this car in Website](#)

Exterior (Continued...)

Right Tail Light

Condition : **Excellent**

Good Condition

Left Tail Light

Condition : **Excellent**

Good Condition

Rear Left Indicator

Condition : **Excellent**

Good Condition

Rear Right Indicator

Condition : **Excellent**

Good Condition

Front Left Indicator

Condition : **Excellent**

Good Condition

Front Right Indicator

Condition : **Excellent**

Good Condition

Left Headlight (Both Points)

Condition : **Excellent**

Good Condition

Right Headlight (Both Points)

Condition : **Excellent**

Good Condition

Fog lamps

Condition : **Excellent**

Good Condition

Wheel Cap

Condition : **Excellent**

Not Applicable

[View this car in Website](#)

RHS Front Door Trim

Condition : **Excellent**

Good Condition

RHS Rear Door Trim

Condition : **Excellent**

Good Condition

Rubber Beading Front RHS

Condition : **Excellent**

Good Condition

Rubber Beading Rear RHS

Condition : **Excellent**

Good Condition

LHS Front Door Trim

Condition : **Excellent**

Good Condition

LHS Rear Door Trim

Condition : **Excellent**

Good Condition

Rubber Beading Front LHS

Condition : **Excellent**

Good Condition/Same Make

Rubber Beading Rear LHS

Condition : **Excellent**

Good Condition/Same Make

Carpets

Condition : **Excellent**

Good Condition

Roof Inside

Condition : **Excellent**

Good Condition

Driver Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

Driver Seat recliner

Condition : **Excellent**

Good Condition

Driver Seat Up Down

Condition : **Excellent**

Good Condition

Passenger Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

Passenger Seat recliner

Condition : **Excellent**

Good Condition

Passenger Seat Up Down

Condition : **Excellent**

Good Condition

Safety belts inertia locking system Driver Seat

Condition : **Excellent**

Good Condition

Safety belts inertia locking system Passenger

Condition : **Excellent**

Good Condition

Interior (Continued...)

Dash Board

Condition : **Excellent**

Good Condition

Sunroof System

Condition : **Excellent**

Not Applicable

Steering Mounted Controls

Condition : **Excellent**

Good Condition

Inside Rear View mirror

Condition : **Excellent**

Good Condition

Driver Seat Condition

Condition : **Excellent**

Good Condition

Passenger Seat Condition

Condition : **Excellent**

Good Condition

Rear Seat Condition

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Odometer**

Condition : **Excellent**

Good Condition

**Instrument panel Warning
Lights**

Condition : **Bad**

Warning Lights On - Bad

Instrument panel gauges: Fuel

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Tachometer**

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Temperature**

Condition : **Excellent**

Good Condition

Horn

Condition : **Excellent**

Good Condition

Combination Switch

Condition : **Excellent**

Good Condition

Stereo Controls

Condition : **Excellent**

Good Condition

Charger/USB Port

Condition : **Excellent**

Good Condition

Interior lights

Condition : **Excellent**

Good Condition

Hazard lights

Condition : **Excellent**

Good Condition

[View this car in Website](#)

Interior (Continued...)

Trunk Light

Condition : **Excellent**

Good Condition

Music System

Condition : **Excellent**

Good Condition

Music system type

Dashboard Mounted Music
Control-Buttons

Speakers

Condition : **Excellent**

Good Condition

Defogger

Condition : **Excellent**

Good Condition

Central Locking System

Condition : **Excellent**

Good Condition

**AC cooling (Check
undershade)**

Condition : **Excellent**

Good Condition

Heating

Condition : **Excellent**

Good Condition

Air distribution (AC Vents)

Condition : **Good**

Not Working 1

Recirculation/ Fresh air

Condition : **Excellent**

Good Condition

Steering Type

Power Steering

Power Steering Type

Electronic

Steering condition

Condition : **Excellent**

Good Condition

Air Bags

Condition : **Bad**

Not Functional (or warning
light glowing)

Hand Brake

Condition : **Excellent**

Working less than 4 notches

**CNG/LPG kit -
OEM/Aftermarket**

Condition : **Excellent**

Aftermarket

Jack And Tommy (Tool Kit)

Condition : **Excellent**

Available

[View this car in Website](#)

Battery

Condition : Satisfactory

Age above 3 years

Alternator

Condition : Excellent

Good Condition

Starter Motor

Condition : Excellent

Good Condition

Fuel Pump

Condition : Excellent

Good Condition

AC Compressor

Condition : Excellent

Good Condition

Condenser Fan

Condition : Excellent

Good Condition

Blower motor

Condition : Excellent

Good Condition

**Steering / Column with motor
Rattling Noise**

Condition : Excellent

Working Properly

Suspension Arms

Condition : Excellent

All rubber boot & bushing ok

Front struts (Shock Absorber)

Condition : Excellent

No Leakage & Rubber boots ok

Rear Shock Absorber/Spring

Condition : Excellent

No Leakage & Rubber boots ok

Stabiliser Bar & Other bushes

Condition : Excellent

Good Condition

Link Rods (Ball joints)

Condition : Excellent

No Noise & Rubber boots ok

ABS

Condition : Excellent

Working

Brake Pedal

Condition : Excellent

Operating Properly

Accelerator

Condition : Excellent

Working Properly

Check Front Brake Efficiency

Condition : Excellent

Operating Efficiently

Check Rear Brake Efficiency

Condition : Excellent

Operating Efficiently

Engine & Transmission (Continued...)

Master Cylinder & Booster

Condition : **Excellent**

Good Condition

**Gearshift lever
Automatic/Manual**

Condition : **Excellent**

Good Condition

Clutch Engagement

Condition : **Satisfactory**

Less than 50% life

Axle Noise

Condition : **Excellent**

No noise & Boot okay

Front Wheel bearings

Condition : **Excellent**

Good Condition

Rear Wheel bearings

Condition : **Excellent**

Good Condition

Differential

Condition : **Excellent**

Good Condition

Alignment

Condition : **Excellent**

Good Condition

Balancing

Condition : **Excellent**

Good Condition

**Transmission Oil (Manual/
Automatic)**

Condition : **Excellent**

Oil Level Condition OK

**Engine and transmission
mountings**

Condition : **Excellent**

Good Condition

Abnormal Engine Noise

Condition : **Excellent**

No Noise

Back Compression

Condition : **Excellent**

Back Compression Not Present

Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

Gasket - tappet cover

Condition : **Excellent**

Good Condition

**Engine oil leaks From
Bottom/Oil Sump**

Condition : **Excellent**

Good Condition

Silencer

Condition : **Excellent**

Good Condition

Catalytic Converter

Condition : **Excellent**

Good Condition

[View this car in Website](#)

Engine & Transmission (Continued...)

Engine Smoke Colour

Condition : **Excellent**

No colour

Air Filter

Condition : **Bad**

Not Replaced or Not Cleaned

Radiator

Condition : **Excellent**

Good Condition

Condenser

Condition : **Excellent**

Good Condition

Engine oil & Oil Filter

Condition : **Satisfactory**

Not Replaced

Coolant

Condition : **Excellent**

Good Condition

Brake Oil

Condition : **Satisfactory**

Low Fluid

Hose Pipe

Condition : **Excellent**

Good Condition

Alternator Drive Belt

Condition : **Excellent**

Good Condition

Water Pump

Condition : **Excellent**

Good Condition

Tappet Noise

Condition : **Excellent**

Working Smoothly

Turbo Charger

Condition : **Excellent**

Good Condition

Heater Plugs (in Diesel)

Condition : **Excellent**

Good Condition

Spark Plugs (in Petrol)

Condition : **Excellent**

Not Applicable

Radiator Fan

Condition : **Excellent**

Temperature Sensor Working

Ignition Coil (petrol only)

Condition : **Excellent**

Not Applicable

Ignition Wire Harness (petrol only)

Condition : **Excellent**

Not Applicable

Fuel Tank and Pipes

Condition : **Excellent**

Good Condition

[View this car in Website](#)

Engine & Transmission (Continued...)

Fuel Filter (Petrol & Diesel)

Condition : **Excellent**

Good Condition

Fuel Injectors

Condition : **Excellent**

Working Smoothly

[View this car in Website](#)

Vehicle Images

Front Side



Mar 20, 2023 12:59:54 PM

Lat 18.4998289, Long 73.9267281

Front Right Side



Mar 20, 2023 1:00:02 PM

Lat 18.4998325, Long 73.9267414

Front Right Tyre



Mar 20, 2023 12:55:40 PM

Lat 18.4998146, Long 73.9268103

Right Side



Mar 20, 2023 1:00:10 PM

Lat 18.4998515, Long 73.926795

Rear Right Tyre



Mar 20, 2023 1:00:34 PM

Lat 18.4998797, Long 73.9268161

Rear Right Side



Mar 20, 2023 1:00:20 PM

Lat 18.4998622, Long 73.926804

Back Side



Mar 20, 2023 1:00:27 PM

Lat 18.4998773, Long 73.9268142

Spare Tyre



Mar 20, 2023 1:00:48 PM

Lat 18.4998527, Long 73.9268213

[View this car in Website](#)

Rear Left Side



Mar 20, 2023 1:01:11 PM

Lat 18.4998176,Long 73.9268451

Rear Left Tyre



Mar 20, 2023 1:01:04 PM

Lat 18.4998382,Long 73.9268337

Left Side



Mar 20, 2023 1:01:40 PM

Lat 18.4998163,Long 73.9268233

Front Left Tyre



Mar 20, 2023 12:55:52 PM

Lat 18.4998155,Long 73.926777

Front Left Side



Mar 20, 2023 1:01:48 PM

Lat 18.4998262,Long 73.926791

Odometer



Mar 20, 2023 12:53:25 PM

Lat 18.4998054,Long 73.9267747

[View this car in Website](#)

Videos

Car Exterior Video

https://chnimgs3bkt.s3.amazonaws.com/autoinspekt/2023/03/20/295692863/original/1679296875380_1679296813592.m

Car Engine Video

https://chnimgs3bkt.s3.amazonaws.com/autoinspekt/2023/03/20/295692863/original/1679296979576_1679296938441.m

[View this car in Website](#)