


Mahindra First Choice Wheels Certification Report



2014 TOYOTA ETIOS(2014-2016) V

Dehradun | 70376 km | Petrol | Manual | Silver Colour | 1st Owner

- ✔ Eligible for Warranty
- ✔ 200+ Points Inspected



Overall
Fair Buy 🍀



Explore this car in website [View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

Deals On Wheels-Dehradun

Registration Month

April

Registration Year

2014

Color

Silver

Odometer Reading(km)

70376

Registration Number

UK04XXXXX

No of Owners

1

Chassis Number

MBJBXXXXXXXXXXXXXXXXXXXX

Engine Number

2NRDXXXXXX

Insurance Status

Not available

Accidental / Flooded

Non-Accidental and Non-flooded

CNG Validity Inspection Date

Not Valid

RC Status

Available

PUC Certificate

Available

Keys Availability

Two Keys Available And Both Worn Out

Transfer papers availability

Available

CNG Hydro Test Validity Certificate

Not Applicable

Vehicle Status

Certified

Remarks

ok

[View in Website](#)

Front Bumper

Condition : **Good**

Visible Repaint

Grill

Condition : **Excellent**

Good Condition

Emblem

Condition : **Excellent**

Good Condition

Windscreen glass Front

Condition : **Satisfactory**

Cracks

Bonnet

Condition : **Good**

Visible Repaint

Bonnet Functionality

Condition : **Excellent**

Good Condition

RH Side Apron

Condition : **Excellent**

Good Condition

Right Running Board

Condition : **Excellent**

Good Condition

Right Fender

Condition : **Good**

Visible Repaint

Front Right Door

Condition : **Excellent**

Good Condition

Right Front Door Functionality

Condition : **Excellent**

Good Condition

Front Right Door handle

Condition : **Excellent**

Good Condition

Front Right Window Glass

Condition : **Excellent**

Good Condition/Same Make

Rear Right Door

Condition : **Excellent**

Good Condition

Right Rear Door Functionality

Condition : **Excellent**

Good Condition

Rear Right Door handle

Condition : **Excellent**

Good Condition

Rear Right Window Glass

Condition : **Excellent**

Good Condition/Same Make

RH A Pillars

Condition : **Excellent**

Good Condition

Exterior (Continued...)

RH B Pillars

Condition : **Excellent**
Good Condition

RH C Pillars

Condition : **Excellent**
Good Condition

Right Quarter Panel

Condition : **Excellent**
Good Condition

Right Side View Mirror + Casing

Condition : **Excellent**
Good Condition

Right Side Power Mirror + Casing

Condition : **Excellent**
Good Condition

Front right tyre

Condition : **Satisfactory**
25-40%

Alloy Wheels Present?

Condition : **Yes**
Yes

Wheel Front RHS

Condition : **Excellent**
Good Condition

Rear right tyre

Condition : **Satisfactory**
25-40%

Wheel Rear RHS

Condition : **Excellent**
Good Condition

Windscreen glass Back

Condition : **Excellent**
Good Condition

Trunk

Condition : **Excellent**
Good Condition

Trunk Functionality

Condition : **Excellent**
Good Condition

Rear Bumper

Condition : **Good**
Visible Repaint

Dickey Shock absorber

Condition : **Excellent**
Good Condition

Spare tyre (stephney)

Condition : **Satisfactory**
Same Make/ Good & > 40% life

Spare Wheel / Cover

Condition : **Excellent**
Good Condition

Number Plate (Front & Rear)

Condition : **Excellent**
RTO Format

Exterior (Continued...)

LH A Pillars

Condition : **Excellent**
Good Condition

LH B Pillars

Condition : **Excellent**
Good Condition

LH C Pillars

Condition : **Excellent**
Good Condition

Left Running Board

Condition : **Excellent**
Good Condition

Left Fender

Condition : **Excellent**
Good Condition

Left Front Door

Condition : **Excellent**
Good Condition

Front Left Door Functionality

Condition : **Excellent**
Good Condition

Front Left Door handle

Condition : **Excellent**
Good Condition

Front Left Window Glass

Condition : **Excellent**
Good Condition/Same Make

Left Side View Mirror + Casing

Condition : **Excellent**
Good Condition

Left Side Power Mirror + Casing

Condition : **Excellent**
Good Condition

Rear Left Door

Condition : **Excellent**
Good Condition

Rear Left Door Functionality

Condition : **Excellent**
Good Condition

Rear Left Door handle

Condition : **Excellent**
Good Condition

Left Quarter Panel

Condition : **Excellent**
Good Condition

Rear Left Window Glass

Condition : **Excellent**
Good Condition/Same Make

Fuel Cap

Condition : **Excellent**
Working Properly

Front Left tyre

Condition : **Satisfactory**
25-40%

Exterior (Continued...)

Wheel Front LHS

Condition : **Excellent**
Good Condition

Rear Left tyre

Condition : **Satisfactory**
40%-60%

Wheel Rear LHS

Condition : **Excellent**
Good Condition

LH Side Apron

Condition : **Excellent**
Good Condition

Frame or Underbody

Condition : **Excellent**
No panel Replaced

Reverse Camera & Reverse Parking Sensor

Condition : **Excellent**
Functional

Roof

Condition : **Excellent**
Good Condition

Front Windows Type

Condition : **Power Windows**
Power Windows

Front Right Window Function

Condition : **Excellent**
Smooth Operation

Front Left Window Function

Condition : **Excellent**
Smooth Operation

Rear Windows Type

Condition : **Power Windows**
Power Windows

Rear Right Window Function

Condition : **Excellent**
Smooth Operation

Rear Left Window Function

Condition : **Excellent**
Smooth Operation

Windscreen Wiper Front

Condition : **Excellent**
All speeds working properly

Windscreen Wiper Rear

Condition : **Excellent**
All speeds working properly

Windscreen Jets

Condition : **Bad**
Not Functional

Parking Lights Front

Condition : **Bad**
Broken/missing

Parking Lights Rear

Condition : **Excellent**
Good Condition

Exterior (Continued...)

Right Tail Light

Condition : **Excellent**

Good Condition

Left Tail Light

Condition : **Bad**

Broken/Missing

Rear Left Indicator

Condition : **Excellent**

Good Condition

Rear Right Indicator

Condition : **Excellent**

Good Condition

Front Left Indicator

Condition : **Bad**

Broken/missing

Front Right Indicator

Condition : **Bad**

Broken/missing

Left Headlight (Both Points)

Condition : **Satisfactory**

Not Functional

Right Headlight (Both Points)

Condition : **Excellent**

Good Condition

Fog lamps

Condition : **Bad**

Not Working

Wheel Cap

Condition : **Excellent**

Available

RHS Front Door Trim

Condition : **Excellent**
Good Condition

RHS Rear Door Trim

Condition : **Excellent**
Good Condition

Rubber Beading Front RHS

Condition : **Excellent**
Good Condition

Rubber Beading Rear RHS

Condition : **Excellent**
Good Condition

LHS Front Door Trim

Condition : **Excellent**
Good Condition

LHS Rear Door Trim

Condition : **Excellent**
Good Condition

Rubber Beading Front LHS

Condition : **Excellent**
Good Condition/Same Make

Rubber Beading Rear LHS

Condition : **Excellent**
Good Condition/Same Make

Carpets

Condition : **Excellent**
Good Condition

Roof Inside

Condition : **Excellent**
Good Condition

Driver Seat Sliding Front to Back

Condition : **Excellent**
Good Condition

Driver Seat recliner

Condition : **Bad**
Not Functional

Driver Seat Up Down

Condition : **Bad**
Not Functional

Passenger Seat Sliding Front to Back

Condition : **Bad**
Not Functional

Passenger Seat recliner

Condition : **Bad**
Not Functional

Passenger Seat Up Down

Condition : **Bad**
Not Functional

Safety belts inertia locking system Driver Seat

Condition : **Bad**
Not Functional

Safety belts inertia locking system Passenger

Condition : **Bad**
Not Functional

Interior (Continued...)

Dash Board

Condition : **Excellent**

Good Condition

Sunroof System

Condition : **Excellent**

Not Applicable

Steering Mounted Controls

Condition : **Excellent**

Good Condition

Inside Rear View mirror

Condition : **Bad**

Deep/long Scratches

Driver Seat Condition

Condition : **Excellent**

Good Condition

Passenger Seat Condition

Condition : **Excellent**

Good Condition

Rear Seat Condition

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Odometer**

Condition : **Excellent**

Good Condition

**Instrument panel Warning
Lights**

Condition : **Excellent**

Warning Lights Off - Good

Instrument panel gauges: Fuel

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Tachometer**

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Temperature**

Condition : **Excellent**

Good Condition

Horn

Condition : **Excellent**

Good Condition

Combination Switch

Condition : **Bad**

Not Functional/Broken

Stereo Controls

Condition : **Excellent**

Good Condition

Charger/USB Port

Condition : **Bad**

Not Functional

Interior lights

Condition : **Bad**

Broken/missing

Hazard lights

Condition : **Excellent**

Good Condition

Interior (Continued...)

Trunk Light

Condition : **Bad**
Not Functional

Music System

Condition : **Bad**
Not Working

Music system type

Steering Wheel Mounted Music Control

Speakers

Condition : **Excellent**
Good Condition

Defogger

Condition : **Excellent**
Good Condition

Central Locking System

Condition : **Excellent**
Good Condition

AC cooling (Check undershade)

Condition : **Excellent**
Good Condition

Heating

Condition : **Excellent**
Good Condition

Air distribution (AC Vents)

Condition : **Excellent**
Good Condition

Recirculation/ Fresh air

Condition : **Excellent**
Good Condition

Steering Type

Manual Steering

Power Steering Type

Electronic

Steering condition

Condition : **Excellent**
Good Condition

Air Bags

Condition : **Excellent**
Functional

Hand Brake

Condition : **Excellent**
Working less than 4 notches

CNG/LPG kit - OEM/Aftermarket

Condition : **Excellent**
Aftermarket

Jack And Tommy (Tool Kit)

Condition : **Excellent**
Available

Battery

Condition : Satisfactory

Age above 3 years

Alternator

Condition : Excellent

Good Condition

Starter Motor

Condition : Excellent

Good Condition

Fuel Pump

Condition : Excellent

Good Condition

AC Compressor

Condition : Excellent

Good Condition

Condenser Fan

Condition : Excellent

Good Condition

Blower motor

Condition : Excellent

Good Condition

**Steering / Column with motor
Rattling Noise**

Condition : Excellent

Working Properly

Suspension Arms

Condition : Excellent

All rubber boot & bushing ok

Front struts (Shock Absorber)

Condition : Excellent

No Leakage & Rubber boots ok

Rear Shock Absorber/Spring

Condition : Excellent

No Leakage & Rubber boots ok

Stabiliser Bar & Other bushes

Condition : Excellent

Good Condition

Link Rods (Ball joints)

Condition : Excellent

No Noise & Rubber boots ok

ABS

Condition : Excellent

Working

Brake Pedal

Condition : Excellent

Operating Properly

Accelerator

Condition : Satisfactory

Excessive Play

Check Front Brake Efficiency

Condition : Excellent

Operating Efficiently

Check Rear Brake Efficiency

Condition : Excellent

Operating Efficiently

Engine & Transmission (Continued...)

Master Cylinder & Booster

Condition : **Excellent**

Good Condition

**Gearshift lever
Automatic/Manual**

Condition : **Satisfactory**

Excessive Play

Clutch Engagement

Condition : **Satisfactory**

Less than 50% life

Axle Noise

Condition : **Excellent**

No noise & Boot okay

Front Wheel bearings

Condition : **Excellent**

Good Condition

Rear Wheel bearings

Condition : **Excellent**

Good Condition

Differential

Condition : **Excellent**

Good Condition

Alignment

Condition : **Excellent**

Good Condition

Balancing

Condition : **Excellent**

Good Condition

**Transmission Oil (Manual/
Automatic)**

Condition : **Excellent**

Oil Level Condition OK

**Engine and transmission
mountings**

Condition : **Excellent**

Good Condition

Abnormal Engine Noise

Condition : **Excellent**

No Noise

Back Compression

Condition : **Excellent**

Back Compression Not Present

Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

Gasket - tappet cover

Condition : **Excellent**

Good Condition

**Engine oil leaks From
Bottom/Oil Sump**

Condition : **Excellent**

Good Condition

Silencer

Condition : **Excellent**

Good Condition

Catalytic Converter

Condition : **Excellent**

Good Condition

Engine & Transmission (Continued...)

Engine Smoke Colour

Condition : **Excellent**

No colour

Air Filter

Condition : **Bad**

Not Replaced or Not Cleaned

Radiator

Condition : **Excellent**

Good Condition

Condenser

Condition : **Excellent**

Good Condition

Engine oil & Oil Filter

Condition : **Satisfactory**

Not Replaced

Coolant

Condition : **Excellent**

Good Condition

Brake Oil

Condition : **Excellent**

Good Condition

Hose Pipe

Condition : **Excellent**

Good Condition

Alternator Drive Belt

Condition : **Satisfactory**

Noise

Water Pump

Condition : **Excellent**

Good Condition

Tappet Noise

Condition : **Excellent**

Working Smoothly

Turbo Charger

Condition : **Excellent**

Good Condition

Heater Plugs (in Diesel)

Condition : **Excellent**

Not Applicable

Spark Plugs (in Petrol)

Condition : **Excellent**

Good Condition

Radiator Fan

Condition : **Excellent**

Temperature Sensor Working

Ignition Coil (petrol only)

Condition : **Excellent**

Good Condition

Ignition Wire Harness (petrol only)

Condition : **Excellent**

Good Condition

Fuel Tank and Pipes

Condition : **Excellent**

Good Condition

Engine & Transmission (Continued...)

Fuel Filter (Petrol & Diesel)

Condition : **Satisfactory**

Not Cleaned

Fuel Injectors

Condition : **Excellent**

Working Smoothly

Vehicle Images

Front Side



06-Apr-2023 12:04:33 pm

Lat 30.2761963,Long 77.9892739

Front Right Side



06-Apr-2023 12:04:37 pm

Lat 30.2763461,Long 77.9892908

Front Right Tyre



06-Apr-2023 12:04:42 pm

Lat 30.2763752,Long 77.9893111

Right Side



06-Apr-2023 12:04:46 pm

Lat 30.2763899,Long 77.9891233

Rear Right Tyre



06-Apr-2023 12:04:50 pm

Lat 30.2764027,Long 77.9889322

Rear Right Side



06-Apr-2023 12:04:55 pm

Lat 30.2764045,Long 77.9889158

Back Side



06-Apr-2023 12:05:00 pm

Lat 30.2763677,Long 77.9889668

Rear Left Side



06-Apr-2023 12:05:05 pm

Lat 30.276308,Long 77.9889922

[View this car in Website](#)

Rear Left Tyre



06-Apr-2023 12:05:08 pm

Lat 30.2762404,Long 77.9889905

Left Side



06-Apr-2023 12:05:13 pm

Lat 30.2762712,Long 77.9889736

Front Left Tyre



06-Apr-2023 12:05:17 pm

Lat 30.2762664,Long 77.9890087

Front Left Side



06-Apr-2023 12:05:21 pm

Lat 30.2762629,Long 77.9890116

Odometer



06-Apr-2023 12:10:00 pm

Lat 30.2762167,Long 77.9891802

Videos

Car Exterior Video

<https://tinyurl.com/24vkpyxy>

Car Engine Video

<https://tinyurl.com/2dandug9>