


Mahindra First Choice Wheels Inspection Report



2012 HYUNDAI ELANTRA(2012-2015) 1.6 SX AT

Pathankot | 138123 km | Diesel | Automatic | Silver Colour | 2nd Owner

- ✔ Assist First Warranty
- ✔ 200+ Points Inspected



Overall
Fair Buy 🙌

M R Mahajan

M Mahajan
Head Certification
& Warranty - MFCWL

Explore this car in website [View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

J.S grover Auto Pvt Ltd

Registration Month

October

Registration Year

2012

Color

Silver

Odometer Reading(km)

138123

Registration Number

PB08XXXXXX

No of Owners

2

Chassis Number

XXXXXXXX

Engine Number

XXXXXXXX

Insurance Status

Not available

Accidental / Flooded

Non-Accidental and Non-flooded

CNG Validity Inspection Date

Not Valid

RC Status

Available

PUC Certificate

Not Available

Keys Availability

One Key Available And Good

Transfer papers availability

Available

CNG Hydro Test Validity Certificate

Not Available

Vehicle Status

Inspected

Remarks

vehicles about 10 years old

[View in Website](#)

Front Bumper

Condition : **Excellent**

Good Condition

Grill

Condition : **Excellent**

Good Condition

Emblem

Condition : **Excellent**

Good Condition

Windscreen glass Front

Condition : **Excellent**

Good Condition

Bonnet

Condition : **Excellent**

Good Condition

Bonnet Functionality

Condition : **Excellent**

Good Condition

RH Side Apron

Condition : **Excellent**

Good Condition

Right Running Board

Condition : **Excellent**

Good Condition

Right Fender

Condition : **Excellent**

Deep/long Scratches-under 2

Front Right Door

Condition : **Excellent**

Dents without paint damage-under 2

Right Front Door Functionality

Condition : **Excellent**

Good Condition

Front Right Door handle

Condition : **Excellent**

Good Condition

Front Right Window Glass

Condition : **Excellent**

Good Condition/Same Make

Rear Right Door

Condition : **Excellent**

Good Condition

Right Rear Door Functionality

Condition : **Excellent**

Good Condition

Rear Right Door handle

Condition : **Excellent**

Good Condition

Rear Right Window Glass

Condition : **Excellent**

Good Condition/Same Make

RH A Pillars

Condition : **Excellent**

Good Condition

Exterior (Continued...)

RH B Pillars

Condition : **Excellent**

Good Condition

RH C Pillars

Condition : **Excellent**

Good Condition

Right Quarter Panel

Condition : **Excellent**

Good Condition

Right Side View Mirror + Casing

Condition : **Excellent**

Good Condition

Right Side Power Mirror + Casing

Condition : **Excellent**

Good Condition

Front right tyre

Condition : **Satisfactory**

40%-60%

Alloy Wheels Present?

Condition : **Yes**

Yes

Wheel Front RHS

Condition : **Excellent**

Good Condition

Rear right tyre

Condition : **Satisfactory**

40%-60%

Wheel Rear RHS

Condition : **Excellent**

Good Condition

Windscreen glass Back

Condition : **Excellent**

Good Condition

Trunk

Condition : **Excellent**

Good Condition

Trunk Functionality

Condition : **Excellent**

Good Condition

Rear Bumper

Condition : **Excellent**

Good Condition

Dickey Shock absorber

Condition : **Excellent**

Good Condition

Spare tyre (stephney)

Condition : **Good**

Same Make/ Good & > 60% life

Spare Wheel / Cover

Condition : **Excellent**

Good Condition

Number Plate (Front & Rear)

Condition : **Excellent**

RTO Format

Exterior (Continued...)

LH A Pillars

Condition : **Excellent**
Good Condition

LH B Pillars

Condition : **Excellent**
Good Condition

LH C Pillars

Condition : **Excellent**
Good Condition

Left Running Board

Condition : **Excellent**
Good Condition

Left Fender

Condition : **Excellent**
Good Condition

Left Front Door

Condition : **Excellent**
Good Condition

Front Left Door Functionality

Condition : **Excellent**
Good Condition

Front Left Door handle

Condition : **Excellent**
Good Condition

Front Left Window Glass

Condition : **Excellent**
Good Condition/Same Make

Left Side View Mirror + Casing

Condition : **Excellent**
Good Condition

Left Side Power Mirror + Casing

Condition : **Excellent**
Good Condition

Rear Left Door

Condition : **Excellent**
Good Condition

Rear Left Door Functionality

Condition : **Excellent**
Good Condition

Rear Left Door handle

Condition : **Excellent**
Good Condition

Left Quarter Panel

Condition : **Excellent**
Good Condition

Rear Left Window Glass

Condition : **Excellent**
Good Condition/Same Make

Fuel Cap

Condition : **Excellent**
Working Properly

Front Left tyre

Condition : **Satisfactory**
40%-60%

Exterior (Continued...)

Wheel Front LHS

Condition : **Excellent**

Good Condition

Rear Left tyre

Condition : **Satisfactory**

40%-60%

Wheel Rear LHS

Condition : **Excellent**

Good Condition

LH Side Apron

Condition : **Excellent**

Good Condition

Frame or Underbody

Condition : **Excellent**

No panel Replaced

Reverse Camera & Reverse Parking Sensor

Condition : **Excellent**

Not Applicable

Roof

Condition : **Excellent**

Good Condition

Front Windows Type

Condition : **Power Windows**

Power Windows

Front Right Window Function

Condition : **Excellent**

Smooth Operation

Front Left Window Function

Condition : **Excellent**

Smooth Operation

Rear Windows Type

Condition : **Power Windows**

Power Windows

Rear Right Window Function

Condition : **Excellent**

Smooth Operation

Rear Left Window Function

Condition : **Excellent**

Smooth Operation

Windscreen Wiper Front

Condition : **Excellent**

All speeds working properly

Windscreen Wiper Rear

Condition : **Excellent**

Not Applicable

Windscreen Jets

Condition : **Excellent**

Good Condition

Parking Lights Front

Condition : **Excellent**

Good Condition

Parking Lights Rear

Condition : **Excellent**

Good Condition

Exterior (Continued...)

Right Tail Light

Condition : **Excellent**

Good Condition

Left Tail Light

Condition : **Excellent**

Good Condition

Rear Left Indicator

Condition : **Excellent**

Good Condition

Rear Right Indicator

Condition : **Excellent**

Good Condition

Front Left Indicator

Condition : **Excellent**

Good Condition

Front Right Indicator

Condition : **Excellent**

Good Condition

Left Headlight (Both Points)

Condition : **Excellent**

Good Condition

Right Headlight (Both Points)

Condition : **Excellent**

Good Condition

Fog lamps

Condition : **Excellent**

Good Condition

Wheel Cap

Condition : **Excellent**

Available

RHS Front Door Trim

Condition : **Excellent**
Good Condition

RHS Rear Door Trim

Condition : **Excellent**
Good Condition

Rubber Beading Front RHS

Condition : **Excellent**
Good Condition

Rubber Beading Rear RHS

Condition : **Excellent**
Good Condition

LHS Front Door Trim

Condition : **Excellent**
Good Condition

LHS Rear Door Trim

Condition : **Excellent**
Good Condition

Rubber Beading Front LHS

Condition : **Excellent**
Good Condition/Same Make

Rubber Beading Rear LHS

Condition : **Excellent**
Good Condition/Same Make

Carpets

Condition : **Excellent**
Good Condition

Roof Inside

Condition : **Excellent**
Good Condition

Driver Seat Sliding Front to Back

Condition : **Excellent**
Good Condition

Driver Seat recliner

Condition : **Excellent**
Good Condition

Driver Seat Up Down

Condition : **Excellent**
Good Condition

Passenger Seat Sliding Front to Back

Condition : **Excellent**
Good Condition

Passenger Seat recliner

Condition : **Excellent**
Good Condition

Passenger Seat Up Down

Condition : **Excellent**
Good Condition

Safety belts inertia locking system Driver Seat

Condition : **Excellent**
Good Condition

Safety belts inertia locking system Passenger

Condition : **Excellent**
Good Condition

Interior (Continued...)

Dash Board

Condition : **Excellent**

Good Condition

Sunroof System

Condition : **Excellent**

Not Applicable

Steering Mounted Controls

Condition : **Excellent**

Good Condition

Inside Rear View mirror

Condition : **Excellent**

Good Condition

Driver Seat Condition

Condition : **Excellent**

Good Condition

Passenger Seat Condition

Condition : **Excellent**

Good Condition

Rear Seat Condition

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Odometer**

Condition : **Excellent**

Good Condition

**Instrument panel Warning
Lights**

Condition : **Excellent**

Warning Lights Off - Good

Instrument panel gauges: Fuel

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Tachometer**

Condition : **Excellent**

Good Condition

**Instrument panel gauges:
Temperature**

Condition : **Excellent**

Good Condition

Horn

Condition : **Excellent**

Good Condition

Combination Switch

Condition : **Excellent**

Good Condition

Stereo Controls

Condition : **Excellent**

Good Condition

Charger/USB Port

Condition : **Excellent**

Good Condition

Interior lights

Condition : **Excellent**

Good Condition

Hazard lights

Condition : **Excellent**

Good Condition

Interior (Continued...)

Trunk Light

Condition : **Excellent**
Good Condition

Music System

Condition : **Excellent**
Good Condition

Music system type

Steering Wheel Mounted Music Control

Speakers

Condition : **Excellent**
Good Condition

Defogger

Condition : **Excellent**
Good Condition

Central Locking System

Condition : **Excellent**
Good Condition

AC cooling (Check undershade)

Condition : **Excellent**
Good Condition

Heating

Condition : **Excellent**
Good Condition

Air distribution (AC Vents)

Condition : **Excellent**
Good Condition

Recirculation/ Fresh air

Condition : **Excellent**
Good Condition

Steering Type

Power Steering

Power Steering Type

Electronic

Steering condition

Condition : **Excellent**
Good Condition

Air Bags

Condition : **Excellent**
Functional

Hand Brake

Condition : **Excellent**
Working less than 4 notches

CNG/LPG kit - OEM/Aftermarket

Condition : **Excellent**
Aftermarket

Jack And Tommy (Tool Kit)

Condition : **Excellent**
Available

Battery

Condition : **Excellent**
Good Condition

Alternator

Condition : **Excellent**
Good Condition

Starter Motor

Condition : **Excellent**
Good Condition

Fuel Pump

Condition : **Excellent**
Good Condition

AC Compressor

Condition : **Excellent**
Good Condition

Condenser Fan

Condition : **Excellent**
Good Condition

Blower motor

Condition : **Excellent**
Good Condition

**Steering / Column with motor
Rattling Noise**

Condition : **Excellent**
Working Properly

Suspension Arms

Condition : **Excellent**
All rubber boot & bushing ok

Front struts (Shock Absorber)

Condition : **Excellent**
No Leakage & Rubber boots ok

Rear Shock Absorber/Spring

Condition : **Excellent**
No Leakage & Rubber boots ok

Stabiliser Bar & Other bushes

Condition : **Excellent**
Good Condition

Link Rods (Ball joints)

Condition : **Excellent**
No Noise & Rubber boots ok

ABS

Condition : **Excellent**
Working

Brake Pedal

Condition : **Excellent**
Operating Properly

Accelerator

Condition : **Excellent**
Working Properly

Check Front Brake Efficiency

Condition : **Excellent**
Operating Efficiently

Check Rear Brake Efficiency

Condition : **Excellent**
Operating Efficiently

Engine & Transmission (Continued...)

Master Cylinder & Booster

Condition : **Excellent**

Good Condition

**Gearshift lever
Automatic/Manual**

Condition : **Excellent**

Good Condition

Clutch Engagement

Condition : **Excellent**

More than 50% life

Axle Noise

Condition : **Excellent**

No noise & Boot okay

Front Wheel bearings

Condition : **Excellent**

Good Condition

Rear Wheel bearings

Condition : **Excellent**

Good Condition

Differential

Condition : **Excellent**

Good Condition

Alignment

Condition : **Excellent**

Good Condition

Balancing

Condition : **Excellent**

Good Condition

**Transmission Oil (Manual/
Automatic)**

Condition : **Excellent**

Oil Level Condition OK

**Engine and transmission
mountings**

Condition : **Excellent**

Good Condition

Abnormal Engine Noise

Condition : **Excellent**

No Noise

Back Compression

Condition : **Excellent**

Back Compression Not Present

Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

Gasket - tappet cover

Condition : **Excellent**

Good Condition

**Engine oil leaks From
Bottom/Oil Sump**

Condition : **Excellent**

Good Condition

Silencer

Condition : **Excellent**

Good Condition

Catalytic Converter

Condition : **Excellent**

Good Condition

Engine & Transmission (Continued...)

Engine Smoke Colour

Condition : **Excellent**

No colour

Air Filter

Condition : **Excellent**

Cleaned/Replaced

Radiator

Condition : **Excellent**

Good Condition

Condenser

Condition : **Excellent**

Good Condition

Engine oil & Oil Filter

Condition : **Excellent**

Good Condition

Coolant

Condition : **Excellent**

Good Condition

Brake Oil

Condition : **Excellent**

Good Condition

Hose Pipe

Condition : **Excellent**

Good Condition

Alternator Drive Belt

Condition : **Excellent**

Good Condition

Water Pump

Condition : **Excellent**

Good Condition

Tappet Noise

Condition : **Excellent**

Working Smoothly

Turbo Charger

Condition : **Excellent**

Good Condition

Heater Plugs (in Diesel)

Condition : **Excellent**

Good Condition

Spark Plugs (in Petrol)

Condition : **Excellent**

Not Applicable

Radiator Fan

Condition : **Excellent**

Temperature Sensor Working

Ignition Coil (petrol only)

Condition : **Excellent**

Not Applicable

Ignition Wire Harness (petrol only)

Condition : **Excellent**

Not Applicable

Fuel Tank and Pipes

Condition : **Excellent**

Good Condition

Engine & Transmission (Continued...)

Fuel Filter (Petrol & Diesel)

Condition : **Excellent**

Good Condition

Fuel Injectors

Condition : **Excellent**

Working Smoothly

Vehicle Images

Front Side



Apr 8, 2023 13:44:22

Lat 32.2730775, Long 75.6733012

Front Right Side



Apr 8, 2023 13:44:31

Lat 32.2728494, Long 75.6730981

Front Right Tyre



Apr 8, 2023 13:44:50

Lat 32.2728045, Long 75.6732749

Right Side



Apr 8, 2023 13:44:41

Lat 32.2728814, Long 75.6732022

Rear Right Tyre



Apr 8, 2023 13:44:56

Lat 32.2728386, Long 75.6732106

Rear Right Side



Apr 8, 2023 13:45:04

Lat 32.2728716, Long 75.6732655

Back Side



Apr 8, 2023 13:45:13

Lat 32.2728381, Long 75.6732212

Rear Left Side



Apr 8, 2023 13:45:21

Lat 32.2728349, Long 75.6732132

[View this car in Website](#)

Rear Left Tyre



Apr 8, 2023 13:45:38
GPS - 32.272812 , 75.673195

Apr 8, 2023 13:45:38

Lat 32.2728115,Long 75.6731949

Left Side



Apr 8, 2023 13:45:30

Lat 32.2728246,Long 75.6731979

Front Left Tyre



Apr 8, 2023 13:46:04
GPS - 32.272858 , 75.673199

Apr 8, 2023 13:46:04

Lat 32.2728577,Long 75.6731994

Front Left Side



Apr 8, 2023 13:46:12

Lat 32.2727854,Long 75.6730573

Odometer



Apr 8, 2023 13:48:01
GPS - 32.27278 , 75.673112

Apr 8, 2023 13:48:01

Lat 32.2727802,Long 75.6731119

Videos

Car Exterior Video

<https://www.carandbike.com/AUTOIN/2810600>

Car Engine Video

<https://www.carandbike.com/AUTOIN/528fb22>