

Mahindra First Choice Wheels Certification Report



2015 MAHINDRA SCORPIO(2014-2017) S4

West Champaran | 57205 km | Diesel | Manual | White Colour | 2nd Owner

✓ Eligible for Warranty ✓ 200+ Points InspectedOverall
Fair Buy 🍏Exterior FairInterior FairEngine & Transmission Fair
M Mahajan
Head Certification
& Warranty - MFCWL[Explore this car in website](#)[View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

Sonakshi Automobiles

Registration Month

November

Registration Year

2015

Color

White

Odometer Reading(km)

57205

Registration Number

BR07XXXXXX

No of Owners

2

Chassis Number

MAITXXXXXXXXXXXXX

Engine Number

SJF4XXXXXX

Insurance Status

Not available

Insurance Type

Company

Accidental / Flooded

Non-Accidental and Non-flooded

CNG Validity Inspection Date

Not Applicable

RC Status

Available

PUC Certificate

Not Available

Keys Availability

One Key Available And Good

Transfer papers availability

Available

CNG Hydro Test Validity Certificate

Not Applicable

Vehicle Status

Certified

Remarks

ok

[View in Website](#)

<div>Front Bumper</div> <div>Condition : Excellent</div> <div>Good Condition</div>	<div>Grill</div> <div>Condition : Excellent</div> <div>Good Condition</div>	<div>Emblem</div> <div>Condition : Excellent</div> <div>Good Condition</div>
<div>Windscreen glass Front</div> <div>Condition : Excellent</div> <div>Good Condition</div>	<div>Bonnet</div> <div>Condition : Excellent</div> <div>Good Condition</div>	<div>Bonnet Functionality</div> <div>Condition : Excellent</div> <div>Good Condition</div>
<div>RH Side Apron</div> <div>Condition : Excellent</div> <div>Good Condition</div>	<div>Right Running Board</div> <div>Condition : Excellent</div> <div>Good Condition</div>	<div>Right Fender</div> <div>Condition : Excellent</div> <div>Good Condition</div>
<div>Front Right Door</div> <div>Condition : Excellent</div> <div>Good Condition</div>	<div>Right Front Door Functionality</div> <div>Condition : Excellent</div> <div>Good Condition</div>	<div>Front Right Door handle</div> <div>Condition : Excellent</div> <div>Good Condition</div>
<div>Front Right Window Glass</div> <div>Condition : Excellent</div> <div>Good Condition/Same Make</div>	<div>Rear Right Door</div> <div>Condition : Excellent</div> <div>Good Condition</div>	<div>Right Rear Door Functionality</div> <div>Condition : Excellent</div> <div>Good Condition</div>
<div>Rear Right Door handle</div> <div>Condition : Excellent</div> <div>Good Condition</div>	<div>Rear Right Window Glass</div> <div>Condition : Excellent</div> <div>Good Condition/Same Make</div>	<div>RH A Pillars</div> <div>Condition : Excellent</div> <div>Good Condition</div>

Exterior (Continued...)

RH B Pillars

Condition : **Excellent**

Good Condition

RH C Pillars

Condition : **Excellent**

Good Condition

Right Quarter Panel

Condition : **Excellent**

Good Condition

Right Side View Mirror + Casing

Condition : **Excellent**

Good Condition

Right Side Power Mirror + Casing

Condition : **Excellent**

Good Condition

Front right tyre

Condition : **Satisfactory**

40%-60%

Alloy Wheels Present?

Condition : **No**

No

Wheel Front RHS

Condition : **Excellent**

Good Condition

Rear right tyre

Condition : **Satisfactory**

40%-60%

Wheel Rear RHS

Condition : **Excellent**

Good Condition

Windscreen glass Back

Condition : **Excellent**

Good Condition

Trunk

Condition : **Excellent**

Good Condition

Trunk Functionality

Condition : **Excellent**

Good Condition

Rear Bumper

Condition : **Excellent**

Good Condition

Dickey Shock absorber

Condition : **Excellent**

Good Condition

Spare tyre (stephney)

Condition : **Bad**

Not Applicable

Spare Wheel / Cover

Condition : **Excellent**

Not Applicable

Number Plate (Front & Rear)

Condition : **Excellent**

RTO Format

Exterior (Continued...)

LH A Pillars

Condition : **Excellent**

Good Condition

LH B Pillars

Condition : **Excellent**

Good Condition

LH C Pillars

Condition : **Excellent**

Good Condition

Left Running Board

Condition : **Excellent**

Good Condition

Left Fender

Condition : **Excellent**

Good Condition

Left Front Door

Condition : **Excellent**

Good Condition

Front Left Door Functionality

Condition : **Excellent**

Good Condition

Front Left Door handle

Condition : **Excellent**

Good Condition

Front Left Window Glass

Condition : **Excellent**

Good Condition/Same Make

Left Side View Mirror + Casing

Condition : **Excellent**

Good Condition

Left Side Power Mirror + Casing

Condition : **Excellent**

Good Condition

Rear Left Door

Condition : **Excellent**

Good Condition

Rear Left Door Functionality

Condition : **Excellent**

Good Condition

Rear Left Door handle

Condition : **Excellent**

Good Condition

Left Quarter Panel

Condition : **Excellent**

Good Condition

Rear Left Window Glass

Condition : **Excellent**

Good Condition/Same Make

Fuel Cap

Condition : **Excellent**

Working Properly

Front Left tyre

Condition : **Satisfactory**

40%-60%

Exterior (Continued...)

Wheel Front LHS

Condition : **Excellent**

Good Condition

Rear Left tyre

Condition : **Satisfactory**

40%-60%

Wheel Rear LHS

Condition : **Excellent**

Good Condition

LH Side Apron

Condition : **Excellent**

Good Condition

Frame or Underbody

Condition : **Excellent**

No panel Replaced

Reverse Camera & Reverse Parking Sensor

Condition : **Excellent**

Not Applicable

Roof

Condition : **Excellent**

Good Condition

Front Windows Type

Condition : **Power Windows**

Power Windows

Front Right Window Function

Condition : **Excellent**

Smooth Operation

Front Left Window Function

Condition : **Excellent**

Smooth Operation

Rear Windows Type

Condition : **Power Windows**

Power Windows

Rear Right Window Function

Condition : **Excellent**

Smooth Operation

Rear Left Window Function

Condition : **Excellent**

Smooth Operation

Windscreen Wiper Front

Condition : **Excellent**

All speeds working properly

Windscreen Wiper Rear

Condition : **Excellent**

Not Applicable

Windscreen Jets

Condition : **Excellent**

Good Condition

Parking Lights Front

Condition : **Excellent**

Good Condition

Parking Lights Rear

Condition : **Excellent**

Good Condition

Exterior (Continued...)

Right Tail Light

Condition : **Excellent**

Good Condition

Left Tail Light

Condition : **Excellent**

Good Condition

Rear Left Indicator

Condition : **Excellent**

Good Condition

Rear Right Indicator

Condition : **Excellent**

Good Condition

Front Left Indicator

Condition : **Excellent**

Good Condition

Front Right Indicator

Condition : **Excellent**

Good Condition

Left Headlight (Both Points)

Condition : **Excellent**

Good Condition

Right Headlight (Both Points)

Condition : **Excellent**

Good Condition

Fog lamps

Condition : **Excellent**

Good Condition

Wheel Cap

Condition : **Excellent**

Available

RHS Front Door Trim

Condition : Excellent

Good Condition

RHS Rear Door Trim

Condition : Excellent

Good Condition

Rubber Beading Front RHS

Condition : Excellent

Good Condition

Rubber Beading Rear RHS

Condition : Excellent

Good Condition

LHS Front Door Trim

Condition : Excellent

Good Condition

LHS Rear Door Trim

Condition : Excellent

Good Condition

Rubber Beading Front LHS

Condition : Excellent

Good Condition/Same Make

Rubber Beading Rear LHS

Condition : Excellent

Good Condition/Same Make

Carpets

Condition : Excellent

Good Condition

Roof Inside

Condition : Excellent

Good Condition

Driver Seat Sliding Front to Back

Condition : Excellent

Good Condition

Driver Seat recliner

Condition : Excellent

Good Condition

Driver Seat Up Down

Condition : Excellent

Good Condition

Passenger Seat Sliding Front to Back

Condition : Excellent

Good Condition

Passenger Seat recliner

Condition : Excellent

Good Condition

Passenger Seat Up Down

Condition : Excellent

Good Condition

Safety belts inertia locking system Driver Seat

Condition : Excellent

Good Condition

Safety belts inertia locking system Passenger

Condition : Excellent

Good Condition

Interior (Continued...)

Dash Board

Condition : **Excellent**

Good Condition

Sunroof System

Condition : **Excellent**

Not Applicable

Steering Mounted Controls

Condition : **Excellent**

Not Applicable

Inside Rear View mirror

Condition : **Excellent**

Good Condition

Driver Seat Condition

Condition : **Excellent**

Good Condition

Passenger Seat Condition

Condition : **Excellent**

Good Condition

Rear Seat Condition

Condition : **Excellent**

Good Condition

Instrument panel gauges: Odometer

Condition : **Excellent**

Good Condition

Instrument panel Warning Lights

Condition : **Excellent**

Warning Lights Off - Good

Instrument panel gauges: Fuel

Condition : **Excellent**

Good Condition

Instrument panel gauges: Tachometer

Condition : **Excellent**

Good Condition

Instrument panel gauges: Temperature

Condition : **Excellent**

Good Condition

Horn

Condition : **Excellent**

Good Condition

Combination Switch

Condition : **Excellent**

Good Condition

Stereo Controls

Condition : **Excellent**

Good Condition

Charger/USB Port

Condition : **Excellent**

Good Condition

Interior lights

Condition : **Excellent**

Good Condition

Hazard lights

Condition : **Excellent**

Good Condition

Interior (Continued...)

Trunk Light

Condition : **Excellent**

Good Condition

Music System

Condition : **Excellent**

Good Condition

Music system type

Dashboard Mounted Music
Control-Buttons

Speakers

Condition : **Excellent**

Good Condition

Defogger

Condition : **Excellent**

Not Applicable

Central Locking System

Condition : **Excellent**

Good Condition

AC cooling (Check undershade)

Condition : **Excellent**

Good Condition

Heating

Condition : **Excellent**

Good Condition

Air distribution (AC Vents)

Condition : **Excellent**

Good Condition

Recirculation/ Fresh air

Condition : **Excellent**

Good Condition

Steering Type

Power Steering

Power Steering Type

Hydraulic

Steering condition

Condition : **Satisfactory**

Noise

Air Bags

Condition : **Excellent**

Not Applicable

Hand Brake

Condition : **Excellent**

Working less than 4 notches

CNG/LPG kit - OEM/Aftermarket

Condition : **Excellent**

Not Applicable

Jack And Tommy (Tool Kit)

Condition : **Excellent**

Available

<div><div>Battery</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Alternator</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Starter Motor</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Fuel Pump</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>AC Compressor</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Condenser Fan</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Blower motor</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Steering / Column with motor Rattling Noise</div><div>Condition : Excellent</div><div>Working Properly</div></div>	<div><div>Suspension Arms</div><div>Condition : Excellent</div><div>All rubber boot & bushing ok</div></div>
<div><div>Front struts (Shock Absorber)</div><div>Condition : Excellent</div><div>No Leakage & Rubber boots ok</div></div>	<div><div>Rear Shock Absorber/Spring</div><div>Condition : Excellent</div><div>No Leakage & Rubber boots ok</div></div>	<div><div>Stabiliser Bar & Other bushes</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Link Rods (Ball joints)</div><div>Condition : Excellent</div><div>No Noise & Rubber boots ok</div></div>	<div><div>ABS</div><div>Condition : Excellent</div><div>Not Applicable</div></div>	<div><div>Brake Pedal</div><div>Condition : Excellent</div><div>Operating Properly</div></div>
<div><div>Accelerator</div><div>Condition : Excellent</div><div>Working Properly</div></div>	<div><div>Check Front Brake Efficiency</div><div>Condition : Excellent</div><div>Operating Efficiently</div></div>	<div><div>Check Rear Brake Efficiency</div><div>Condition : Excellent</div><div>Operating Efficiently</div></div>

Engine & Transmission (Continued...)

Master Cylinder & Booster

Condition : **Excellent**

Good Condition

Gearshift lever Automatic/Manual

Condition : **Excellent**

Good Condition

Clutch Engagement

Condition : **Excellent**

More than 50% life

Axle Noise

Condition : **Excellent**

No noise & Boot okay

Front Wheel bearings

Condition : **Excellent**

Good Condition

Rear Wheel bearings

Condition : **Excellent**

Good Condition

Differential

Condition : **Excellent**

Good Condition

Alignment

Condition : **Excellent**

Good Condition

Balancing

Condition : **Excellent**

Good Condition

Transmission Oil (Manual/ Automatic)

Condition : **Excellent**

Oil Level Condition OK

Engine and transmission mountings

Condition : **Excellent**

Good Condition

Abnormal Engine Noise

Condition : **Excellent**

No Noise

Back Compression

Condition : **Excellent**

Back Compression Not Present

Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

Gasket - tappet cover

Condition : **Excellent**

Good Condition

Engine oil leaks From Bottom/Oil Sump

Condition : **Excellent**

Good Condition

Silencer

Condition : **Excellent**

Good Condition

Catalytic Converter

Condition : **Excellent**

Good Condition

Engine & Transmission (Continued...)

Engine Smoke Colour

Condition : **Excellent**

No colour

Air Filter

Condition : **Excellent**

Cleaned/Replaced

Radiator

Condition : **Excellent**

Good Condition

Condenser

Condition : **Excellent**

Good Condition

Engine oil & Oil Filter

Condition : **Excellent**

Good Condition

Coolant

Condition : **Excellent**

Good Condition

Brake Oil

Condition : **Excellent**

Good Condition

Hose Pipe

Condition : **Excellent**

Good Condition

Alternator Drive Belt

Condition : **Satisfactory**

Noise

Water Pump

Condition : **Excellent**

Good Condition

Tappet Noise

Condition : **Excellent**

Working Smoothly

Turbo Charger

Condition : **Excellent**

Good Condition

Heater Plugs (in Diesel)

Condition : **Excellent**

Good Condition

Spark Plugs (in Petrol)

Condition : **Excellent**

Not Applicable

Radiator Fan

Condition : **Excellent**

Temperature Sensor Working

Ignition Coil (petrol only)

Condition : **Excellent**

Not Applicable

Ignition Wire Harness (petrol only)

Condition : **Excellent**

Not Applicable

Fuel Tank and Pipes

Condition : **Excellent**

Good Condition

Fuel Filter (Petrol & Diesel)
Condition : **Excellent**
Good Condition

Fuel Injectors
Condition : **Excellent**
Working Smoothly

Vehicle Images

Front Side



May 4, 2023 4:37:21 PM

Lat 26.9777829,Long 84.843441

Front Right Side



May 4, 2023 4:37:27 PM

Lat 26.9778034,Long 84.8435019

Front Right Tyre



May 4, 2023 4:37:33 PM

Lat 26.9777815,Long 84.8434862

Right Side



May 4, 2023 4:37:50 PM

Lat 26.9777839,Long 84.8434718

Rear Right Tyre



May 4, 2023 4:37:57 PM

Lat 26.9778008,Long 84.84346

Rear Right Side



May 4, 2023 4:38:03 PM

Lat 26.9777737,Long 84.8434737

Back Side



May 4, 2023 4:38:08 PM

Lat 26.9777787,Long 84.8434733

Rear Left Side



May 4, 2023 4:38:55 PM

Lat 26.9777925,Long 84.8435136

[View this car in Website](#)

Rear Left Tyre



May 4, 2023 4:39:03 PM Lat 26.9778053,Long 84.84352

Left Side



May 4, 2023 4:38:40 PM Lat 26.9777836,Long 84.8434702

Front Left Tyre



May 4, 2023 4:39:09 PM Lat 26.9778066,Long 84.8435164

Front Left Side



May 4, 2023 4:39:15 PM Lat 26.977782,Long 84.8435007

Odometer



May 4, 2023 4:31:31 PM Lat 26.9774587,Long 84.8435975

Videos

Car Exterior Video

<https://tinyurl.com/2om9nebb>

Car Engine Video

<https://tinyurl.com/2n84hs2x>