

## Mahindra First Choice Wheels Certification Report

**2018 MARUTI SUZUKI ALTO K10(2015-2019) VXI**

Udham Singh Nagar | 42729 km | Petrol | Manual | Others Colour | 1st Owner

✅ Eligible for Warranty ✅ 200+ Points InspectedExterior FairInterior FairEngine & Transmission Fair

Overall

**Excellent Buy** 🚗



M Mahajan  
Head Certification  
& Warranty - MFCWL

[Explore this car in website](#)[View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

## Vehicle Details

Owner Name

**Naveen Enterprises**

Registration Month

**September**

Registration Year

**2018**

Color

**Others**

Odometer Reading(km)

**42729**

Registration Number

**UP21XXXXXX**

No of Owners

**1**

Chassis Number

**MA3EXXXXXXXXXXXXX**

Engine Number

**K10BXXXXXXXXXX**

Insurance Status

**Not available**

Accidental / Flooded

**Non-Accidental and Non-flooded**

CNG Validity Inspection Date

**Not Valid**

RC Status

**Available**

PUC Certificate

**Available**

Keys Availability

**One Key Available And Worn Out**

Transfer papers availability

**Available**

CNG Hydro Test Validity Certificate

**Not Applicable**

Vehicle Status

**Certified**

Remarks

**ok**

[View in Website](#)

<div><div>Front Bumper</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Grill</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Emblem</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Windscreen glass Front</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Bonnet</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Bonnet Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>RH Side Apron</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Running Board</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Fender</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Front Right Door</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Front Door Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Front Right Door handle</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Front Right Window Glass</div><div>Condition : Excellent</div><div>Deep/long Scratches-1</div></div>	<div><div>Rear Right Door</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Rear Door Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Rear Right Door handle</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Rear Right Window Glass</div><div>Condition : Excellent</div><div>Good Condition/Same Make</div></div>	<div><div>RH A Pillars</div><div>Condition : Excellent</div><div>Good Condition</div></div>

Exterior (Continued...)

**RH B Pillars**

Condition : **Excellent**

Good Condition

**RH C Pillars**

Condition : **Excellent**

Good Condition

**Right Quarter Panel**

Condition : **Excellent**

Good Condition

**Right Side View Mirror + Casing**

Condition : **Excellent**

Good Condition

**Right Side Power Mirror + Casing**

Condition : **Excellent**

Good Condition

**Front right tyre**

Condition : **Satisfactory**

25-40%

**Alloy Wheels Present?**

Condition : **Yes**

Yes

**Wheel Front RHS**

Condition : **Excellent**

Good Condition

**Rear right tyre**

Condition : **Satisfactory**

40%-60%

**Wheel Rear RHS**

Condition : **Excellent**

Good Condition

**Windscreen glass Back**

Condition : **Excellent**

Good Condition

**Trunk**

Condition : **Excellent**

Good Condition

**Trunk Functionality**

Condition : **Excellent**

Good Condition

**Rear Bumper**

Condition : **Excellent**

Good Condition

**Dickey Shock absorber**

Condition : **Excellent**

Good Condition

**Spare tyre (stephney)**

Condition : **Satisfactory**

Same Make/ Good & > 40% life

**Spare Wheel / Cover**

Condition : **Excellent**

Good Condition

**Number Plate (Front & Rear)**

Condition : **Excellent**

RTO Format

Exterior (Continued...)

**LH A Pillars**

Condition : **Excellent**

Good Condition

**LH B Pillars**

Condition : **Excellent**

Good Condition

**LH C Pillars**

Condition : **Excellent**

Good Condition

**Left Running Board**

Condition : **Excellent**

Good Condition

**Left Fender**

Condition : **Excellent**

Good Condition

**Left Front Door**

Condition : **Excellent**

Good Condition

**Front Left Door Functionality**

Condition : **Excellent**

Good Condition

**Front Left Door handle**

Condition : **Excellent**

Good Condition

**Front Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Left Side View Mirror + Casing**

Condition : **Excellent**

Good Condition

**Left Side Power Mirror + Casing**

Condition : **Excellent**

Good Condition

**Rear Left Door**

Condition : **Excellent**

Good Condition

**Rear Left Door Functionality**

Condition : **Excellent**

Good Condition

**Rear Left Door handle**

Condition : **Excellent**

Good Condition

**Left Quarter Panel**

Condition : **Excellent**

Good Condition

**Rear Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Fuel Cap**

Condition : **Excellent**

Working Properly

**Front Left tyre**

Condition : **Satisfactory**

40%-60%

## Exterior (Continued...)

### Wheel Front LHS

Condition : **Excellent**

Good Condition

### Rear Left tyre

Condition : **Satisfactory**

40%-60%

### Wheel Rear LHS

Condition : **Excellent**

Good Condition

### LH Side Apron

Condition : **Excellent**

Good Condition

### Frame or Underbody

Condition : **Excellent**

No panel Replaced

### Reverse Camera & Reverse Parking Sensor

Condition : **Excellent**

Functional

### Roof

Condition : **Excellent**

Good Condition

### Front Windows Type

Condition : **Power Windows**

Power Windows

### Front Right Window Function

Condition : **Excellent**

Smooth Operation

### Front Left Window Function

Condition : **Excellent**

Smooth Operation

### Rear Windows Type

Condition : **Power Windows**

Power Windows

### Rear Right Window Function

Condition : **Excellent**

Smooth Operation

### Rear Left Window Function

Condition : **Excellent**

Smooth Operation

### Windscreen Wiper Front

Condition : **Excellent**

All speeds working properly

### Windscreen Wiper Rear

Condition : **Excellent**

All speeds working properly

### Windscreen Jets

Condition : **Excellent**

Good Condition

### Parking Lights Front

Condition : **Excellent**

Good Condition

### Parking Lights Rear

Condition : **Excellent**

Good Condition

Exterior (Continued...)

**Right Tail Light**  
Condition : **Excellent**  
Good Condition

**Left Tail Light**  
Condition : **Excellent**  
Good Condition

**Rear Left Indicator**  
Condition : **Excellent**  
Good Condition

**Rear Right Indicator**  
Condition : **Excellent**  
Good Condition

**Front Left Indicator**  
Condition : **Excellent**  
Good Condition

**Front Right Indicator**  
Condition : **Excellent**  
Good Condition

**Left Headlight (Both Points)**  
Condition : **Excellent**  
Good Condition

**Right Headlight (Both Points)**  
Condition : **Excellent**  
Good Condition

**Fog lamps**  
Condition : **Excellent**  
Good Condition

**Wheel Cap**  
Condition : **Excellent**  
Not Applicable

**RHS Front Door Trim**

Condition : **Excellent**

Good Condition

**RHS Rear Door Trim**

Condition : **Excellent**

Good Condition

**Rubber Beading Front RHS**

Condition : **Excellent**

Good Condition

**Rubber Beading Rear RHS**

Condition : **Excellent**

Good Condition

**LHS Front Door Trim**

Condition : **Excellent**

Good Condition

**LHS Rear Door Trim**

Condition : **Excellent**

Good Condition

**Rubber Beading Front LHS**

Condition : **Excellent**

Good Condition/Same Make

**Rubber Beading Rear LHS**

Condition : **Excellent**

Good Condition/Same Make

**Carpets**

Condition : **Satisfactory**

Unclean

**Roof Inside**

Condition : **Satisfactory**

Unclean

**Driver Seat Sliding Front to Back**

Condition : **Excellent**

Good Condition

**Driver Seat recliner**

Condition : **Excellent**

Good Condition

**Driver Seat Up Down**

Condition : **Bad**

Not Functional

**Passenger Seat Sliding Front to Back**

Condition : **Excellent**

Good Condition

**Passenger Seat recliner**

Condition : **Excellent**

Good Condition

**Passenger Seat Up Down**

Condition : **Bad**

Not Functional

**Safety belts inertia locking system Driver Seat**

Condition : **Excellent**

Good Condition

**Safety belts inertia locking system Passenger**

Condition : **Excellent**

Good Condition



## Interior (Continued...)

### Dash Board

Condition : **Excellent**

Good Condition

### Sunroof System

Condition : **Excellent**

Not Applicable

### Steering Mounted Controls

Condition : **Excellent**

Not Applicable

### Inside Rear View mirror

Condition : **Excellent**

Good Condition

### Driver Seat Condition

Condition : **Excellent**

Good Condition

### Passenger Seat Condition

Condition : **Excellent**

Good Condition

### Rear Seat Condition

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Odometer

Condition : **Excellent**

Good Condition

### Instrument panel Warning Lights

Condition : **Excellent**

Warning Lights Off - Good

### Instrument panel gauges: Fuel

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Tachometer

Condition : **Excellent**

Good Condition

### Instrument panel gauges: Temperature

Condition : **Excellent**

Good Condition

### Horn

Condition : **Bad**

Not Working

### Combination Switch

Condition : **Excellent**

Good Condition

### Stereo Controls

Condition : **Excellent**

Good Condition

### Charger/USB Port

Condition : **Excellent**

Good Condition

### Interior lights

Condition : **Excellent**

Good Condition

### Hazard lights

Condition : **Excellent**

Good Condition

## Interior (Continued...)

### Trunk Light

Condition : **Excellent**

Good Condition

### Music System

Condition : **Excellent**

Good Condition

### Music system type

Steering Wheel Mounted Music Control

### Speakers

Condition : **Excellent**

Good Condition

### Defogger

Condition : **Excellent**

Good Condition

### Central Locking System

Condition : **Excellent**

Good Condition

### AC cooling (Check undershade)

Condition : **Excellent**

Good Condition

### Heating

Condition : **Excellent**

Good Condition

### Air distribution (AC Vents)

Condition : **Excellent**

Good Condition

### Recirculation/ Fresh air

Condition : **Excellent**

Good Condition

### Steering Type

Manual Steering

### Power Steering Type

Electronic

### Steering condition

Condition : **Excellent**

Good Condition

### Air Bags

Condition : **Excellent**

Not Applicable

### Hand Brake

Condition : **Excellent**

Working less than 4 notches

### CNG/LPG kit - OEM/Aftermarket

Condition : **Excellent**

Aftermarket

### Jack And Tommy (Tool Kit)

Condition : **Excellent**

Available

<div><div>Battery</div><div>Condition : Satisfactory</div><div>Age above 3 years</div></div>	<div><div>Alternator</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Starter Motor</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Fuel Pump</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>AC Compressor</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Condenser Fan</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Blower motor</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Steering / Column with motor Rattling Noise</div><div>Condition : Excellent</div><div>Working Properly</div></div>	<div><div>Suspension Arms</div><div>Condition : Excellent</div><div>All rubber boot &amp; bushing ok</div></div>
<div><div>Front struts (Shock Absorber)</div><div>Condition : Excellent</div><div>No Leakage &amp; Rubber boots ok</div></div>	<div><div>Rear Shock Absorber/Spring</div><div>Condition : Excellent</div><div>No Leakage &amp; Rubber boots ok</div></div>	<div><div>Stabiliser Bar &amp; Other bushes</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Link Rods (Ball joints)</div><div>Condition : Excellent</div><div>No Noise &amp; Rubber boots ok</div></div>	<div><div>ABS</div><div>Condition : Excellent</div><div>Not Applicable</div></div>	<div><div>Brake Pedal</div><div>Condition : Excellent</div><div>Operating Properly</div></div>
<div><div>Accelerator</div><div>Condition : Excellent</div><div>Working Properly</div></div>	<div><div>Check Front Brake Efficiency</div><div>Condition : Excellent</div><div>Operating Efficiently</div></div>	<div><div>Check Rear Brake Efficiency</div><div>Condition : Excellent</div><div>Operating Efficiently</div></div>

## Engine & Transmission (Continued...)

### Master Cylinder & Booster

Condition : **Excellent**

Good Condition

### Gearshift lever Automatic/Manual

Condition : **Satisfactory**

Excessive Play

### Clutch Engagement

Condition : **Satisfactory**

Less than 50% life

### Axle Noise

Condition : **Bad**

Noise

### Front Wheel bearings

Condition : **Satisfactory**

Noise

### Rear Wheel bearings

Condition : **Excellent**

Good Condition

### Differential

Condition : **Excellent**

Good Condition

### Alignment

Condition : **Excellent**

Good Condition

### Balancing

Condition : **Excellent**

Good Condition

### Transmission Oil (Manual/ Automatic)

Condition : **Excellent**

Oil Level Condition OK

### Engine and transmission mountings

Condition : **Excellent**

Good Condition

### Abnormal Engine Noise

Condition : **Excellent**

No Noise

### Back Compression

Condition : **Excellent**

Back Compression Not Present

### Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

### Gasket - tappet cover

Condition : **Excellent**

Good Condition

### Engine oil leaks From Bottom/Oil Sump

Condition : **Excellent**

Good Condition

### Silencer

Condition : **Excellent**

Good Condition

### Catalytic Converter

Condition : **Excellent**

Good Condition

## Engine & Transmission (Continued...)

### Engine Smoke Colour

Condition : **Excellent**

No colour

### Air Filter

Condition : **Bad**

Not Replaced or Not Cleaned

### Radiator

Condition : **Excellent**

Good Condition

### Condenser

Condition : **Excellent**

Good Condition

### Engine oil & Oil Filter

Condition : **Satisfactory**

Not Replaced

### Coolant

Condition : **Excellent**

Good Condition

### Brake Oil

Condition : **Excellent**

Good Condition

### Hose Pipe

Condition : **Excellent**

Good Condition

### Alternator Drive Belt

Condition : **Excellent**

Good Condition

### Water Pump

Condition : **Excellent**

Good Condition

### Tappet Noise

Condition : **Excellent**

Working Smoothly

### Turbo Charger

Condition : **Excellent**

Not Applicable

### Heater Plugs (in Diesel)

Condition : **Excellent**

Not Applicable

### Spark Plugs (in Petrol)

Condition : **Excellent**

Good Condition

### Radiator Fan

Condition : **Excellent**

Temperature Sensor Working

### Ignition Coil (petrol only)

Condition : **Excellent**

Good Condition

### Ignition Wire Harness (petrol only)

Condition : **Excellent**

Good Condition

### Fuel Tank and Pipes

Condition : **Excellent**

Good Condition

**Fuel Filter (Petrol & Diesel)**

Condition : **Bad**

Not Cleaned

**Fuel Injectors**

Condition : **Excellent**

Working Smoothly

## Vehicle Images

### Front Side



16-May-2023 2:22:28 pm

Lat 29.15214,Long 79.142164

### Front Right Side



16-May-2023 2:22:37 pm

Lat 29.1521375,Long 79.1421577

### Front Right Tyre



16-May-2023 2:22:41 pm

Lat 29.1521363,Long 79.1421593

### Right Side



16-May-2023 2:22:46 pm

Lat 29.1521362,Long 79.1421571

### Rear Right Tyre



16-May-2023 2:22:50 pm

Lat 29.1521433,Long 79.1421582

### Rear Right Side



16-May-2023 2:22:55 pm

Lat 29.152131,Long 79.1421585

### Back Side



16-May-2023 2:22:59 pm

Lat 29.1517942,Long 79.1418533

### Rear Left Side



16-May-2023 2:23:04 pm

Lat 29.1519408,Long 79.1419794

[View this car in Website](#)



Rear Left Tyre



16-May-2023 2:23:07 pm

Lat 29.1520558,Long 79.1420826

Front Left Tyre



16-May-2023 2:23:17 pm

Lat 29.1521174,Long 79.1421379

Odometer



16-May-2023 2:24:42 pm

Lat 29.1521403,Long 79.1421597

Left Side



16-May-2023 2:23:12 pm

Lat 29.1521159,Long 79.142135

Front Left Side



16-May-2023 2:23:21 pm

Lat 29.1521209,Long 79.1421428



## Videos

Car Exterior Video

<https://tinyurl.com/22lzhdb0>

Car Engine Video

<https://tinyurl.com/22u4fdse>

[View this car in Website](#)