

## Mahindra First Choice Wheels Certification Report

**2018 MARUTI SUZUKI ALTO 800(2016-2019) VXI**

Krishnagiri | 41682 km | Petrol | Manual | Blue Colour | 1st Owner

✔ Eligible for Warranty ✔ 200+ Points InspectedExterior FairInterior FairEngine & Transmission Fair

Overall  
**Excellent Buy** 🚗



*M R Mahajan*  
M Mahajan  
Head Certification  
& Warranty - MFCWL

[Explore this car in website](#)[View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

## Vehicle Details

Owner Name

**Green Emerald Cars**

Registration Month

**January**

Registration Year

**2018**

Color

**Blue**

Odometer Reading(km)

**41682**

Registration Number

**TN70XXXXX**

No of Owners

**1**

Chassis Number

**MA3EXXXXXXXXXXXXXX**

Engine Number

**F8DNXXXXXXXXX**

Insurance Status

**Available**

Insurance Type

**Company**

Accidental / Flooded

**Non-Accidental and Non-flooded**

CNG Validity Inspection Date

**Not Valid**

RC Status

**Available**

PUC Certificate

**Available**

Keys Availability

**Both Keys Available And Good**

Transfer papers availability

**Available**

CNG Hydro Test Validity Certificate

**Not Applicable**

Vehicle Status

**Certified**

Remarks

**ok**

[View in Website](#)

<div><div>Front Bumper</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Grill</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Emblem</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Windscreen glass Front</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Bonnet</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Bonnet Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>RH Side Apron</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Running Board</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Fender</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Front Right Door</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Front Door Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Front Right Door handle</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Front Right Window Glass</div><div>Condition : Excellent</div><div>Good Condition/Same Make</div></div>	<div><div>Rear Right Door</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Rear Door Functionality</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Rear Right Door handle</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Rear Right Window Glass</div><div>Condition : Excellent</div><div>Good Condition/Same Make</div></div>	<div><div>RH A Pillars</div><div>Condition : Excellent</div><div>Good Condition</div></div>

Exterior (Continued...)

**RH B Pillars**

Condition : **Excellent**

Good Condition

**RH C Pillars**

Condition : **Excellent**

Good Condition

**Right Quarter Panel**

Condition : **Excellent**

Good Condition

**Right Side View Mirror + Casing**

Condition : **Excellent**

Good Condition

**Right Side Power Mirror + Casing**

Condition : **Excellent**

Good Condition

**Front right tyre**

Condition : **Good**

60%-80%

**Steel Wheel Rim Front RHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Front RHS**

Condition : **Excellent**

Not Applicable

**Rear right tyre**

Condition : **Good**

60%-80%

**Steel Wheel Rim Rear RHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Rear RHS**

Condition : **Excellent**

Not Applicable

**Windscreen glass Back**

Condition : **Excellent**

Good Condition

**Trunk**

Condition : **Excellent**

Good Condition

**Trunk Functionality**

Condition : **Excellent**

Good Condition

**Rear Bumper**

Condition : **Excellent**

Good Condition

**Dickey Shock absorber**

Condition : **Excellent**

Good Condition

**Spare tyre (stephney)**

Condition : **Good**

Same Make/ Good & > 60% life

**Spare Wheel / Cover**

Condition : **Excellent**

Good Condition

Exterior (Continued...)

**Number Plate (Front & Rear)**

Condition : **Excellent**

RTO Format

**LH A Pillars**

Condition : **Excellent**

Good Condition

**LH B Pillars**

Condition : **Excellent**

Good Condition

**LH C Pillars**

Condition : **Excellent**

Good Condition

**Left Running Board**

Condition : **Excellent**

Good Condition

**Left Fender**

Condition : **Excellent**

Good Condition

**Left Front Door**

Condition : **Excellent**

Good Condition

**Front Left Door Functionality**

Condition : **Excellent**

Good Condition

**Front Left Door handle**

Condition : **Excellent**

Good Condition

**Front Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Left Side View Mirror + Casing**

Condition : **Excellent**

Good Condition

**Left Side Power Mirror + Casing**

Condition : **Excellent**

Good Condition

**Rear Left Door**

Condition : **Excellent**

Good Condition

**Rear Left Door Functionality**

Condition : **Excellent**

Good Condition

**Rear Left Door handle**

Condition : **Excellent**

Good Condition

**Left Quarter Panel**

Condition : **Excellent**

Good Condition

**Rear Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Fuel Cap**

Condition : **Excellent**

Working Properly

Exterior (Continued...)

**Front Left tyre**

Condition : **Good**

60%-80%

**Steel Wheel Rim Front LHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Front LHS**

Condition : **Excellent**

Not Applicable

**Rear Left tyre**

Condition : **Good**

60%-80%

**Steel Wheel Rim Rear LHS**

Condition : **Excellent**

Good Condition

**Alloy Wheels Rear LHS**

Condition : **Excellent**

Not Applicable

**LH Side Apron**

Condition : **Excellent**

Good Condition

**Frame or Underbody**

Condition : **Excellent**

No panel Replaced

**Reverse Camera & Reverse  
Parking Sensor**

Condition : **Excellent**

Functional

**Roof**

Condition : **Excellent**

Good Condition

**Windscreen Wiper Front**

Condition : **Excellent**

All speeds working properly

**Windscreen Wiper Rear**

Condition : **Excellent**

Not Applicable

**Windscreen Jets**

Condition : **Excellent**

Good Condition

**Parking Lights Front**

Condition : **Excellent**

Good Condition

**Parking Lights Rear**

Condition : **Excellent**

Good Condition

**Right Tail Light**

Condition : **Excellent**

Good Condition

**Left Tail Light**

Condition : **Excellent**

Good Condition

**Rear Left Indicator**

Condition : **Excellent**

Good Condition

Exterior (Continued...)

<div><div>Rear Right Indicator</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Front Left Indicator</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Front Right Indicator</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Left Headlight (Both Points)</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Right Headlight (Both Points)</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Fog lamps</div><div>Condition : Bad</div><div>Not Working</div></div>
<div><div>Wheel Cap</div><div>Condition : Excellent</div><div>Available</div></div>		

Interior Rating - Fair

61 Good 0 Issues

<div><div>RHS Front Door Trim</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>RHS Rear Door Trim</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>Rubber Beading Front RHS</div><div>Condition : Excellent</div><div>Good Condition</div></div>
<div><div>Rubber Beading Rear RHS</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>LHS Front Door Trim</div><div>Condition : Excellent</div><div>Good Condition</div></div>	<div><div>LHS Rear Door Trim</div><div>Condition : Excellent</div><div>Good Condition</div></div>

## Interior (Continued...)

### Rubber Beading Front LHS

Condition : **Excellent**

Good Condition/Same Make

### Rubber Beading Rear LHS

Condition : **Excellent**

Good Condition/Same Make

### Carpets

Condition : **Excellent**

Good Condition

### Roof Inside

Condition : **Excellent**

Good Condition

### Driver Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

### Driver Seat recliner

Condition : **Excellent**

Good Condition

### Driver Seat Up Down

Condition : **Excellent**

Good Condition

### Passenger Seat Sliding Front to Back

Condition : **Excellent**

Good Condition

### Passenger Seat recliner

Condition : **Excellent**

Good Condition

### Passenger Seat Up Down

Condition : **Excellent**

Good Condition

### Safety belts inertia locking system Driver Seat

Condition : **Excellent**

Good Condition

### Safety belts inertia locking system Passenger

Condition : **Excellent**

Good Condition

### Dash Board

Condition : **Excellent**

Good Condition

### Sunroof System

Condition : **Excellent**

Not Applicable

### Front Right Window Type

Power Windows

### Front Right Window Function

Condition : **Excellent**

Smooth Operation

### Front Left Window Type

Power Windows

### Front Left Window Function

Condition : **Excellent**

Smooth Operation



**Rear Right Window Type**

Manual Windows

**Rear Right Window Function**

Condition : **Excellent**

Smooth Operation

**Rear Left Window Type**

Manual Windows

**Rear Left Window Function**

Condition : **Excellent**

Smooth Operation

**Steering Mounted Controls**

Condition : **Excellent**

Good Condition

**Inside Rear View mirror**

Condition : **Excellent**

Good Condition

**Driver Seat Condition**

Condition : **Excellent**

Good Condition

**Passenger Seat Condition**

Condition : **Excellent**

Good Condition

**Rear Seat Condition**

Condition : **Excellent**

Good Condition

**Instrument panel gauges:  
Odometer**

Condition : **Excellent**

Good Condition

**Instrument panel Warning  
Lights**

Condition : **Excellent**

Warning Lights Off - Good

**Instrument panel gauges: Fuel**

Condition : **Excellent**

Good Condition

**Instrument panel gauges:  
Tachometer**

Condition : **Excellent**

Good Condition

**Instrument panel gauges:  
Temperature**

Condition : **Excellent**

Good Condition

**Horn**

Condition : **Excellent**

Good Condition

**Combination Switch**

Condition : **Excellent**

Good Condition

**Stereo Controls**

Condition : **Excellent**

Good Condition

**Charger/USB Port**

Condition : **Excellent**

Good Condition

## Interior (Continued...)

### Interior lights

Condition : **Excellent**

Good Condition

### Hazard lights

Condition : **Excellent**

Good Condition

### Trunk Light

Condition : **Excellent**

Good Condition

### Music System

Condition : **Excellent**

Good Condition

### Music system type

Dashboard Mounted Music  
Control-Touch Screen

### Speakers

Condition : **Excellent**

Good Condition

### Defogger

Condition : **Excellent**

Not Applicable

### Central Locking System

Condition : **Excellent**

Good Condition

### AC cooling (Check undershade)

Condition : **Excellent**

Good Condition

### Heating

Condition : **Excellent**

Good Condition

### Air distribution (AC Vents)

Condition : **Excellent**

Good Condition

### Recirculation/ Fresh air

Condition : **Excellent**

Good Condition

### Steering Type

Power Steering

### Power Steering Type

Electronic

### Steering condition

Condition : **Excellent**

Good Condition

### Air Bags

Condition : **Excellent**

Functional

### Hand Brake

Condition : **Excellent**

Working less than 4 notches

### CNG/LPG kit - OEM/Aftermarket

Condition : **Excellent**

No

**Jack And Tommy (Tool Kit)**  
Condition : Excellent  
Available

Engine & Transmission Rating - Fair

56 Good

0 Issues

**Battery**  
Condition : Excellent  
Good Condition

**Alternator**  
Condition : Excellent  
Good Condition

**Starter Motor**  
Condition : Excellent  
Good Condition

**Fuel Pump**  
Condition : Excellent  
Good Condition

**AC Compressor**  
Condition : Excellent  
Good Condition

**Condenser Fan**  
Condition : Excellent  
Good Condition

**Blower motor**  
Condition : Excellent  
Good Condition

**Steering / Column with motor  
Rattling Noise**  
Condition : Excellent  
Working Properly

**Suspension Arms**  
Condition : Excellent  
All rubber boot & bushing ok

**Front struts (Shock Absorber)**  
Condition : Excellent  
No Leakage & Rubber boots ok

**Rear Shock Absorber/Spring**  
Condition : Excellent  
No Leakage & Rubber boots ok

**Stabiliser Bar & Other bushes**  
Condition : Excellent  
Good Condition

## Engine & Transmission (Continued...)

### Link Rods (Ball joints)

Condition : **Excellent**

No Noise & Rubber boots ok

### ABS

Condition : **Excellent**

Not Applicable

### Brake Pedal

Condition : **Excellent**

Operating Properly

### Accelerator

Condition : **Excellent**

Working Properly

### Check Front Brake Efficiency

Condition : **Excellent**

Operating Efficiently

### Check Rear Brake Efficiency

Condition : **Excellent**

Operating Efficiently

### Master Cylinder & Booster

Condition : **Excellent**

Good Condition

### Gearshift lever Automatic/Manual

Condition : **Excellent**

Good Condition

### Clutch Engagement

Condition : **Excellent**

More than 50% life

### Axle Noise

Condition : **Excellent**

No noise & Boot okay

### Front Wheel bearings

Condition : **Excellent**

Good Condition

### Rear Wheel bearings

Condition : **Excellent**

Good Condition

### Differential

Condition : **Excellent**

Good Condition

### Alignment

Condition : **Excellent**

Good Condition

### Balancing

Condition : **Excellent**

Good Condition

### Transmission Oil (Manual/ Automatic)

Condition : **Excellent**

Oil Level Condition OK

### Engine and transmission mountings

Condition : **Excellent**

Good Condition

### Abnormal Engine Noise

Condition : **Excellent**

No Noise

## Engine & Transmission (Continued...)

### Back Compression

Condition : **Excellent**

Back Compression Not Present

### Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

### Gasket - tappet cover

Condition : **Excellent**

Good Condition

### Engine oil leaks From Bottom/Oil Sump

Condition : **Excellent**

Good Condition

### Silencer

Condition : **Excellent**

Good Condition

### Catalytic Converter

Condition : **Excellent**

Good Condition

### Engine Smoke Colour

Condition : **Excellent**

No colour

### Air Filter

Condition : **Excellent**

Cleaned/Replaced

### Radiator

Condition : **Excellent**

Good Condition

### Condenser

Condition : **Excellent**

Good Condition

### Engine oil & Oil Filter

Condition : **Excellent**

Good Condition

### Coolant

Condition : **Excellent**

Good Condition

### Brake Oil

Condition : **Excellent**

Good Condition

### Hose Pipe

Condition : **Excellent**

Good Condition

### Alternator Drive Belt

Condition : **Excellent**

Good Condition

### Water Pump

Condition : **Excellent**

Good Condition

### Tappet Noise

Condition : **Excellent**

Working Smoothly

### Turbo Charger

Condition : **Excellent**

Not Applicable

**Heater Plugs (in Diesel)**  
Condition : **Excellent**  
Not Applicable

**Spark Plugs (in Petrol)**  
Condition : **Excellent**  
Good Condition

**Radiator Fan**  
Condition : **Excellent**  
Temperature Sensor Working

**Ignition Coil (petrol only)**  
Condition : **Excellent**  
Good Condition

**Ignition Wire Harness (petrol only)**  
Condition : **Excellent**  
Good Condition

**Fuel Tank and Pipes**  
Condition : **Excellent**  
Good Condition

**Fuel Filter (Petrol & Diesel)**  
Condition : **Excellent**  
Good Condition

**Fuel Injectors**  
Condition : **Excellent**  
Working Smoothly

## Vehicle Images

### Front Side



01-Dec-2022 3:20:54 pm

Lat 12.7117958,Long 77.889422

### Front Right Side



01-Dec-2022 3:21:10 pm

Lat 12.7117968,Long 77.8894238

### Front Right Tyre



01-Dec-2022 3:21:16 pm

Lat 12.7117953,Long 77.8894252

### Right Side



01-Dec-2022 3:21:27 pm

Lat 12.7117948,Long 77.8894244

### Rear Right Tyre



01-Dec-2022 3:21:35 pm

Lat 12.7117945,Long 77.8894232

### Rear Right Side



01-Dec-2022 3:21:43 pm

Lat 12.7117948,Long 77.8894245

### Back Side



01-Dec-2022 3:21:51 pm

Lat 12.7117894,Long 77.889422

### Rear Left Side



01-Dec-2022 3:21:59 pm

Lat 12.7117942,Long 77.8894245

[View this car in Website](#)



Rear Left Tyre



01-Dec-2022 3:22:17 pm

Lat 12.7117984,Long 77.8894213

Left Side



01-Dec-2022 3:22:08 pm

Lat 12.7117957,Long 77.8894244

Front Left Tyre



01-Dec-2022 3:22:27 pm

Lat 12.7117967,Long 77.8894199

Front Left Side



01-Dec-2022 3:22:45 pm

Lat 12.7117881,Long 77.8894263

Odometer



01-Dec-2022 3:24:08 pm

Lat 12.7117884,Long 77.8894225



## Videos

Car Exterior Video

<https://tinyurl.com/2e39r773>

Car Engine Video

<https://tinyurl.com/2gm5um43>