


### Mahindra First Choice Wheels Certification Report



## 2017 HYUNDAI I20 ACTIVE(2015-2018) 1.2 SX

Pudukkottai | 68891 km | Petrol | Manual | White Colour | 1st Owner

- ✔ Eligible for Warranty
- ✔ 200+ Points Inspected



Overall  
**Excellent Buy** 🙌

**VERIFIED**  
M. Mahajan  
Head Certification & Warranty - MFCWL

[Explore this car in website](#)

[View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

## Vehicle Details

Owner Name

**Chandramathy Motors**

Registration Month

**April**

Registration Year

**2017**

Color

**White**

Odometer Reading(km)

**68891**

Registration Number

**TN22XXXXXX**

No of Owners

**1**

Chassis Number

**MALMXXXXXXXXXXXXXXXXXX**

Engine Number

**G4LAXXXXXXXXXX**

Insurance Status

**Available**

Insurance Type

**Company**

Accidental / Flooded

**Non-Accidental and Non-flooded**

CNG Validity Inspection Date

**Not Valid**

RC Status

**Available**

PUC Certificate

**Available**

Keys Availability

**Both Keys Available And Good**

Transfer papers availability

**Available**

CNG Hydro Test Validity Certificate

**Not Applicable**

Vehicle Status

**Certified**

Remarks

**General service required**

[View in Website](#)

**Front Bumper**

Condition : **Excellent**

Good Condition

**Grill**

Condition : **Excellent**

Good Condition

**Emblem**

Condition : **Excellent**

Good Condition

**Windscreen glass Front**

Condition : **Excellent**

Good Condition

**Bonnet**

Condition : **Good**

Replaced - Not Original

**Bonnet Functionality**

Condition : **Excellent**

Good Condition

**RH Side Apron**

Condition : **Excellent**

Good Condition

**Right Running Board**

Condition : **Excellent**

Good Condition

**Right Fender**

Condition : **Excellent**

Good Condition

**Front Right Door**

Condition : **Excellent**

Good Condition

**Right Front Door Functionality**

Condition : **Excellent**

Good Condition

**Front Right Door handle**

Condition : **Excellent**

Good Condition

**Front Right Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Rear Right Door**

Condition : **Excellent**

Good Condition

**Right Rear Door Functionality**

Condition : **Excellent**

Good Condition

**Rear Right Door handle**

Condition : **Excellent**

Good Condition

**Rear Right Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**RH A Pillars**

Condition : **Excellent**

Good Condition

Exterior (Continued...)

**RH B Pillars**

Condition : **Excellent**

Good Condition

**RH C Pillars**

Condition : **Excellent**

Good Condition

**Right Quarter Panel**

Condition : **Excellent**

Good Condition

**Right Side View Mirror + Casing**

Condition : **Excellent**

Good Condition

**Right Side Power Mirror + Casing**

Condition : **Excellent**

Good Condition

**Front right tyre**

Condition : **Satisfactory**

40%-60%

**Steel Wheel Rim Front RHS**

Condition : **Excellent**

Not Applicable

**Alloy Wheels Front RHS**

Condition : **Excellent**

Good Condition

**Rear right tyre**

Condition : **Satisfactory**

40%-60%

**Steel Wheel Rim Rear RHS**

Condition : **Excellent**

Not Applicable

**Alloy Wheels Rear RHS**

Condition : **Excellent**

Good Condition

**Windscreen glass Back**

Condition : **Excellent**

Good Condition

**Trunk**

Condition : **Excellent**

Good Condition

**Trunk Functionality**

Condition : **Excellent**

Good Condition

**Rear Bumper**

Condition : **Excellent**

Good Condition

**Dickey Shock absorber**

Condition : **Excellent**

Good Condition

**Spare tyre (stephney)**

Condition : **Good**

Same Make/ Good & > 60% life

**Spare Wheel / Cover**

Condition : **Excellent**

Not Applicable

Exterior (Continued...)

**Number Plate (Front & Rear)**

Condition : **Excellent**

RTO Format

**LH A Pillars**

Condition : **Excellent**

Good Condition

**LH B Pillars**

Condition : **Excellent**

Good Condition

**LH C Pillars**

Condition : **Excellent**

Good Condition

**Left Running Board**

Condition : **Excellent**

Good Condition

**Left Fender**

Condition : **Excellent**

Good Condition

**Left Front Door**

Condition : **Excellent**

Good Condition

**Front Left Door Functionality**

Condition : **Excellent**

Good Condition

**Front Left Door handle**

Condition : **Excellent**

Good Condition

**Front Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Left Side View Mirror + Casing**

Condition : **Excellent**

Good Condition

**Left Side Power Mirror + Casing**

Condition : **Excellent**

Good Condition

**Rear Left Door**

Condition : **Excellent**

Good Condition

**Rear Left Door Functionality**

Condition : **Excellent**

Good Condition

**Rear Left Door handle**

Condition : **Excellent**

Good Condition

**Left Quarter Panel**

Condition : **Excellent**

Good Condition

**Rear Left Window Glass**

Condition : **Excellent**

Good Condition/Same Make

**Fuel Cap**

Condition : **Excellent**

Working Properly

Exterior (Continued...)

**Front Left tyre**

Condition : **Satisfactory**

40%-60%

**Steel Wheel Rim Front LHS**

Condition : **Excellent**

Not Applicable

**Alloy Wheels Front LHS**

Condition : **Excellent**

Good Condition

**Rear Left tyre**

Condition : **Good**

60%-80%

**Steel Wheel Rim Rear LHS**

Condition : **Excellent**

Not Applicable

**Alloy Wheels Rear LHS**

Condition : **Excellent**

Good Condition

**LH Side Apron**

Condition : **Excellent**

Good Condition

**Frame or Underbody**

Condition : **Excellent**

No panel Replaced

**Reverse Camera & Reverse Parking Sensor**

Condition : **Excellent**

Functional

**Roof**

Condition : **Excellent**

Good Condition

**Windscreen Wiper Front**

Condition : **Excellent**

All speeds working properly

**Windscreen Wiper Rear**

Condition : **Excellent**

All speeds working properly

**Windscreen Jets**

Condition : **Excellent**

Good Condition

**Parking Lights Front**

Condition : **Excellent**

Good Condition

**Parking Lights Rear**

Condition : **Excellent**

Good Condition

**Right Tail Light**

Condition : **Excellent**

Good Condition

**Left Tail Light**

Condition : **Excellent**

Good Condition

**Rear Left Indicator**

Condition : **Excellent**

Good Condition

Exterior (Continued...)

**Rear Right Indicator**

Condition : **Excellent**

Good Condition

**Front Left Indicator**

Condition : **Excellent**

Good Condition

**Front Right Indicator**

Condition : **Excellent**

Good Condition

**Left Headlight (Both Points)**

Condition : **Excellent**

Good Condition

**Right Headlight (Both Points)**

Condition : **Excellent**

Good Condition

**Fog lamps**

Condition : **Excellent**



Good Condition

**Wheel Cap**

Condition : **Excellent**

Not Applicable

Interior Rating - **Fair**

 61 Good  0 Issues

**RHS Front Door Trim**

Condition : **Excellent**

Good Condition

**RHS Rear Door Trim**

Condition : **Excellent**

Good Condition

**Rubber Beading Front RHS**

Condition : **Excellent**

Good Condition

**Rubber Beading Rear RHS**

Condition : **Excellent**

Good Condition

**LHS Front Door Trim**

Condition : **Excellent**

Good Condition

**LHS Rear Door Trim**

Condition : **Excellent**

Good Condition

Interior (Continued...)

**Rubber Beading Front LHS**

Condition : **Excellent**

Good Condition/Same Make

**Rubber Beading Rear LHS**

Condition : **Excellent**

Good Condition/Same Make

**Carpets**

Condition : **Excellent**

Good Condition

**Roof Inside**

Condition : **Excellent**

Good Condition

**Driver Seat Sliding Front to Back**

Condition : **Excellent**

Good Condition

**Driver Seat recliner**

Condition : **Excellent**

Good Condition

**Driver Seat Up Down**

Condition : **Excellent**

Good Condition

**Passenger Seat Sliding Front to Back**

Condition : **Excellent**

Good Condition

**Passenger Seat recliner**

Condition : **Excellent**

Good Condition

**Passenger Seat Up Down**

Condition : **Excellent**

Good Condition

**Safety belts inertia locking system Driver Seat**

Condition : **Excellent**

Good Condition

**Safety belts inertia locking system Passenger**

Condition : **Excellent**

Good Condition

**Dash Board**

Condition : **Excellent**

Good Condition

**Sunroof System**

Condition : **Excellent**

Not Applicable

**Front Right Window Type**

Power Windows

**Front Right Window Function**

Condition : **Excellent**

Smooth Operation

**Front Left Window Type**

Power Windows

**Front Left Window Function**

Condition : **Excellent**

Smooth Operation

Interior (Continued...)

**Rear Right Window Type**

Power Windows

**Rear Right Window Function**

Condition : **Excellent**  
Smooth Operation

**Rear Left Window Type**

Power Windows

**Rear Left Window Function**

Condition : **Excellent**  
Smooth Operation

**Steering Mounted Controls**

Condition : **Excellent**  
Good Condition

**Inside Rear View mirror**

Condition : **Excellent**  
Good Condition

**Driver Seat Condition**

Condition : **Excellent**  
Good Condition

**Passenger Seat Condition**

Condition : **Excellent**  
Good Condition

**Rear Seat Condition**

Condition : **Excellent**  
Good Condition

**Instrument panel gauges:  
Odometer**

Condition : **Excellent**  
Good Condition

**Instrument panel Warning  
Lights**

Condition : **Excellent**  
Warning Lights Off - Good

**Instrument panel gauges: Fuel**

Condition : **Excellent**  
Good Condition

**Instrument panel gauges:  
Tachometer**

Condition : **Excellent**  
Good Condition

**Instrument panel gauges:  
Temperature**

Condition : **Excellent**  
Good Condition

**Horn**

Condition : **Excellent**  
Good Condition

**Combination Switch**

Condition : **Excellent**  
Good Condition

**Stereo Controls**

Condition : **Excellent**  
Good Condition

**Charger/USB Port**

Condition : **Excellent**  
Good Condition

Interior (Continued...)

**Interior lights**

Condition : **Excellent**  
Good Condition

**Hazard lights**

Condition : **Excellent**  
Good Condition

**Trunk Light**

Condition : **Excellent**  
Good Condition

**Music System**

Condition : **Excellent**  
Good Condition

**Music system type**

Dashboard Mounted Music  
Control-Buttons

**Speakers**

Condition : **Excellent**  
Good Condition

**Defogger**

Condition : **Excellent**  
Good Condition

**Central Locking System**

Condition : **Excellent**  
Good Condition

**AC cooling (Check  
undershade)**

Condition : **Excellent**  
Good Condition

**Heating**

Condition : **Excellent**  
Good Condition

**Air distribution (AC Vents)**

Condition : **Excellent**  
Good Condition

**Recirculation/ Fresh air**

Condition : **Excellent**  
Good Condition

**Steering Type**

Power Steering

**Power Steering Type**

Electronic

**Steering condition**

Condition : **Excellent**  
Good Condition

**Air Bags**

Condition : **Excellent**  
Functional

**Hand Brake**

Condition : **Excellent**  
Working less than 4 notches

**CNG/LPG kit -  
OEM/Aftermarket**

Condition : **Excellent**  
No

Interior (Continued...)

**Jack And Tommy (Tool Kit)**

Condition : **Excellent**

Available

**Engine & Transmission Rating - Excellent**

 55 Good

 1 Issues

**Battery**

Condition : **Excellent**

Good Condition

**Alternator**

Condition : **Excellent**

Good Condition

**Starter Motor**

Condition : **Excellent**

Good Condition

**Fuel Pump**

Condition : **Excellent**

Good Condition

**AC Compressor**

Condition : **Excellent**

Good Condition

**Condenser Fan**

Condition : **Excellent**

Good Condition

**Blower motor**

Condition : **Excellent**

Good Condition

**Steering / Column with motor  
Rattling Noise**

Condition : **Excellent**

Working Properly

**Suspension Arms**

Condition : **Excellent**

All rubber boot & bushing ok

**Front struts (Shock Absorber)**

Condition : **Excellent**

No Leakage & Rubber boots ok

**Rear Shock Absorber/Spring**

Condition : **Excellent**

No Leakage & Rubber boots ok

**Stabiliser Bar & Other bushes**

Condition : **Excellent**

Good Condition

[View this car in Website](#)

Engine & Transmission (Continued...)

**Link Rods (Ball joints)**

Condition : **Excellent**

No Noise & Rubber boots ok

**ABS**

Condition : **Excellent**

Working

**Brake Pedal**

Condition : **Excellent**

Operating Properly

**Accelerator**

Condition : **Excellent**

Working Properly

**Check Front Brake Efficiency**

Condition : **Excellent**

Operating Efficiently

**Check Rear Brake Efficiency**

Condition : **Excellent**

Operating Efficiently

**Master Cylinder & Booster**

Condition : **Excellent**

Good Condition

**Gearshift lever  
Automatic/Manual**

Condition : **Excellent**

Good Condition

**Clutch Engagement**

Condition : **Excellent**

More than 50% life

**Axle Noise**

Condition : **Excellent**

No noise & Boot okay

**Front Wheel bearings**

Condition : **Excellent**

Good Condition

**Rear Wheel bearings**

Condition : **Excellent**

Good Condition

**Differential**

Condition : **Excellent**

Good Condition

**Alignment**

Condition : **Excellent**

Good Condition

**Balancing**

Condition : **Excellent**

Good Condition

**Transmission Oil (Manual/  
Automatic)**

Condition : **Excellent**

Oil Level Condition OK

**Engine and transmission  
mountings**

Condition : **Excellent**

Good Condition

**Abnormal Engine Noise**

Condition : **Excellent**

No Noise

Engine & Transmission (Continued...)

**Back Compression**

Condition : **Excellent**

Back Compression Not Present

**Head Gasket leakage/replaced**

Condition : **Excellent**

Good Condition

**Gasket - tappet cover**

Condition : **Excellent**

Good Condition

**Engine oil leaks From Bottom/Oil Sump**

Condition : **Excellent**

Good Condition

**Silencer**

Condition : **Excellent**

Good Condition

**Catalytic Converter**

Condition : **Excellent**

Good Condition

**Engine Smoke Colour**

Condition : **Excellent**

No colour

**Air Filter**

Condition : **Bad**

Not Replaced or Not Cleaned

**Radiator**

Condition : **Excellent**

Good Condition

**Condenser**

Condition : **Excellent**

Good Condition

**Engine oil & Oil Filter**

Condition : **Satisfactory**

Not Replaced

**Coolant**

Condition : **Excellent**

Good Condition

**Brake Oil**

Condition : **Excellent**

Good Condition

**Hose Pipe**

Condition : **Excellent**

Good Condition

**Alternator Drive Belt**

Condition : **Excellent**

Good Condition

**Water Pump**

Condition : **Excellent**

Good Condition

**Tappet Noise**

Condition : **Excellent**

Working Smoothly

**Turbo Charger**

Condition : **Excellent**

Not Applicable

Engine & Transmission (Continued...)

**Heater Plugs (in Diesel)**

Condition : **Excellent**

Not Applicable

**Spark Plugs (in Petrol)**

Condition : **Excellent**

Good Condition

**Radiator Fan**

Condition : **Excellent**

Temperature Sensor Working

**Ignition Coil (petrol only)**

Condition : **Excellent**

Good Condition

**Ignition Wire Harness (petrol only)**

Condition : **Excellent**

Good Condition

**Fuel Tank and Pipes**

Condition : **Excellent**

Good Condition

**Fuel Filter (Petrol & Diesel)**

Condition : **Excellent**

Good Condition

**Fuel Injectors**

Condition : **Excellent**

Working Smoothly

## Vehicle Images

### Front Side



18-Feb-2023 11:01:30 am

Lat 10.3971237,Long 78.8294488

### Front Right Side



18-Feb-2023 11:01:38 am

Lat 10.39712,Long 78.829435

### Front Right Tyre



18-Feb-2023 11:01:54 am

Lat 10.3971354,Long 78.8294334

### Right Side



18-Feb-2023 11:01:46 am

Lat 10.3971267,Long 78.8294343

### Rear Right Tyre



18-Feb-2023 11:02:03 am

Lat 10.3971343,Long 78.8294335

### Rear Right Side



18-Feb-2023 11:02:14 am

Lat 10.3971131,Long 78.8294259

### Back Side



18-Feb-2023 11:02:26 am

Lat 10.3971226,Long 78.8294448

### Rear Left Side



18-Feb-2023 11:02:42 am

Lat 10.3971231,Long 78.8294482

[View this car in Website](#)

**Rear Left Tyre**



18-Feb-2023 11:02:57 am

Lat 10.397123, Long 78.8294488

**Left Side**



18-Feb-2023 11:02:51 am

Lat 10.3971228, Long 78.8294488

**Front Left Tyre**



18-Feb-2023 11:03:04 am

Lat 10.3971226, Long 78.8294484

**Front Left Side**



18-Feb-2023 11:03:14 am

Lat 10.3976546, Long 78.8298659

**Odometer**



18-Feb-2023 11:04:19 am

Lat 10.3966789, Long 78.8290812

## Videos

Car Exterior Video

<https://tinyurl.com/2p7b8eyx>

Car Engine Video

<https://tinyurl.com/2fbhrqh>