



**2016 MARUTI SUZUKI
BALENO (2015-2019)
ALPHA 1.2**

- 📍 Alwar 🔢 82,185 km
- ⛽ Petrol ⚙️ Manual
- 🚗 Red 👤 1st Owner

₹ 4,25,000

xmart SMART BUY. SMART EXCHANGE. 📍 X-Mart Store, Burja, Alwar

Car Quality Score

👍 Fair Buy



Registration Number RJ02XXXXXX	Registration Year January, 2017	Manufacturing Year December, 2016	Insurance Type Third Party
--	---	---	--------------------------------------

- 🛡️ Road Side Assistance 🚗 No Structural / Water Damage
- 🔄 7-Day* Easy Return 📋 200+ Inspection Checkpoints

To know more, explore this car in website


[View in website](#)

Overall rating is the 'quality score' of a vehicle derived from a 200+ point inspection process. This is backed by a machine learning algorithm that processes millions of data points to objectively depict the condition of the car in a standard & reliable way. *7-day return policy and insurance renewal may not be applicable for all the vehicles.

Inspection Report Summary

EXTERIOR

Body Panel

Right Fender, Roof are in excellent condition 

Bonnet, Trunk are replaced 

Front Bumper, Bonnet are repainted 

Chassis and Frame

Right A Pillar, Right B Pillar are in excellent condition 

Underbody Frame is replaced 

Glasses & Mirrors

All in excellent condition 

Wheels & Rims


All in excellent condition 

Standard Fitments


Left Running Board, Right Running Board are in excellent condition 

INTERIOR

Steering

Power Steering system makes noise while operating 


Dashboard & Infotainment

Dashboard, Music System and Speakers are in excellent condition 

Seats and Carpets


Seats and floormats are in excellent condition 

Standard Fitments & Features

Central Locking System and Air Bags are functioning well 

ENGINE & TRANSMISSION


Engine & Ignition System

Master Cylinder, Engine Smoke Colour, Spark Plugs are in Excellent condition 

Transmission

Alternator Drive Belt, Accelerator, Clutch system, and Gear Shifting are in excellent condition 

Fuel System

All fuel pumps, pipes and filters are in excellent condition 


SUSPENSION & BRAKES

Suspension

Link Rods, Alignment are in excellent condition 

Control Arms are not smooth 

Braking System

ABS, front and rear brakes are efficient 


Master Cylinder and Brake Pedals are in excellent condition 

ELECTRICALS & AIR CONDITIONING

Electricals

Combination Switch, Alternator are in excellent condition 

Air Conditioning

AC Compressor, all cooling and heating components are in excellent condition 

REMAINING TYRE LIFE

Front Right Tyre : 60% to 80%

Front Left Tyre : 60% to 80%

Rear Right Tyre : 60% to 80%

Rear Left Tyre : 60% to 80%

Spare Tyre (Stepney) : > 60%

Images 



Front Side



Front Right Side



Right Side



Rear Right Side



Rear Side



Rear Left Side



Left Side



Front Left Side



Engine Image



Odometer



Front Right Tyre



Front Left Tyre



Rear Right Tyre



Rear Left Tyre

Videos

















 Walkaround Video

 Engine Video

Exterior 

We Inspected 77 Points related to Exterior Parts.

 66 Good 11 Issues

-  Grill
-  Windscreen Glass
-  Right Side Apron
-  Right Fender
-  Front Right Door Functionality
-  Front Right Window Glass
-  Rear Right Door Handle
-  Right A Pillar
-  Right C Pillar
-  Front Right Wheel
-  Rear Glass
-  Dickey Shock Absorber
-  Number Plates
-  Left B Pillar
-  Left Running Board
-  Emblem
-  Bonnet Functionality
-  Right Running Board
-  Front Right Door
-  Front Right Door Handle
-  Rear Right Door Functionality
-  Rear Right Window Glass
-  Right B Pillar
-  Right Side Power Mirror
-  Rear Right Wheel
-  Trunk Functionality
-  Spare Wheel / Cover
-  Left A Pillar
-  Left C Pillar
-  Front Left Door Functionality

Exterior continued...

- ✓ Front Left Door Handle
- ✓ Left Side Power Mirror
- ✓ Rear Left Door Handle
- ✓ Fuel Cap
- ✓ Rear Left Wheel
- ✓ Reverse Camera & Parking Sensors
- ✓ Front Right Window Function
- ✓ Rear Right Window Function
- ✓ Front Windscreen Wipers
- ✓ Windscreen Jets
- ✓ Front Parking Lights
- ✓ Right Tail Lights
- ✓ Rear Left Indicator
- ✓ Front Left Indicator
- ✓ Left Headlight
- ✓ Front Left Window Glass
- ✓ Rear Left Door Functionality
- ✓ Rear Left Window Glass
- ✓ Front Left Wheel
- ✓ Left Side Apron
- ✓ Roof
- ✓ Front Left Window Function
- ✓ Rear Left Window Function
- ✓ Rear Windscreen Wiper
- ✓ Hazard Lights
- ✓ Rear Parking Lights
- ✓ Left Tail Lights
- ✓ Rear Right Indicator
- ✓ Front Right Indicator
- ✓ Right Headlight

Exterior continued...

✓ Defogger

✓ Keys

✓ Front Windows Type
Power Windows

! Front Bumper
Visible Repaint

! Right Rear Door
Replaced

! Trunk
Replaced

! Left Fender
Dents

! Rear Left Door
Visible Repaint

! Underbody Frame
Replaced

✓ Fog Lamps

✓ Wheels Type
Alloy Wheels

✓ Rear Windows Type
Power Windows



! Bonnet
Replaced

! Right Quarter Panel
Visible Repaint

! Rear Bumper
Visible Repaint

! Front Left Door
Scratches





























! Left Quarter Panel
Visible Repaint

Interior 

We Inspected 36 Points related to Interior Parts.

 35 Good

 1 Issue

- | | |
|---|--|
|  Front Right Door Trim |  Rear Right Door Trim |
|  Front Right Rubber Beading |  Rear Right Rubber Beading |
|  Front Left Door Trim |  Rear Left Door Trim |
|  Front Left Rubber Beading |  Rear Left Rubber Beading |
|  Floor Mats |  Roof Inside |
|  Driver Seat Slider |  Driver Seat Recliner |
|  Driver Seat Height Adjustment |  Passenger Seat Slider |
|  Passenger Seat Recliner |  Passenger Seat Height Adjustment |
|  Driver Seat - Safety Belts & Locking System |  Passenger Seat - Safety Belts & Locking System |
|  Dashboard |  Steering Mounted Controls |
|  Inside Rear-View Mirror |  Driver Seat |
|  Passenger Seat |  Rear Seats |
|  Stereo Controls |  Interior Lights |
|  Trunk Light |  Music System |

Interior continued...

✓ Speakers

✓ Air Bags

✓ Music System Type
Steering Wheel Mounted

✓ Power Steering Type
Electronic

✓ Central Locking System


✓ Jack And Tommy (Tool Kit)

✓ Steering Type
Power Steering

! Steering
Noisy




Engine & Transmission

We Inspected 29 Points related to Engine & Transmission.



 29 Good

 0 Issues

-  Fuel Pump
-  Master Cylinder
-  Clutch Engagement
-  Gear System
-  Engine and Transmission Mountings
-  Back Compression
-  Gasket Tappet Cover
-  Silencer
-  Engine Smoke Colour
-  Radiator
-  Hose Pipe
-  Engine Tappet Noise
-  Radiator Fan
-  Ignition Wire Harness
-  Fuel Injectors
-  Accelerator
-  Gearshift Lever
-  Axle Functioning
-  Transmission Oil
-  Engine (noise)
-  Head Gasket
-  Engine Oil Leaks
-  Catalytic Converter
-  Air Filter
-  Engine Oil & Filter
-  Alternator Drive Belt
-  Spark Plugs
-  Ignition Coil
-  Fuel Tank and Pipes

Suspension & Brakes



We Inspected 16 Points related to Suspension & Brakes.

 15 Good

 1 Issue



 Steering Column

 Front Shock Absorbers

 Rear Shock Absorbers

 Stabiliser Bar & Bushes

 Link Rods

 ABS

 Brake Pedal

 Hand Brake

 Front Brakes

 Rear Brakes

 Front Wheel Bearings

 Rear Wheel Bearings

 Alignment

 Balancing

 Brake Oil

 Control Arms
Bushing condition Worn Out

Electricals & Air Conditioning



We Inspected 21 Points on Electricals & Air Conditioning.

 19 Good

 2 Issues



 Alternator

 Starter Motor

 Odometer

 Fuel Gauge

 Tachometer

 Temperature Gauge

 Horn

 Combination Switch

 Charger/USB Port

 AC Compressor

 Condenser Fan

 Blower Motor

 AC Cooling

 Heating


 Air distribution


 Air Recirculation


 Condenser

 Coolant

 Water Pump

 Battery
Age above 3 years

 Instrument Panel Warning Lights
Warning Lights On (issues present)

Tyres 



We Inspected 5 Points related to Tyres.



 5 Good

 0 Issues


 **Front Right Tyre**
60% to 80%



 **Rear Right Tyre**
60% to 80%

 **Spare Tyre (Stepney)**
>60%

 **Front Left Tyre**
60% to 80%

 **Rear Left Tyre**
60% to 80%

car&bike Promises 



To know more, explore this car in website

[View in website](#)