



**2022 MARUTI SUZUKI
ERTIGA(2018-2022) VXI
CNG BS-VI**


- 📍 Alwar 🔢 107,178 km
- ⛽ CNG ⚙️ Manual
- 👤 Others 👤 1st Owner

₹ 10,00,000

xmart SMART BUY. SMART EXCHANGE. 📍 X-Mart Store, Burja, Alwar

Car Quality Score

👍 Fair Buy



Registration Number RJ11XXXXXX	Registration Year March, 2022	Manufacturing Year February, 2022	Insurance Type Third Party
--	---	---	--------------------------------------

🛡️ Road Side Assistance

🚗 Structural Damage

🔄 7-Day* Easy Return

📋 200+ Inspection Checkpoints

To know more, explore this car in website

[View in website](#)

Overall rating is the 'quality score' of a vehicle derived from a 200+ point inspection process. This is backed by a machine learning algorithm that processes millions of data points to objectively depict the condition of the car in a standard & reliable way. *7-day return policy and insurance renewal may not be applicable for all the vehicles.


Inspection Report Summary

EXTERIOR


Body Panel

All in excellent condition 

No panel is repaired or repainted 

No alignment issues, dents or scratches 

Chassis and Frame

Chassis, frames and pillars are in excellent condition 

No corrosion / rusting in any of the frames or pillars 


Glasses & Mirrors

All in excellent condition 

Wheels & Rims

All in excellent condition 

Standard Fitments


Rear Bumper, Left Running Board are in excellent condition 

INTERIOR


Steering

Power Steering system is working smoothly 


Dashboard & Infotainment

Dashboard, Music System and Speakers are in excellent condition 

Seats and Carpets


Seats and floormats are in excellent condition 

Standard Fitments & Features

Central Locking System and Air Bags are functioning well 

ENGINE & TRANSMISSION


Engine & Ignition System

Master Cylinder, Engine Smoke Colour, Spark Plugs are in Excellent condition 

Transmission

Alternator Drive Belt, Accelerator, Clutch system, and Gear Shifting are in excellent condition 

Fuel System


All fuel pumps, pipes and filters are in excellent condition 

SUSPENSION & BRAKES

Suspension

Control arms are smooth. Alignment and Balance are excellent 

Braking System

ABS, front and rear brakes are efficient 


Master Cylinder and Brake Pedals are in excellent condition 

ELECTRICALS & AIR CONDITIONING

Electricals

Battery and all electrical components are in excellent condition 

Air Conditioning

AC Compressor, all cooling and heating components are in excellent condition 

REMAINING TYRE LIFE

Front Right Tyre : 40% to 60%
Front Left Tyre : 40% to 60%
Rear Right Tyre : 40% to 60%
Rear Left Tyre : 40% to 60%
Spare Tyre (Stepney) : > 60%

Images 



Front Side



Front Right Side



Right Side



Rear Right Side



Rear Side



Rear Left Side



Left Side



Front Left Side



Engine Image



Odometer

Jul 27, 2024, 12:40:04 pm
GPS = 27.553249, 76.643392



Front Right Tyre

Jul 27, 2024, 12:40:32 pm
GPS = 27.553249, 76.643392



Front Left Tyre

Jul 27, 2024, 12:40:10 pm
GPS = 27.553249, 76.643392



Rear Right Tyre

Jul 27, 2024, 12:40:24 pm
GPS = 27.553249, 76.643392



Rear Left Tyre

Videos

 Walkaround Video

 Engine Video































Exterior 

We Inspected 78 Points related to Exterior Parts.

 78 Good

 0 Issues





-  Front Bumper
-  Emblem
-  Bonnet
-  Right Side Apron
-  Right Fender
-  Front Right Door Functionality
-  Front Right Window Glass
-  Rear Right Door Functionality
-  Rear Right Window Glass
-  Right B Pillar
-  Right Quarter Panel
-  Right Side Power Mirror
-  Rear Right Wheel
-  Trunk
-  Rear Bumper
-  Grill
-  Windscreen Glass
-  Bonnet Functionality
-  Right Running Board
-  Front Right Door
-  Front Right Door Handle
-  Right Rear Door
-  Rear Right Door Handle
-  Right A Pillar
-  Right C Pillar
-  Right Side View Mirror
-  Front Right Wheel
-  Rear Glass
-  Trunk Functionality
-  Dickey Shock Absorber

Exterior continued...

- ✓ Spare Wheel / Cover
- ✓ Left A Pillar
- ✓ Left C Pillar
- ✓ Left Fender
- ✓ Front Left Door Functionality
- ✓ Front Left Window Glass
- ✓ Left Side Power Mirror
- ✓ Rear Left Door Functionality
- ✓ Left Quarter Panel
- ✓ Fuel Cap
- ✓ Rear Left Wheel
- ✓ Underbody Frame
- ✓ Roof
- ✓ Front Left Window Function
- ✓ Rear Left Window Function
- ✓ Number Plates
- ✓ Left B Pillar
- ✓ Left Running Board
- ✓ Front Left Door
- ✓ Front Left Door Handle
- ✓ Left Side View Mirror
- ✓ Rear Left Door
- ✓ Rear Left Door Handle
- ✓ Rear Left Window Glass
- ✓ Front Left Wheel
- ✓ Left Side Apron
- ✓ Reverse Camera & Parking Sensors
- ✓ Front Right Window Function
- ✓ Rear Right Window Function
- ✓ Front Windscreen Wipers

Exterior continued...





























- ✓ Windscreen Jets
- ✓ Front Parking Lights
- ✓ Right Tail Lights
- ✓ Rear Left Indicator
- ✓ Front Left Indicator
- ✓ Left Headlight
- ✓ Defogger
- ✓ Keys
- ✓ Front Windows Type
Power Windows
- ✓ Hazard Lights
- ✓ Rear Parking Lights
- ✓ Left Tail Lights
- ✓ Rear Right Indicator
- ✓ Front Right Indicator
- ✓ Right Headlight
- ✓ Wheel Caps
- ✓ Wheels Type
Steel Wheels
- ✓ Rear Windows Type
Power Windows

Interior 

We Inspected 36 Points related to Interior Parts.

 36 Good

 0 Issues

- | | |
|---|--|
|  Front Right Door Trim |  Rear Right Door Trim |
|  Front Right Rubber Beading |  Rear Right Rubber Beading |
|  Front Left Door Trim |  Rear Left Door Trim |
|  Front Left Rubber Beading |  Rear Left Rubber Beading |
|  Floor Mats |  Roof Inside |
|  Driver Seat Slider |  Driver Seat Recliner |
|  Driver Seat Height Adjustment |  Passenger Seat Slider |
|  Passenger Seat Recliner |  Passenger Seat Height Adjustment |
|  Driver Seat - Safety Belts & Locking System |  Passenger Seat - Safety Belts & Locking System |
|  Dashboard |  Steering Mounted Controls |
|  Inside Rear-View Mirror |  Driver Seat |
|  Passenger Seat |  Rear Seats |
|  Stereo Controls |  Interior Lights |
|  Trunk Light |  Music System |

Interior continued...

✓ Speakers

✓ Central Locking System

✓ Steering

✓ Air Bags

✓ Jack And Tommy (Tool Kit)


✓ Music System Type
Steering Wheel Mounted

✓ Steering Type
Power Steering

✓ Power Steering Type
Electronic




Engine & Transmission

We Inspected 29 Points related to Engine & Transmission.



 29 Good

 0 Issues

-  Fuel Pump
-  Master Cylinder
-  Clutch Engagement
-  Gear System
-  Engine and Transmission Mountings
-  Back Compression
-  Gasket Tappet Cover
-  Silencer
-  Engine Smoke Colour
-  Radiator
-  Hose Pipe
-  Engine Tappet Noise
-  Radiator Fan
-  Ignition Wire Harness
-  Fuel Injectors
-  Accelerator
-  Gearshift Lever
-  Axle Functioning
-  Transmission Oil
-  Engine (noise)
-  Head Gasket
-  Engine Oil Leaks
-  Catalytic Converter
-  Air Filter
-  Engine Oil & Filter
-  Alternator Drive Belt
-  Spark Plugs
-  Ignition Coil
-  Fuel Tank and Pipes

Suspension & Brakes










We Inspected 16 Points related to Suspension & Brakes.

 16 Good

 0 Issues



- | | |
|---|--|
|  Steering Column |  Control Arms |
|  Front Shock Absorbers |  Rear Shock Absorbers |
|  Stabiliser Bar & Bushes |  Link Rods |
|  ABS |  Brake Pedal |
|  Hand Brake |  Front Brakes |
|  Rear Brakes |  Front Wheel Bearings |
|  Rear Wheel Bearings |  Alignment |
|  Balancing |  Brake Oil |

Electricals & Air Conditioning



We Inspected 21 Points on Electricals & Air Conditioning.

 21 Good

 0 Issues



-  Battery
-  Starter Motor
-  Instrument Panel Warning Lights
-  Tachometer
-  Horn
-  Charger/USB Port
-  Condenser Fan
-  AC Cooling
-  Air distribution
-  Condenser
-  Water Pump
-  Alternator
-  Odometer
-  Fuel Gauge
-  Temperature Gauge
-  Combination Switch
-  AC Compressor
-  Blower Motor
-  Heating
-  Air Recirculation
-  Coolant

Tyres



We Inspected 5 Points related to Tyres.




 5 Good

 0 Issues

 **Front Right Tyre**
40% to 60%



 **Rear Right Tyre**
40% to 60%

 **Spare Tyre (Stepney)**
>60%

 **Front Left Tyre**
40% to 60%

 **Rear Left Tyre**
40% to 60%

car&bike Promises



To know more, explore this car in website

[View in website](#)