



# 2022 KIA SONET(2022-2023) GTX PLUS 1.0 DCT


- Noida
- 4 11,500 km
- Petrol
- Automatic (dual Clutch)
- White
- 1<sup>st</sup> Owner

# ₹ 13,65,000



carthile carthile carthile Select Store, Noida Sector 16, Gautam Buddha Nagar

# **Car Quality Score**



Registration Number Registration Year **UP32XXXXXX** 

July, 2022

Manufacturing Year July, 2022

Insurance Type **Third Party** 

Free 2-Year Warranty

💫 No Structural / Water Damage

( 7-Day\* Easy Return

200+ Inspection Checkpoints

### To know more, explore this car in website

View in website

Overall rating is the 'quality score' of a vehicle derived from a 200+ point inspection process. This is backed by a machine learning algorithm that processes millions of data points to objectively depict the condition of the car in a standard & reliable way. \*7-day return policy and insurance renewal may not be applicable for all the vehicles.

Report ID: 4WCAN299104403 Stock ID: 615618

# Inspection Report Summary



#### **EXTERIOR**



#### **ENGINE & TRANSMISSION**



### **Body Panel**

All in excellent condition

No panel is repaired or repainted

No alignment issues, dents or scratches

## **Engine & Ignition System** Master Cylinder, Engine Smoke



- Colour, Spark Plugs are in Excellent
- condition
- Engine Oil & Filter not replaced

### **Chassis and Frame**

Chassis, frames and pillars are in excellent condition

No corrosion / rusting in any of the frames or pillars

# **Transmission**



Alternator Drive Belt, Accelerator, Clutch system, and Gear Shifting are in excellent condition



Fuel Injectors, Fuel Pump are in excellent condition



#### **Glasses & Mirrors**

All in excellent condition

### **SUSPENSION & BRAKES**

and Balance are excellent



#### Wheels & Rims

All in excellent condition

### Suspension



#### Standard Fitments

Rear Bumper, Left Running Board are

### **Braking System**



in excellent condition

ABS, front and rear brakes are

efficient



### INTERIOR



Master Cylinder and Brake Pedals are in excellent condition



#### Steering

condition

Power Steering system is working smoothly

### **ELECTRICALS & AIR CONDITIONING**



#### **Dashboard & Infotainment**

Dashboard, Music System and Speakers are in excellent condition

#### **Electricals**



**Seats and Carpets** Seats and floormats are in excellent Battery and all electrical components are in excellent condition



# Standard Fitments & Features

Central Locking System and Air Bags are functioning well

### **Air Conditioning**

AC Compressor, all cooling and heating components are in excellent condition



## **REMAINING TYRE LIFE**



Front Right Tyre: 60% to 80% Front Left Tyre: 60% to 80% Rear Right Tyre: 60% to 80% Rear Left Tyre: 60% to 80% Spare Tyre (Stepney): > 80%



# Images =






























Front Left Tyre





# Videos







# Exterior =

We Inspected 76 Points related to Exterior Parts.



76 Good

0 lssues

- Front Bumper
- Emblem
- Bonnet
- Right Side Apron
- Right Fender
- Front Right Door Functionality
- Front Right Window Glass
- Rear Right Door Functionality
- Rear Right Window Glass
- Right B Pillar
- Right Quarter Panel
- Front Right Wheel
- Rear Glass
- Trunk Functionality
- Dickey Shock Absorber

- **⊘** Grill
- Windscreen Glass
- Bonnet Functionality
- Right Running Board
- Front Right Door
- Front Right Door Handle
- Right Rear Door
- Rear Right Door Handle
- Right A Pillar
- Right C Pillar
- Right Side Power Mirror
- Rear Right Wheel
- Trunk
- Rear Bumper
- Number Plates



### Exterior continued...

✓ Left A Pillar	✓ Left B Pillar
✓ Left C Pillar	✓ Left Running Board
✓ Left Fender	Front Left Door
Front Left Door Functionality	Front Left Door Handle
Front Left Window Glass	✓ Left Side Power Mirror
Rear Left Door	Rear Left Door Functionality
Rear Left Door Handle	✓ Left Quarter Panel
Rear Left Window Glass	✓ Fuel Cap
Front Left Wheel	Rear Left Wheel
✓ Left Side Apron	✓ Underbody Frame
Reverse Camera & Parking Sensors	
Front Right Window Function	Front Left Window Function
Rear Right Window Function	Rear Left Window Function
Front Windscreen Wipers	Rear Windscreen Wiper
Windscreen Jets     ■	Hazard Lights
<ul> <li>Front Left Wheel</li> <li>Left Side Apron</li> <li>Reverse Camera &amp; Parking Sensors</li> <li>Front Right Window Function</li> <li>Rear Right Window Function</li> <li>Front Windscreen Wipers</li> </ul>	<ul> <li>✓ Rear Left Wheel</li> <li>✓ Underbody Frame</li> <li>✓ Roof</li> <li>✓ Front Left Window Function</li> <li>✓ Rear Left Window Function</li> <li>✓ Rear Windscreen Wiper</li> </ul>



### Exterior continued...

- Front Parking Lights
- Right Tail Lights
- Rear Left Indicator
- Front Left Indicator
- Left Headlight
- Defogger
- Keys
- Front Windows Type
  Power Windows

- Rear Parking Lights
- Left Tail Lights
- Rear Right Indicator
- Front Right Indicator
- Right Headlight
- Fog Lamps
- Wheels Type
  Alloy Wheels
- Rear Windows Type
  Power Windows



# Interior =

We Inspected 37 Points related to Interior Parts.







- Front Right Door Trim
- Front Right Rubber Beading
- Front Left Door Trim
- Front Left Rubber Beading
- Floor Mats
- Driver Seat Slider
- Driver Seat Height Adjustment
- Passenger Seat Recliner
- Driver Seat Safety Belts & Locking System
- Dashboard
- Steering Mounted Controls
- Driver Seat
- Rear Seats
- Interior Lights

- Rear Right Door Trim
- Rear Right Rubber Beading
- Rear Left Door Trim
- Rear Left Rubber Beading
- Roof Inside
- Driver Seat Recliner
- Passenger Seat Slider
- Passenger Seat Height Adjustment
- Passenger Seat Safety Belts & Locking System
- Sunroof System
- ✓ Inside Rear-View Mirror
- Passenger Seat
- Stereo Controls
- Trunk Light



### Interior continued...

- Music System
- Central Locking System
- Air Bags
- Music System Type Steering Wheel Mounted
- Power Steering Type Electronic

- Speakers
- Steering
- Jack And Tommy (Tool Kit)
- Steering Type
  Power Steering



# Engine & Transmission =

We Inspected 30 Points related to Engine & Transmission.



28 Good

O 2 Issues

- Fuel Pump
- Master Cylinder
- Clutch Engagement
- Gear System
- Engine and Transmission Mountings
- Back Compression
- ✓ Gasket Tappet Cover
- Silencer
- Engine Smoke Colour
- Hose Pipe
- Engine Tappet Noise
- Spark Plugs
- Ignition Coil
- Fuel Tank and Pipes

- Accelarator
- Gearshift Lever
- Axle Functioning
- Transmission Oil
- Engine (noise)
- Head Gasket
- Engine Oil Leaks
- Catalytic Converter
- Radiator
- Alternator Drive Belt
- Turbo Charger
- Radiator Fan
- Ignition Wire Harness
- Fuel Injectors



Air FilterNeeds Replacement

• Engine Oil & Filter
Needs Replacement



# Suspension & Brakes 🚍

We Inspected 16 Points related to Suspension & Brakes.



O 16 Good

0 lssues

- Steering Column
- Front Shock Absorbers
- Stabiliser Bar & Bushes
- ABS
- Hand Brake
- Rear Brakes
- Rear Wheel Bearings
- Balancing

- Control Arms
- Rear Shock Absorbers
- Link Rods
- Brake Pedal
- Front Brakes
- Front Wheel Bearings
- Alignment
- Brake Oil



# Electricals & Air Conditioning 🚍

We Inspected 21 Points on Electricals & Air Conditioning.



21 Good

0 lssues

- Battery
- Starter Motor
- Instrument Panel Warning Lights
- Tachometer
- Horn
- Charger/USB Port
- Condenser Fan
- AC Cooling
- Air distribution
- Condenser
- Water Pump

- Alternator
- Odometer
- Fuel Gauge
- Temperature Gauge
- Combination Switch
- AC Compressor
- Blower Motor
- Heating
- Air Recirculation
- Coolant



# Tyres =

We Inspected 5 Points related to Tyres.




0 lssues



- Front Right Tyre 60% to 80%
- Spare Tyre (Stepney) >80%
- Rear Left Tyre 60% to 80%

- Rear Right Tyre 60% to 80%
- Front Left Tyre 60% to 80%



To know more, explore this car in website

View in website