



2023 MARUTI SUZUKI GRAND VITARA ZETA SMART HYBRID AT

Gurgaon

27,291 km

Torque Converter (automatic)


White

1st Owner

₹ 15,40,000

cartice sates of carticles carticles

Car Quality Score



Registration Number Registration Year HR26XXXXXX

November, 2023

Manufacturing Year March, 2023

Insurance Type **Third Party**

Free 2-Year Warranty

No Structural / Water Damage

(7-Day* Easy Return

200+ Inspection Checkpoints

To know more, explore this car in website

View in website

Overall rating is the 'quality score' of a vehicle derived from a 200+ point inspection process. This is backed by a machine learning algorithm that processes millions of data points to objectively depict the condition of the car in a standard & reliable way. *7-day return policy and insurance renewal may not be applicable for all the vehicles.

Report ID: 4WCAN299233050 Stock ID: 616997



Inspection Report Summary =



EXTERIOR



ENGINE & TRANSMISSION



Body Panel

Bonnet, Trunk are in excellent condition

Right Fender, Right Rear Door have dents

Front Bumper has scratches

Chassis and Frame

Chassis, frames and pillars are in excellent condition

No corrosion / rusting in any of the frames or pillars

Glasses & Mirrors

All in excellent condition

Wheels & Rims

All in excellent condition

Standard Fitments

Rear Bumper, Left Running Board are in excellent condition

INTERIOR



Steering

Power Steering system is working smoothly

Dashboard & Infotainment

Dashboard, Music System and Speakers are in excellent condition

Seats and Carpets

Seats and floormats are in excellent condition

Standard Fitments & Features

Central Locking System and Air Bags are functioning well

Engine & Ignition System

Master Cylinder, Engine Smoke Colour, Spark Plugs are in Excellent condition

Transmission

Alternator Drive Belt, Accelerator, Clutch system, and Gear Shifting are in excellent condition

Fuel System

All fuel pumps, pipes and filters are in excellent condition

SUSPENSION & BRAKES



Suspension

Control arms are smooth. Alignment and Balance are excellent

Braking System

ABS, front and rear brakes are efficient

Master Cylinder and Brake Pedals are in excellent condition

ELECTRICALS & AIR CONDITIONING



Battery and all electrical components

are in excellent condition

Air Conditioning

Electricals

AC Compressor, all cooling and heating components are in excellent condition

REMAINING TYRE LIFE



Front Right Tyre: 60% to 80% Front Left Tyre: 60% to 80% Rear Right Tyre: 60% to 80% Rear Left Tyre: 60% to 80% Spare Tyre (Stepney): > 80%



Images =



































Videos







Exterior =

We Inspected 76 Points related to Exterior Parts.



72 Good

4 Issues

- Grill
- Windscreen Glass
- Bonnet Functionality
- Front Right Door
- Front Right Door Handle
- Rear Right Door Functionality
- Rear Right Window Glass
- Right B Pillar
- Right Quarter Panel
- Front Right Wheel
- Rear Glass
- Trunk Functionality
- Dickey Shock Absorber
- Left A Pillar
- Left C Pillar

- Emblem
- Bonnet
- Right Side Apron
- Front Right Door Functionality
- Front Right Window Glass
- Rear Right Door Handle
- Right A Pillar
- Right C Pillar
- Right Side Power Mirror
- Rear Right Wheel
- Trunk
- Rear Bumper
- Number Plates
- Left B Pillar
- Left Running Board



Exterior continued...

✓ Left Fender	Front Left Door
Front Left Door Functionality	Front Left Door Handle
Front Left Window Glass	Left Side Power Mirror
	Rear Left Door Functionality
✓ Rear Left Door Handle	✓ Left Quarter Panel
Rear Left Window Glass	✓ Fuel Cap
Front Left Wheel	Rear Left Wheel
✓ Left Side Apron	Underbody Frame
Reverse Camera & Parking Sensors	Roof
Front Right Window Function	Front Left Window Function
Rear Right Window Function	Rear Left Window Function
Front Windscreen Wipers	Rear Windscreen Wiper
Windscreen Jets	Hazard Lights
Front Parking Lights	Rear Parking Lights
	Left Tail Lights



Exterior continued...

- Rear Left Indicator
- Front Left Indicator
- Left Headlight
- Defogger
- Keys
- Front Windows Type
 Power Windows
- Front Bumper
 Scratches
- Right FenderDents

- Rear Right Indicator
- Front Right Indicator
- Right Headlight
- Fog Lamps
- Wheels Type
 Alloy Wheels
- Rear Windows Type Power Windows
- Right Running BoardScratches
- Right Rear DoorDents



Interior <u>=</u>

We Inspected 36 Points related to Interior Parts.







- Front Right Door Trim
- Front Right Rubber Beading
- Front Left Door Trim
- Front Left Rubber Beading
- Floor Mats
- Driver Seat Slider
- Driver Seat Height Adjustment
- Passenger Seat Recliner
- Driver Seat Safety Belts & Locking System
- Dashboard
- Inside Rear-View Mirror
- Passenger Seat
- Stereo Controls
- Trunk Light

- Rear Right Door Trim
- Rear Right Rubber Beading
- Rear Left Door Trim
- Rear Left Rubber Beading
- Roof Inside
- Driver Seat Recliner
- Passenger Seat Slider
- Passenger Seat Height Adjustment
- Passenger Seat Safety Belts & Locking System
- Steering Mounted Controls
- Driver Seat
- Rear Seats
- Interior Lights
- Music System



Interior continued...

- Speakers
- Steering
- Jack And Tommy (Tool Kit)
- Steering Type
 Power Steering

- Central Locking System
- Air Bags
- Music System Type Steering Wheel Mounted
- Power Steering Type Electronic



Engine & Transmission =

We Inspected 29 Points related to Engine & Transmission.



29 Good

0 Issues

- Fuel Pump
- Master Cylinder
- Clutch Engagement
- Gear System
- Engine and Transmission Mountings
- Back Compression
- Gasket Tappet Cover
- Silencer
- Engine Smoke Colour
- Radiator
- Hose Pipe
- Engine Tappet Noise
- Radiator Fan
- Ignition Wire Harness
- Fuel Injectors

- Accelarator
- Gearshift Lever
- Axle Functioning
- Transmission Oil
- Engine (noise)
- Head Gasket
- Engine Oil Leaks
- Catalytic Converter
- Air Filter
- Engine Oil & Filter
- Alternator Drive Belt
- Spark Plugs
- Ignition Coil
- ✓ Fuel Tank and Pipes



Suspension & Brakes 🚍

We Inspected 16 Points related to Suspension & Brakes.



O 16 Good

0 lssues

- Steering Column
- Front Shock Absorbers
- Stabiliser Bar & Bushes
- ABS
- Hand Brake
- Rear Brakes
- Rear Wheel Bearings
- Balancing

- Control Arms
- Rear Shock Absorbers
- Link Rods
- Brake Pedal
- Front Brakes
- Front Wheel Bearings
- Alignment
- Brake Oil



Electricals & Air Conditioning 🚍

We Inspected 21 Points on Electricals & Air Conditioning.



21 Good

0 lssues

Battery

Alternator

Starter Motor

- Odometer
- Instrument Panel Warning Lights
- Fuel Gauge

Tachometer

Horn

Combination Switch

Temperature Gauge

Charger/USB Port

AC Compressor

Condenser Fan

Blower Motor

AC Cooling

Heating

Air distribution

Air Recirculation

Condenser

Coolant

Water Pump



Tyres =

We Inspected 5 Points related to Tyres.




0 Issues



- Front Right Tyre 60% to 80%
- Spare Tyre (Stepney) >80%
- Rear Left Tyre 60% to 80%

- Rear Right Tyre 60% to 80%
- Front Left Tyre 60% to 80%



To know more, explore this car in website

View in website