



2023 MARUTI SUZUKI XL6 ZETA MT PETROL


- Gurgaon
- 25,252 km
- Manual
- White
- 1st Owner

₹ 11,49,000



car (Store, Rithoj, Gurgaon

Car Quality Score



Registration Number Registration Year HR33XXXXX

November, 2023

Manufacturing Year August, 2023

Insurance Type **Third Party**

Free 2-Year Warranty

No Structural / Water Damage

7-Day* Easy Return

200+ Inspection Checkpoints

To know more, explore this car in website

View in website

Overall rating is the 'quality score' of a vehicle derived from a 200+ point inspection process. This is backed by a machine learning algorithm that processes millions of data points to objectively depict the condition of the car in a standard & reliable way. *7-day return policy and insurance renewal may not be applicable for all the vehicles.

Report ID: 4WCAN299366504 Stock ID: 617958

Inspection Report Summary =



EXTERIOR



ENGINE & TRANSMISSION

Engine & Ignition System



Body Panel

Front Bumper, Right Fender are in excellent condition

Bonnet. Trunk have dents

Chassis, frames and pillars are in





Colour, Spark Plugs are in Excellent condition

Transmission

Alternator Drive Belt, Accelerator, Clutch system, and Gear Shifting are

in excellent condition

No corrosion / rusting in any of the frames or pillars

Glasses & Mirrors

Chassis and Frame

excellent condition

All in excellent condition

Fuel System

All fuel pumps, pipes and filters are in excellent condition

Wheels & Rims

SUSPENSION & BRAKES



All in excellent condition

Suspension

Control arms are smooth. Alignment and Balance are excellent

Master Cylinder and Brake Pedals are

Standard Fitments

Rear Bumper, Left Running Board are in excellent condition

Braking System

ABS, front and rear brakes are efficient

INTERIOR

Steering



Power Steering system is working smoothly

in excellent condition



Dashboard & Infotainment

Dashboard, Music System and Speakers are in excellent condition

ELECTRICALS & AIR CONDITIONING



Seats and Carpets

Seats and floormats are in excellent condition

Air Conditioning

Electricals

AC Compressor, all cooling and heating components are in excellent condition

Battery and all electrical components



Standard Fitments & Features

Central Locking System and Air Bags are functioning well

REMAINING TYRE LIFE

are in excellent condition



Front Right Tyre: 60% to 80% Front Left Tyre: 60% to 80% Rear Right Tyre: 60% to 80% Rear Left Tyre: 60% to 80% Spare Tyre (Stepney): > 80%



Images =



Front Side



Right Side





Engine Image



Front Right Side



Rear Right Side




Rear Left Side



ot 03, 2024 03:38:59 pm PSI = 28.404194 ₀ 77.059513 Odometer





Front Right Tyre



Front Left Tyre





Rear Left Tyre

Videos







Exterior =

We Inspected 76 Points related to Exterior Parts.



75 Good



- Front Bumper
- Emblem
- Bonnet Functionality
- Right Running Board
- Front Right Door
- Front Right Door Handle
- Right Rear Door
- Rear Right Door Handle
- Right A Pillar
- Right C Pillar
- Right Side Power Mirror
- Rear Right Wheel
- Trunk
- Rear Bumper
- Number Plates

- Grill
- Windscreen Glass
- Right Side Apron
- Right Fender
- Front Right Door Functionality
- Front Right Window Glass
- Rear Right Door Functionality
- Rear Right Window Glass
- Right B Pillar
- Right Quarter Panel
- Front Right Wheel
- Rear Glass
- Trunk Functionality
- Dickey Shock Absorber
- Left A Pillar



Exterior continued...

✓ Left B Pillar	✓ Left C Pillar
Left Running Board	✓ Left Fender
Front Left Door	Front Left Door Functionality
Front Left Door Handle	Front Left Window Glass
Left Side Power Mirror	
Rear Left Door Functionality	
✓ Left Quarter Panel	Rear Left Window Glass
✓ Fuel Cap	Front Left Wheel
✓ Rear Left Wheel	✓ Left Side Apron
✓ Underbody Frame	Reverse Camera & Parking Sensors
✓ Roof	Front Right Window Function
Front Left Window Function	Rear Right Window Function
Rear Left Window Function	Front Windscreen Wipers
Rear Windscreen Wiper	Windscreen Jets
✓ Hazard Lights	Front Parking Lights



Exterior continued...

- Rear Parking Lights
- Left Tail Lights
- Rear Right Indicator
- Front Right Indicator
- Right Headlight
- Fog Lamps
- Wheels Type
 Alloy Wheels
- Rear Windows Type
 Power Windows

- Right Tail Lights
- Rear Left Indicator
- Front Left Indicator
- Left Headlight
- Defogger
- Keys
- Front Windows Type
 Power Windows
- BonnetDents



Interior <u>=</u>

We Inspected 36 Points related to Interior Parts.







- Front Right Door Trim
- Front Right Rubber Beading
- Front Left Door Trim
- Front Left Rubber Beading
- Floor Mats
- Driver Seat Slider
- Driver Seat Height Adjustment
- Passenger Seat Recliner
- Driver Seat Safety Belts & Locking System
- Dashboard
- Inside Rear-View Mirror
- Passenger Seat
- Stereo Controls
- Trunk Light

- Rear Right Door Trim
- Rear Right Rubber Beading
- Rear Left Door Trim
- Rear Left Rubber Beading
- Roof Inside
- Driver Seat Recliner
- Passenger Seat Slider
- Passenger Seat Height Adjustment
- Passenger Seat Safety Belts & Locking System
- Steering Mounted Controls
- Driver Seat
- Rear Seats
- Interior Lights
- Music System



Interior continued...

- Speakers
- Steering
- Jack And Tommy (Tool Kit)
- Steering Type
 Power Steering

- Central Locking System
- Air Bags
- Music System Type Steering Wheel Mounted
- Power Steering Type Electronic



Engine & Transmission =

We Inspected 29 Points related to Engine & Transmission.



29 Good

0 Issues

- Fuel Pump
- Master Cylinder
- Clutch Engagement
- Gear System
- Engine and Transmission Mountings
- Back Compression
- Gasket Tappet Cover
- Silencer
- Engine Smoke Colour
- Radiator
- Hose Pipe
- Engine Tappet Noise
- Radiator Fan
- Ignition Wire Harness
- Fuel Injectors

- Accelarator
- Gearshift Lever
- Axle Functioning
- Transmission Oil
- Engine (noise)
- Head Gasket
- Engine Oil Leaks
- Catalytic Converter
- Air Filter
- Engine Oil & Filter
- Alternator Drive Belt
- Spark Plugs
- Ignition Coil
- Fuel Tank and Pipes



Suspension & Brakes 🚍

We Inspected 16 Points related to Suspension & Brakes.



O 16 Good

0 lssues

- Steering Column
- Front Shock Absorbers
- Stabiliser Bar & Bushes
- ABS
- Hand Brake
- Rear Brakes
- Rear Wheel Bearings
- Balancing

- Control Arms
- Rear Shock Absorbers
- Link Rods
- Brake Pedal
- Front Brakes
- Front Wheel Bearings
- Alignment
- Brake Oil



Electricals & Air Conditioning 🚍

We Inspected 21 Points on Electricals & Air Conditioning.



21 Good

0 lssues

Battery

Alternator

Starter Motor

- Odometer
- Instrument Panel Warning Lights
- Fuel Gauge

Tachometer

Horn

Combination Switch

Temperature Gauge

Charger/USB Port

AC Compressor

Condenser Fan

Blower Motor

AC Cooling

Heating

Air distribution

Air Recirculation

Condenser

Coolant

Water Pump



Tyres =

We Inspected 5 Points related to Tyres.




0 Issues



- Front Right Tyre 60% to 80%
- Spare Tyre (Stepney) >80%
- Rear Left Tyre 60% to 80%

- Rear Right Tyre 60% to 80%
- Front Left Tyre 60% to 80%



To know more, explore this car in website

View in website